



ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspection Vehicle No: SYM7697  
 at Workshop m/s: Woolworth  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SYM76976 Yr Regn: 1199  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA  
 Make: Toyota Allion c.c. 1496  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 240437 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: N2T260 303427  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185/70R14  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 1.31 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 21A24989  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 mm Rear 6 mm  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 18/1/19 D.O.I. 10/6/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: 0/S only / Frt / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>11/6/19</u>	<u>confirmed final by #600 with Angies. (red \$1172.68 / 621)</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_) )  
 : Interview (\$ \_\_\_\_\_) )  
 : Tech. Invs (\$ \_\_\_\_\_) )  
 : Weekend (\$ \_\_\_\_\_) )  
 ) \$ + RS \_\_\_ \$  
 ) Photos  
 ) Others  
 TOTAL \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG19001614/hb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 24-01-2019	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJX 2479U	Veh. Inspected	SJM 7697G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/01/2019
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/01/2019	Inspection Date	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
 BEDOK NORTH AVE 4,  
 #01-2008/10/12 SINGAPORE 489977  
 TEL : 6441 5655 FAX : 6441 5355/6243 8121  
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

**TO :** SXXX0426D  
 PATAMA LOVAJANA  
 BLK 579 PASIR RIS STREET 53  
 #11-79  
 SINGAPORE 510579  
 TEL : FAX :  
 PH : 96613772  
 ATTN :

## ESTIMATE BILL

**Number :** EB00005069  
**Date :** 24/01/2019  
**Case No :** AD00010207  
**Vehicle No :** SJM7697G  
**Chassis:** NZT2603034217  
**Year of Mfr** 2008  
**Policy No** 5055198005-06  
**Model :** TOYOTA ALLION A15  
 1.5 (A)

**Term:**

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT DOOR RH	1.0	896.90	25	672.68
	<b>List Price - Parts Sub Total</b>				672.68
2	WING MIRROR RH - REPAIR	1.0			
3	FRONT DOOR HANDLE RH - REPAIR	1.0			
4	ROCKER PANEL RH - REPAIR	1.0			
	<b>Special Nett Price - Parts Sub Total</b>				0.00
	<b>Parts Total</b>				672.68
5	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
7	ANTI-RUST COATING	1.0	100.00	0	100.00
	<b>Labour 1 Sub Total</b>				1,100.00
<p><i>not about</i></p> <p><i>10/6/19</i></p> <p><i>Whiggle Office</i></p>					
<p><i>plp 600</i></p> <p><i>327.</i></p>					
<p><i>10/6/19</i></p>					
<p><i>Whiggle Office</i></p>					
<p>SINGAPORE DOLLARS : ONE THOUSAND EIGHT HUNDRED NINETY-SIX AND CENTS SEVENTY-SEVEN ONLY</p>			<p><b>Less Excess</b></p> <p><b>SUBTOTAL</b></p> <p>GST 7.00%</p> <p><b>TOTAL</b></p>		<p>0.00</p> <p>1,772.68</p> <p>124.09</p> <p><b>1,896.77</b></p>

Date of accident : 18/01/2019 03:30 PM. Place : CARPARK OF BLK147 POTONG PASIR AVE 1

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	0426D
<b>Vehicle Details</b>	
Vehicle No.:	SJM7697G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION A15 A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1NZD227209
Chassis No.:	NZT2603034217
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,104.00
Original Registration Date:	15 Jan 2009
First Registration Date:	15 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$16,104.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Jan 2029
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$26,047.00
COE Rebate Amount:	\$24,989.00
<b>Total Rebate Amount:</b>	<b>\$24,989.00</b>

The information contained herein is correct as at 10 Jun 2019

OK

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#08-16  
Singapore 079120  
Attn: Motor Claims Dept

Dear Sir/ Madam

**ACCIDENT INVOLVING VEHICLE NO SJM 7697G & SJX 2479U ALONG  
CARPARK OF BLK 147 POTONG PASIR AVE 1 ON 18/01/2019**

We understand that you are the insurer of SJX 2479U vehicle.

I/We wish to inform you that my/our vehicle SJM 7697G have been completed repairs to my/our satisfaction by M/s HOCK WAH MOTOR WORKSHOP PTE LTD. I/We therefore propose to claim from your as follows:

1.	Cost of Repairs (w/GST)	SS	642.00
2.	Loss of Use/Rental( <u>SS120</u> x <u>3</u> days)	SS	360.00
3.	LTA Search Fee/GIA Reports	SS	2.00
	<b>TOTAL</b>	<b>SS</b>	<b><u>1,004.00</u></b>

Please let us have your reply soonest possible.

Thank you.

Yours faithfully



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19001614/HB3

29 APRIL 2019

**TAN JOCK HUA**  
BLK 23 HAIG ROAD  
# 16-23  
SINGAPORE 430023

Dear Sir/Madam,

**ACCIDENT INVOLVING SJX2479U & SJM7697G ALONG/AT OPEN CARPARK AT  
BLK 148 POTONG PASIR ON 18/01/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SJM7697G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

**KHANCHNA**  
Case Handler  
DID: 6841-2360  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*



AUTHORIZATION TO ACT  
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)


I, PATANA LOVAJANA ("the third party claimant")  
of BLK 571 PASIR RUC ST 53, #11-79, S (510879) (address),  
owner of SJM7697C (vehicle no.) hereby authorize  
HOCK WAH MOTOR WORKSHOP PTE LTD

("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SJM7697C that was  
damaged pursuant to the accident which occurred on 18/01/2019 (date) along  
CARPARK OF BLK 147 POTONG PASIR AVE 1 (location)  
involving vehicle no/s SJX 24714 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment furtherto settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 18 day of JAN (month) 20 19 (year)

  
Signed by "the third party claimant"

  
  
Signed by "the workshop"



**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, HOCK WAH MOTOR WORKSHOP PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 642.00 (repair costs), S\$ 300.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SJM 7697G that was damaged pursuant to the accident which occurred on 18.01.2019 (date) along CARPARK OF BLK147 TOWNH PASIR AVE 1 (location) involving vehicle no/s SJK 2479U.

This is pursuant to the inspection conducted on 10.06.2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PATAMA LOVAGANA ("third party claimant") of vehicle no. SJM 7697G to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJM 7697G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.


This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29<sup>th</sup> day of Aug (month) 20 19 (year)



CKS

Signed by AIG appointed surveyor



Chopped & Signed by

# HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E  
BEDOK NORTH AVE 4,  
#01-2008/10/12 SINGAPORE 489977  
TEL : 6441 5655 FAX : 6441 5355/6243 8121  
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX0426D  
AIG Asia Pacific Insurance Pte Ltd  
NO 78 Shenton Way  
# 07-16 CHARTIS Building  
SINGAPORE 079120  
TEL : 1800 4193000 FAX : 68357416  
PH :  
ATTN :

## TAX INVOICE

Number : IV00060646  
Date : 23/07/2019  
Case No :  
Vehicle No : SJM7697G  
Chassis : NZT2603034217  
Year of Mfr : 2008  
Policy No : 5055198005-06  
Model : TOYOTA ALLION A15  
1.5 (A)

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT DOOR RH - REPAIR	1.0			
2	WING MIRROR RH - REPAIR	1.0			
3	FRONT DOOR HANDLE RH - REPAIR	1.0			
4	ROCKER PANEL RH - REPAIR	1.0			
	Special Nett Price - Parts Sub Total				0.00
	Parts Total				0.00
5	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	200.00	0	200.00
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	400.00	0	400.00
7	ANTI-RUST COATING	1.0			
	Labour 1 Sub Total				600.00
SINGAPORE DOLLARS : SIX HUNDRED FORTY-TWO AND CENTS ZERO ONLY			Less Excess		0.00
			SUBTOTAL		600.00
			GST 7.00%		42.00
			TOTAL		642.00

Date of accident : 18/01/2019 03:30 PM. Place : CARPARK OF BLK147 POTONG PASIR AVE 1

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



KOH CAR HO PTE.LTD.  
 Reg No: 201422857D  
 3011 PEEKAI INDUSTRIAL PARK E  
 #01-2010 SINGAPORE 489977

## INVOICE

Refer to Rental Agreement: CRA# 200096.  
 Reference Vehicle: SJM7697C.  
 Date: 13.06.2019.

### Customer Information

Name: PATAMA LOVAJANA NRIC No.: S77704260  
 Address: BLK579 PASIR RIS ST 53 #11-79  
S (510579.) Contact No: 96613772

### Rental Car Information

Vehicle No.: SLA 5867 X  
 Make & Model: TOYOTA VIOS.  
 Start Date: 10 / 06 / 19  
 End Date: 13 / 06 / 19

Rent for (No. of Days) 3  
 Rate at (Per Day) \$120.00  
 Total Amount \$ 360.00

  
 Customer Signature

  
 Authorized Signature



KOH CAR HO PTE.LTD.  
Reg No: 201422837D  
3011 BEDOK INDUSTRIAL PARK E  
#01-2010 SINGAPORE 489977

R.Vehicle No. SJM7697C

CRA# -200096

## RENTAL AGREEMENT - CLAIM

### Hirer's Particulars

Name: PATAMA LOVAJANA NRIC No.: S7770426D

Address: BLK 579 PASIR RIS ST 53 # 11-79

S ( 510579 )

Contact No: 96613722

Licence Date: 02 / 08 / 2002

Birth Date: 27 / 12 / 1977

### Additional Driver's Particulars

Name: \_\_\_\_\_ NRIC No.: \_\_\_\_\_

Licence Date:  / /

Contact No: \_\_\_\_\_

### Rental Vehicle

Vehicle No.: 8LR587X Start Date: 10 / 06 / 2019

Rate (Per day): \_\_\_\_\_ No. of days: \_\_\_\_\_ End Date: 13 / 06 / 2019

PL (Out): \_\_\_\_\_ PL (In): OK /  Time out/in: 12:00hrs - 14:00hrs

The Hirer agreed to the Rental Agreement as followed: -

- Rental vehicle is restricted to SINGAPORE use only, check water and engine oil daily.
- No refund if vehicle return early.
- Hirer is liable to pay all fines, summons, claims, excess within rental period.
- Hirer shall bear the responsibility if any damages found on/in vehicle.
- Extension: One day in advance notice is required otherwise no extension will be allowed.
- Car collection and return shall be within the office operating hour.
- Excess: In the event when accident occurred, the Hirer is liable to bear the excess of at least S\$4,000 / S\$8,000 (Young, Inexperience Driver) in cash plus loss of earnings.

Any problem arises to vehicle within rental period, Hirer must inform 6441 5655 immediately.

Hirer acknowledges all T&C and signifies acceptance upon signing.

  
Hirer and Driver Signature

\_\_\_\_\_  
Date & Company Stamp (if any)



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-19-010849

Date of Request: 18/01/2019

Your Ref No:

Online Purchase

 Hock Wah Motor Workshop Pte Ltd  
 Blk 3011, Bedok Industrial Park E,  
 #01-2008/2010/2012  
 Singapore 489977

Dear Sir/Madam,

 Enquiry Date 18/01/2019  
 Enquiry By Adeline Tan Qun Fang  
 TP Vehicle No. SJX2479U  
 Accident Date 18/01/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJX2479U	AIG Asia Pacific Insurance Pte. Ltd.	25/08/2018-24/08/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-19-010849

Date of Request: 18/01/2019

Your Ref No: Online Purchase

 Hock Wah Motor Workshop Pte Ltd  
 Blk 3011, Bedok Industrial Park E,  
 #01-2008/2010/2012  
 Singapore 489977

Dear Sir/Madam,

 Enquiry Date 18/01/2019  
 Enquiry By Adeline Tan Qun Fang  
 TP Vehicle No. SJX2479U  
 Accident Date 18/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO  Cash  Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019 <a href="#">Edit Reg</a>		10 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$600.00</b> <a href="#">Edit Estimates</a>	<b>S\$600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>TAN JOCK HUA</b> , ID: -								
Main Claimant:	<b>PATAMA LOVAJANA</b> , ID: S7770426D								
Vehicle Reg. No.:	<b>SJM7697G</b>	Date of Loss:	18/01/2019 15:00 - :59 [120 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 2117864755SG</b>	Policy/Cover Note No.:	1800100643 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SJX2479U</b>	Policy No. (Claimant):	5055198005-06						
		Excess:							
Repairer:	<b>Hock Wah Motor Workshop Pte Ltd (Bedok)</b> Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 04/02/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
<ul style="list-style-type: none"> <li>AIG_SG (16/04/2019): <b>Conflicting DOA</b></li> <li>AIG_SG (25/01/2019): <b>Confirmation of DOA</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SJM7697G (2117864755SG)  
[SJX2479U]  
TP  
PATAMA LOVAJANA  
Jan 18 2019 3:00PM  
[TAN JOCK HUA]  
Hock Wah Motor Workshop Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float: right;">View in Browser <input type="button" value="v"/></span>	
<b>Letters/Correspondences</b>										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	{Draft}	Third Party Express Settlement – Payment Breakdown							Edit		
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	13/06/19 16:02	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
2	13/06/19 16:02	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
3	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
4	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
5	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
6	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
7	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
8	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
9	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
10	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
11	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
12	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
13	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
14	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
15	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
16	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
17	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
18	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
19	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
20	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
21	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
22	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
23	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
24	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
25	13/06/19 16:02	General View							Load JPG	<input checked="" type="checkbox"/>	
26	13/06/19 16:02	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
27	13/06/19 16:02	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
28	13/06/19 16:02	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
29	13/06/19 16:02	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
30	13/06/19 16:02	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
31	13/06/19 16:02	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	24/01/19 16:30	TP GIA REPORT							Load PDF		
2	24/01/19 16:30	TP ESTIMATE							Load PDF		
3	29/01/19 09:25	OI DRIVING LICENCE STATUS							Load PDF		
4	12/06/19 08:42	TP ESTIMATE- MARKED							Load PDF		
5	18/07/19 16:18	AMENDED OI GIA REPORT							Load PDF		
6	17/09/19 12:13	WORKSHOP INVOICE							Load PDF		
7	17/09/19 12:13	Authorisation to Act							Load PDF		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
8	17/09/19 12:13	Release Voucher		Load PDF
9	17/09/19 12:13	RENTAL RECEIPT		Load PDF
10	17/09/19 12:13	GIA SEARCH		Load PDF
11	17/09/19 12:13	LOD		Load PDF
12	17/09/19 12:13	LETTER TO OI		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	25/01/19 09:50	OI GIA REPORT		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001614/UDB3Q2

Date: 17/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800100643  
**Claimant**  
**Vehicle No :** SJM7697G **Insured Vehicle No :** SJX2479U  
**Date of Loss:** 18/01/2019 **Nature of Claim:** TP **Claim No:** 2117864755SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJM7697G**  
 Make & Model: TOYOTA ALLION, 1.5 (A) Engine No: 1NZD227209  
 Reg. Date: 15/01/2009 (Man. Year: 2008) Chassis No: NZT2603034217  
 Colour: Black Odometer: 240437 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14  
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	672.67	0.00	672.67	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	600.00	500.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,772.67</b>	<b>600.00</b>	<b>1,172.67</b>	<b>66.15</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>124.09</b>	<b>42.00</b>	<b>82.09</b>	<b>66.15</b>
<b>Nett Amount (S\$)</b>	<b>1,896.76</b>	<b>642.00</b>	<b>1,254.76</b>	<b>66.15</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>944.00</b>		

## INSPECTION

Date of Assignment: 10/06/2019  
 Date Inspected: 10/06/2019 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)  
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012 Singapore 489977  
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	896.90 FL	*- FL
2	1		*WIRNG MIRROR RH (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*FRONT DOOR HANDLE RH (NPA)	Repair	0.00 FS	*- FS
4	1		*ROCKER PANEL RH (NPA)	Not Necessary	0.00 FS	*- FS
<b>Sub Total (S\$)</b>					<b>896.90</b>	<b>0.00</b>
- List Item Discount on L Items 25.00/25.00% (S\$)					224.23	0.00
<b>Total Parts (S\$)</b>					<b>672.67</b>	<b>0.00</b>

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	500.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	500.00	400.00
3	ANTI-RUST COATING	New	100.00	0.00
			<b>Gross Labour Cost (S\$)</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >