

Surveyor

REF: CS/LAW19001648 / T1 v13e2

Special Instruction:

US: \$ 16400.00

From (Person): Belle of Comlaw LLC Date/Time: 18072019

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Auto Performance & JP Knights

Workshop: 833 Motorsport

OD (IP Re-inspection) / Evaluation

To Inspect Vehicle No: SJC 8999G Insured: SKW 91675

at Workshop m/s 833 Motorsport

of 81k 20 Sun Ming Ind Est # D1-16

Policy No: LIM.509725-E Claim No: PCS-CCC-18-217959-ERG10

Sum Insured: Excess:

Make of Veh: D.O.A. 27-12-2016

(Client's Record)

01-02-2019 (Friday) @ 3 pm - 4pm SJE

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 7 days)

Date/Time: 7/3/19 Submit Final Fig 15713150, 6 days (Red \$ 3050 / 20 %; Original days)

Date/Time	Action/Instruction
	3 Church Street Singapore 049483 (Mr. Lim - 92328116)
	SJC 8999G - X
	SKW 91675 - CBS / C7118017606 / G13e2
	QIN: 25092018
	RECEIVED 08 MAR 2019
	7/3/2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

1000

1000

1) Date/Time 8/3- typist File Pass to

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

Belle

From: Belle
Sent: Friday, 18 January, 2019 4:28 PM
To: 'Admin-D (LKKAuto)'; 'SUR'
Cc: 'Sophie'
Subject: NEW ASSIGNMENT; RE-INSPECTION OF SJC 8999G; OUR REF: LIM.509725.E;
YOUR REF: PCS.CCC.18.217959.ERGO; PART 1 & 2
Attachments: 18012019155744.pdf; 18012019160007.pdf

M/s LKK AUTO CONSULTANTS PTE LTD

Block 51 Paya Ubi Industrial Park
Ubi Avenue 1, #02-25
Singapore 409933
Tel: 6256 3561 / Fax: 6256 4315
Email: sur@lkkauto.com

Dear Sirs,

**MC/MC 7821/2018; CLAIMANT: LIM CHEW CHONG
ACCIDENT ON 27.12.16 INVOLVING SKW91675 & SJC8999G ALONG TRAFFIC JUNCTION OF NEW
UPPER CHANGI ROAD AND CHAI CHEE ROAD**

We refer to the above matter.

We act for the Defendant **(SKW91675)** and M/s Riaz LLC act for the Plaintiff (vehicle no. SJC8999G).

Please be informed that by consent of all parties, you are appointed as the Single Joint Expert for this action to provide an independent assessment in respect of costs of repairs for vehicle no. SJC8999G. ***We enclose herewith relevant documents:-***

1. All parties' GIA Reports and police reports;
2. All parties' damage photographs;
3. Final Repair Bill;
4. Survey Report by Auto Performance Appraisal; and
5. Pre-Repair Report by JP Knights Adjusters & Surveyors.

Kindly note that as a Single Joint Expert appointed by the Court, your primary duty is to the Court and you are required to give a fair and reasonable assessment of costs for **SJC8999G**.

Please conduct a re-inspection of the Plaintiff's car and let us have your views on the costs of repairs, period of repairs, etc.

Please see attached a copy of a letter from the Plaintiff's solicitor M/s RIAZ LLC which is self-explanatory for your attention. Re-inspection to be carried out the Plaintiff's work place.

Please let us have your Single Joint Report in due course.

P.S. ATTACHMENT WILL BE SEND SEPARATELY.

Thank You and Best Regards
Ms Balqis (Bel)
Secretary

For and on behalf of **Ms Charlene Chee**
Associate Director

M/s ComLaw LLC

64 Cecil Street
#03-02 IOB Building
Singapore 049711
Tel: (65) 6538 1221
Direct Fax: (65) 6506 9156
DID : (65) 6506 9162
Email: belle@comlaw.com.sg

This email is intended solely for the abovenamed addresses(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arises as a result of internet transmission.

From: Sophie [<mailto:riaz@justice.com.sg>]
Sent: Monday, 14 January, 2019 10:10 AM
To: Charlene Chee <charlenechee@comlaw.com.sg>
Cc: Belle <belle@comlaw.com.sg>
Subject: RE-INSPECTION OF SJC 8999G; OUR REF: LIM.509725.E; YOUR REF: PCS.CCC.18.217959.ERGO

WITHOUT PREJUDICE

Dear Charlene/Belle,

We refer to the above matter and our letter to you dated 8th January 2019.

Kindly let us know whether the re-inspection can be carried out at our client's workplace for us to obtain his availability on dates. Thank you.

Best regards,
Sophie
Legal Executive
RIAZ LLC
Tel: 65340110
Fax: 65340220

**** DISCLAIMER****

THIS EMAIL AND ANY FILES TRANSMITTED WITH IT ARE CONFIDENTIAL AND SUBJECT TO LEGAL PROFESSIONAL PRIVILEGE AND INTENDED SOLELY FOR THE USE OF THE INDIVIDUAL OR ENTITY TO WHO THEY ARE ADDRESSED. IF YOU HAVE RECEIVED THIS EMAIL IN ERROR PLEASE NOTIFY THE SYSTEM MANAGER. THIS MESSAGE CONTAINS CONFIDENTIAL INFORMATION AND IS INTENDED ONLY FOR THE INDIVIDUAL

NAMED. IF YOU ARE NOT THE NAMED ADDRESSEE YOU SHOULD NOT DISSEMINATE, DISTRIBUTE OR COPY THIS EMAIL. PLEASE NOTIFY THE SENDER IMMEDIATELY BY EMAIL IF YOU HAVE RECEIVED THIS EMAIL BY MISTAKE AND DELETE THIS EMAIL FROM YOUR SYSTEM. IF YOU ARE NOT THE INTENDED RECIPIENT YOU ARE NOTIFIED THAT DISCLOSING, COPYING, DISTRIBUTING OR TAKING ANY ACTION IN RELIANCE ON THE CONTENTS OF THIS INFORMATION IS STRICTLY PROHIBITED.

Catherine Chong (LKK Auto)

From: Sophie <riaz@justice.com.sg>
Sent: Wednesday, 23 January, 2019 5:43 PM
To: 'Admin-D (LKKAuto)'; 'Belle'
Cc: 'assignments'
Subject: RE: NEW ASSIGNMENT; RE-INSPECTION OF SJC 8999G; OUR REF: LIM.509725.E; YOUR REF: PCS.CCC.18.217959.ERGO; PART 1 & 2

Dear Catherine,

We refer to the above matter and your email to us dated 21 January 2019.

Our client's car is available for re-inspection on the following dates at 3 Church Street, Samsung Hub Singapore 049483:

S/R	Date	Time
1	29/1/19 (Tuesday)	11.45am – 12.45am
2	30/1/19 (Wednesday)	
3	1/2/19 (Friday)	3pm- 4pm

Kindly let us know your availability so we may relay the same to our client. Thank you.

Best regards,
Sophie
Legal Executive
RIAZ LLC
Tel: 65340110
Fax: 65340220

**** DISCLAIMER****

THIS EMAIL AND ANY FILES TRANSMITTED WITH IT ARE CONFIDENTIAL AND SUBJECT TO LEGAL PROFESSIONAL PRIVILEGE AND INTENDED SOLELY FOR THE USE OF THE INDIVIDUAL OR ENTITY TO WHO THEY ARE ADDRESSED. IF YOU HAVE RECEIVED THIS EMAIL IN ERROR PLEASE NOTIFY THE SYSTEM MANAGER. THIS MESSAGE CONTAINS CONFIDENTIAL INFORMATION AND IS INTENDED ONLY FOR THE INDIVIDUAL NAMED. IF YOU ARE NOT THE NAMED ADDRESSEE YOU SHOULD NOT DISSEMINATE, DISTRIBUTE OR COPY THIS EMAIL. PLEASE NOTIFY THE SENDER IMMEDIATELY BY EMAIL IF YOU HAVE RECEIVED THIS EMAIL BY MISTAKE AND DELETE THIS EMAIL FROM YOUR SYSTEM. IF YOU ARE NOT THE INTENDED RECIPIENT YOU ARE NOTIFIED THAT DISCLOSING, COPYING, DISTRIBUTING OR TAKING ANY ACTION IN RELIANCE ON THE CONTENTS OF THIS INFORMATION IS STRICTLY PROHIBITED.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, January 23, 2019 10:21 AM
To: 'Belle' <belle@comlaw.com.sg>
Cc: 'Sophie' <riaz@justice.com.sg>; assignments <assignments@lkkauto.com>
Subject: RE: NEW ASSIGNMENT; RE-INSPECTION OF SJC 8999G; OUR REF: LIM.509725.E; YOUR REF: PCS.CCC.18.217959.ERGO; PART 1 & 2

Dear Belle,

Received with thanks.

Best Regards,

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 8181F

Vehicle Details

Vehicle No.: SJC8999G

Vehicle to be Exported: No

Intended: 06 Mar 2019

Deregistration Date:

Vehicle Make: MITSUBISHI

Vehicle Model: EVO X GSR SST
6-SPEED AMT

Primary Colour: Red

Manufacturing Year: 2008

Engine No.: 4B11BT9127

Chassis No.: JMF5MCZ4A9U000413

Maximum Power: 217.0 kW (290 bhp)

Output:

Open Market Value: \$47,577.00

Original Registration: 25 Aug 2008

Date:

First Registration Date: 25 Aug 2008

Transfer Count: 3

Actual ARF Paid: \$52,335.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry

Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 24 Aug 2028

COE Category: B - Car (1601cc &
above)

COE Period(Years): 10

PQP Paid: \$34,991.00

COE Rebate Amount: \$33,119.00

Total Rebate Amount: \$33,119.00

The information contained herein is correct as at 06 Mar 2019

OK

SUPREME



CLICK HERE OR

Mitsubishi Evolution

Price Range

Depreciation

> 10 year(s) of

Vehicle Type

Home » Used Cars » Karz Konec » Mitsubishi Evolution 10 GSR SST (COE till 08/2028)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Rental

For Private &
Commercial Vehicles
Rental From
\$50/Day



Mitsubishi Evolution 10 GSR SST (COE till 08/2028)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price \$96,888

Depreciation \$10,260 /yr

Reg Date 14-Aug-2008
(9yrs 5mths 7days COE left)

Manufactured 2008

Mileage 89,000 km (8.4k /yr)

Transmission Auto

Engine Cap 1,998 cc

Road Tax \$1,331 /yr

Power 206.0 kW (276 bhp)
View specs of the Mitsubishi Evolution

Curb Weight 1,540 kg

Features Powerful 2.0 MIVEC 4B11T Turbo Charged Engine. 6
Speed Dual Clutch SST Gearbox. Paddle Shifters. 4
Wheel Drive System.

Accessories 18" Advan RS Rims With Toyo R1R Tyres. Stock
Condition. Lower Spring By Eibach Pro Kit Lowering
Springs. Fujitsubo Exhaust W Cert. Voltex Type 5 Rep.

Description Well Maintained 2 Owner. Resprayed To Yas Marina
Blue. Fully Stock With Fujitsubo LTA Approved Exhaust.
18" Advan RS Rims With Toyo R1R Tyres. Eibach Prokit
Lowering Springs. Track Free Car. Recaro Stock
Alcantara Seats. SMS Now To Enquire More.

COE \$34,991

OMV \$31,422

ARF \$31,422

Dereg Value \$33,055 as of today (change)

No. of Owners 2



Location Map

Seller Informat

Company

Address

Location

Contact Person(s)

Useful Services

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/12/2016 19:17
Date Of Accident	27/12/2016 12:05
Exact Location Of Accident	NEW UPPER CHANGI ROAD & CHAI CHEE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC8999G
Insured/Policyholder	
Name Of Registered Owner	LIM CHEW CHONG
NRIC No	S7218181F
Email Address	MAVE7221@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-92328116
Alternative Phone No	OFFICE-92328116

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	EVO X GSR SST 6-SPEED 1998CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ16-004572
Cover Note Number	N.A.

Driver

Name of Driver	LIM CHEW CHONG
NRIC No	S7218181F
Date Of Birth	25/04/1972
Occupation	INDOOR
Date Of Driving Pass	05/08/1991
Driving Experience	25 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92328116
Fax Number	
Contact Number	OFFICE-92328116
Email Address	MAVE7221@SINGNET.COM.SG

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION- HEAD TO SIDE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name THOMSON NPP 25 SIN MING ROAD
 Police Station Address ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 27/12/2016 AT ABOUT 12.03 PM, I TRAVELLED ALONG THE FIRST LANE OF NEW UPPER CHANGI ROAD GOING TOWARDS CHANGI VILLAGE IN MY CAR (SKW8999G). I WAS TRAVELLING ABOUT 60 KM/HR AND AS I APPROACHED THE JUNCTION OF NEW UPPER CHANGI ROAD AND CHAI CHEE ROAD, THE TRAFFIC LIGHT WAS GREEN IN MY FAVOUR. SO I CONTINUED GOING STRAIGHT. HOWEVER, BEFORE I PASSED THE JUNCTION, ANOTHER CAR (SKW9167S), TRAVELLING ON THE FIRST LANE OF NEW UPPER CHANGI ROAD GOING TOWARDS CHANGI ROAD, MADE A RIGHT TURN INTO CHAI CHEE ROAD. I TRIED BUT I COULD NOT AVOID THE ACCIDENT. THE FRONT OF MY CAR COLLIDED WITH THE LEFT SIDE OF HIS CAR. MY CAR WAS SERIOUSLY DAMAGED. FURTHERMORE, DUE TO THE COLLISION, HIS CAR SWERVED AND HIT TRAFFIC LIGHT BOX SIGNAL NO 172. AS SUCH, POLICE ASSISTANCE WAS CALLED FOR (VIDE: G/20161227/0088) BUT NONE OF US WAS CONVEYED. I HAD ONE PASSENGER WITH ME. I HAVE A VIDEO FOOTAGE OF THE ACCIDENT. I AM LODGING THIS REPORT AS ADVISED BY THE TP OFFICER THAT ATTENDED TO ME DURING THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKW9167S
 Vehicle Make/Model/Colour MAZDA/ GREY
 Details Of Properties NA
 Name of Driver ZENG HAOFEI
 NRIC/Passport Number S2665000C
 Contact Number 97663967
 Address NA
 NA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

NA

Vehicle Make/Model/Colour

NA

Details Of Properties

TRAFFIC LIGHT BOX

Name of Driver

NA

NRIC/Passport Number

Contact Number

NA

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. The First Aid kit provided by the Police/Police Officer is for use in emergency only. It is not intended to be used for anything other than first aid.
3. Insurance companies must be notified and advised 24 hours after the accident. Any delay in notification is a breach of insurance conditions.
4. The insurance companies must be notified of the accident as soon as possible.
5. Any delay in reporting may be treated as a breach of the Police by the insurance companies.
6. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
7. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
8. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
9. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
10. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
11. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
12. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
13. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
14. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
15. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
16. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
17. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
18. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
19. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.
20. The report will be forwarded to the relevant insurance companies established by the General Insurance Association of Singapore (GIA) for processing and any delay in the report will be a breach of the insurance conditions.

VERIFIED BY ALAN MARS
REPORTING OFFICER


ALAN MARS

Signature of Driver / Owner / Third Party

Signature of Driver / Owner / Third Party

Signature of Reporting Officer

Sketch Plan



Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

Refer to police report No.T/20161227/2114

Taxi voucher No:

Are you claiming your own insurance policy for the repair of your vehicle?

No. Own/3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER
AJZAM BIN ATAN

MARS Official



Registered Owner or Driver's Signature

Job Complete Date/Time

28 December 2016 5:00 pm

Date/Time

28 December 2016 5:00 pm

POLICE REPORT



**SINGAPORE
POLICE FORCE**



12018122700114

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

1 of 3
Report No: 12018122700114

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/12/2016 16:48
Vide Report No: G/20161227/0088
Station Diary No: 60

Informant's Particulars

Name of Informant LIM CHEW CHONG	Address 95 PUNGGOL DRIVE #13-16 SINGAPORE 628797		
ID Type / ID No NRIC NO / S721B181F	Contact No Home/Office	Mobile: 92328116	
Nationality SINGAPORE CITIZEN	Email		
Sex Male	Age 44	Date of Birth 25/04/1972	Type of Informant Driver
Race Chinese	Language		Institution / School Name
Occupation Taxi driver	Driving Licence Information Class		Date of Expiry

General Information of the Accident

Type of Accident	Non-Injury Government Property	Driver Drive No	Date/Time of Accident 27/12/2016 12:05	Type of Location
Location Junction of Road 1 and Road 2 NEW UPPER CHANGI ROAD CHAI CHEE ROAD				
Weather: Clear	Road Surface Dry		Road Speed Limit	
Traffic Flow:	Traffic Control Traffic Light - Working		Traffic Volume Light	
Type of Collision Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJC8999G	Car	MITSUBISHI	EVQ X GSR SST 6- SPEED AMT	Red	Seriously Damaged	1
SKW91675	Car					0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJC8999G	EQ INSURANCE COMPANY LTD	DMPPHQ16- 004572	28/09/2016	27/09/2017

POLICE REPORT



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No. 1800-4529999



T/20161227/0116

Report No. T/20161227/0116

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM CHEW CHONG	ID No.	S7218181F
Related Vehicle	SJC8999G (Car)	Contact No.	92328116
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ZENG HAOFEI	ID No.	S2885000C
Related Vehicle	SKW9167S (Car)	Contact No.	97663967
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/12/2016 at about 12.03 p.m., I travelled along the first lane of New Upper Changi Road going towards Changi Village in my car (SJC8999G). I was travelling at about 60 km/hr, and as I approached the junction of New Upper Changi Road and Chai Chee Road, the traffic light was green in my favour. So I continued going straight. However, before I passed the junction, another car (SKW9167S), travelling on the first lane of New Upper Changi Road going towards Changi Road, made a right turn into Chai Chee Road. I tried but I could not avoid the accident. The front of my car collided with the left side of his car. My car was seriously damaged. Furthermore, due to the collision, his car swerved and hit traffic light box signal no. 172. As such, police assistance was called for (vide: G/20161227/0088), but none of us was conveyed. I had one passenger with me. I have a video footage of the accident. I'm lodging this report as advised by the TP officer that attended to me during the accident.

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20161227/2114

3 of 3

Report No: T/20161227/2114

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report
E /
LOKMAN BIN ABDUL GHANI

Signature Of Informant

Signature Of Interpreter
Not applicable

Date/Time:
27/12/2016 16.48

Officer In Charge Of Case:
TP / AEIT /
SSI 2 ABDUL RAZAK S/O RAHMAT ALI
Contact No. 65476169

Classification Of Case

Authentication Stamp
NP168



Singapore Police Force

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2016 18:19
Date Of Accident	27/12/2016 12:00
Exact Location Of Accident	JUNCTION OF CHAI CHEE ST & NEW UPPER CHANGI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW9167S
Insured/Policyholder	
Name Of Registered Owner	LION CITY RENTALS PTE LTD
Co Reg No	201504621K
Email Address	REPORTING@AUTOINSURE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63682788

Vehicle Particulars

Manufacturer	MAZDA
Model	3-SP 20 SDN (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMPF16S001858
Cover Note Number	

Driver

Name of Driver	ZENG HAOFEI
NRIC No	S2665000C
Date Of Birth	21/07/1962
Occupation	OUTDOOR
Date Of Driving Pass	10/06/2000
Driving Experience	16 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97663967

Fax Number

Contact Number

EMail Address REPORTING@AUTOINSURE.COM.SG

Address	BLK 418 CHOA CHU KANG AVE 4 #11-302
Postcode	680418
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION- CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 . POSTCODE: 408865 . COUNTRY: SINGAPORE
Police Station Contact	TEL NO. - FAX NO.
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJC8999G
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LIM CHEW CHONG
NRIC/Passport Number	S7218181F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	

• Email Address



TRAFFIC INVESTIGATION BRANCH
TRAFFIC POLICE DEPARTMENT
10 UBI AVE 3
SINGAPORE 408865
Fax: 65476259

REPT/IP/PV NO.: G/2016/227/0088 CASE CARD

Traffic Accident along New Upp Chang Rd x
Chai Chee Rd
involving vehicles: on 9 two cars and
government property (Traffic Light Box)
on 29/12/2016 at about 1200 am/pm

With reference to the above, you are advised to lodge an accident report at the nearest Police Stations/Neighbourhood Police Centres/Posts within 24 hours if you have not done so.

You are required to be present at Traffic Police on date: _____, at about _____ am/pm to see the Investigation Officer to assist in the investigation to the traffic accident.

2. Please bring along your:-

- a) Identity card/Passport/Work Permit
- b) Driving Licence/Vocational Licence/LTA Licence
- c) Vehicle Insurance/Medical Certificate
- d) Any other relevant documents/Witnesses (if any)

3. If you are unable to keep to the appointment, kindly contact the investigation officer:

Name: IO Rizwan

Contact: 6547 6185

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Record Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of the report to the insurers, you hereby consent to the archiving of the report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore (GIAS) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in the Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insured's who have insured vehicle(s) involved in the accident (all insured's) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insureds"). The Insureds are hereby told that the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
(i) processing, handling and/or dealing with my claim including the settlement of the claim; and/or necessary investigations relating to the claim;
(ii) investigating the accident and/or my claim;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claim (including the making of correspondence, statements, invoices, reports provided to some who have insured my vehicle or other personal data about me to bring about delivery of the same as well as in the externalisation of and/or related packages); and/or
(v) complying with applicable law; or administering, processing, handling and/or dealing with my claim;
collectively the "Purposes".
(b) All insured's who have insured vehicle(s) involved in the accident and the Insureds are hereby told that they are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) My Personal Information may not be disclosed by any of the Insureds and/or GIAS to their third party service providers or agents (including their law firm/s law firm), which may be based outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature Date & Time

Driver's Signature (if driver is not the policyholder) Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Section of G.I.A. Form 11 (2012) Acc. No. 1111111111

1. Name of Insured	2. Name of Insured	3. Name of Insured
4. Name of Insured	5. Name of Insured	6. Name of Insured
7. Name of Insured	8. Name of Insured	9. Name of Insured
10. Name of Insured	11. Name of Insured	12. Name of Insured



Private Car (Fleet)

ERGOPHF
N SB
R000015
Cover Type: C**CERTIFICATE OF INSURANCE**MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION ACT) CHAPTER 189
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT, 1987
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT, 1987 (MALAYSIA)**CERTIFICATE NO.** DMPF16S0018581) Index Mark and Registration:
No. of Vehicle: SKW91675

2) Name of Policyholder: LION CITY RENTALS PTE. LTD.

3) Commencement Date of Insurance: 25 FEBRUARY 2016
Excess: All Claims SGD 2,000
Excess: Young & Inexp. Div. SGD 3,500
(All Claims)4) Expiry Date of Insurance: 24 FEBRUARY 2017
Excess: Windscreen SGD 100

5) Persons or Classes of Persons entitled to drive

- 1) Any person who is driving on the Policyholder's order or permission

6) Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage

7) Limitations as to Use

- 1) Use in connection with the Policyholder's business
-
- 2) Use for carriage of passengers in connection with the Policyholder's business
-
- 3) Use for social domestic and pleasure purposes

This policy does not cover:

- 1) Use for racing pace-making reliability trial or speed-testing
-
- 2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings (for Items 6 & 7)

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Legend

Cov Type:

C - Comprehensive

F - Third Party, Fire & Theft

I - Third Party

For and on behalf of ERGO Insurance Pte. Ltd.
Approved Insurer

Authorized Signature

Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with which you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS

Original Report No: _____ Vehicle Registration No: _____
Name (as shown in NRIC): _____
(**Vehicle Driver / Vehicle Owner) (**) Please delete as appropriate
NRIC/Passport No: _____
Address: _____
Contact (Tel): _____ (H/F): _____
(Email): _____
Date of Accident: _____ Time of Accident: _____
Place of Accident: _____
Insurance Company: _____

(B) ADDITIONAL INFORMATION / AMENDMENTS

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Signature of Vehicle Owner / Driver
Date



10 Anson Road #06-16 International Plaza Singapore 079901 Phone: +65 6324 0010 Fax: +65 6324 0030
Operating Hours: Monday to Friday 9am to 5pm



CUSTOMER NAME: LIM CHEW CHONG

DATE: 15.06.2017

VEHICLE NO.: SJC 8999G

VEHICLE MAKE: MITSUBISHI EVO X GSR SST 6-SPEED 1998CC

VEHICLE MODEL: EVO X GSR

BEING LUMP SUM REPAIR AS RECOMMENDED BY
INDEPENDENT SURVEYOR

S 16,400.00

VEHICLE DAMAGE PRE REPAIR SURVEY REPORT

ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

Our File No: MS16-ERGO-12832/EY
Insurer Ref: DSMPF1604695/SL/pl
Insured Name: LION CITY RENTALS PTE LTD

Date: 11-May-17

REFERENCE

Insured Veh No: SKW8167S Policy No: DMPF16S001858
Date of loss: 27-Dec-16
Claimant Veh No: SJC8999G

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJC8999G Make: MITSUBISHI
Reg Year: 25-Aug-08 Model: EVO X GSR SST 6-SPEED AMT
Colour: Red Engine No: 4B11BT9127
Type: - Chassis No: JMF5MCZ4A9U000413
Type of Claim: Third Party's Claim Odometer: 173519 KM
Market Value: - Engine Cap: 1988 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

(STATIC ONLY)

General Condition: Good Steering: Serviceable Engine Modification: Nil
Paint work: Good Handbrake: Serviceable Pre-accident damage: Nil
Footbrake: Serviceable

CONDITION OF TYRES

Front Left Size: Yokohama 245/40/R18 3mm Front Right Size: Yokohama 245/40/R18 3mm
Rear Left Size: Yokohama 245/40/R18 4mm Rear Right Size: Yokohama 245/40/R18 4mm

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

	Repairer's S\$	Adjuster's S\$	Difference S\$
Parts	-	-	-
Labour	-	-	-
Calculated Cost (S\$) :	-	-	-

Recommended Lump Sum Repair Cost (S\$) : 10,000.00

INSPECTION

Date of Assignment: 30-Dec-16 Inspected At: 833 Motorsports Pte Ltd
Date of Pre-Repair Survey: 30-Dec-16 Bik 20 Sin Ming Industrial Estate
Date of Interim Survey: 3-Jan-17 Sector A #01-16
Date of Post Repair Survey: 5-May-17 Singapore 575678
Est. repair Period: 10 days
Recommended Reserve(S\$): NA
Sum Insured (S\$): NA
Repair status: Surveyed on a "Without Prejudice" Basis
(Estimate < \$10,000.00)

MS16-ERGO-12832/EY
SJC8999G

POINT OF IMPACT

The vehicle sustained damages to the front right portion	
----------------------------------------------------------	------------------------------------------------------------------------------------

BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle and Third Party's vehicle collided at along Junction of Chai Chee Street & New Upper Changi Road.

CONSISTENCY OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are consistent with the accident as reported.

SPECIAL REMARKS

1. The repairer did not provide Repair Estimate during our pre-repair survey.
2. This inspection was conducted on a "Without Prejudice" Basis.
3. We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Pre-Repair Survey Report and photographs.



Edwin Yeo, WMSAAA
Automobile Appraiser



NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

VEHICLE SURVEY REPORTS																																				
Lim Chew Chong C/O 833 MotorSports Pte Ltd 160 Sin Ming Drive Sin Ming AutoCity #02-09 Singapore 575722																																				
1	Reference Job Reference No : 16/001251 Claim No : - Claim Type : Third Party Accident Date : 27/12/2016 Survey Date : 30/12/2016 Survey Report Date : 06/06/2017																																			
2	Particulars Of Vehicle Vehicle Registration No : SJC8999G Make & Model : Mitsubishi Evo X GSR Vehicle Registration Date : 25/08/2006 Chassis No : JMFSMCZA9U000413 Engine No : Blocked Colour : Red																																			
3	Condition Of Vehicle And Tyres <table border="0"> <tr> <td><u>Mileage (KM)</u></td> <td><u>Brakes</u></td> <td><u>Steering</u></td> <td><u>Modification</u></td> </tr> <tr> <td>173520</td> <td>Serviceable</td> <td>Affected</td> <td>None</td> </tr> <tr> <td colspan="4"> </td> </tr> <tr> <td><u>Tyres</u></td> <td><u>Make</u></td> <td><u>Size</u></td> <td><u>Balance (MM)</u></td> </tr> <tr> <td>Front RHS</td> <td>Yokohama</td> <td>245/40R18</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Yokohama</td> <td>245/40R18</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Yokohama</td> <td>245/40R18</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Yokohama</td> <td>245/40R18</td> <td>6</td> </tr> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	173520	Serviceable	Affected	None					<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Yokohama	245/40R18	5	Front LHS	Yokohama	245/40R18	5	Rear RHS	Yokohama	245/40R18	6	Rear LHS	Yokohama	245/40R18	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																																	
173520	Serviceable	Affected	None																																	
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																																	
Front RHS	Yokohama	245/40R18	5																																	
Front LHS	Yokohama	245/40R18	5																																	
Rear RHS	Yokohama	245/40R18	6																																	
Rear LHS	Yokohama	245/40R18	6																																	
4	Description Of Damages The vehicle sustained damages at front right hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)																																			
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																																			

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

Ref No : 16/001251

Damage And Repair Cost Adjustment

S/No	Qty	Parts Description	Comments/condition	Workshop Estimate (\$)	Our Assessment (\$)
			<u>List Items</u>		
1	1	Front bumper	Deformed	810.00	810.00
2	2	Front bumper side retainer	Broken	46.00	46.00
3	1	Front bumper inner reinforcement	Bent/dented	410.00	410.00
4	1 set	Front bumper clips	Broken	40.00	40.00
5	2	Front headlamp	RH smashed/LH reuse	2,200.00	1,100.00
6	1	Front RH fender	Buckled	943.00	943.00 871
7	1	Front RH fender under shield	Deformed	105.00	105.00
8	1 set	Front fender under shield clips	Broken	30.00	30.00
9	1	Front support panel upper panel	Bent/dented	232.00	232.00 R x
10	1	Front support panel upper cover	Deformed	62.00	62.00 X RH
11	1	Front support panel complete	Buckled	580.00	580.00 R x
12	1	Front RH transmission cooler	Buckled/bent	746.00	746.00
13	1	Front air cooler	Bent/dented	715.00	715.00 X RH
14	1	Air on condenser	Bent/dented	1,023.00	1,023.00
15	1	Radiator	Bent/dented	1,084.00	1,084.00 X RH
16	1	Front RH lower arm	Bent	58.00	58.00
17	1	Front RH knuckle arm	Bent	443.00	443.00
18	1	Front RH wheel hub & bearing	Bent/necessary	406.00	406.00
				9,933.00	8,833.00 6160
Less discount 10%				993.30	883.30
Total :				8,939.70	7,949.70 5544
			<u>Special Nett Items</u>		350
19	1	Front grille outer carbon fiber garnish	Deformed/dented	450.00	450.00 1000
20	1	Front bumper lower carbon fiber skirting	Deformed/dented	1,200.00	1,200.00 400
21	1 set	Front bumper RH fog lamp carbon fiber cover (C/w 1 set)	Broken/cut	500.00	500.00
22	1 set	Front RH fog lamp	Reuse	220.00	150
23	1 set	Front RH headlamp carbon fiber garnish (C/w 1 set)	Deformed	250.00	250.00 1000
24	1	Front carbon fiber bonnet	Dented/bent	2,200.00	2,200.00
25	1	Front lower engine cover	Bent	450.00	450.00 350
26	2	Engine intercooler (inner & outer)	Dented/bent	2,792.00	2,792.00
27	1	Engine intercooler cover	Bent	300.00	300.00
28	1	Front RH shock absorber	Bent	1,100.00	1,100.00
29	1	Front RH sports rims	Dented/warped	650.00	650.00 500

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

30 1 Front RH tyre

Cut

320.00

320.00

Total : 10,432.00 10,212.00

Total Spare Parts : 19,371.70 18,161.70

AUTO PERFORMANCE APPRAISAL

Annex B

Vehicle Assessment Reports

Ref No : 16/001251

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To tow vehicle to workshop.	60.00	60.00 ✓
2	To remove, jack out, straighten, panel beating, align and renew replaced parts.	1,200.00	800.00 700
3	To putty and respray painting on affected areas.	1,200.00	900.00 700
4	To check wirings and lightings.	50.00	30.00 ✓
5	To remove, refix transmission cooler, air cooler and engine inter cooler.	150.00	100.00 ✓
6	To remove, refix aircon condenser, pipes, drier vacuum and recharge gas.	150.00	120.00 ✓
7	To remove, refix front under carriages.	280.00	220.00 150
8	To conduct computerise wheel alignment test.	80.00	60.00 ✓
9	To apply undersealing	100.00	60.00 40
Total Labour :		3,270.00	2,350.00 1900
Total Spare Parts :		19,371.70	18,161.70
Total Labour :		3,270.00	2,350.00
Total Repair Costs :		22,641.70	20,511.70

Assessor's Recommendation

Repairer Estimate : 22,641.70
Our Adjustment : 20,511.70

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$16,400.00, with a repair period of 7 working days.

Surveyed By:

Lek Boon Hwee
Automobile Appraiser

16436
4/5 of 15,150
6 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
COMLAW LLC*		Ref : CS/LAW19001648/T1vd3e2		
64 CECIL ST #06-01 IOB BLDG SINGAPORE 049711		Date : 08-03-2019		
		Code : L050		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SKW 9167S	Veh. Inspected	SJC 8999G	
Policy No.	LIM.509725.E	Coverage (\$)	0.00	
Claim No.	PCS.CCC.18.217959.ERGO	Excess (\$)	0.00	
Assign From	BELLE	Assign Date	18/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI EVO X GSR	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JMF5MCZ4A9U000413	Colour	RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	YOKOHAMA	6 mm	
L/H Front Tyre	245/40 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	245/40 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	245/40 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	27/12/2016	Inspection Date	01/02/2019	
Survey held at	3 CHURCH STREET			
Repairer	833 MOTORSPORTS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJC 8999G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	REPLACED	810.00	810.00
2	FRONT BUMPER SIDE RETAINER	REPLACED	46.00	46.00
1	FRONT BUMPER INNER REINFORCEMENT	REPLACED	410.00	410.00
1	SET FRONT BUMPER CLIPS	REPLACED	40.00	40.00
2	FRONT HEADLAMP	O/S REPLACED	2,200.00	1,100.00
1	FRONT RH FENDER	REPLACED	943.00	871.00
1	FRONT RH FENDER UNDER SHIELD	REPLACED	105.00	105.00
1	SET FRONT FENDER UNDER SHIELD CLIPS	REPLACED	30.00	30.00
1	FRONT SUPPORT PANEL UPPER PANEL	REPAIRED SEE LABOUR	232.00	-
1	FRONT SUPPORT PANEL UPPER COVER	NOT NECESSARY	62.00	-
1	FRONT SUPPORT PANEL COMPLETE	REPAIRED SEE LABOUR	580.00	-
1	FRONT RH TRANSMISSION COOLER	REPLACED	746.00	746.00
1	FRONT AIR COOLER	NOT NECESSARY	715.00	-
1	AIR CON CONDENSER	REPLACED	1,023.00	1,023.00
1	RADIATOR	NOT NECESSARY	1,084.00	-
1	FRONT RH LOWER ARM	REPLACED	58.00	58.00
1	FRONT RH KNUCKLE ARM	REPLACED	443.00	443.00
1	FRONT RH WHEEL HUB & BEARING	REPLACED	406.00	406.00
	LESS 10% DISCOUNT		-993.30	-608.80
			8,939.70	5,479.20
SPECIAL NETT ITEMS				
1	FRONT GRILLE OUTER CARBIN FIBER GARNISH (SN)	REPLACED	450.00	350.00
1	FRONT BUMPER LOWER CARBON FIBER SKIRTING (SN)	REPLACED	1,200.00	1,000.00
1	SET FRONT BUMPER RH FOG LAMP CARBON FIBER COVER (C/W 1 SET) (SN)	REPLACED	500.00	400.00
1	SET FRONT RH FOG LAMP (SN)	REUSE	220.00	-
1	SET FRONT RH HEADLAMP CARBON FIBER GARNISH (C/W 1 SET) (SN)	REPLACED	250.00	150.00
1	FRONT CARBON FIBER BONNET (SN)	REPLACED	2,200.00	1,800.00
1	FRONT LOWER ENGINE COVER (SN)	REPLACED	450.00	350.00

Report Ref No. CS/LAW19001648/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	ENGINE INTERCOOLER (INNER & OUTER) (SN)	REPLACED	2,792.00	2,792.00
1	ENGINE INTERCOOLER COVER (SN)	REPLACED	300.00	300.00
1	FRONT RH SHOCK ABSORBER (SN)	REPLACED	1,100.00	1,100.00
1	FRONT RH SPORTS RIMS (SN)	REPLACED	650.00	500.00
1	FRONT RH TYRE (SN)	REPLACED	320.00	250.00
			10,432.00	8,992.00
	LABOUR			
	TO TOW VEHICLE TO WORKSHOP.		60.00	60.00
	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL UPPER PANEL AND FRONT SUPPORT PANEL COMPLETE.		1,200.00	700.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		1,200.00	700.00
	TO CHECK WIRINGS AND LIGHTINGS.		50.00	30.00
	TO REMOVE, REFIX TRANSMISSION COOLER, AIR COOLER AND ENGINE INTER COOLER.		150.00	100.00
	TO REMOVE, REFIX AIRCON CONDENSER, PIPES, DRIER VACUUM AND RECHARGE GAS.		150.00	120.00
	TO REMOVE, REFIX FRONT UNDER CARRIAGES.		280.00	150.00
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.		80.00	60.00
	TO APPLY UNDERSEALING.		100.00	40.00
			3,270.00	1,960.00
GRAND TOTAL			22,641.70	16,431.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,150.00

Report Ref No. CS/LAW19001648/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.