REF: CB3 /ASM 19001654 | BCUSEN Special Instruction: ASS. REC. BY: Mrlim mun dum From (Person): ASSIGNMENT (Office) retar Wang Date/Time: 25012019 M2A. 9.20 um Estimated Cost: Bill to: OD THE WST TP RES / OD RES / EVA / INV / MV / CS To Inspect Vehicle No: 87N3151K SLD 4722K Insured: The Gurage 9090 1137 at Workshop m/s Tel: 8 Kuki Bukt #03-32 of Ave S9MOIAYB Policy No: Claim No: Sum Insured: Excess: Make of Veh: 12012019 D.O.A. (Client's Record) Look for Ah Hao CA / REV / REP. / REV 24 HRS W/D H.O.D. Endorsement: Date/Time: 7501 2019 11210M Gina Vehicle (IN) OUT Person Contacted: Date/Time Action/Instruction) Estimate. DIA-17 DISOIS

· YY40	ull.	1

A581		15.1	15	17.	N	1
, Ach 25	3.	11.7	1	1.1.	1	Ą

From Date: 35012019	Veh No. SJN 315/K Yr Regn. 11/2/2009
Estimated Cost.	Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TF) WS / TP RES / OD RES / EVA / INV / MY	Truck / Trailer or
To Inspect Vehicle No: SJN 3151K	Maker TOGOTALCOROLLA ALTIS CC 1598
at Workshop m/s The Garage	Colour SILVER A/G: Insured / Std / NI / NA
8 Kaki Bukit AVR 4 #03-32	Sp.Reading 323667 T/Radio: Insured / Std / NI / NA
Insured: a	Eng/No: 3ZZ4867553
Policy No.	CINO: 11RO53ZEE106139077
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh: Look for Ah Hao	Modi: Nil / S/Rim / STD A/Rim or
2	Tyre Size: F: 195/65/15 MIL 9
(Policy Condition)	Tyre Size: F: 195/65/15 MIL 9 R: 195/65/16 Yoko.V
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear -
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: 6 days Res.: Yes or No	D.O.A. 12/01/19 D.O.I. 25/1/19@0400
Lum Sum: % 3 Val.: Yes or No	Survey held at THE GARAGE
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
. Vehicle: IN/O	
Date: Person Confacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	, ^, ;
Range 4,000/2 - 5,00	13/2/2019
MV 26500/2	
PV 12,810 F	TGUIN
NV 13,690/2	the 11/2/19
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: - Survey Fee: 100
Date/Time, File Return to?	Transportation.
Add F	
	. Interview (\$) Photos
Report Format: PRS.	Tech Invs (\$) Others
Lump Sum / I.B.I: (\$	Weekend (\$
	TOTAL 100

LKK AUTO CONSULTANTS PTE LTD (TP) 🕶

Menu



Service Request Details

Claim

S9M01AYB

Reference

None 🔊

Loss Date

January 12, 2019

Request Date

January 25, 2019

Due Date

February 1, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions Next Step Agree to perform service Decline Work Accept Work

Vehicle Information

Incident Vehicle Registration # SJN3151K

Make

TPVD

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu

Service Agaress

, , ,

Primary Contact/Insured

JEROME JACQUES ANTOINE FERRACCI 97 ROBERTSON QUAY, #06-07, 238257, Singapore 93808502 jerome.ferracci@octis.com.sg

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From:

JB GEM <vcssg01@gmail.com>

Sent:

Thursday, 24 January, 2019 4:00 PM

To:

SG AXA Insurance SM AXA SGP - Motor Survey

Subject:

LETTER TO CONDUCT PRE REPAIR INSPECTION FOR VEH NO: SJN 3151K & SLD

4722K DOA:12/1/19

Attachments:

SJN 3151K FORM1.pdf; SJN 3151K GIA.pdf; LIST OF SURVEYORS.pdf

Categories:

Shailendra

WITHOUT PREJUDICE

TO: MOTOR CLAIMS DEPT

PLEASE REFER TO ATTACH FOR YOUR NECESSARY ACTION AT YOUR SOONEST.

REGARDS

VCS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	8034J
Vehicle No.:	SJN3151K
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4857553
Chassis No.:	MR053ZEE106139077
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,990.00
Original Registration Date:	11 Feb 2009
First Registration Date:	11 Feb 2009
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$16,990.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	*
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	10 Feb 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$12,864.00
COE Rebate Amount:	\$12,861.00
Total Rebate Amount: Message	\$12,861.00

The information contained herein is correct as at 11 Feb 2019

Dep 5,640fgr 470/mmll ОК

MV 26,500/2 PV 12,810/2 NV 13,690/2



Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

500+ dealers competed to buy my car!



▶ Sell ur Car for More Cash

▶ Highest Price or Get \$100 Free

• Get Paid Now, Handover Later

SELL YOUR CAR

QUOTZ

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Advertiser Login

Make

Ways of Selling



BMW 7 Series 730Li Sunroof.

Cheapest In The Market, Low Depreciation, Cheaper Than 3 Series Or Rental.

Direct Owner StarAd



Browse by Category

Post an Ad

« Back (1 2 3) Next »

Sort by Date Posted Advanced Search

▼ 100 results/page ▼

ΔII

269 vehicles

Toyota Corolla

Price Depreciation

Reg Date Eng Cap Mileage

Veh Type Status

Any

Search Selection

Toyota Corolla

2009

Any

Any

Available

Toyota Corolla Altis 1.6A (New 5-yr COE)

\$29,800

\$27,800

\$5,960 /yr

21-Apr-2009

1,598 cc

138,249 km

Sedan

Well Maintained And Fuel Efficient Sedan! Known For It's Practicality And Reliability! Selling Cheap! Monthly Installment From \$458! High/Full Loan And Trade In Available Here! Call For An Viewing App...

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used

Mayfair Motoring

Posted: 11-Feb-2019

\$5,640 /yr

16-Jan-2009

1,598 cc

Sedan

Available

PREMIUM AD

PREMIUM AD

till 01/2024) 2.88%P.A Lowest Interest At \$568 Monthly For Toyota Altis. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

GV Credit Pte Ltd

Posted: 11-Feb-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used

Toyota Corolla Altis 1.6A (New 5-yr COE)

Toyota Corolla Altis 1.6A (COE

\$27,800

\$5,560 /yr

24-Jun-2009

1,598 cc

Sedan

Available

PREMIUM AD

2.88%P.A Lowest Interest At \$568 Monthly For Toyota Altis. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

GV Credit Pte Ltd

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used Posted: 11-Feb-2019

Available

Toyota Corolla Altis 1.6A (New 5-yr COE)

\$27,800

\$5,560 /yr

11-Feb-2009

1.598 cc

Sedan

PREMIUM AD

2.88%P.A Lowest Interest At \$568 Monthly For Toyota Altis. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

GV Credit Pte Ltd

Posted: 11-Feb-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Corolla Altis 1.6A (COE

\$27,800

\$5,630 /yr

20-Jan-2009

1,598 cc

Sedan

Available

PREMIUM AD

Available.

till 01/2024) 2.88%P.A Lowest Interest At \$568 Monthly For Toyota Altis, \$0 Admin Fees For All GV Purchase, 2 Years Warranty For Engine And Gearbox, Add Ons

GV Credit Pte Ltd

Posted: 11-Feb-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, Corolla, Used Toyota

Compare [1]

Select used cars to Compare or Add to Alert



Toyota Corolla Altis 1.6A (COE till 16-Jan-2009

To compare cars, select from the search results.

To compare cars, select from the search results.

To compare cars, select from the search results.

Shortlist [1]

Add to Shortlist Compare Now Clear All

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	14/01/2019 10:35
Date Of Accident	12/01/2019 21:00
Exact Location Of Accident	HAVELOCK RD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SJN3151K
Insured/Policyholder	
Name Of Registered Owner	CHUT HUI YAN
NRIC No	S8228034J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97985712
Alternative Phone No	OFFICE-97985712
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095852533
Cover Note Number	
Driver Paradala Control of the Contr	
Name of Driver	CHAN BEE LAY
NRIC No	S7425388A
Date Of Birth	11/08/1974
Occupation	OUTDOOR
Date Of Driving Pass	08/08/2011
Driving Experience	7 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93377093

NOEMAIL

Address

BLK 445B BUKIT BATOK WEST AVE 8 #10-435

Postcode

852445

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

FRIEND

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

DRIZZLING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s)

YES

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

HOUGANG NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 60 HOUGANG AVE 9, POSTCODE: 538775, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4890999 - FAX NO: 63128989

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLD4722K

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

FERRACCI

NRIC/Passport Number

Contact Number

93808502

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or igents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN			
1 11			N= SIN BISTK
1 1			
1 / /			8: SLD 4 722K
1 1			
A			
1	Havelo	en Rd	
	l diages		
DESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT		
DESCRIBE CIRCOMSTANCE	3 OF THE ACCIDENT		
21 -	A	Police	Report
Please	Refer to	To tice	150777
		1	
		1	
		1	
		1	
		1	
		1	
		1	
		1	
		1	
		1	
		1	
		1	
		1	
		1	
DECLARATION		1	
DECLARATION I/We declare the foregoing pa	rticulars are true in every respect.	1	
DECLARATION I/We declare the foregoing pa	rticulars are true in every respect.	1	had a
DECLARATION I/We declare the foregoing pa	rticulars are true in every respect. Driver's Signature		Reporting Centre Personnel's Signat



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM19001654/Bcd3e2 AXA INSURANCE PTE LTD 14-02-2019 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 068811 ATTN: PETER WANG Code: ASM Policy Particulars :- (THIRD PARTY CLAIM) SLD 4722K SJN 3151K Insured Veh. Veh. Inspected 0.00 Policy No. Coverage (\$) S9M01AYB 0.00 Claim No. Excess (\$) PETER WANG 25/01/2019 **Assign From Assign Date** Vehicle Particulars & Condition TOYOTA COROLLA ALTIS 1598 Make & Model Engine No. 2009 HIDDEN Year of Reg. Chassis No. MR053ZEE106139077 Colour SILVER 323667 KM Odometer IN ORDER Steering IN ORDER SPORTS RIM Brakes Modification GOOD General 3. **Conditions of Tyres** Size Make Balance 195/65 R15 YOKOHAMA 5 mm R/H Front Tyre 195/65 R15 YOKOHAMA L/H Front Tyre 5 mm 195/65 R15 MICHELIN 5 mm R/H Rear Tyre 195/65 R15 MICHELIN 5 mm L/H Rear Tyre **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. 5. **General Information** Inspect Date / Time **Accident Date** 12/01/2019 25/01/2019 (04:00 PM) THE GARAGE - 8 KAKI BUKIT AVE 4 #03-32 Survey held at Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000 5b. Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days

Report Ref No. CS3/ASM19001654/Bcd3e2

Inspected By

(Mm

LIM TEOW GUAN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.