

ASS. REC. BY:

REF:

CS3/AIG19001673/Gcd302

Special Instruction:

Surveyor:

Cimo Ching

ASSIGNMENT (Office)

From (Person):

Menmen chin lee Ying

of

AIG

Date/Time:

25/11/19 @ 11:42am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JZ 5296A

Insured:

SDZ 3331R

at Workshop m/s

SZE Kang Automobile

Tel:

6481 2712

of

10 Amk Ind. Park 2A #03-09 17

Policy No:

2100469940

Claim No:

135654230286

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/01/2019

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

11:54am 25/11/19

Person Contacted:

Ms. Lee

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	8JZ 5296A -X
	SDZ 3331R -X
	Dismantle: 25/11/2019

(08/11/13)

Surveyor

PRS  
Khal

REF:

ALG

15940

(2019)

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Sze Keng Auto

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$700032k

IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJ85296AYr Regn: 14 Jul 2009Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MH EVO X C.C. 1998Colour: Red A/C: Insured / Std / NI / NASp. Reading: 150624 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: IMFS MC24A94000351Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/408R18R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 25-01-19Survey held at w/sDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final ReportResurvey No. of Trip: 1Survey Fee: 180

Date/Time, File Return to?

Transportation: \_\_\_\_\_

2)

Add Fee: ☐ : Site Insp (\$ )

\$ + RS. SI

☐ : Interview (\$ )

Photos

☐ : Tech. Invs (\$ )

Others

☐ : Weekend (\$ )Report Format: DAR

Lump Sum / I.B.I: (\$ )

TOTAL

190

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 25/1/2019 11:42:25 AM  
Attachments:  tmp43.tif

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
Lee-Ying.Chin@aig.com | www.aig.sg

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# Ascentsia

Law Corporation

Your Ref: Please advise

Our Ref: CK/YSY/19.021701

24 January 2019

**AIG Asia Pacific Insurance Pte. Ltd.**  
78 Shenton Way  
#07-16  
Singapore 079120

By fax & post  
(Fax no.: 6835 7416)

Attn: Motor claims department

Dear Sirs

A Law Corporation with limited liability  
(Company Registration No. 200204598E)

Commissioner for Oaths  
Notary Public

10 Anson Road  
#03-22 International Plaza  
Singapore 079903  
Tel : (65) 6534 3552  
Fax : (65) 6535 9920

Email: [enquiry@ascentsialawcorp.com](mailto:enquiry@ascentsialawcorp.com)  
Website: [www.ascentsialawcorp.com](http://www.ascentsialawcorp.com)  
(Service of Court documents by fax not accepted)

**ACCIDENT INVOLVING SJZ5296A & SDZ3331R AT TAMPINES AVE 9 BEFORE  
TAMPINES AVE 7 ON 23 JANUARY 2019 AT 0910HOURS**

1. We act for Tan Siew Luan who is the registered owner of motor vehicle no. SJZ5296A at the material time.
2. Our client was involved in the captioned accident with your insured's motor vehicle no. SDZ3331R and has suffered damages, loss and expenses.
3. In accordance with the NIMA protocol, we hereby give you two (2) working days' notice for you to conduct a pre-repair inspection of our client's motor vehicle at the following workshop:

**Sze Kang Automobile Spraying Services**  
10 Ang Mo Kio Industrial Park 2A  
#03-09/17  
Singapore 568047  
Tel: 6481 2712/8201 9979

4. Kindly make the necessary arrangements with the aforesaid workshop for your surveyor to conduct a pre-repair inspection, if required.
5. In the absence of your response by 28 January 2019, we will proceed on the basis that you have waived your rights to a pre-repair inspection.

Yours faithfully

Yip Shee Yin/Clarisse Khoo

Writers' DID: 6327 5777/6327 5763

Writers' Email: [yipsheeyin@ascentsialawcorp.com](mailto:yipsheeyin@ascentsialawcorp.com)/[clarissekhoo@ascentsialawcorp.com](mailto:clarissekhoo@ascentsialawcorp.com)

Directors Kenny Khoo ♦ Leong Why Kong ♦ Yip Shee Yin Legal Consultant Thomas Au  
Associates Chiang Wan Ting ♦ Clarisse Khoo ♦ Ong Li Ling ♦ Tan Choon Hiang

Confidentiality note: The contents herein are strictly meant for the addressee only and may contain privileged communications. If you are not the intended recipient, please either immediately return this document to us at our costs or destroy this document.

[➤ Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1594D
Vehicle Details	
Vehicle No.:	SJZ5296A
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	EVO X GSR SST 6-SPEED AMT
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	4B11BY1225
Chassis No.:	JMFSMCZ4A9U000351
Maximum Power Output:	217.0 kW (290 bhp)
Open Market Value:	\$48,252.00
Original Registration Date:	14 Jul 2009
First Registration Date:	14 Jul 2009
Transfer Count:	3
Actual ARF Paid:	\$48,252.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2019
PARF Rebate Amount:	\$24,126.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jul 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$15,100.00
COE Rebate Amount:	\$678.00
<b>Total Rebate Amount:</b>	<b>\$24,804.00</b>

The information contained herein is correct as at 28 Jan 2019

OK

**► Mitsubishi Evolution Used Vehicle List (20 vehicles)**

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Available
<b>Mitsubishi Evolution 10 GSR (New 10-yr COE)</b>	<b>\$105,000</b>	\$10,490 /yr	07-Apr-2009	1,998 cc	-	Choon's Motor Trading	Available

A Daily Driver And A Track Day Weapon For The Weekends. Built Extensively For Outright Grip And Handling And A Modest 450hp Setup. If You Are Looking For A Accident-free Evo 10 With A Clean History, Drive...

Office No. - 64811606

Eddie Ng - 90082358

<b>Mitsubishi Evolution 10 GSR SST (New 10-yr COE)</b>	<b>\$89,800</b>	\$8,970 /yr	10-Mar-2009	1,998 cc	-	United Motoring Pte Ltd	Available
--	-----------------	-------------	-------------	----------	---	-------------------------	-----------

CarbonF Bonnet, Boot, Wings, Carnard, Steering, Interior, Brembo Front & Rear. Hurry Now To Seize This Opportunity To Own An E10! Up To 95% Loan Available With Guaranteed The Best Interest In Town! Suitable...

Office No. - 64635355

Zack - 87672182 | Jasper - 88188897 | Calvin - 88008820 | Alan - 93483386

<b>Mitsubishi Evolution 10 GSR (New 10-yr COE)</b>	<b>\$93,888</b>	\$9,380 /yr	06-Mar-2009	1,998 cc	160,000 km		Available
--	-----------------	-------------	-------------	----------	------------	--	-----------

Gearbox Just Fully Rebuilt! Major Wear And Tear Replaced. Lots Of New Parts Changed Recently Such As Coilovers, AEM Gauges, Exhaust Manifold, Air Filter, Blow Off Valve, Boost Controller, PMU Pads N S...

Office No. - -

Jo - 94882809

<b>Mitsubishi Evolution 10 GSR SST (New 10-yr COE)</b>	<b>\$88,000</b>	\$8,790 /yr	24-Feb-2009	1,998 cc	115,000 km		Available
--	-----------------	-------------	-------------	----------	------------	--	-----------

90% Loan Can Be Arranged. Subject To Approval. Almost Stock For This Final Edition. My Price Is Fixed! Kindly Call For More Enquiry. Thank You...

Office No. - -

Andrew - 92334848

<b>Mitsubishi Evolution 10 GSR SST (New 10-yr COE)</b>	<b>\$86,800</b>	\$8,670 /yr	26-Nov-2008	1,998 cc	-	Car Guru.Com Pte Ltd	Available
--	-----------------	-------------	-------------	----------	---	----------------------	-----------

Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available Trade In Welcome. Call For Appointment For A Test Drive Now Before...

Office No. - 67639595

Lawrence - 92228747 | Jimmy - 90079944

<b>Mitsubishi Evolution 10 GSR (New 10-yr COE)</b>	<b>\$98,888</b>	\$9,880 /yr	26-Sep-2008	1,998 cc	-		Available
--	-----------------	-------------	-------------	----------	---	--	-----------

Price Comes With New 10 Years COE. 1 Owner Only. New Paintwork. Available For Viewing Anytime.

Office No. - -

Kelvin - 97227833 | Adrian - 93200003

<b>Mitsubishi Evolution 10 GSR SST (New 10-yr COE)</b>	<b>\$93,888</b>	\$9,380 /yr	25-Sep-2008	1,998 cc	173,000 km	Munich Alpina Pte Ltd	Available
--	-----------------	-------------	-------------	----------	------------	-----------------------	-----------

Extremely Well Maintained! This Beast Does Not Just Look Beautiful, It's 100% Accident Free. View To Believe! Up To 80% Financing Possible Trade In Welcome! Call/SMS To Arrange A Viewing Today! View...

Office No. - -

Ben - 91849182 | Dave - 94559794

<b>Mitsubishi Evolution 10 GSR SST (COE till 08/2028)</b>	<b>\$89,900</b>	\$9,420 /yr	12-Aug-2008	1,998 cc	-	Prem Roy Motoring	Available
---	-----------------	-------------	-------------	----------	---	-------------------	-----------

Rare 1 Owner Unit, Parts Worth \$20k, Whatsapp For Viewing Appointment, Consignment Unit. Loan Available. Stock Engine. HKS Legamax Exhaust.

Office No. - 66028046

Prem Roy - 84684000

<b>Mitsubishi Evolution 10 RS (New 10-yr COE)</b>	<b>\$99,800</b>	\$9,970 /yr	24-Jun-2008	1,998 cc	-	Classic Credit Pte Ltd	Available
---	-----------------	-------------	-------------	----------	---	------------------------	-----------



(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched  
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary  
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

## MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(✓) (3)Check (✓)  
(4)Not Consistent (NC)

### Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	/	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	CPA	/	
1141	992958	Rear Bumper	TV	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam	BT	/	
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	Repair		
1160	993339	Rear End Panel Top Garnish	CC	/	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	Repair		
1171	991328	Bootlid Emblem	NC	/	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BT	/	
1178	990377	Bootlid Rubber	TV	/	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: **8JB 5296A**

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	Repair		
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Garnish			
1222	993415	Rear LH Fender Inner Trim			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

ORIGINAL COPY

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019 <a href="#">Edit Reg</a>		25 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>MOY SIN PIN</b> , ID: S25775921									
Main Claimant: -									
Vehicle Reg. No.: <b>SJZ5296A</b>		Date of Loss: 23/01/2019 00:00 - :59 <b>[114 Months and 9 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / 1356542302SG</b>		Policy/Cover Note No.: 2100469940 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SDZ3331R</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Sze Kang Automobile Spraying Services (HQ)</b> BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-17, 568047 Ang Mo Kio - Tel: 64812712									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ] Kianmeng.Chan1@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 07/02/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (28/01/2019): <b>Request to upload TP GIA Report</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SJZ5296A (1356542302SG)




































[SDZ3331R]





































TP

Jan 23 2019 12:00AM

[MOY SIN PIN]

Sze Kang Automobile Spraying Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
2	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
3	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
4	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
5	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
6	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
7	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
8	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
9	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
10	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
11	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
12	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
13	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
14	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
15	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
16	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
17	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
18	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
19	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
20	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
21	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
22	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
23	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
24	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
25	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
26	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
27	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
28	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
29	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
30	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
31	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
32	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
33	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
34	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
35	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
36	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	
37	28/01/19 09:30	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/01/19 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/01/19 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/01/19 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/01/19 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/01/19 09:30	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/01/19 09:31	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
44	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	28/01/19 09:31	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/01/19 11:46	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001673/GCD3E2

Date: 30/01/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100469940

Claimant Vehicle No : SJZ5296A

Insured Vehicle No : SDZ3331R

Date of Loss: 23/01/2019

Nature of Claim: TP

Claim No: 1356542302SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJZ5296A

Make &amp; Model: MITSUBISHI EVO 10, 2.0 GSR (M)

Engine No: 4B11BY1225

Reg. Date: 14/07/2009 (Man. Year: 2008)

Chassis No: JMF5MCZ4A9U000351

Colour: Red

Odometer: 150624 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size: 245/40Z R18

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

## INSPECTION

Date of Assignment: 25/01/2019

Date Inspected: 25/01/2019 Inspected At:

Sze Kang Automobile Spraying Services (HQ)

BLK 10 ANG MO KIO INDUSTRIAL PARK

2A, #03-17

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
3	1		*REAR BUMPER	Torn	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER BEAM	Bent	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
8	1		*BOOTLID	Repair	0.00 F	*- F
9	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
10	1		*BOOTLID LOCK	Bent	0.00 F	*- F
11	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
12	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >