

ASS. REC. BY:

REF:

083/CTI1900/677/Bcd3<sup>57</sup>

Special Instruction:

Surveyor:

Mr Kim

ASSIGNMENT (Office)

From (Person):

Catherine Thia

CTI

Date/Time:

25/1/2019.

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 7214U

Insured:

GBH 9452D

at Workshop m/s

R.S. Automotive

Tel:

9182 6089

of

Blk 3006 Ubi Rd 1 #01-394

Policy No:

DMCVSN 3070681800

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:40am @ 25/1/19

Person Contacted:

Richard

Vehicle:  IN /  OUT

Date/Time	Action/Instruction (x) Estimate
	GX7214U - NA/4PI9001461/h4 Dof: 21/1/19
	GBH 9452D - NA/4PI9001461/h4 Dof: 21/1/2019
	Dismantle: 28/1/2019.



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jan 2019 10:50		25 Jan 2019 10:50 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>PROTRACK PRODUCTIONS</b> , Co. Reg. No.: 53133483W		
Main Claimant:	<b>RS AUTOMOTIVE PTE LTD</b> , Co. Reg. No.: 201230654Z		
Vehicle Reg. No.:	<b>GX7214U</b>	Date of Loss:	21/01/2019 17:00 - :59 [172 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	DMCVSN30706818000 (Comprehensive) Coverage: 01/11/2018 - 31/10/2019
Vehicle Reg. No. (Insured):	<b>GBH9452D</b>	Policy No. (Claimant):	SI18V09920/VCV/R04
		Excess:	S\$0.00
Repairer:	<b>RS Automotive Workshop (HQ)</b> 3066 Ubi Road 1, #01-394/384, 408700 Ubi - Tel: 67483032		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Catherine Thia</b> ]		
Claimant's Insurer:	<b>Liberty Insurance Pte Ltd (HQ)</b> - Tel: (65) 6221 8611		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Final Rpt due 07/02/2019]		
Driver/Custodian (Insured):	MUHAMMAD SYAHIN BIN SAMSUDIN ( / Male), NRIC: S9433390C		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/01/2019 16:50
Date Of Accident	21/01/2019 17:50
Exact Location Of Accident	BLK 3005 UBI RD 1 CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX7214U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RS AUTOMOTIVE PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67483032

### Vehicle Particulars

Manufacturer	RENAULT
Model	-
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	SI18V09920/VCV/R04
Cover Note Number	-

### Driver

Name of Driver	WONG CHAI MING
NRIC No	S7268453B
Date Of Birth	19/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	25/09/1995
Driving Experience	23 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91826089
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 109 PASIR RIS GROVE #09-23
Postcode	518199
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9452D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUHAMMAD SYAHIN BIN SAMSUDIN
NRIC/Passport Number	S9433390C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Accident Sketch Plan**

MY VEH WAS PARKED OPPOSITE MY SHOP AT THE BLK 3005 UBI RD 1. AN EYEWITNESS INFROM ME, HE SAW THE VEH B (BEARING NO GBH9452D) WHILE REVERSING AND HIT ONTO MY VEH FRONT PORTION.

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0654Z
Vehicle Details	
Vehicle No.:	GX7214U
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	RENAULT
Vehicle Model:	KNG 1.5 6DR
Primary Colour:	Red
Manufacturing Year:	2004
Engine No.:	K9KA704D801748
Chassis No.:	VF1FC07AF32054369
Maximum Power Output:	-
Open Market Value:	\$19,118.00
Original Registration Date:	25 Aug 2004
First Registration Date:	25 Aug 2004
Transfer Count:	1
Actual ARF Paid:	\$956.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$21,466.00
COE Rebate Amount:	\$2,296.00
<b>Total Rebate Amount:</b>	<b>\$2,296.00</b>
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 11 Feb 2019

OK

Dep 12,430/yr  
1036/mth

MV 5,000/2  
PV 2,296/2  
NV 2707/2

  
11/2/19

**SUPREME** NEW CARS | PRE-LOVED CARS | INSURANCE | FINANCING

**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

BMW 7 Series 730Li Sunroof.



Cheapest In The Market, Low Depreciation, Cheaper Than 3 Series Or Rental, Direct Owner StarAd

**HIN LUNG AUTO**  
 Ho Bee Group  
**One Stop Car Hub**  
 Finance, Insurance, Workshop  
 New and Used Cars  
 30 years of car sale

Browse by Category

Sort by Date Posted 100 results/page

6 vehicles

Renault Kangoo

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b> Renault Kangoo Any Any 2009 Any Any Any All								
	<b>Renault Kangoo II Express 1.5M</b>	<b>\$7,800</b>	<b>\$12,430 /yr</b>	<b>29-Sep-2009</b>	<b>1,461 cc</b>	-	Van	Available
<b>Fuel Type:</b> Diesel								
Posted: 31-Jan-2019 Tags: 2009 Renault Kangoo, 2009 renaul kangoo, Renault Kangoo, renaul kangoo, Renault, Kangoo, kangoo, Used Renault								
	<b>Renault Kangoo 1.5 (New 5-yr COE)</b>	<b>\$19,300</b>	<b>\$3,860 /yr</b>	<b>12-Feb-2009</b>	<b>1,461 cc</b>	-	Van	Available
<b>Fuel Type:</b> Diesel								
Too Good To Scrap! Good For Company And Private Use. (\$1.5k Optional Package = Fresh Coat Of External Paint, 2 x Servicing ) Well Maintain Engine With Low Fuel Consumption. Up To 90% Loan Available. T...								
Posted: 16-Jan-2019 Tags: 2009 Renault Kangoo, 2009 renaul kangoo, Renault Kangoo, renaul kangoo, Renault, Kangoo, kangoo, Used Renault								
	<b>Renault Kangoo 1.6A</b>	-	N.A	<b>31-Jul-2009</b>	<b>1,598 cc</b>	-	Van	<b>SOLD</b>
<b>Fuel Type:</b> Petrol								
Condition Still Good. 1 Owner. Worth To Renew COE. <span style="float: right;"><b>DIRECT OWNER</b></span>								
Posted: 03-Jan-2019 Tags: 2009 Renault Kangoo, 2009 renaul kangoo, Renault Kangoo, renaul kangoo, Renault, Kangoo, kangoo, Used Renault								
	<b>Renault Kangoo II Express 1.5M</b>	-	N.A	<b>29-Sep-2009</b>	<b>1,461 cc</b>	-	Van	<b>SOLD</b>
<b>Fuel Type:</b> Diesel								
Drive This Spacious Cargo Van For Just \$4,800 Only! Super Ideal For Newly Start-Up Business. Very Nice Number Plate G8B6661T. Hurry Now, Don't Miss This Good Deal. Cash & Carry! Kindly Call Our Friend...								
Posted: 02-Jan-2019 Tags: 2009 Renault Kangoo, 2009 renaul kangoo, Renault Kangoo, renaul kangoo, Renault, Kangoo, kangoo, Used Renault								
	<b>Is your COE expiring? Let us help you renew it!</b>							
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	<b>Renault Kangoo 1.5 (New 5-yr COE)</b>	-	N.A	<b>09-Jan-2009</b>	<b>1,461 cc</b>	-	Van	<b>SOLD</b>
<b>Fuel Type:</b> Diesel								
6 Weeks Warranty! Free Insurance! \$450 A Month Only! This Very Well Kept Kangoo Is Possibly The Most Popular Van In It's Class, This Manual Diesel Version Still Holds Plenty Of Appeal For Buyers Looki...								
Net Link Partners Pte Ltd <span style="float: right;"><b>PREMIUM AD</b></span>								
Posted: 14-Dec-2018 Tags: 2009 Renault Kangoo, 2009 renaul kangoo, Renault Kangoo, renaul kangoo, Renault, Kangoo, kangoo, Used Renault								
	<b>Renault Kangoo II Express 1.6A</b>	-	N.A	<b>30-Jun-2009</b>	<b>1,598 cc</b>	-	Van	<b>SOLD</b>
<b>Fuel Type:</b> Petrol								
Price Is Firm. Viewing At Sembawang Hill. <span style="float: right;"><b>DIRECT OWNER</b></span>								
Posted: 05-Dec-2018 Tags: 2009 Renault Kangoo, 2009 renaul kangoo, Renault Kangoo, renaul kangoo, Renault, Kangoo, kangoo, Used Renault								

Compare

Save this search criteria, to get email alerts whenever a match is found.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jan 2019 10:50		25 Jan 2019 10:50 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	PROTRACK PRODUCTIONS, Co. Reg. No.: 53133483W								
Main Claimant:	RS AUTOMOTIVE PTE LTD, Co. Reg. No.: 201230654Z								
Vehicle Reg. No.:	GX7214U	Date of Loss:	21/01/2019 17:00 - :59 [172 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	DMCVSN30706818000 (Comprehensive) Coverage: 01/11/2018 - 31/10/2019						
Vehicle Reg. No. (Insured):	GBH9452D	Policy No. (Claimant):	SI18V09920/VCV/R04						
		Excess:	S\$0.00						
Repairer:	RS Automotive Workshop (HQ) 3066 Ubi Road 1, #01-394/384, 408700 Ubi - Tel: 67483032								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 07/02/2019]								
Driver/Custodian (Insured):	MUHAMMAD SYAHIN BIN SAMSUDIN ( / Male), NRIC: S9433390C								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# Claim Documents

**\*GX7214U**  
**[GBH9452D]**  
**TP**  
**RS AUTOMOTIVE PTE LTD**  
**Jan 21 2019 5:00PM**  
**[PROTRACK PRODUCTIONS]**  
**RS Automotive Workshop**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>		<a href="#">Compose New Letter</a>		<b>View</b>		<a href="#">View in Browser</a>	
<b>Assessment Reports</b>							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)					Thumbnail	Print	
1	22/01/19 17:00	<b>Accident Statement</b>					Load HTM		
<b>Photos/Images</b>							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
2	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
3	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
4	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
5	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
6	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
7	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
8	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
9	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
10	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
11	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
12	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
13	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
14	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
15	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
16	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
17	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
18	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
19	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
20	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
21	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
22	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
23	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
24	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
25	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
26	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
27	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
28	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
29	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
30	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
31	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	
32	11/02/19 13:54	<b>General View</b>					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
33	11/02/19 13:54	General View	Load JPG	<input checked="" type="checkbox"/>
34	11/02/19 13:54	General View	Load JPG	<input checked="" type="checkbox"/>
35	11/02/19 13:54	General View	Load JPG	<input checked="" type="checkbox"/>
36	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	11/02/19 13:54	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/01/19 10:51	PRS EMAIL	Load PDF	
2	25/01/19 10:51	INSD GIA REPORT	Load PDF	
3	25/01/19 10:51	TP GX7214U GIA REPORT	Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	22/01/19 17:00	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	22/01/19 16:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	22/01/19 16:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	22/01/19 16:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	22/01/19 16:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19001677/BCD3S2

Date: 14/02/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30706818000	
Claimant Vehicle No :	GX7214U	Insured Vehicle No :	GBH9452D	
Date of Loss:	21/01/2019	Nature of Claim:	TP	Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>GX7214U</b>		
Make & Model:	RENAULT KNG, 1.5 D (M)	Engine No:	K9KA704D801748
Reg. Date:	25/08/2004 (Man. Year: 2004)	Chassis No:	VF1FC07AF32054369
Colour:	Red	Odometer:	175198 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	175/65R14	Rear Tyre Size:	175/65R14
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	25/01/2019		
Date Inspected:	25/01/2019	Inspected At:	RS Automotive Workshop (HQ) 3066 Ubi Road 1, #01-394/384 Singapore 408700
Estimated Period of Repair:	3.0 days		

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$2,500.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 14 Feb 2019)

**Parts:** N/A RENAULT KNG 1.5 D (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GX7214U)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >