

ASS. REC. BY:

REF: ES3/AIG19001706/Bed302

Special Instruction:

Surveyor: Mr Kim

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 25/1/19 @ 9:40am

Estimated Cost:

Bill to:

~~OD~~ ~~TP~~ ~~WS~~ / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJQ 7053T

Insured: SME 1126D

at Workshop m/s Zolar Auto

Tel: 9146 1186

of 8 Kaki Bukit Ave 4 # 06-21

Policy No: 1800128093

Claim No: 685964630286

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS ^(up)

H.O.D. Endorsement:

Date/Time: 10:04am 25/1/19

Person Contacted: Mark

Vehicle IN OUT

Date/Time	Action/Instruction (x) Estimate
	<u>SJQ 7053T - X</u>
	<u>SME 1126D - X</u>
	<u>Dismantle: 25/1/2019</u>
	<u>After repair: 31/1/2019</u>

REF: AIG

ASSIGNMENT

From _____ Date 25/01/2019

Estimated Cost _____

OD / PWS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SJQ 7053T

at Workshop n/s Zolar Auto

of 8 kaki Bkt Ave 4 # 06-21

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Marko 9146 1186

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value. _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up} _____

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No SJQ 7053T Yr Regn. 22/5/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUZUKI SWIFT 1.5XE A CO 1490

Colour WHITE A/C Insured / Std / NI / NA

Sp. Reading 139821 T/Radio: Insured / Std / NI / NA

Eng/No: M15A1360897

C/No: JSAEZC21500A29069

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50/15

R: 195/50/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/1/19 D.O.I. 25/1/19

Survey held at Zolar Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

MV 10,000/2
PV 7,630/2
NV 2,370/2

TTCI Mr Nil
8/2/19

Date/Time. File Pass to? : Preli. Report

1) : Final Report

Date/Time. File Return to? _____

2) _____

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:	150
Transportation	
_____ S + RS _____ SI	
Photos	
Films	
	10
TOTAL	190

- Add Fee:
- Site Insp (\$)
 - Interview (\$)
 - Tech Invs (\$)
 - Weekend (\$)

Report Format : DAR

Lump Sum / I.B.I: (\$)

* - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 25/1/2019 9:49:01 AM

Attachments:  Zolar - Pre-Repair Notice (AIG)(SJQ7053T).pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.Zolar (SJQ7053T)
Your Ref: SMF1126D

24 January 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

BY FAX: 6835 7416 & EMAIL

URGENT

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: CHEW ZI HANG
TRAFFIC ACCIDENT ON 23 JANUARY 2019 AT 17:50 HRS ALONG TOWNER ROAD
(HONG WEN PRIMARY EXIT) INVOLVING VEHICLES NO. SJQ7053T & SMF1126D

We are instructed by Chew Zi Hang to notify you of a road accident 23 January 2019 at about 17:50 hrs along Towner Road (Hong Wen Primary Exit) involving our client's vehicle registration number SJQ7053T and vehicle registration number SMF1126D driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Zolar Auto Service
Address: Premier@Kaki Bukit
#06-21
Singapore 415875
Contact: Pamela @ 9146 1186

Please liaise with the above workshop directly.

Yours faithfully

Crossborders LLC
Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com
encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5511I
Vehicle Details	
Vehicle No.:	SJQ7053T
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Feb 2019
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.5XE A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	M15A1360897
Chassis No.:	JSAEYC21500429069
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$14,856.00
Original Registration Date:	22 May 2009
First Registration Date:	22 May 2009
Transfer Count:	2
Actual ARF Paid:	\$14,856.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 May 2019
PARF Rebate Amount:	\$7,428.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,326.00
COE Rebate Amount:	\$202.00
Total Rebate Amount:	\$7,630.00

The information contained herein is correct as at 08 Feb 2019

OK

MV 10,000/2
 PV 7630/2
 NV 2070/2

Handwritten signature
 8/2/19

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 23/01/2019 (dd/mm/yy) Time of Accident: 17:50 (24-HR-FORMAT)

Vehicle No.: SJQ7053T Vehicle Make & Model: Suzuki Swift 1.5 A

Exact location of Accident: Towner Rd (Hong Wen primary exit)

Policyholder's Name / IC No.: Chew Zi Hang / S9055115

Driver's Name / IC No.: _____ (As Above)

Driver's Contact No.: 82927869 Company Contact No.: _____

Driver's Address: 10A Bendemeer Rd #18-101 S (331010)

Insurance Company: Direct Asia Email address (if any): _____

Relationship between Owner & Driver: (Please **CIRCLE** one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please **TICK** one only)

Own Insurance / Other Vehicle (The one you want to claim against) / Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Private use / Work purpose

Occupation (nature of job) Indoor / Outdoor

No. of Passengers (Including Driver): 1

Passenger Name : _____
Passenger Name : _____

Gender : Male / Female
Gender : Male / Female

Weather condition & Road conditions? (On the day of accident)

Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? Yes / No

Any Injuries: Yes / No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: Yes / No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: Tan Xin Yi Drlys / S90353025 Vehicle No.: SMF1126D

Driver's Contact No.: 91508153 Insurance Company (If any): _____

2. Driver's Name / IC No.: _____ Vehicle No.: _____

Driver's Contact No.: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No.: _____

Preferred Workshop Name: _____ Contact No.: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


X 
Policyholder's Signature

Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On mentioned date and time, I was travelling along Towner Rd outside Hong Wen Primary. Suddenly veh B drove out from Hong Wen primary exit and collided onto my vehicle right front portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

x 
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTOR CAR (Frt)

Front Portion

Vehicle No: 5JQ 7053T

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR		
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	BT	✓	
1009	991318	Frt Bumper Beam	BT	✓	
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT	✓	
1026	992025	Frt Support Panel Top Garnish Cover	BR	✓	
1027	992416	Horn			
1028	991277	Frt Brace Panel	BT	✓	
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	DD	✓	
1034	991328	Bonnet Emblem	NEC	✓	
1035	990287	Bonnet Lock	BT	✓	
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)	BT	✓	
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom	CUT	✓	
1058	992741	Radiator Expansion Tank	CUT	✓	
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	DD	✓	
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover	BR	✓	
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member	BT	✓	
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BT	✓	
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

Handwritten signature
 13/2/2017

No of Items: 26

AGREATOR: TGCIN

Handwritten date
 8/2/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019 Edit Reg		25 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAN BOON LAY , ID: S1150001C								
Main Claimant:	CHEW ZI HANG , ID: S9005511I								
Vehicle Reg. No.:	SJQ7053T	Date of Loss:	23/01/2019 00:00 - :59 [116 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6859646302SG	Policy/Cover Note No.:	1800128093 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMF1126D	Policy No. (Claimant):							
		Excess:							
Repairer:	Zolar Auto Services (kaki Bukit#06-21) (HQ) No. 8 KakiBukit Avenue 4,, Premier (Gate 2) #06-21, 415875 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 07/02/2019]								
Claimant's Solicitor:	CROSSBORDERS LLC - Tel: 64381323								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (28/01/2019): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJQ7053T (6859646302SG)**
[SMF1126D]
TP
CHEW ZI HANG
Jan 23 2019 12:00AM
[TAN BOON LAY]
Zolar Auto Services (kaki Bukit#06-21)

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>		
Photos/Images										3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
2	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
3	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
4	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
5	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
6	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
7	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
8	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
9	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
10	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
11	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
12	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
13	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
14	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
15	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
16	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
17	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
18	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
19	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
20	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
21	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
22	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
23	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
24	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
25	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
26	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
27	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
28	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
29	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
30	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
31	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
32	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
33	11/02/19 16:21	General View							Load JPG	<input checked="" type="checkbox"/>		
34	11/02/19 16:21	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
35	11/02/19 16:21	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
36	11/02/19 16:21	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
37	11/02/19 16:21	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	11/02/19 16:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	11/02/19 16:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	11/02/19 16:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	11/02/19 16:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	11/02/19 16:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
89	11/02/19 16:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
90	11/02/19 16:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
91	11/02/19 16:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
92	11/02/19 16:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
93	11/02/19 16:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
94	11/02/19 16:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
95	11/02/19 16:22	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/01/19 09:23	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001706/BCD3E2

Date: 14/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800128093
Claimant Vehicle No: SJQ7053T	Insured Vehicle No:	SMF1126D
Date of Loss: 23/01/2019	Nature of Claim:	TP
		Claim No: 6859646302SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK7053T	Engine No:	M15A1360897
Make & Model:	SUZUKI SWIFT, 1.5 (A)	Chassis No:	JSAEZC21S00429069
Reg. Date:	22/05/2009 (Man. Year: 2008)	Odometer:	139821 km
Colour:	White		
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/01/2019	
Date Inspected:	25/01/2019 Inspected At:	Zolar Auto Services (kaki Bukit#06-21) (HQ) No. 8 KakiBukit Avenue 4., Premier (Gate 2) #06-21 Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
4	1		*FRT BUMPER BEAM	Bent	0.00 F	*- F
5	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
6	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
7	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Broken	0.00 F	*- F
8	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
9	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
10	1		*BONNET	Dented	0.00 F	*- F
11	1		*BONNET EMBLEM	Necessary	0.00 F	*- F
12	1		*BONNET LOCK	Bent	0.00 F	*- F
13	1		*BONNET HINGE	* Check	0.00 F	*- F
14	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
15	1		*AIR CON FAN ASSY	* Check	0.00 F	*- F
16	1		*AIR CON SUCTION PIPE (LOW PRESSURE)	* Check	0.00 F	*- F
17	1		*AIR CON DISCHARGE PIPE (HIGH PRESSURE)	Bent	0.00 F	*- F
18	1		*RADIATOR	* Check	0.00 F	*- F
19	1		*RADIATOR COWLING	* Check	0.00 F	*- F
20	1		*RADIATOR HOSE TOP	Cut	0.00 F	*- F
21	1		*RADIATOR HOSE BOTTOM	Cut	0.00 F	*- F
22	1		*AIR DUCT	Cracked	0.00 F	*- F
23	1		*WIPER WASHER TANK	Dented	0.00 F	*- F
24	1		*ENGINE UNDER COVER	Broken	0.00 F	*- F
25	1		*FRT VERTICAL CROSS MEMBER	Bent	0.00 F	*- F
26	1		*FRT RH FENDER	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >