

ASS. REC. BY:

REF:

CTI 19001710/

d3

Special Instruction:

Surveyor:

Rajul

ASSIGNMENT (Office)

From (Person):

Shang Euan Sen

of

CTI

Date/Time: 25/1/19 @ 2:41pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKN 4592C

Insured:

at Workshop in/s

Sng Ah Tee

Tel:

G268 6183

of

Blk 3, Pioneer Rd North #01-18

Policy No:

DMPCSN3056271800

Claim No:

SNM19D200367C01

Sum Insured:

Excess:

TBA

Make of Veh:

D.O.A

11/12/2018

(Client's Record)

CA / REV

/

REV

/ REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:53pm @ 25/1/19

Person Contacted:

Jamenka

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKN 4592C-X

Call boon sen tomorrow

30/1/19

Boon sen MC 2 days. called and informed Irene Tay that vehicle already survey by CTI in Haze surveyor. providing instructions.

21/1/19-

case already closed in moimen. (spoken to Irene Tay yesterday).

Close 1/2/19

ASSIGNMENT

Franch

Date:

Estimated Cost

CITY TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SKN 4592C

at Workshop no. SNG AH TEE

of Pioneer RD North #01-18

Insured: CTI

Policy No.

Claim No.

Sum Insured:

Excess: TBA

(Client's Record)

Make of Veh.

(Policy Condition)

Survey by
In-house surveyorRemark: The veh had commenced its
repair at the time of inspection. CTI

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Lump Sum

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Veh No.

SKN 4592C

Vt. Regn.

Type: Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ CLAZON

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal

6

mm

Rear

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A.

D.O.I.

25/01/19

Survey held at

SNG AH TEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/1

Vehicle already inspected by China. In-house surveyor.

Date/Time: For Page 1/2

☐

: Prelim. Report

11

☐

: Final Report

Date/Time: For Return V1/2

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1. S+RT 31

1. Phone

1. Filter

TOTAL

Report Format:

Lump Sum / I.B.T. / S

Add Fee:

☐

Site Insp. / S

☐

Interview / S

☐

Tech. Insp. / S

☐

Week-end / S

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2019 11:38 Sendback Est	18 Jan 2019 11:38 \$10,667.55	25 Jan 2019 14:41 Assign				New Assignment Cancel Case

Main Reference Claim Details Documents Show All

CLAIM SUBFOLDER DETAILS

Insured:	MILLENNIUM TOURS COACH SERVICE PTE LTD, Co. Reg. No.: 201108666G		
Vehicle Reg. No.:	SKN4592C	Date of Loss:	17/12/2018 16:00 - :59 [54 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D200367C01	Policy/Cover Note No.:	DMPCSN3056271800 (Comprehensive)
		Excess:	\$50.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/02/2019]		
Driver/Custodian:	WEI SHAO JIE (31 / Female), NRIC: G5260692L, Tel: +6583766291		
Adj. Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) | [Compose Cash Mail](#)

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									