





SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 24/01/2019

User ID : GohKK2

| Section A - Accident Details      |  |
|-----------------------------------|--|
| Registration Number               | SG1762R  |
| Case Reference Number             | BUS/01/19/7024   |
| Registration Date                 | 18/10/2018   |
| Company Type                      | SMRT Buses Ltd   |
| Make                              | MAN  |
| Model                             | MAN NL320F(A22)  |
| Name of Driver                    | Tee Fong Kiow  |
| Type of Accident                  | Side Swipe   |
| Accident Date and Time            | 23/1/2019 5:13 PM  |
| Accident Reported Date and Time   | 23/1/2019 5:45 PM  |
| Is Surveyor Required?             | Yes  |
| Survey by                         |  |
| Vehicle is Towed Back?            | No   |
| Towed Back Date and Time          |  |
| Replacement Vehicle issued?       | No   |
| Job Card Number                   |  |
| Special Instruction to ARC,if any | SG1762R - REAR RIGHT PORTION<br>PC3804Y (TP) - INSURED WITH AXA. |
| Prepared Date and Time            | 24/1/2019 3:57 PM  |
| Chassis Number                    | WMAA22ZZ4JF006977  |
| Mileage                           |  |
| Work Shop                         |  |
| Repair Completion Date and Time   |  |

| Section B - Summary of Repair Estimates |   |   |
|---|---|---|
| Summary of Repair Estimates             |   |   |
|   | Quotation from ARC  | Adjusted by Surveyor, if applicable   |
| Total Labour Cost                       | \$795.00  | \$0.00  |
| Total Spray Cost                        | \$446.00  | \$0.00  |
| Total Spare Part Cost                   | \$2,654.22  | \$0.00  |
| Total Other Cost                        | \$0.00  | \$0.00  |
| TOTAL COST                              | \$3,895.22  | \$0.00  |
| Lump Sum Total                          | \$0.00  | \$0.00  |
| Number of Repair Days                   | 3.0   |   |
| Prepared / Adjusted By                  | Kok Khoon Goh   |   |
| ARC / Surveyor Sign Off Date            | 24/01/2019 4:02 PM  |   |
| Signature                               |  |  |
| Remarks                                 |   |   |

| Section C - Quotation and Accident Invoice Details |  |                |  |
|--|--|----------------|--|
| Quotation Number                                   |  | Invoice Number |  |
| Quotation Date                                     |  | Invoice Date   |  |
| Invoice Amount                                     |  | Prepared Date  |  |



SMRT Accident Vehicle Repair Estimates

|   |
|---|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 24/01/2019

User ID : GohKK2

| Section D - Details of Repair Estimates                                       |         |               |                              |          |                 |              |                                     |                    |                   |
|---|---------|---------------|------------------------------|----------|-----------------|--------------|-------------------------------------|--------------------|-------------------|
| Part 1 - Labour Works   |         |               |                              |          |                 |              |                                     |                    |                   |
| Job Scope   |         |               | Quotation from AR            |          |                 |              | Adjusted by Surveyor, if applicable |                    |                   |
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. |         |               | \$795.00                     |          |                 |              |                                     |                    |                   |
| Total Labour  |         |               | \$795.00                     |          |                 |              |                                     |                    |                   |
| Part 2 - Spray Painting & Panel Beating Related Works                         |         |               |                              |          |                 |              |                                     |                    |                   |
| Job Scope   |         |               | Quotation from ARC           |          |                 |              | Adjusted by Surveyor, if applicable |                    |                   |
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS           |         |               | \$446.00                     |          |                 |              |                                     |                    |                   |
| Total Spray Painting & Panel Beating  |         |               | \$446.00                     |          |                 |              |                                     |                    |                   |
| Part 3 - Other Costs - Accident and Accident Repair Related Expense           |         |               |                              |          |                 |              |                                     |                    |                   |
| Job Scope   |         |               | Quotation from ARC           |          |                 |              | Adjusted by Surveyor, if applicable |                    |                   |
| Total Other Costs   |         |               |                              |          |                 |              |                                     |                    |                   |
| Part 4 - Spare Parts / Material Usage   |         |               |                              |          |                 |              |                                     |                    |                   |
| Part Number   | Portion | Stock Number  | Part Name                    | Quantity | List Price (\$) | Discount (%) | Final Price (\$)                    | Estimator Approved | Surveyor Approved |
| 6010299   | VE      | 88-25320-6008 | LAMP,INDICATOR:LED (MAN BUS) | 1.00     | \$1,274.10      | 10.00        | \$1,146.69                          | Replace            |                   |
| 6010298   | VE      | 88-25225-6039 | LAMP,STOP:LED (MAN BUS)      | 1.00     | \$1,141.70      | 10.00        | \$1,027.53                          | Replace            |                   |
| 6012636   | VE      |               | REVERSE LAMP BULB (A95 MAN)  | 1.00     | \$235.00        | 0.00         | \$235.00                            | Replace            |                   |
| Total   |         |               |                              |          | \$2,650.80      |              | \$2,409.22                          |                    |                   |
| Added Spare Parts / Material Usage After Surveyor Signed off                  |         |               |                              |          |                 |              |                                     |                    |                   |
| Part Number   | Portion | Stock Number  | Part Name                    | Quantity | List Price \$   | Discount (%) | Final Price (\$)                    | ARC Check          | Surveyor Check    |
| 6012635   | VE      |               | REAR LAMP BULB (A95 MAN)     | 1.00     | \$245.00        | 0.00         | \$245.00                            | Replace            |                   |
| Total   |         |               |                              |          | 245.00          |              | 0.00                                |                    |                   |