

ASS. REC. BY:

REF

CS3/III 9001713/Gcd 302

Special Instruction:

Sub Agent:

GVO Qianq

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

25/1/19 @ 1:53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FR 9827G

Insured:

8HD 35 832

at Workshop m/s

Gp Motoring

Tel:

9168 6744

of

282 Macpherson Road

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

25/12/2018

CA / REV / REP. / REV 24 HRS

up)

H.O.D. Endorsement:

Date/Time:

3:32pm @ 25/1/19

Person Contacted:

Marius

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FR 9827G-X
	SHD 35832-CC4/III 18010628/Rlea3
	Disassemble: 15/2/2019 @ 0707PM
	After repair: 20/2/2019 @ 0536PM

DOA: 18/5/2018

Surveyor

PRS
KAL

REF:

III

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP WS TP RES OD RES EVA INV MV

To Inspect Vehicle No:

at Workshop m/s

GP Motoring

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$800

IDAC Accident Rpt.

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

\$800 - \$1000

Veh No:

FR 9827G

Yr Regn:

-

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha RX8

C.C.

-

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

56539

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

80/90-17

R:

90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

mm

D.O.A.

D.O.I.

25-01-19

Survey held at

w/s

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

120

Transportation:

S + RS, SI

Photos

Others

10

TOTAL

130

1)

Date/Time, File Return to?

2)

Report Format :

PRS

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 25 January 2019 1:53 PM
To: Alfred Ng; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: ACCIDENT INVOLVING FR9827G AND SHD3583Z ON 23 DECEMBER 2018.
Attachments: shd3583Z_20190125105552.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : FR9827G
III INSURED VEHICLE NO. : SHD3583Z
DATE OF LOSS : 25.12.18

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSUTLANT to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Alfred Ng [mailto:alfred_ng@juseq.com.sg]
Sent: 25 January, 2019 12:10 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: ACCIDENT INVOLVING FR9827G AND SHD3583Z ON 23 DECEMBER 2018.

Your ref: SHD3583Z

Our ref: JEQ/190078/0119/GP

Dear Sirs,

We refer to your email today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Delta V Consultant;
5. Prominent Appraisal Services Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;
8. S K Auto Consultants;
9. Oh Appraisal Services;
10. KAAS.

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

GP Motoring Pte Ltd
282 Macpherson Road
Singapore 348607

Tel: 6746-4240 Mobile: 9168-6744.

Fax: 6746-4596

Person In charge : Mr. Marcus

* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11

With Regards

Alfred Ng
Executive
On behalf of Mr Michael Yap
M/s JusEquity Law Corporation
No. 171 Chin Swee Road
#02-01/02/06 Singapore 169877
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



JusEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road #02-05, CES Centre, Singapore 169877

Telephone (65) 6536 9339,

Email : claims@juseq.com.sg

Fax : (65) 6536 5368 (Litigation & Conveyancing)

website : www.juseq.com.sg

Our Ref: JEQ/190078/0119/GP (zl)

Your Ref: SHD3583Z

24 January 2019

COMFORT TRANSPORTATION PTE LTD

383 Sin Ming Drive

GAS Building

Singapore 575717

By Post Only

INDIA INTERNATIONAL INSURANCE PTE LTD

Singapore

By Fax: 6224 4174 Only

Dear Sir

ACCIDENT INVOLVING FR9827G & SHD3583Z ON 23.12.2018

We act for the owner of vehicle no. FR9827G.

We hereby notify you of a road traffic accident on **23 December 2018** at about **2315 hrs**, at junction of Yuan Ching Road & Yung Ho Road involving our client's vehicle and vehicle registration no. **SHD3583Z** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5428D
Vehicle Details	
Vehicle No.:	FR9827G
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Red
Manufacturing Year:	1999
Engine No.:	3B5249925
Chassis No.:	ZMC249925
Maximum Power Output:	-
Open Market Value:	\$3,376.00
Original Registration Date:	28 Mar 2000
First Registration Date:	28 Mar 2000
Transfer Count:	11
Actual ARF Paid:	\$507.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$884.00
COE Rebate Amount:	\$96.00
Total Rebate Amount:	\$96.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 22 Feb 2019

OK

MVA319009212 / VAC - Kaki Bukit
ENTRY DATE & TIME: 19/01/2019 16:19
SUBMITTED BY: Norhaini Bte Abdul Majid

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 19/01/2019 17:02

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2019 16:19
Date Of Accident	23/12/2018 23:15
Exact Location Of Accident	YUAN CHING ROAD / YUNG HO ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FR9827G
Insured/Policyholder	
Name Of Registered Owner	GP MOTORING PTE. LTD.
Co Reg No	201205428D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-87844536
Vehicle Particulars	
Manufacturer	YAMAHA
Model	RXZ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5101796673 TP
Cover Note Number	
Driver	
Name of Driver	NURUL 'AISHAH BTE JAMALUDIN
NRIC No	S9048485J
Date Of Birth	18/12/1990
Occupation	OUTDOOR
Date Of Driving Pass	09/05/2016
Driving Experience	2 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87844536
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 65 YUNG KUANG ROAD #16-95
 Postcode 610065
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name

JURONG WEST NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 700 CORPORATION ROAD, POSTCODE: 649818, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2689999 - FAX NO: 62672438

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	NURUL 'AISHAH BTE JAMALUDIN
Approximate Age	28
Injuries Sustain	
Injured person in which vehicle?	FR9827G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 65 YUNG KUANG ROAD #16-95
Postcode	610065

Sketch Plan Pg. 1

SKETCH PLAN



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

19 JAN 2019

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: enquiry@idac.gov.sg
Name:
NRIC/FIN No

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



Refer to

Police Report

DECLARATION

I/We declare the following particulars are true in every respect.

 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 19 JAN 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sgReporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Individual Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181225/2106

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20181225/2106

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/12/2018 23:17		Vide Report No.:		Station Diary No.: 120	
Informant's Particulars:					
Name of Informant: NURUL AISHAH BINTE JAMALUDIN			Address: APT BLK 65 YUNG KUANG ROAD #16-95 SINGAPORE 610065		
ID Type / ID No.: NRIC NO / S9048485J			Contact No.: Home/Office: Mobile: 87844536		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 28	Date of Birth: 18/12/1990	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: RIDER			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident:				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 23/12/2018 23:15	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 YUAN CHING ROAD YUNG HO ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved:						
Vehicle No:	Type:	Make:	Model:	Colour:	Condition:	No of Passenger:
FR9827G	Motorcycle	YAMAHA	RXZ	Red	Seriously Damaged	0

Details of Person Involved:	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Individual Statement Pg. 1

**SINGAPORE
POLICE FORCE**

T/20181225/2106

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20181225/2106

CONTINUATION OF REPORT

Rider			
Name	NURUL 'AISHAH BINTE JAMALUDIN	ID No.	S9048485J
Related Vehicle	FR9827G (Motorcycle)	Contact No.	87844536
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	23/12/2018	Date Discharge	24/12/2018
No. of Days granted Medical Leave	05	Degree of Injury	Serious

Brief Details.

On 23/12/2018 at about 2310hrs, I was travelling along Yuan Ching Road heading towards AYE. At that moment of time, the traffic condition was moderate and it was not raining. I was travelling on 1st lane and there was a taxi (unknown registration number) from Comfort Delgro that was on the 2nd lane, a metre ahead from me. Soon as I passed by the junction of Yuan Ching Road and Yung Ho Road, the taxi made an immediate right turn without signal. I could not react on time and my front hit onto his side. The next thing I knew was that I was on the ground. Police and Ambulance were called in and I was conveyed to Ng Teng Fong General Hospital. I was discharge the same night with 5 days of medical leaves given.

Individual Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181225/2106

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3

Report No. T/20181225/2106


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Sgt 3 SUFYANRAFIE BIN SUKAIME
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRO Contact No.: 65476904
 Authentication Stamp NP168 Signature : Singapore Police Force

Signature Of Informant: 
Date/Time: 25/12/2018 23:17
Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2019 09:34 Edit Reg		25 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case






















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: GP MOTORING PTE LTD , Co. Reg. No.: 201205428D									
Vehicle Reg. No.: FR9827G		Date of Loss: 23/12/2018 23:00 - :59 [224 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHD3583Z		Policy No. (Claimant):							
		Excess:							
Repairer: GP MOTORING PTE LTD (HQ) 282 Macpherson Road, 348607 Macpherson - Tel: 67464240									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/02/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									
























Claim Documents

*FR9827G
[SHD3583Z]
TP
GP MOTORING PTE LTD
Dec 23 2018 11:00PM
[-]
GP MOTORING PTE LTD

Upload Documents | Upload Photos | Compose New Letter

View View in Browser v

Photos/Images			3 per page v	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
2	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
3	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
4	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
5	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
6	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
7	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
8	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
12	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
13	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
14	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
15	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
16	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/01/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/01/19 09:35	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
30	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	22/02/19 10:16	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	22/02/19 10:16	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 08:55	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19001713/GCD3E2

Date: 27/02/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : FR9827G

Insured Vehicle No : SHD3583Z

Date of Loss: 23/12/2018

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FR9827G

Make & Model: YAMAHA RXZ, 133cc (M)

Engine No: 3BS249925

Reg. Date: 28/03/2000 (Man. Year: 1999)

Chassis No: ZMC249925

Colour: Red

Odometer: 56539 km

Engine Capacity: 133 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-17

Rear Tyre Size: 90/80-17

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/01/2019

Date Inspected: 25/01/2019 Inspected At:

GP MOTORING PTE LTD (HQ)
282 Macpherson Road
Singapore 348607

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 27 Feb 2019)
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for FR9827G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >