

ASS. REC. BY:

REF:

CS3/III 99001714/Acd36

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

5/3/2019 @ 9:21 am.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EYA / INV / MY / CS

To Inspect Vehicle No:

SPQ 8787A

Insured:

SHD 3103B

at Workshop m/s

Yup Lee motor

Tel:

of

11 kaki Bkt Ave 6 # 01-26

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/01/2019

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Shirley

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SPQ 8787A - X
	SHD 3103B - X
	Dismantle: 12/3/2019 @ 1131 AM
	After repair: 15/3/2019 @ 1115 AM

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SF28787A Yr Regn: 2018 AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 216D c.c. 1496Colour: Grey A/C: Insured / Std / NI / NASp. Reading 25234 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA2B32020V926370Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 10/03/19 @ 0302 pmSurvey held at Yap Lee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP in PRS.MV:P.V:Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Preli. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

12010130

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 5 March 2019 9:21 AM  
**To:** Ruby Ong; 'sur@lkkauto.com'; admin-d@lkkauto.com  
**Cc:** Yap Lee Motor  
**Subject:** RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SFQ 8787A [ OUR REF. TCL.GCN.RO.50133.19.YLM]

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SFQ8787A  
III INSURED VEHICLE NO. : SHD3103B  
DATE OF LOSS : 22.01.19

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**  
**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Ruby Ong [mailto:ruby@htapartners.com.sg]  
**Sent:** 04 March, 2019 5:02 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Yap Lee Motor <yap\_lee\_motor@singnet.com.sg>  
**Subject:** RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SFQ 8787A [ OUR REF. TCL.GCN.RO.50133.19.YLM]  
**Importance:** High

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Sirs

We refer to your email of even date.

Our client has decided to withdraw his claim from Performance Motors Limited and our client is not agreeable to use LKK as the single joint expert.

**TAKE NOTICE** that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

1. Andrew How      Prominent Appraiser Services Pte Ltd
2. Alan              CL Appraiser Pte Ltd

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

**Venue :**              **Yap Lee Motor**  
1 Kaki Bukit Avenue 6  
#01-26 Autobay@Kaki Bukit (417883)

**Contact Person :**      **Mrs Chua / Shirley : 6844 1555**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

**Tel : 6533 0212 ext 278**

**Fax : 6338 3536 / 6533 0313**

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

---

**From:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Sent:** Monday, March 04, 2019 10:30 AM

**To:** Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>

**Subject:** RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SFQ 8787A [ OUR REF. TCL.GCN.RO.50133.19.YLM]

Dear Sirs,

We refer to the matter above.

We have received PRI request from Performance Motors Limited. LKK has been assigned to conduct the PRI.

Kindly confirm that your client has decided to withdraw his claim from Performance Motors Limited and if you are agreeable to using LKK as the single joint expert.

Best Regards,  
Gabriel Wee



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

---

**From:** Ruby Ong [mailto:ruby@htapartners.com.sg]  
**Sent:** 01 March, 2019 5:43 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SFQ 8787A [ OUR REF. TCL.GCN.RO.50133.19.YLM]  
**Importance:** High

Your ref: SHD 3103B  
Our ref: TCL.MH.ro.50133.19.ylm

**WITHOUT PREJUDICE**

1 March 2019

**URGENT**

**India International Insurance Pte Ltd**  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711  
**Attn: Motor Claims Dept**

By Email only

Dear Sirs

**CLAIMANT: NEO TJIN WHA ALVIN**

**NOTICE OF ACCIDENT AND PRE-REPAIR SURVEY - ACCIDENT INVOLVING SFQ 8787A & SHD 3103B ALONG NEWTON CIRCUS ROUNDABOUT ON 22 JANUARY 2019 @ 2140HRS**

We are instructed by Neo Tjin Wha Alvin to notify you of a road traffic accident on 22 January 2019 at about 21405hrs along Newton Circus Roundabout involving our client's vehicle registration number SFQ 8787A and vehicle registration number SHD 3103B driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,  
Ruby Ong  
Secretary  
M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416

**Tel : 6533 0212 ext 278**

**Fax : 6338 3536 / 6533 0313**

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5140C
<b>Vehicle Details</b>	
Vehicle No.:	SFQ8787A
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	216D ACTIVE TOURER LED EU6
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	32395262B37C15A
Chassis No.:	WBA2B32020V926370
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$31,486.00
Original Registration Date:	10 Apr 2018
First Registration Date:	10 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$26,081.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Apr 2028
PARF Rebate Amount:	\$19,560.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$34,407.00
<b>Total Rebate Amount:</b>	<b>\$53,967.00</b>

The information contained herein is correct as at 20 Mar 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	24/01/2019 00:30
Date Of Accident	22/01/2019 21:40
Exact Location Of Accident	NEWTON CIRCUS ROUND ABOUT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFQ8787A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NEO TJIN WHA ALVIN
NRIC No	S7905140C
Email Address	ALVINNEOTW@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96815717
Alternative Phone No	OFFICE-96815717
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	216D ACTIVE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10824901
Cover Note Number	N.A.
<b>Driver</b>	
Name of Driver	NEO TJIN WHA , ALVIN
NRIC No	S7905140C
Date Of Birth	16/02/1979
Occupation	INDOOR
Date Of Driving Pass	09/09/2004
Driving Experience	14 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96815717
Fax Number	
Contact Number	OFFICE-96815717
EEmail Address	ALVINNEOTW@YAHOO.COM.SG



Address	5A HOLLAND HILL #08-00
Postcode	278730
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : XAVIER NEO GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I was on Newton circus and driving on the leftmost lane, the blue taxi cut across 2 lanes to exit and collided into my vehicles right front bumper. No injuries involved at that point in time.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UPLOADED INTO AVIVA FILE ZILLA
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3103B
Vehicle Make/Model/Colour	HYUNDAI/I40/BLU
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	JUAN CHIN LOON
NRIC/Passport Number	S0038366Z
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**6. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


**VERIFIED BY AJAX MARS  
REPORTING OFFICER**

Mohamed Salfullah S/O Syed  
Masood  
Witnessed by Reporting Centre  
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

**Sketch Plan**



## Common Statement

### ACCIDENT STATEMENT (2000 characters)

I was on Newton circus and driving on the leftmost lane, the blue taxi cut across 2 lanes to exit and collided into my vehicles right front bumper.

No injuries involved at that point in time.

Taxi Voucher No

### DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHAMED SAIFULLAH S/O SYED MASOOD

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

23 January 2019 at 4:50 PM

Date/Time

23 January 2019 at 4:50 PM

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING
























Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jan 2019 <a href="#">Edit Reg</a>		05 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>NEO TJIN WHA ALVIN</b> , ID: S7905140C									
Vehicle Reg. No.: <b>SFQ8787A</b>		Date of Loss: 22/01/2019 21:00 - :59 [9 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / MCT19010665</b>		Policy/Cover Note No.: MCOM0015							
Vehicle Reg. No. (Insured): <b>SHD3103B</b>		Policy No. (Claimant): 10824901							
		Excess:							
Repairer: <b>Yap Lee Motor (HQ)</b> 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:									
Handling Insurer: <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sundari Nagarajan</b> - 6347 6071]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 07/02/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (20/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SFQ8787C - Claim Handler: Sundari Nagara...</li> <li>III_SG (19/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SFQ8787C - Claim Handler: Sundari Nagara...</li> <li>III_SG (15/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SFQ8787C - Claim Handler: Sundari Nagara...</li> <li>III_SG (01/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SFQ8787C - Claim Handler: Sundari Nagara...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SFQ8787A (MCT19010665)  
[SHD3103B]  
TP  
NEO TJIN WHA ALVIN  
Jan 22 2019 9:00PM  
[-]  
Yap Lee Motor

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)						Thumbnail	Print	
1	19/02/19 09:11	Video - Accident-TP						Load MP4		
2	19/02/19 14:37	Video - Accident						Load MP4		
3	22/02/19 15:24	Video - Accident						Load MP4		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
2	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
3	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
4	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
5	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
6	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
7	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
8	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
9	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
10	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
11	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
12	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
13	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
14	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
15	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
16	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
17	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
18	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
19	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
20	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
21	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
22	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
23	20/03/19 15:15	General View						Load JPG	<input checked="" type="checkbox"/>	
24	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
25	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
26	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
27	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
28	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
29	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
30	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
31	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
32	20/03/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
33	20/03/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	20/03/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	20/03/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	20/03/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	20/03/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	20/03/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/19 16:17	TP EST & GIA REPORT	 Load PDF	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 08:55	Singapore Accident Statement	 Load PDF	<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19001714/ACD3E2

Date: 21/03/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle  
No : SFQ8787A

Insured Vehicle No : SHD3103B

Date of Loss: 22/01/2019

Nature of Claim:

TP

Claim No: MCT19010665

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SFQ8787A

Make &amp; Model: BMW 216D, 1.5 D Active Tourer (F45) (A)

Engine No: 32395262B37C15A

Reg. Date: 10/04/2018 (Man. Year: 2018)

Chassis No: WBA2B32020V926370

Colour: Grey

Odometer: 25234 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 05/03/2019

Date Inspected: 11/03/2019 Inspected At:

Yap Lee Motor (HQ)

1 Kaki Bukit Avenue 6, #01-26 Autobay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2019)
Parts:	M1-MPV	BMW 216D 1.5 D Active Tourer (F45) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFQ8787A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >