

ASS. REC. BY:

REF:

Q83/CTI19001715/ Bcd302

Special Instruction:

JCS 4140M Urgent

Surveyor:

Mr. hm

ASSIGNMENT (Office)

From (Person): Catherine Chia

of

CTI

Date/Time:

24/11/19 @ 4:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JRJ 143

Insured:

GBB17194

at Workshop m/s

MS Auto

Tel:

63851838

of

8 kaki Bukit Ave 4 # 01-07 premier

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/01/2019

CA / REV / REP. / REV 24 HRS

lupl

H.O.D. Endorsement:

Date/Time:

25/11/19 @ 9:41am

Person Contacted:

Desmond

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

JRJ143-X

GBB17194 - NA/INC16015568/Ch4

DOA: 19/8/16

REF: CTI

PRS

ASSIGNMENT

From Date 25/01/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

at Workshop n/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS lupi

Vehicle: IN / OUT

Date: Person Contacted:

Veh No JRJ 143 Yt Regn 7/2/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KAWASAKI

C.C. 249

Colour: GREEN

A/C Insured / Std / NI / NA

Sp. Reading 41678

T/Radio: Insured / Std / NI / NA

Eng/No: EX250LEA29978

C/No: JKAER250C0DA27450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70ZR17

R: 160/60ZR7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 16/1/19

D.O.I. 25/1/19

Survey held at

MS AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 1500/2 - 2,000/2

[Signature]
26/4/2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

Survey Fee:

Transportation

2)

Add Fee: ☐ Site Insp (\$)

S + RS SI

☐ Interview (\$)

Photos

☐ Tech Invs (\$)

Other

☐ Weekend (\$)

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$)

Tolin
25/2/19

150
150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	
Main	23 Jan 2019		30 Jan 2019 17:26 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	CHOO JIANN WEN
Vehicle Reg. No.:	JRJ143
Claim Type:	TP / SNM19D200428
Vehicle Reg. No. (Insured):	GBB1719U
Date of Loss:	16/01/2019 00:00 - :59
Policy/Cover Note No.:	NA
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	Ms Auto Pte Ltd (HQ) 8 KAKI BUKIT #01-07 PREMIER@KAKI BUKIT, 415875 Kaki Bukit - Tel:
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 12/02/2019]
Adj Asg. Remarks:	APPOINTED VIA EMAIL PREVIOUSLY

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Thursday, 24 January 2019 4:52 PM
To: assignments
Cc: jiarong@roypartners.com.sg
Subject: our ref: GBB1719U (your ref: MKR/307/8588/2019/as.jr)
Attachments: 20190124163450.pdf

Dear LKK oic

Please conduct PRI inspection. We will create in Merimen shortly

Thanks

Dear Jiarong

As spoken you are rejecting our panel of SJE. As such, we are appointing LKK for the survey

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

ROY & PARTNERS

(Business Registration No. 53131170L)

Advocates & Solicitors

Commissioner For Oaths

Notary Public

MONOJ KUMAR ROY LLB (Hons.) S'pore

HARPAL SINGH BAJAJ LLB (Hons.) London

101 Cecil Street #11-09 Tong Eng Building Singapore 069533

Tel : 6536 8466

Fax : 6536 1963 (Not For Service Of Documents)

Enquiries: roypartners@roypartners.com.sg

Our Ref: MKR/307/8588/2019/as.jr

Your Ref: To be advised (Your insured vehicle: GBB 1719U)

AME

21st January 2019

IMMEDIATE ATTENTION

M/S CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

BY FAX: 6224 7175 ONLY

3 Anson Road,

#16-00 Springleaf Tower,

Singapore 079909

(Attn: Motor Claims Department)

Dear Sirs,

CLAIMANT: Choo Jiann Wen

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NO. JRJ 143 AND GBB 1719U AT THE JUNCTION OF WOODLANDS AVE 2 JUNCTION MARSLING ROAD ON 16.01.2019 AT ABOUT 0950 HOURS.

We refer to the above matter.

We act for CHOO JIANN WEN, the owner of motor car No. JRJ 143.

We are instructed by our client to notify you of a road traffic accident on 16.01.2019 at about 9.50 am at the junction of **WOODLANDS AVE 2 JUNCTION MARSLING ROAD** involving our client's motor vehicle registration number **JRJ 143** and motor car registration number **GBB 1719U** driven by your insured at the material time. A copy of the Singapore police report filed is enclosed.

As a result of the accident, our client's motor vehicle **JRJ 143** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **JRJ 143** at our client's repairer workshop, M/s MS Auto Pte Ltd 8 Kaki Bukit #01-07 Premier @ Kaki Bukit Singapore 415875. Your said surveyor may contact Desmond at 6385 1838 to arrange the said inspection. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

Yours faithfully

Jiann Wen @ roypartners.com.sg

22 Jan 2019

Monoj Kumar Roy

MONOJ KUMAR ROY

Enc

Cc: Clients (MS Car Pte Ltd)
(JRJ 143)

(Fax No. 6386-1838)

PACIFIC & ORIENT INSURANCE CO. BERHAD (No.12557-W)
A Member Of The Pacific & Orient Group

image003.gif

11th Floor, Wisma Bank Negara, No. 12, Jalan Raja Laut, 50050 Kuala Lumpur, PO Box 10501, 50729 Kuala Lumpur, Malaysia
Telephone: 603-2607 9177 Fax: 603-2607 8225 Toll Free: 1-800-88-3321
Website: www.pacific-orient.com / info@pacific-orient.com

**PA PLUS - PERSONAL ACCIDENT CERTIFICATE /
SIJIL KEMALANGAN PERIBADI PLUS**

The Insured / Address / Pihak Diinsuranskan / Alamat CHOO JIANN WEN NO 12 JLN BATIK 1 TJIN SENTOSA 80150 JOHOR BAHRU JOHOR				Motor Policy No. / No. Polisi Induk: 01-06-18-JLF-029901 Issued by / Dikeluarkan Oleh: Pacific & Orient Insurance Co. Berhad Agency Code / Kod Ajenai: 30677-01 Batch No. / No. Kumpulan: 04*MCP-640309 Issue Date / Time / Tarikh Dikeluarkan / Masa: 11-04-2018 11:04:46 PA Certificate No. / No. Sijil PA: 306770118000112 Period of Insurance / Tempoh Insurans: From / Dari: 11-04-2018 To / Hingga: 10-04-2019			
Name / Old IC No. / No. K/P Baru / Lama: 750214-01-6685	Age / Umur: 43	Date Of Birth / Tarikh Lahir: 14-02-1975	Gender / Jantina: MALE	Plan / Pelan: A1	Sum Insured (RM) / Jumlah Diinsuranskan: 5,000.00	Premium (RM) / Premium: 13.60	
Hire Purchase Owner / Lessor / Credit Company / Pemilik Sewa Beli / Pajakan / Sykt. Kredit				GST / CBP: 0.72	Total Premium (RM) / Jumlah Premium: 13.78		

Subject to the terms, definitions, conditions, limitations and exclusions contained in the policy, the insured above named shall, during the period of the validity of the Policy above stated be covered for Death or Permanent Disablement by reason of Bodily Injury/Accident. The insured, subject always to the limitation set out in the Policy, is insured for the Capital Sum set out above.

Tertakluk kepada terma-terma, definisi-definisi, syarat-syarat, had dan pengecualian yang terkandung di dalam polisi, pihak diinsuranskan bernama seperti di atas, harus semasa di dalam tempoh sah polisi yang tertera di atas akan dilindungi untuk kematian atau hilang keupayaan kekal dengan sebab kemalangan / kesederhanaan Tubuh Badan. Pihak diinsuranskan, harus sentiasa tertakluk kepada penghadan yang digariskan di dalam polisi dan adalah merupakan pihak yang diinsuranskan bagi Jumlah Insurans yang terkandung di atas.

Note: A Summary of Coverage and the Benefit Limits, Exclusions and Claim Procedures are printed on the next page.
Nota: Ringkasan perlindungan dan Had Faedah, Pengecualian dan Tatacara Tuntutan adalah dicetak di muka surat berikutnya.

**Statement Pursuant to Section 149 (4) of the Insurance Act, 1996. You are to disclose in the proposal form, fully and faithfully all the facts, which you know or ought to know, otherwise the policy may be invalidated.
Kenyataan menurut Seksyen 149 (4) Akta Insurans, 1996. Anda hendaklah memberitahu di dalam borang cadangan, segala fakta yang anda tahu atau yang anda patut tahu secara penuh dan jujur. Jika tidak polisi menjadi tidak sah.

****Consumer Insurance Contracts / Kontrak Insurans Pengguna**

This Policy is issued in consideration of the payment of premium as specified in the Policy / Certificate Schedule and pursuant to the answers given in your Proposal Form (or when you applied for this insurance) and any other disclosures made by you between the time of submission of your Proposal Form (or when you applied for this insurance) and the time this contract is entered into. The answers and any other disclosures given by you shall form part of this contract of insurance between you and us. However, in the event of any pre-contractual misrepresentation made in relation to your answers or in any disclosures given by you, only the remedies in Schedule 6 of the Financial Services Act 2013 will apply.

This Policy reflects the terms and conditions of the contract of insurance as agreed between you and us.

Polisi diisrukan sebagai pertukaran dengan pembayaran dan premium yang ditentukan dalam jadual Polisi/Sijil dan menurut kepada kenyataan yang telah dikemukakan di dalam borang cadangan (atau semasa permohonan insurans ini) dan segala maklumat yang telah dibuat oleh pihak anda pada atau semasa penyediaan borang cadangan (atau semasa permohonan insurans ini) dan pada masa perjanjian ini diandatangani. Jawapan dan sebarang maklumat lain yang anda berikan akan menjadi sebahagian daripada kontrak insurans antara anda dan pihak kami. Walau bagaimanapun, sekiranya terdapat sebarang salah nyatakan semasa pre-kontrak berhubung dengan jawapan anda atau di mana-mana maklumat yang diberikan oleh anda, hanya remedies yang terdapat dalam Jadual 6 Akta Perkhidmatan Kewangan 2013 akan diguna pakai. Polisi ini berkuatkuasa atas terma-terma dan syarat-syarat kontrak insurans seperti yang telah dipersetujui antara anda dan pihak kami.

Assignment Form / Borang Serah Hak
I/We hereby assign all monies payable under this policy to the Assignee _____ whose receipt shall be a full and final discharge to Pacific & Orient Insurance Co. Berhad (hereinafter referred to as the "Company") for all liability in respect of this policy.
Saya/Kami dengan ini menyerahkan semua bayaran dibawah polisi ini kepada Pemegang Serah Hak _____ dengan ini mengarahkan semua bayaran dibawah polisi ini kepada Pemegang Serah Hak _____ sebagai penerima keseluruhan pelepasan kepada Pacific & Orient Insurance Co. Berhad (yang dirujuk sebagai "Syarikat Insurans") untuk segala pertanggungjawaban dalam polisi ini.

We hereby acknowledge and agree that the Company is entitled to rely on any statement provided by the Assignee as to the balance due under the said financing agreement and I/We hereby instruct the Company to make payment to the Assignee all the monies payable under this Policy without any obligation to investigate the accuracy, genuineness or validity of the said statement. We hereby agree that if I/We wish to revoke the assignment, such revocation shall be by notice in writing and shall be deemed effective only upon acknowledged receipt of the revocation by the Company.

Saya/Kami dengan ini mengesahkan dan bersetuju bahawa Syarikat Insurans berhak bergantung atas segala kenyataan yang diberikan oleh Pemegang Serah Hak yang mana baki tertunggak dibawah perjanjian sewa beli dan Saya/Kami dengan ini mengarahkan Syarikat Insurans untuk membuat pembayaran kepada Pemegang Serah Hak tanpa sebarang keraguan untuk memulau katempatan, ketulenan atau kelayakan kenyataan tersebut. Saya/Kami dengan ini bersetuju sekiranya Saya/Kami ingin membatalkan Penyerahan Hak, segala pembatalan perlulah

Signature of Insured/
Tandatangan pihak Diinsuranskan

MOTORCYCLIST'S PERSONAL ACCIDENT.....(1 of 2)

PACIFIC CERTIFICATE 000

**PA PLUS - PERSONAL ACCIDENT /
KEMALANGAN PERIBADI PLUS**

THE BENEFITS LIMIT PER COVERED PERSON / HAD FAEDAH BAGI ORANG YANG DILINDUNGI

PERCENTAGE OF COMPENSATION
PERATUSAN PAMPASAN

Section 1 / Seksyen Accident Death (Loss of Life) /

1 Kematian akibat kemalangan (Kehilangan nyawa)

100%

Section 2 / Seksyen

2 Permanent Disablement / Kehilangan Upaya Kekal

(a) Complete loss of one or both hands /

Hilang keseluruhan satu atau kedua belah tangan



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

KFS72D5X

No. Pendaftaran	: JRJ143
No. ID	: 750214016685
Nama Pemunya Berdaftar	: CHOO JIANN WEN
Alamat	: 12, JALAN BATIK 1, TMN SENTOSA, 80150 JOHOR BAHRU JOHOR
No. Chasis/No. Enjin	: JKAER250CCDA27450 / EX250LEAA9978
Buatan>Nama Model	: KAWASAKI / ER250-C
Keupayaan Enjin	: 249
Bahan Bakar	: PETROL
Status Asal	: KENDERAAN IMPORT BARU
Kelas Kegunaan	: MOTOSIKAL
Jenis Badan/Tahun Dibuat	: MOTOSIKAL / 2015
Tarikh Pendaftaran	: 07/02/2016
B. D. M/B. G. K/BTM	: -
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -



SINGAPORE POLICE FORCE



T/20190117/2129

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190117/2129

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/01/2019 16:42	Vide Report No.: L/20190116/0061	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars		
Name of Informant: CHOO JIANN WEN		Address: 20 SENOKO DRIVE SINGAPORE 758207
ID Type / ID No.: FIN NO / F7472840P		Contact No.: Home/Office: Mobile: 93581686
Nationality: MALAYSIAN		Email:
Sex: Male	Age: 43	Date of Birth: 14/02/1975
Type of Informant: Rider		
Race: Chinese		Language: Institution / School Name:
Occupation: CONSTRUCTION WORKER		Driving Licence Information: Class: Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 16/01/2019 09:50	Type of Location:
Location: Along Road 1 RIVERSIDE ROAD WOODLANDS AVE 2 JUNCTION MARSILING RD LP 22				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBB1719U	Van	RENAULT	KANGOO DCI70	Blue		0
JRJ143 (Not Accurate)	Motorcycle					0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Rider				
Name	CHOO JIANN WEN		ID No.	F7472840P
Related Vehicle	JRJ143 (Motorcycle)		Contact No.	93581686
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	16/01/2019		Date Discharge	17/01/2019
No. of Days granted Medical Leave	14		Degree of Injury	Serious
Driver				
Name	RAJU VELLAI		ID No.	G72312645U
Related Vehicle	NIL		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

ON THE DATE, LOCATION AND TIME MENTIONED,

I WAS TRAVELLING ON THE 2ND LANE OF 4 LANES ON THE MENTIONED RD. SUDDENLY, I SAW A VEHICLE(GBB1719U) INFRONT OF ME ON THE 3RD LANE SWITCH LANES AND COME INTO MY PATH. UNABLE TO STOP IN TIME, I MANAUVOURED MY VEHICLE TO THE RIGHT AND SKIDDED TO AVOID ANY COLLISION WITH THE VEHICLE.



SINGAPORE
POLICE FORCE



T/20190117/2129

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190117/2129

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
AHMAD JALALUDDIN BIN AHMAD

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt RAZIZ BIN TAHAR
Contact No.: 65476200

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
17/01/2019 16:42

Classification Of Case:



Signature: _____



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

KFS72D5X

No. Pendaftaran : JRJ143
No. ID : 750214016685
Nama Pemunya Berdaftar : CHOO JIANN WEN
Alamat : 12, JALAN BATIK 1, TMN SENTOSA,
80150 JOHOR BAHRU JOHOR

No. Chasis/No. Enjin : JKAER250GCCDA27450 / EX250LEAA9978
Buatan/Nama Model : KAWASAKI / ER250-C
Keupayaan Enjin : 249
Bahan Bakar : PETROL
Status Asal : KENDERAAN IMPORT BARU
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2015
Tarikh Pendaftaran : 07/02/2016
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



































...CLAIM SUBFOLDER...(Pending for Survey Report)






CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jan 2019		30 Jan 2019 17:26 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	CHOO JIANN WEN								
Vehicle Reg. No.:	JRJ143	Date of Loss:	16/01/2019 00:00 - :59 [35 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200428	Policy/Cover Note No.:	NA						
Vehicle Reg. No. (Insured):	GBB1719U	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Ms Auto Pte Ltd (HQ) 8 KAKI BUKIT #01-07 PREMIER@KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 12/02/2019]								
Adj Asg. Remarks:	APPOINTED VIA EMAIL PREVIOUSLY								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JRJ143 (SNM19D200428)
[GBB1719U]
TP
CHOO JIANN WEN
Jan 16 2019 12:00AM
[-]
Ms Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
2	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
3	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
4	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
5	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
6	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
7	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
8	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
9	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
10	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
11	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
12	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
13	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
14	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
15	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
16	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
17	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
18	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
19	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
20	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
21	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
22	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
23	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
24	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
25	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
26	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
27	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
28	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
29	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
30	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
31	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
32	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
33	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
34	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
35	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
36	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						
37	21/03/19 18:25	General View		Load JPG	<input checked="" type="checkbox"/>						

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/03/19 18:25	General View	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119001715/BCD3E2

Date: 10/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: NA

Claimant Vehicle No: JRJ143

Insured Vehicle No: GBB1719U

Date of Loss: 16/01/2019

Nature of Claim: TP

Claim No: SNM19D200428

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JRJ143

Make & Model: KAWASAKI ER250-C, 249cc

Engine No: EX250LEAA9978

Reg. Date: 07/02/2016 (Man. Year: 2015)

Chassis No: JKAER250CCDA27450

Colour: Green

Odometer: 41678 km

Engine Capacity: 249 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/01/2019

Date Inspected: 25/01/2019 Inspected At:

Ms Auto Pte Ltd (HQ)
8 KAKI BUKIT #01-07 PREMIER@KAKI
BUKIT
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 -\$2,000.00

REPAIR DETAILS

Reference

Part Source:**Parts:** N/A KAWASAKI ER250-C 249cc (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for JRJ143)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >