

22/03/2002

ASS. REC. BY:

REF: es3/Lpc19001733/Rtd3/n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

Lpc

Date/Time: 28/11/19 @ 3:54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KA 5370M

Insured:

SLV 6334P

at Workshop m/s

Jingkia Car Services

Tel:

64814055/93822000

of

10 AMK Ind. Park 2A #05-09

Policy No:

Claim No:

18/19/19/vpos/021365

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23012019

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wop'

28/01/2019

H.O.D. Endorsement:

Date/Time:

4:13pm @ 28/11/19

Person Contacted:

Mr. Tan

Vehicle: IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

agreed change on 28/11/19

8KA 5370M-X

14/2-

Submit PRS Report


PRS

REF:

48124

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SKA 5370M**
 at Workshop m/s **JINH KIA CAR**
 of **10, AMK Airport # 05/09**
 Insured: **LPL**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **26K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SKA 5370M** Yr Regn: **2010 MAR**
 Type: **C** M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **NISSAN TEANA 2.5 CIT** C.C. **2496**
 Colour: **GRY** A/C: Insured / Std / NI / NA
 Sp.Reading: **136974** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JN1BB43320002090**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: **C** Inorder / Jammed / Leaked / Burnt or
 Brake: **C** Inorder / Jammed / Leaked / Burnt or
 Modi: **C** Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **215/55R17**
 R: **215/55R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **FRANK**

Front: _____ Rear: _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **23/01/19** D.O.I. **28/01/19 3.01pm**
 Survey held at **JINH KIA CAR**
 Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 FEB 2019

Date/Time, File Pass to?

14/2 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

TP PRS

☐ : Preli. Report
☐ : Final Report

Days Of Repair: **—**

Resurvey No. of Trip: **—**

Add Fee: ☐ Site Insp (\$
☐ Interview (\$
☐ Tech. Invs (\$
☐ Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

450

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Friday, 25 January 2019 3:54 PM
To: assignments
Subject: FW: PRE-REPAIR SURVEY OF SKA5370M

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 25 January 2019 3:43 PM
To: Admin A <admin-a@lkkauto.com>; LKK <lkk@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; Joseph Goh <joseph_goh@juseq.com.sg>
Subject: FW: PRE-REPAIR SURVEY OF SKA5370M

Dear Catherine,

Kindly proceed to contact the workshop to arrange the pre-repair survey.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Joseph Goh [mailto:joseph_goh@juseq.com.sg]
Sent: Friday, 25 January, 2019 3:39 PM
To: GERALD POH WEE BIN
Subject: RE: PRE-REPAIR SURVEY OF SKA5370M

Dear Gerald

We refer to your email below.

Please have your surveyor contact our client's workshop (details below) to make the necessary arrangement for pre repair inspection:-

Jingkia Car Services
10 Ang Mo Kio Industrial Park 2A
Ang Mo Kio Autopoint #05-09
Singapore 568047
Contact Person: Mr Tan 64814055 (o) / 9382 2000(hp)

Regards
Joseph Goh
M/s JusEquity Law Corporation
171 Chin Swee Road #02-06
Singapore 169877
Tel: 6536 9339
Fax: 6536 5368
Email: joseph_goh@juseq.com.sg

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: Friday, 25 January 2019 2:46 PM
To: Joseph Goh <joseph_goh@juseq.com.sg>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: PRE-REPAIR SURVEY OF SKA5370M


WITHOUT PREJUDICE

Dear Joseph,

We are not agreeable to Lee Automobile Appraisers Services as the Single Joint Expert and shall proceed to appoint LKK Auto Consultants Pte Ltd for the pre-repair survey.

Please advise the location of the workshop whereby the pre-repair inspection can be conducted

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Joseph Goh [mailto:joseph_goh@juseq.com.sg]
Sent: Friday, 25 January, 2019 2:39 PM
To: GERALD POH WEE BIN
Subject: RE: PRE-REPAIR SURVEY OF SKA5370M

Your ref : 18/19/19/VP05/021365
Our ref: JEQ/JG/7235-19.JCS

Dear Gerald

We refer to your email below.

Our client is not agreeable to your list of surveyors. Our client proposes Mr Lee Kok Weng from Lee Automobile Appraisers Services as the single joint expert to conduct the pre-repair inspection.

Please let us know if you have any objections to our client's proposal. If you do not agree with our client's proposal, we suggest that the pre repair inspection be conducted by both surveyors. In this respect, please let us know the surveyor whom you will be appointing to conduct the pre repair inspection so that our client's workshop can contact your surveyor directly.

Regards

Joseph Goh

M/s JusEquity Law Corporation

171 Chin Swee Road #02-06

CES Centre

Singapore 169877

Tel : 6536 9339

Fax: 6536 5368

Email: joseph_goh@juseq.com.sg

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Friday, 25 January 2019 2:06 PM

To: joseph_goh@juseq.com.sg

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: PRE-REPAIR SURVEY OF SKA5370M

WITHOUT PREJUDICE

Our Ref : 18/19/19/VP05/021365

Dear Joseph,

Please see attached and revert.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4812G
Vehicle Details	
Vehicle No.:	SKA5370M
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	TEANA 2.5 CVT ABS D/AB HID 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	VQ25436895A
Chassis No.:	JN1BBUJ32Z0002090
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$33,977.00
Original Registration Date:	31 Mar 2010
First Registration Date:	31 Mar 2010
Transfer Count:	1
Actual ARF Paid:	\$33,977.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2020
PARF Rebate Amount:	\$18,687.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$24,229.00
COE Rebate Amount:	\$2,799.00
Total Rebate Amount:	\$21,486.00

The information contained herein is correct as at 28 Jan 2019

OK

26,000
21,486
4514

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/01/2019 17:50
Date Of Accident	23/01/2019 18:10
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA5370M
Insured/Policyholder	
Name Of Registered Owner	PANG TONG FONG
NRIC No	S7124812G
Email Address	RAYMOND@CURRENT.COM.SG
Mobile Phone No	(LOCAL) +65-93874748
Alternative Phone No	OTHERS-93874748

Vehicle Particulars

Manufacturer	NISSAN
Model	TEANA 2.5 CVT ABS D/AB HID 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MX002338-R04
Cover Note Number	05/04/2018 - 04/04/2019

Driver

Name of Driver	PANG TONG FONG
NRIC No	S7124812G
Date Of Birth	26/07/1971
Occupation	INDOOR
Date Of Driving Pass	07/07/1992
Driving Experience	26 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93874748
Fax Number	
Contact Number	OTHERS-93874748

Address	BLK 122B SENGKANG EAST WAY #12-19
Postcode	542122
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PANG XINYING, CASSIA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	ANG MO KIO DIVISION HQ
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV6334P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN PANG KUAN, JASON
NRIC/Passport Number	S9029668Z
Contact Number	
Address	
Postcode	
Insurance Company Name	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SDA1648Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

YEO KIM NEO

NRIC/Passport Number

S1477531E

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

Date of accident: 23/01/19 Time: 18-10 Location: Upper Serangoon road
 My Vehicle A: SKA 5370M Vehicle B: SLV 8334P Vehicle C: SDA 1648Y
 SKETCH PLAN SLV 6334P



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

Veh B: Tan Pang Kuan, Jason / 890296682

Veh C: Yeo Kim Neo / 81477531E

☐ Claim OD/TP at Ah Lim Motor ☒ Claim ~~OD~~ TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop : Jingkia Car Services

Email address : Jingkiacarservices@yahoo.com.sg

& myself : raymond@current.com.sg

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature] 24/01/19
 Policyholder's Signature
 Date & Time:

[Signature] 24/01/19
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC19001733/R1td3n2		
300 BEACH ROAD		Date: 14-02-2019		
#17-04/07 THE CONCOURSESINGAPORE 199555				
		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLV 6334P	Veh. Inspected	SKA 5370M	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021365	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	25/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN TEANA 2.5 CVT	c.c	2496	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1BBUJ32Z0002090	Colour	GREY	
Odometer	136974 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	FALKEN	6 mm	
L/H Front Tyre	215/55 R17	FALKEN	6 mm	
R/H Rear Tyre	215/55 R17	FALKEN	6 mm	
L/H Rear Tyre	215/55 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	23/01/2019	Inspect Date / Time	28/01/2019 (03:01 PM)	
Survey held at	JINGKIA CAR SERVICES BLK 10,ANG MO KIO INDUSTRIAL PARK 2A #05-09 ANG MO KIO AUTOPOINT . SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC19001733/R1td3n2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.