22/03/2002

S. REC. BY: | REF: CS3 /MSG19001763/Jcl3b2 Special Instruction:

Surveyor: Kenny Ong

ASSIGNMENT (Office)

From (Person): Kenny Ong of MSIG Date/Time 28012019 1004am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 8115U Insured: WC 2430R

at Workshop m/s SW motor Tel: 81819694 98631300

of No. 211 Kranji Road

Policy No: B29088496MKF Claim No: 583339

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 18012019

CA / REV / REP. / REV 24 HRS 'Wp' 29012019 @ 2pm H.O.D. Endorsement:

Date/Time: 28012019 1055am Person Contacted: Win Vehicle IN / OUT

| Date/Time | Action/Instruction ( X ) Estimate |
|---|---|
| | XD 8115U - CS/EGI 17007133 / K1h3h2 DOA: 16012017 |
| | WC 2430R - CS/MSG 17011190 / R1h6h2 DOA: 06062017 |
| | |
| | |
| | |
| | |

Surveyor: Huee Jie
PRS (Meriner)

REF: MS1G

ASSIGNMENT

From: Date: 29/1/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 8115 U

at Workshop m/s: SW Motor

of: No. 211 Kranji Road

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh: 2pm Win@ 81829694

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: XD 8115 U Yr Regn: 9 Jan 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes MB Actros C.C.

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: 574667 T/Radio: Insured / Std / NI / NA

Eng/No: —

C/No: WDB9321612L783119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 315/80 R22.5

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Triangle

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 8 mm | R/Bal. | 8 mm |
| L/Bal. | 8 mm | L/Bal. | 8 mm |

D.O.A. 18/1/19 D.O.I. 29/1/19

Survey held at: SW motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | Range: $2,500 - $3,000<br>3 days.<br>13/2/2019 |

Date/Time File Pass to?

1)

Date/Time File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: —

Add Fee: ☐ Site Insp ($ ) ☐ Interview ($ ) ☐ Tech. Invs ($ ) ☐ Weekend ($ )

Report Format: PRS

Lump Sum / I.B.I: ($ )

| | |
|---|---|
| Survey Fee | 120 |
| Transportation | |
| S + PS | |
| Photos | |
| Other | 10 |
| TOTAL | 130 |

# ...CLAIM SUBFOLDER...(New Assignment)

**CLAIM SUBFOLDER TRACKING**

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | *Status* |
|---|---|---|---|---|---|---|---|
| Main | 19 Jan 2019 | | 28 Jan 2019 10:04 Assign | | | | ***New Assignment*** Cancel Case |

Main | Reference | Claim Details | Documents | Show All

**CLAIM SUBFOLDER DETAILS** **[Created by insurer]**

| | | | |
|---|---|---|---|
| Insured: | **ALLIANCE CONCRETE SINGAPORE PTE LTD,** Co. Reg. No.: 200516266D | | |
| Main Claimant: | **RLS TRANSPORT & ENGINEERING PTE LTD,** Co. Reg. No.: 201327760D | | |
| Vehicle Reg. No.: | **XD8115U** | Date of Loss: | 18/01/2019 09:00 - :59 [**60** Months and **9** Days From LTA Reg Date (Man Yr)] |
| Claim Type: | **TP** / 583339 | Policy/Cover Note No.: | B29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019 |
| Vehicle Reg. No. (Insured): | **WC2430R** | Policy No. (Claimant): | DMCVSN1840651800 |
| | | Excess: | S$1,500.00 |
| Repairer: | **Sw Motor Trading (HQ)** No.211 Kranji Road, 739461 Kranji - Tel: | | |
| Handling Insurer: | **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Keny Ong Thiam Beng** - 6643 1309] | | |
| Claimant's Insurer: | **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 | | |
| Adjuster: | **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Imm.Advice** due 29/01/2019] | | |
| Adj Asg. Remarks: | liability 100 % on OI appoint surveyor LKK Auto Consultants Pte Ltd contact Mr Tan @ 8182 9694 | | |

**ASSOCIATED MAIL RECEIVED** View All | Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS** View All | Search Tasks | Create New Task | Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|---|---|---|---|---|---|---|---|---|---|

No results.

> Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|---|
| **Vehicle Owner Particulars** | |
| Owner ID Type: | Company |
| Owner ID: | 7760D |
| **Vehicle Details** | |
| Vehicle No.: | XD8115U |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 30 Jan 2019 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | MB ACTROS 3336K 6X4 3300 (AUTO, ABS) |
| Primary Colour: | White |
| Manufacturing Year: | 2013 |
| Engine No.: | 541972C0903564 |
| Chassis No.: | WDB9321612L783119 |
| Maximum Power Output: | - |
| Open Market Value: | $118,527.00 |
| Original Registration Date: | 09 Jan 2014 |
| First Registration Date: | 09 Jan 2014 |
| Transfer Count: | 1 |
| Actual ARF Paid: | $5,927.00 |
| **Intended PARF Rebate Details** | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | $0.00 |
| **Intended COE Rebate Details** | |
| COE Expiry Date: | 08 Jan 2024 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| QP Paid: | $55,503.00 |
| COE Rebate Amount: | $27,423.00 |
| **Total Rebate Amount:** | **$27,423.00** |

The information contained herein is correct as at 30 Jan 2019

OK

中国太平 CHINA TAIPING
MOTOR COMMERCIAL VEHICLE

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

MZ300/CE SN
AN0420A
Cov.Type: C
AUTOSAFE

# CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No. DMCVSN1840651800

Engine No :541972C0903564
Chassis No:WDB9321612L783119

1. Index Mark and Registration Number of Vehicle: XD8115U

2. Name of Policy Holder: RLS TRANSPORT & ENGINEERING PTE LTD

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment: 18 DECEMBER 2018 (10:53 HOURS)

EXCESS SECT I .....S$1,500.00
EX ON WINDSCREEN .....S$100.00

4. Date of Expiry of Insurance: 17 DECEMBER 2019

5. Persons or Classes of Persons entitled to drive *

ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

5. Limitations as to use: *

(1) USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
(2) USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS.
(3) USE FOR SOCIAL, DOMESTIC OR PLEASURE PURPOSES.

THE POLICY DOES NOT COVER.
(1) USE FOR HIRE OR REWARD OR RACING, PACE-MAKING, RELIABILITY TRIAL OR SPEED TESTING.
(2) USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

HIRE PURCHASE CO. : SWEE SENG CREDIT PTE LTD AS HP OWNER

** Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.*

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse

INXPRESS INSURANCE AGENCY PTE LTD

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

ountersigned By:

Authorised Officer

Authorised Signatory

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Tel: 6389 6111 Fax: 6225 3592 Website: www.sg.cntaiping.com

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7369029C

Name
RAJ ANBUSELVAN

Race
INDIAN
Date of birth
24-08-1973
Sex
M
Country of birth
INDIA

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S7369029C
Name
RAJ ANBUSELVAN
Birth Date 24 Aug 1973
Issue Date 11 Jun 2009

9034772

NRIC No. S7369029C

Nationality
INDIAN
Date of Issue
04-06-2009

APT BLK 24 BENDEMEER ROAD #11-531
SINGAPORE 330024
NRIC No: S7369029C Date: 01/03/2011 No: 6736626

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| | | PASS DATE |
|---|---|---|
| Class 2B | Motorcycles =< 200 cc | 14 Mar 2005 |
| Class 3 | Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg | 14 Mar 2005 |
| Class 4 | *Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg<br>*Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg | 09 Jun 2008 |

NP 428A

Licence No: S7369029C

MSAT19010599 / Sng Ah Tee Motor & Panel Service Pte Ltd - Pioneer
ENTRY DATE & TIME: 22/01/2019 15:32
SUBMITTED BY: Janice Chang Siew Yin

**Your NCD will be affected due to late reporting**
**Actual e-Filling Submission Date & Time: 22/01/2019 17:18**

# SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

| | |
|---|---|
| Date Of Report | 22/01/2019 15:32 |
| Date Of Accident | 18/01/2019 09:00 |
| Exact Location Of Accident | 211 KRANJI ROAD |
| Country/State of Loss | SINGAPORE |

## DETAILS OF OWN VEHICLE

| | |
|---|---|
| Vehicle Registration Number | XD8115U |
| **Insured/Policyholder** | |
| Name Of Registered Owner | RLS TRANSPORT & ENGINEERING PTE LTD |
| Co Reg No | 201327760D |
| Email Address | RLS201327@GMAIL.COM |
| Mobile Phone No | |
| Alternative Phone No | Office-66101971 |
| **Vehicle Particulars** | |
| Manufacturer | MERCEDES-BENZ |
| Model | MB ACTROS-11.9 3336K 6X4 3300 ABS (A) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | COMMERCIAL VEHICLE |
| **Insurance Company** | |
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMCVSN1840651800 |
| Cover Note Number | |
| **Driver** | |
| Name of Driver | RAJ ANBUSELVAN |
| NRIC No | S7369029C |
| Date Of Birth | 24/08/1973 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 09/06/2008 |

| | |
|---|---|
| Driving Experience | 10 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-82831736 |
| Fax Number | |
| Contact Number | |
| EMail Address | RLS201327@GMAIL.COM |
| Address | BLK 24 BENDEMEER RD #11-531 |
| Postcode | 330024 |
| Was driver an employee of the Insured's Company | YES |
| If No, Relationship of the Driver with the Insured | |
| Vehicle Registration Number of Driver's Own Vehicle | -<br>-<br>- |
| Insurance Company of Driver's Own Vehicle | -<br>-<br>- |

**General Information of the Accident**

| | |
|---|---|
| Type Of Accident | HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

**Other Information**

| | |
|---|---|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 0 |

**Details of Police Action**

| | |
|---|---|
| Was the accident reported to the police? | NO |
| If Yes,Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes,against whom? | |

**Circumstances of Accident**

ON 11/01/2019 I SENT MY COMPANY VEHICLE XD8115U TO THE WORKSHOP WHICH LOCATED AT 211 KRANJI ROAD TO REPAIR. ON 18/01/2019 I RECEIVED A CALL FROM THE WORKSHOP SAID THAT MY VEHICLE HAS BEEN HIT BY WC2430R WHILE THE SAID VEHICLE DOING REVERSE. MY VEHICLE WAS DAMAGE AT THE FRONT PORTION. THE COMPANY OF THE VEHICLE WC2430R THEN ASK ME TO SEND MY VEHICLE TO THEIR WORKSHOP & THEY WILL PAY FOR THE REPAIR COST. UP TILL TODAY (22/01/2019) MY VEHICLE DID NOT DO ANY REPAIR AT THE WORKSHOP & THE SAID COMPANY PERSON IN CHARGE THEN ASK TO LODGE INSURANCE CLAIM. THIS CAUSING ME LATE REPORT. THAT'S ALL.

**Attachment(s)**

| | |
|---|---|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

**Details of Witness 1**

| | |
|---|---|
| Name | SELVAM ALEXPANDI |
| Phone Number | 83033815 |
| Email Address | |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|---|---|
| Vehicle Registration Number | WC2430R |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | LOH KHOON HOCK |
| NRIC/Passport Number | S1335830C |
| Contact Number | 90626653 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Rus Transport & Engineering Pte Ltd Singapore

| Policyholder's Signature<br>Date & Time: | Driver's Signature<br>(If driver is not the policyholder)<br>Date & Time: | Reporting Centre Personnel's Signature<br>Name:<br>NRIC/FIN No.: |
|---|---|---|

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

**SKETCH PLAN**

211 Kranji Road




vehicle (A): XD 8115U

vehicle (B): WC 2430R

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

On 18/01/2019 @ abt 0900hrs.

Refer to circumstances of accident.

- ☐ Claim own policy
- ☐ Claim third party
- ☐ Claim OD / (TP) at other workshop Say Neh welding
- ☐ For record purpose

Policy No. DMCVSN1840651800

Insurer China (C) Veh.No. XD8115U

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

RLS Transport & Engineering Singapore

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**IC,DL,CI**

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

**CLAIM SUBFOLDER TRACKING**

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
|---|---|---|---|---|---|---|---|
| Main | 19 Jan 2019 | | 28 Jan 2019 10:04 Edit Adj Rpt | **S$0.00** Edit Estimates | **S$0.00** View Rpt | | **Pending for Survey Report** Cancel Case |

Main | Reference | Claim Details | Documents | Show All

**CLAIM SUBFOLDER DETAILS** **[Created by insurer]**

| | | | |
|---|---|---|---|
| Insured: | **ALLIANCE CONCRETE SINGAPORE PTE LTD**, Co. Reg. No.: 200516266D | | |
| Main Claimant: | **RLS TRANSPORT & ENGINEERING PTE LTD**, Co. Reg. No.: 201327760D | | |
| Vehicle Reg. No.: | **XD8115U** | Date of Loss: | 18/01/2019 09:00 - :59 [**60** Months and **9** Days From LTA Reg Date (Man Yr)] |
| Claim Type: | **TP** / 583339 | Policy/Cover Note No.: | B29088496MKF (Comprehensive) Coverage: 01/07/2018 - 30/06/2019 |
| Vehicle Reg. No. (Insured): | **WC2430R** | Policy No. (Claimant): | DMCVSN1840651800 |
| | | Excess: | S$1,500.00 |
| Repairer: | **Sw Motor Trading (HQ)** No.211 Kranji Road, 739461 Kranji - Tel: | | |
| Handling Insurer: | **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Keny Ong Thiam Beng** - 6643 1309] | | |
| Claimant's Insurer: | **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 | | |
| Adjuster: | **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ONG HWEE JIE**] ... [**Imm.Advice** due 29/01/2019] | | |
| Adj Asg. Remarks: | liability 100 % on OI appoint surveyor LKK Auto Consultants Pte Ltd contact Mr Tan @ 8182 9694 | | |

**ASSOCIATED MAIL RECEIVED** View All | Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS** View All | Search Tasks | Create New Task | Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|---|---|---|---|---|---|---|---|---|---|
| No results. | | | | | | | | | |

# Claim Documents

***XD8115U (583339)**
**[WC2430R]**
**TP**
**RLS TRANSPORT & ENGINEERING PTE LTD**
**Jan 18 2019 9:00AM**
**[ALLIANCE CONCRETE SINGAPORE PTE LTD]**
**Sw Motor Trading**

Upload Documents | Upload Photos | Compose New Letter

View: View in Browser

| Assessment Reports | | | 1 per page | | |
|---|---|---|---|---|---|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 25/01/19 16:09 | **Accident Statement**<br>From:SC - Reg. No: WC2430R, Claimant: LOH KHOON HOCK | | Load HTM | |
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | Print |
| 1 | 22/01/19 17:18 | **Accident Statement** | | Load HTM | |

| Photos/Images | | | 3 per page | | |
|---|---|---|---|---|---|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 2 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 3 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 4 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 5 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 6 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 7 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 8 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 9 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 10 | 30/01/19 10:15 | **General View** | | Load JPG | |
| 11 | 30/01/19 10:15 | **General View** | | Load JPG | |

| Documentation | | | 1 per page | | |
|---|---|---|---|---|---|
| No | Finalized On | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |
| 1 | 25/01/19 16:11 | **PRI-XD8115U** | | Load PDF | |
| 2 | 25/01/19 16:18 | **PRI NOA EMAIL** | | Load PDF | |
| 3 | 25/01/19 16:18 | **TP REJECT SJE APPT LKK AUTO CONSULTANT** | | Load PDF | |

# Linked Accident Report Documents

View: View in Browser

| Assessment Reports | | | 1 per page | | |
|---|---|---|---|---|---|
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | Print |
| 1 | 22/01/19 17:18 | **Accident Statement** | | Load HTM | |

| Photos/Images | | | 3 per page | | |
|---|---|---|---|---|---|
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | Print |
| 1 | 22/01/19 17:18 | **Accident Photo** | | Load JPG | |
| 2 | 22/01/19 17:18 | **Accident Photo** | | Load JPG | |
| 3 | 22/01/19 17:18 | **Accident Photo** | | Load JPG | |
| 4 | 22/01/19 17:18 | **Accident Photo** | | Load JPG | |
| 5 | 22/01/19 17:18 | **Driving License** | | Load JPG | |
| 6 | 22/01/19 17:18 | **Accident Photo** | | Load JPG | |

| Assessment Reports | | | 1 per page | | |
|---|---|---|---|---|---|
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | Print |

| Documentation | | | 1 per page | | |
|---|---|---|---|---|---|
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | Print |
| 1 | 22/01/19 17:17 | Sketch Plan | | Load TIF | |
| 2 | 22/01/19 17:18 | IC,DL,CI | | Load TIF | |

## Documents Checklist

**DOCUMENTS CHECKLIST** Reset Save Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19001763/JCD3E2
**Date:** 14/02/2019

REFERENCE

| | | | | |
|---|---|---|---|---|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | B29088496MKF | |
| **Claimant Vehicle No :** | XD8115U | **Insured Vehicle No :** | WC2430R | |
| Date of Loss: | 18/01/2019 | Nature of Claim: | TP | Claim No: 583339 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|---|---|---|---|
| Reg No: | **XD8115U** | | |
| Make & Model: | MERCEDES-BENZ MB ACTROS, 11.9 3336K 6X4 3300 ABS (A) | Engine No: | 541972C0903564 |
| Reg. Date: | 09/01/2014 (Man. Year: 2013) | Chassis No: | WDB9321612L783119 |
| Colour: | White | Odometer: | 574667 km |
| Engine Capacity: | 11946 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S$): | **Market Value/New Car Price** | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|---|---|---|---|---|---|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|---|---|---|---|
| Front Tyre Size: | 315/80 R22.5 | Rear Tyre Size: | 315/80 R22.5 |
| Front Left Side: | Triangle 8 mm | Rear Left Side: | Triangle 8 mm |
| Front Right Side: | Triangle 8 mm | Rear Right Side: | Triangle 8 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|---|---|---|---|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| **Nett Amount (S$)** | **0.00** | **0.00** | **0.00** | |

INSPECTION

| | | | |
|---|---|---|---|
| Date of Assignment: | 28/01/2019 | | |
| Date Inspected: | 29/01/2019 | Inspected At: | Sw Motor Trading (HQ)<br>No.211 Kranji Road<br>Singapore 739461 |
| Estimated Period of Repair: | 3.0 days | | |

**Adjuster:** ONG HWEE JIE **Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF $2,500.00 -$3,000.00

# REPAIR DETAILS

## Reference

| | | |
|---|---|---|
| **Part Source:** | | (Last Synchronised: 14 Feb 2019) |
| **Parts:** | N/A | MERCEDES-BENZ MB ACTROS 11.9 3336K 6X4 3300 ABS (A) (Model not available in database) |
| **Labour:** | Repairer's | (Price-denominated Standard List) |
| **Print Code:** | (Unsubmitted, no print-code for XD8115U) | |
| **Validity:** | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| **Further Info:** | Items/values not in reference catalogue are prefixed with an asterisk *. | |

## Recommended Parts

**There are no new parts selected.**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

**There are no new miscellaneous items selected.**

## Recommended Labour

**There are no labour items selected.**

| Report was unsubmitted during this print-out. |
|---|

**< END OF ESTIMATES >**