

22/03/2002

ASS. REC. BY:

REF:

CS3 / ALH19001768 / Ucd302

Special Instruction:

Surveyor:

Munim

ASSIGNMENT (Office)

From (Person):

Chin Lee Yiny

of

ALH

Date/Time:

28/12/19 9:35am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 4334S

Insured:

SLR 8056A

at Workshop m/s

Bluwel

Tel:

of

Blk 1 Kaki Bukit Ave # #01-55

Policy No:

Claim No:

9491477791SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

04-11-2018

CA / REV / REP. / REV 24 HRS '2p'

H.O.D. Endorsement:

Date/Time:

28/12/19 10:29am

Person Contacted:

Sally

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SJS 4334S - X
	SLR 8056A - X
	Dismantle: 28/1/2019

1/11/13) wef

SS. REC. BY: Marcus

REF:

4161

ASSIGNMENT

om: Date:

estimated Cost:

D / TP / WS / TP RES / OD RES / EVA / INV / MV

o Inspect Vehicle No: SJS43345

t Workshop m/s 3rd

nsured:

olicy No.

laims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 78

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes- or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJS43345 Yr Regn: 1 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota Estima c.c 2362

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 128817 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ACR 50 7115009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 4/1/18 D.O.I. 28/1/19

Survey held at 010.45am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

LP

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No settlement. RTA 61207
	MV-75089
	PV-61207
	NV-13,793

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format: DAR

Lump Sum / I.B.I: (\$)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

180
10
190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR8056A AND SJS4334S ON 04/11/2018

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: Monday, 28 January, 2019 9:35:04 AM
Attachments:  tmp93D0.tif

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

M NEDUMARAN & COAdvocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Please reply to our Branch Office for this matterNedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)⇒ **Branch Office:** 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sgOur Reference : MN/IG/B1/1812795/st
Your Reference : SLR 8056ADate : 28th November 2018AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claims Department

BY FAX 6835-7416 ONLY

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 4/11/2018 INVOLVING VEHICLE NOS. SJS 4334S & SLR 8056A AT 85 BEDOK NORTH STREET 4 (CARPARK).

We are instructed by NG YONG CHAO (owner of motor vehicle no. SJS 4334S) and/or BLUWEL AUTOMOTIVE SERVICE PTE LTD (the motor workshop for SJS 4334S) to notify you of a road traffic accident on 4/11/2018 at about 1135 hours at 85 BEDOK NORTH ST 4 (CARPARK) involving our client's vehicle registration number [SJS 4334S] and [SLR 8056A] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


M NEDUMARAN & CO - (Branch Office)

Encl

c.c. 1) LCRF PTE LTD

(Vehicle : SLR 8056A)

- 2) NAME OF WORKSHOP :
Bluwel Automotive Service Pte Ltd
No. 1 Kaki Bukit Avenue 6
#01-55, Blk C Autobay @ Kaki Bukit
Singapore 417883

(Vehicle : SJS 4334S)

Telephone : 6745-2088
Facsimile : 6841-2088

(Attention : Ms Sally)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8779C
Vehicle Details	
Vehicle No.:	SJS4334S
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	2AZH948998
Chassis No.:	ACR507115009
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$38,411.00
Original Registration Date:	30 Jan 2013
First Registration Date:	30 Jan 2013
Transfer Count:	1
Actual ARF Paid:	\$38,411.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jan 2023
PARF Rebate Amount:	\$26,887.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jan 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$87,000.00
COE Rebate Amount:	\$34,320.00
Total Rebate Amount:	\$61,207.00

The information contained herein is correct as at 29 Jan 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

Das WeltAuto.

Used cars you can trust. Guaranteed.

**Post an Advertisement**

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6a

Driveaway \$2700 (inc + 1 Yr
Insurance & Adv) 2.88% p.a
Monthly \$568 By GV Finance
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by Date Posted

4 vehicles

estima

Advanced Search

Make Model Price Depreciation Reg Date Eng Cap Mileage V

Search Selection

estima

Any

Any

2013

Any

Any

**Toyota Estima 2.4A Aeras****\$81,188**

\$13,820 /yr

16-Aug-2013

2,362 cc

85,130 km

8 Seater Twin Moonroof Estima. Very Well Maintained By 1 Previous Owner. Flexible Bank And In House High Loan Available At Low Int...
Accident Free. STA/Vicom Evaluation Welcome. 6 Months Cert...

Imperium Car Motor Pte Ltd

Posted: 26-Jan-2019

Tags: 2013 Toyota Estima, 2013 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

**Toyota Estima 2.4A Aeras
Premium Moonroof****\$83,800**

\$14,070 /yr

06-May-2013

2,362 cc

57,000 km

\$47500 High ARF Value, 1 Owner, "One Year In House Warranty", Full Loan Available, Price Stated Above Is Actual Selling Price, Bank A
Loan Available, Purchase Comes With Official Warranty C...

Carway

Posted: 24-Jan-2019

Tags: 2013 Toyota Estima, 2013 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

**Toyota Estima 2.4A Aeras
Premium Moonroof****\$79,800**

\$13,790 /yr

28-Jun-2013

2,362 cc

70,231 km

7 Seaters, Accident-Free, Facelift Premium Model Highest Specs, Apple Carplay And Andriod Auto, Electric Seat And Electric Tailgate, Ele
Pearl White, Most Luxurious MPV In The Market, Hig...

Posted: 09-Jan-2019

Tags: 2013 Toyota Estima, 2013 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

**Toyota Estima 2.4A Aeras
Premium Moonroof****\$83,800**

\$13,660 /yr

11-Oct-2013

2,362 cc

91,000 km

Elegant And Sporty Pearl White! Twin Roof Edition! Very Well Maintained By Meticulous Owner! Very High Paper Value! Zero Modificatio
Electric Tail Gate System. Buy With A Peace Of Mind. Ca...

Posted: 08-Jan-2019

Tags: 2013 Toyota Estima, 2013 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage V

For old advertisements view Archived ads

Compare

12/11/2018 MON 16:10 FAX

001/006

MSME16146337 / SME Motor Pte Ltd - Koki Bunk
 ENTRY DATE & TIME: 12/11/2018 16:51
 SUBMITTED BY: Chio Pui Ying

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 12/11/2018 16:32

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 12/11/2018 15:51
 Date Of Accident 04/11/2018 11:35
 Exact Location Of Accident 85 BEDOK NORTH ST 4 (CARPARK)
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJS4334S
 Insured/Policyholder
 Name Of Registered Owner NG YONG CHAO
 NRIC No S7838779C
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-96444334
 Alternative Phone No OFFICE-96444334

Vehicle Particulars

Manufacturer TOYOTA
 Model ESTIMA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number GA079600

Cover Note Number

Driver

Name of Driver NG YONG CHAO
 NRIC No S7838779C
 Date Of Birth 19/12/1978
 Occupation INDOOR
 Date Of Driving Pass 24/11/2001
 Driving Experience 16 YEARS AND 11 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96444334
 Fax Number
 Contact Number OFFICE-96444334
 Email Address NOEMAIL

12/11 2018 MON 16:18 FAX

002/006

Address 770 BEDOK RESERVOIR ROAD #08-06
 Postcode 479250
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1

NAME: : LEE CHAI GEOK
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 04/11/2018 AT ABOUT 11.35AM, I WAS WAITING FOR A CARPARK LOT. MY CAR WAS STATIONARY. CAR B WHICH WAS PARKED IN A LOT ON MY LEFT MADE A REVERSE. I HONKED AT THE DRIVER BUT HE CONTINUE TO REVERSE AND HIT THE FRONT LEFT SIDE OF MY CAR A. I FILE THIS REPORT LATE BECAUSE I WAS NOT IN SINGAPORE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLR8056A
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver CHEW PIK KEONG
 NRIC/Passport Number S1840176B
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

28-01-19;10:57 ;

MARCUS

:68412088

3 5

12/11 2018 MON 16:19 FAX

003/006

No. Of Passenger (Including Driver)

12/11 2018 MON 16:19 FAX

004/006

Sketch Plan Pg. 1


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renewate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims; (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/con be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 12/11/18



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 12/11/18


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

12/11/2018 MON 16:19 FAX

005/006

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Lots

On 04/11/18 at about 11:35am, I was waiting for a carpark lot. My car was stationary. Car B which was parked in a lot on my left making a reverse. I honked at the driver but he continue to reverse and hit the front-left side of my car A. I file this report late because I was not in Singapore.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 12/11/18

GAPAC Sketch Plan Form_V2

Driver's Signature

(If driver is not the policyholder)

Date & Time: 12/11/18

Reporting Contra Personnel's Signature

Name:

NRIC/FIN No.:

2

THE STATE OF TEXAS, County of _____

MAC	INC	Item	Unit	Act	Tr
1071	992705	Pulse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992683	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992214	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990723	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991834	Frt RH Mudflap			
1111	992037	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992112	Frt Windscreen Rubber			
1116	992103	Frt Windscreen Moulding			
1117	992093	Frt Windscreen Sealant			
1118	991019	FRP Bucket			
1119	991020	FRP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Cutch			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	991382	Glove Box Cover			
1126	992231	Glove Box Compartment			
1127	994453	Steering Wheel Airbag			
1128	994455	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Fr. Driver Seat			
1133	991922	Frt PH Seat Belt Assy			
1134	991399	Frt Passenger Seat			
1135	991432	Frt LH Seat Belt Assy			
1136	990747	Fr. Pass. Seat			

front LH Bumper tow eye cover inner garnish CRU ✓

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Nov 2018 Edit Reg		28 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd , Co. Reg. No.: NA		
Main Claimant:	NG YONG CHAO , ID: S7838779C		
Vehicle Reg. No.:	SJS4334S	Date of Loss:	04/11/2018 11:00 - :59 [69 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9491477791SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLR8056A	Policy No. (Claimant):	
		Excess:	
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Grace-TA] Tianaigrace.Ng@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/02/2019]		
Claimant's Solicitor:	M NEDUMARAN & CO - Tel: 65098480		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (29/01/2019): Request To Upload TP GIA Report








































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS4334S (9491477791SG)
[SLR8056A]
TP
NG YONG CHAO
Nov 4 2018 11:00AM
[LCRF Pte Ltd]
Bluwel Automotive Service Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	28/01/19 17:33	Chassis Number														Load JPG	<input checked="" type="checkbox"/>	
2	28/01/19 17:33	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>	
3	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
4	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
5	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
6	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
7	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
8	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
9	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
10	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
11	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
12	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
13	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
14	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
15	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
16	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
17	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
18	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
19	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
20	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
21	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
22	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
23	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
24	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
25	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
26	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
27	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
28	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
29	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
30	28/01/19 17:33	General View														Load JPG	<input checked="" type="checkbox"/>	
31	28/01/19 17:34	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
32	28/01/19 17:34	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
33	28/01/19 17:34	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
34	28/01/19 17:34	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
35	28/01/19 17:34	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
36	28/01/19 17:34	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	
37	28/01/19 17:34	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	28/01/19 17:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	01/02/19 08:22	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/01/19 11:08	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001768/UCD3E2

Date: 11/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJS4334S

Insured Vehicle No : SLR8056A

Date of Loss: 04/11/2018

Nature of Claim: TP

Claim No: 9491477791SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS4334S

Make & Model: TOYOTA ESTIMA, 2.4 (A)

Engine No: 2AZH948998

Reg. Date: 30/01/2013 (Man. Year: 2012)

Chassis No: ACR507115009

Colour: White

Odometer: 128817 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/01/2019

Date Inspected: 28/01/2019 Inspected At:

Bluwel Automotive Service Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*FRT BUMPER SPONGE	Broken	0.00 F	*- F
5	1		*FRT BUMPER GRILLE LOWER	Broken	0.00 F	*- F
6	1		*FRT BUMPER MOULDING LOWER	Broken	0.00 F	*- F
7	1		*FRT BUMPER SENSOR	Broken	0.00 F	*- F
8	1		*FRT GRILLE	Broken	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
11	1		*FRONT LH BUMPER TOW EYE COVER INNER GARNISH	Crumpled	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >