

REF: ASM (AXA)

ASSIGNMENT

From

Date: 01022019

Estimated Cost:

OD / TF / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKR 9029J

at Workshop m/s

Premium

of

55 Ubi Rd 1

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

1030um

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

SKR9029J.

Yr Regn:

2015 March.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan.

C.C 1395

Colour:

Bronze

A/C:

Insured / Std / NI / NA

Sp. Reading

88599.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU228V0F1094530

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / Run / STD A/Rim or

Tyre Size:

F:

225/45R17.

R:

225/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

01/02/19

Survey held at

Premium.

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AXA

MV : 70K

RV : 48.9K

Nett: 21.1K

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$