

VERSION

INS. CASE OWNER

JACUN

CC 3 /AIG1900

1827 E 1/23/9

LKK

IDAC

Surveyor:

STEVE

DOI:

ASSIGNMENT
20/06/19

Date / Time:

28/11/19

Registered in Merimen:

28/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

847792A

Name of Insured:

PAESAL BIN AHMAD SAID BIN TALIB

Insured Tel No.:

HP:

24/1/19

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

8177777 679756

Policy No.:

20051016-01

Make / Model:

MAZDA

Place of Accident:

JINC 4 SIGLAW RD K
BAST COAST RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

STN 27110



INSRS:
WSP:
Tel:
Liability:
RMKS:

performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

JN 27110-X

4777777-X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI: 20/06/19-301

After call Itr to OI: 20/06/19- UIC

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

ETA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

20/06/19 @ 11:20AM

- JN 27110-X TO OI. INFORMED ABOUT TP CLAIM IN NCD 100000.

20/06/19

- SEND 1ST OFFER TO TP.

27/06/19

- TP ACCEPTED OFFER.
- ALL BOCS IN ORDER.
- TO CLOSE

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PIP

SS 2,710.85

3 days

Reduction:

17 %

Email

Call

FINAL SETTLEMENT

Date/Time:

27/06/19

Confirm with

AROUNE

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost: (w/ GTC)

SS

2,900.61

COI - REPAIR-BUDED TP

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

180.00

60 x 3

days)

Loss of Income (LOI):

SS

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/TA Search

SS

2.00

Medical:

SS

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

-

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

-

3) Survey fee:

\$320.00

Total:

SS

3,082.61

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

2,902.61

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

SS

180.00

Name 2:

LAW SEOW KHIM

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

COPY SENT

AIG

20/2/19

Inthiran.

Date / Time	Action / Instruction
-------------	----------------------

The U/C / Chassis frame / Body Structure affected due to collision

10%	10%	

XX

30-5-19

\$ 2,710.85
CASH: \$ 555.80 (17%)

1994 1995 1996 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006 2007 2008 2009 2010 2011 2012 2013 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050 2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062 2063 2064 2065 2066 2067 2068 2069 2070 2071 2072 2073 2074 2075 2076 2077 2078 2079 2080 2081 2082 2083 2084 2085 2086 2087 2088 2089 2090 2091 2092 2093 2094 2095 2096 2097 2098 2099 2100 2101 2102 2103 2104 2105 2106 2107 2108 2109 2110 2111 2112 2113 2114 2115 2116 2117 2118 2119 2120 2121 2122 2123 2124 2125 2126 2127 2128 2129 2130 2131 2132 2133 2134 2135 2136 2137 2138 2139 2140 2141 2142 2143 2144 2145 2146 2147 2148 2149 2150 2151 2152 2153 2154 2155 2156 2157 2158 2159 2160 2161 2162 2163 2164 2165 2166 2167 2168 2169 2170 2171 2172 2173 2174 2175 2176 2177 2178 2179 2180 2181 2182 2183 2184 2185 2186 2187 2188 2189 2190 2191 2192 2193 2194 2195 2196 2197 2198 2199 2200 2201 2202 2203 2204 2205 2206 2207 2208 2209 2210 2211 2212 2213 2214 2215 2216 2217 2218 2219 2220 2221 2222 2223 2224 2225 2226 2227 2228 2229 2230 2231 2232 2233 2234 2235 2236 2237 2238 2239 2240 2241 2242 2243 2244 2245 2246 2247 2248 2249 2250 2251 2252 2253 2254 2255 2256 2257 2258 2259 2260 2261 2262 2263 2264 2265 2266 2267 2268 2269 2270 2271 2272 2273 2274 2275 2276 2277 2278 2279 2280 2281 2282 2283 2284 2285 2286 2287 2288 2289 2290 2291 2292 2293 2294 2295 2296 2297 2298 2299 2300 2301 2302 2303 2304 2305 2306 2307 2308 2309 2310 2311 2312 2313 2314 2315 2316 2317 2318 2319 2320 2321 2322 2323 2324 2325 2326 2327 2328 2329 2330 2331 2332 2333 2334 2335 2336 2337 2338 2339 2340 2341 2342 2343 2344 2345 2346 2347 2348 2349 2350 2351 2352 2353 2354 2355 2356 2357 2358 2359 2360 2361 2362 2363 2364 2365 2366 2367 2368 2369 2370 2371 2372 2373 2374 2375 2376 2377 2378 2379 2380 2381 2382 2383 2384 2385 2386 2387 2388 2389 2390 2391 2392 2393 2394 2395 2396 2397 2398 2399 2400 2401 2402 2403 2404 2405 2406 2407 2408 2409 2410 2411 2412 2413 2414 2415 2416 2417 2418 2419 2420 2421 2422 2423 2424 2425 2426 2427 2428 2429 2430 2431 2432 2433 2434 2435 2436 2437 2438 2439 2440 2441 2442 2443 2444 2445 2446 2447 2448 2449 2450 2451 2452 2453 2454 2455 2456 2457 2458 2459 2460 2461 2462 2463 2464 2465 2466 2467 2468 2469 2470 2471 2472 2473 2474 2475 2476 2477 2478 2479 2480 2481 2482 2483 2484 2485 2486 2487 2488 2489 2490 2491 2492 2493 2494 2495 2496 2497 2498 2499 2500 2501 2502 2503 2504 2505 2506 2507 2508 2509 2510 2511 2512 2513 2514 2515 2516 2517 2518 2519 2520 2521 2522 2523 2524 2525 2526 2527 2528 2529 2530 2531 2532 2533 2534 2535 2536 2537 2538 2539 2540 2541 2542 2543 2544 2545 2546 2547 2548 2549 2550 2551 2552 2553 2554 2555 2556 2557 2558 2559 2560 2561 2562 2563 2564 2565 2566 2567 2568 2569 2570 2571 2572 2573 2574 2575 2576 2577 2578 2579 2580 2581 2582 2583 2584 2585 2586 2587 2588 2589 2590 2591 2592 2593 2594 2595 2596 2597 2598 2599 2600 2601 2602 2603 2604 2605 2606 2607 2608 2609 2610 2611 2612 2613 2614 2615 2616 2617 2618 2619 2620 2621 2622 2623 2624 2625 2626 2627 2628 2629 2630 2631 2632 2633 2634 2635 2636 2637 2638 2639 2640 2641 2642 2643 2644 2645 2646 2647 2648 2649 2650 2651 2652 2653 2654 2655 2656 2657 2658 2659 2660 2661 2662 2663 2664 2665 2666 2667 2668 2669 2670 2671 2672 2673 2674 2675 2676 2677 2678 2679 2680 2681 2682 2683 2684 2685 2686 2687 2688 2689 2690 2691 2692 2693 2694 2695 2696 2697 2698 2699 2700 2701 2702 2703 2704 2705 2706 2707 2708 2709 2710 2711 2712 2713 2714 2715 2716 2717 2718 2719 2720 2721 2722 2723 2724 2725 2726 2727 2728 2729 2730 2731 2732 2733 2734 2735 2736 2737 2738 2739 2740 2741 2742 2743 2744 2745 2746 2747 2748 2749 2750 2751 2752 2753 2754 2755 2756 2757 2758 2759 2760 2761 2762 2763 2764 2765 2766 2767 2768 2769 2770 2771 2772 2773 2774 2775 2776 2777 2778 2779 2780 2781 2782 2783 2784 2785 2786 2787 2788 2789 2790 2791 2792 2793 2794 2795 2796 2797 2798 2799 2800 2801 2802 2803 2804 2805 2806 2807 2808 2809 2810 2811 2812 2

Camp Sum / LDF / 25

--	--




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/AIG19001827/jb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 28-01-2019	
			Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 7792A	Veh. Inspected	SJN 2211C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/01/2019	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190988 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

28 JAN 2019

ESTIMATE

Estimate No. : b1 49894
Date Estimated : 24/01/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Law Seow Khim
2 Everton Road

Singapore 089359

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJN2211C	ED04985	31/12/2018	216i GT	0

DESCRIPTION

To repair rear bumper and replace lower trim.

VALUE

850 / 1,275.00

Paint rear bumper panel

934.20 / 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 / 177.00

Sundries.

/ 40.00

Total Labour 1: 2,530.00

DESCRIPTION

Cover, bumper /

(UT (C/W (C/W))

QTY	PRIC	VALUE
1	736.65	736.65

736.65

Total Parts : 736.65

LOOK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after repair painting

- To display damaged part(s) during survey

- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed

- Supplementary item(s) must be surveyed and

- is subject to final approval from

Acknowledged by Repairer

Signature:

Grand Total

3,495.32

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

3,266.65

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	8061C
Vehicle Details	
Vehicle No.:	SJN2211C
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	216I GRAN TOURER MSPT NAV
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	31545303B38A15A
Chassis No.:	WBA6V12080ED04985
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$33,712.00
Original Registration Date:	31 Dec 2018
First Registration Date:	31 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$39,197.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2028
PARF Rebate Amount:	\$29,397.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$30,851.00
COE Rebate Amount:	\$23,238.00
Total Rebate Amount:	\$52,635.00

The information contained herein is correct as at 20 Feb 2019

OK

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-014481

Date of Request: 25/01/2019

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 25/01/2019
Enquiry By Melanie Setiawati
TP Vehicle No. SLP7792A
Accident Date 24/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLP7792A	AIG Asia Pacific Insurance Pte. Ltd.	16/06/2018-15/06/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SJN2211C	Model:	
Date of Accident:	24/01/2019		

Global Sum Settlement:	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	
Repair Estimate	:	\$	3,495.32		
Final Repair Cost	:	\$	2,900.61		
Loss of Use	:	\$	240.00		3 days at \$ 80.00 per day
Rental (if any)	:	\$	--		days
LTA / GIA Search Fee	:	\$	2.00		
Others	:	\$	--		
	:	\$	--		
Final Settlement Sum	:	\$	3,142.61		
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)					
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)					
B) For GIA Registered Workshop: BOLA Application: Yes / No					
BOLA Scenario No: _____					
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)					
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	2,900.61
2)	Performance Motor Limited	: \$	2.00
3)	Law Seow Khim	: \$	240.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
**Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
 Survey Report; Medical Report / Bill (if any)**



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

26 JUNE 2019

**FAESAL BIN AHMAD SAID BIN TALIB
626 EAST COAST ROAD
SINGAPORE 459012**

Dear Sir/Madam,

OUR REF : CC3/AIG19001827/Ehb3

YOUR REF : SLP 7792A

**ACCIDENT INVOLVING SLP 7792A AND SJN 2211C ALONG SIGLAP ROAD ON
24.01.2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SJN 2211C against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SJN 2211C. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@ikkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Law Seow Khim ("the third party claimant")
of 7 Lealon Heights #18-18 S(267953) (address),
owner of SJN 2211C (vehicle no.) hereby authorize
Performance Motors Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJN 2211C that was
damaged pursuant to the accident which occurred on 24/1/19 (date) along
Siglap Road (location)
involving vehicle no/s SLP7792A ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 20 day of Feb (month) 20 19 (year)

Signed by "the third party claimant"

Signed by "the workshop"

PERFORMANCE MOTORS LIMITED
303 Resource Road
Sme Darby Performance Centre
Singapore 159941
Tel: 6310 0700 (Sales)
6216 2111 (AfterSales)



RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 2,940.61 (repair costs), S\$ 100.00 (loss of use/~~rental~~) S\$ 2.00 (search fees) for vehicle no. SJN 2211C that was damaged pursuant to the accident which occurred on 24/1/19 (date) along Skytap Road (location) involving vehicle no/s SLP 7792A.

This is pursuant to the inspection conducted on 20 Feb 19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Low Seow Khim ("third party claimant") of vehicle no. SJN 2211C to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJN 2211C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 day of 06 (month) 20 19 (year)



CM

Signed by AIG appointed surveyor

Chopped & Signed by "the workshop"
PERFORMANCE MOTORS LIMITED
303 Aljunied Road
The Carby Performance Centre
Singapore 159941
TEL: 63190100 (Sales)
63190111 (AfterSales)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63390100 (Sales & Admin)
63390111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63390888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63390528 (AfterSales)
63390533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1339095	Page No. : 1 of 2
Date IN : 20/02/2019	Invoice Number : 2105589 / WSB
Motor Claim Advisor: Inthiran A/L Thurasamy	Invoice Date : 31/05/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Ms Law Seow Khim
2 Everton Road

Singapore 089359

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO. SJN2211C	CHASSIS NO. ED04985	REGN. DATE 31/12/2018	MODEL 216I GT	MILEAGE 2684
-----------------------	------------------------	--------------------------	------------------	-----------------

- - - - LABOUR 1 - - - -

	NETT
To replace rear bumper cover including make good the rear bumper panel and knock out dented area caused by the accident.	850.00
To respray rear bumper.	934.20
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
Sundries.	40.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 24.01.2019. 3RD PARTY CAR : SLP7792A.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK AUTO ON 20.02.2019. AUTHORISED REPAIR BY MS JOY IRENE FROM LKK AUTO ON 30.01.2019 VIA EMAIL.	
PROPOSE LOSS OF USE = \$80x3. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00

Total Labour 1: **1,974.20**

- - - - PARTS - - - -

	Qty	Retail Price	NETT
REAR BUMPER COVER (M)	1	736.65	736.65
Total Parts :			736.65

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197481559W GST Reg. No M2-0220841-s



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 61190100 (Sales & Admin)
61190111 (AfterSales)
Fax. 64747770

288, Kampong Arang Road
East Coast Centre
Singapore 418180
Tel. 61190688 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 61190838 (AfterSales)
61190833/310 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1339095	Page No. : 2 of 2
Date IN : 20/02/2019	Invoice Number : 2105589 / WSB
Motor Claim Advisor: Inthiran A/L Thurasamy	Invoice Date : 31/05/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

Labour Charges : 1,934.20	Total Labour & Parts Charges : S\$ 2,710.85
Parts Charges : 736.65	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 40.00	Invoice Total Amount Exclude GST : S\$ 2,710.85
	GST @ 7% : S\$ 189.76
	Invoice Total Amount Include GST : S\$ 2,900.61

Computer generated invoice. No signature is required.	Amount Payable Include GST : S\$ 2,900.61
---	--

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-014481
Date of Request: 25/01/2019

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 25/01/2019
Enquiry By: Melanie Setiawati
TP Vehicle No.: SLP7792A
Accident Date: 24/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLP7792A	AIG Asia Pacific Insurance Pte. Ltd.	16/06/2018-15/06/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-014481

Date of Request: 25/01/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 25/01/2019
Enquiry By Melanie Setiawati
TP Vehicle No. SLP7792A
Accident Date 24/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jan 2019 Edit Reg		20 Feb 2019 00:00 Edit Adj Rpt	S\$2,710.85 Edit Estimates	S\$2,710.85 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Faenal Bin Ahmad Said Bin Talib , ID: S74397622									
Main Claimant: LAW SEOW KHIM , ID: S1808061C									
Vehicle Reg. No.: SJN2211C		Date of Loss: 24/01/2019 07:00 - :59 [24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 8133236797SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SLP7792A		Policy No. (Claimant):							
		Excess:							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 08/02/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN2211C (8133236797SG)
[SLP7792A]
TP
LAW SEOW KHIM
Jan 24 2019 7:00AM
[Faesal Bin Ahmad Said Bin Talib]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
															3 per page			<input checked="" type="checkbox"/>		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	20/02/19 17:57		General View															Load JPG		
2	20/02/19 17:57		General View															Load JPG		
3	20/02/19 17:57		General View															Load JPG		
4	20/02/19 17:57		General View															Load JPG		
5	20/02/19 17:58		General View															Load JPG		
6	20/02/19 17:58		General View															Load JPG		
7	20/02/19 17:58		General View															Load JPG		
8	20/02/19 17:58		General View															Load JPG		
9	20/02/19 17:58		General View															Load JPG		
10	20/02/19 17:58		General View															Load JPG		
11	20/02/19 17:58		General View															Load JPG		
12	20/02/19 17:58		General View															Load JPG		
13	20/02/19 17:58		General View															Load JPG		
14	20/02/19 17:58		General View															Load JPG		
15	20/02/19 17:58		General View															Load JPG		
16	20/02/19 17:58		General View															Load JPG		
17	20/02/19 17:58		Odometer Reading															Load JPG		
18	20/02/19 17:58		Chassis Number															Load JPG		
19	20/02/19 17:58		General View															Load JPG		
20	20/02/19 17:58		General View															Load JPG		
21	20/02/19 17:58		General View															Load JPG		
22	20/02/19 17:58		General View															Load JPG		
23	20/02/19 17:58		General View															Load JPG		
24	20/02/19 17:58		General View															Load JPG		
25	20/02/19 17:58		General View															Load JPG		
26	20/02/19 17:58		General View															Load JPG		
															1 per page			<input checked="" type="checkbox"/>		
Documentation															1 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	28/01/19 17:08		TP ESTIMATE															Load PDF		
2	28/01/19 17:08		TP GIA REPORT															Load PDF		
3	21/02/19 18:22		TP ESTIMATE- MARKED															Load PDF		
4	26/06/19 10:36		LETTER TO OI															Load PDF		
5	11/07/19 09:36		WORKSHOP INVOICE															Load PDF		
6	11/07/19 09:36		AUTHORISATION TO ACT FORM															Load PDF		

Letters/Correspondences				1 per page	✓	✓
No	Finalized On			Thumbnail	Print	
7	11/07/19 09:36	LKK Auto Consultants Pte Ltd (HQ)	Release Voucher	1	Load PDF	
8	11/07/19 09:36		GIA SEARCH	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	29/01/19 13:12	OI GIA REPORT		1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	^ v
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLP7792A (Insd veh)	Model:	BMW 216D 1.5 D GRAN
	SJN2211C (TP veh)		TOURER (A)
Date of Accident:	24/01/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	3,495.32
Final Repair Cost	:	\$	2,900.61
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,082.61

3.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
27

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 2,902.61
2)	Law Seow Khim	:	\$ 180.00
3)		:	\$

JOANNE LEE KHANG MIN

11 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19001827/EHB3Q2

Date: 11/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJN2211C

Insured Vehicle No : SLP7792A

Date of Loss: 24/01/2019

Nature of Claim: TP

Claim No: 8133236797SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN2211C

Make & Model: BMW 216D, 1.5 D Gran Tourer (A)

Engine No: 31545303B38A15A

Reg. Date: 31/12/2018 (Man. Year: 2018)

Chassis No: WBA6V12080ED04985

Colour: White

Odometer: 2684 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size: 205/55 R17

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	776.65	776.65	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.20	555.80	22.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,266.65	2,710.85	555.80	17.01
+ GST 7.00/7.00% (S\$)	228.67	189.76	38.91	17.02
Nett Amount (S\$)	3,495.32	2,900.61	594.71	17.01
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,082.61		

INSPECTION

Date of Assignment: 20/02/2019

Date Inspected: 20/02/2019 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
2	1		*COVER ,BUMPER	Cut	736.65 FS	*736.65 FS
Total Parts (\$\$)					776.65	776.65

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR AND REAR BUMPER AND REPLACE LOWER TRIM	New	1,275.00	850.00
2	PAINTING REAR BUMPER PANEL	New	1,038.00	934.20
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,490.00	1,934.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >