22/03/2002

ASS. REC BY: | REF: CS/SM019001831/Atd3 12 | Special Instruction:

Surveyor: Marmun

ASSIGNMENT (Office)

From (Person): Agnes Chan of SMD Date/Time: 28/1/2019 4.53pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 91B Insured: SKA 3414J

at Workshop m/s Hiap Hong Tel:

of 2 Kaki Bukit Ave 2 #02-13

Policy No: D18MTPV01003722 Claim No: CMTD1900612

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 27/01/2019

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 28/01/2019 5.10pm Person Contacted: Vehicle: IN / OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SKT 91B - NA / INC1900 1756 / T3 DA: 27/01/2019
	SKA 3414J - X
29/01-	Revert pending estimate.
	lump sum $2450/- (Red: 2969.70; 54%)

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

L/Bal. 00 mm L/Bal. 00 mm

D.O.A. D.O.I. 28/01/19.

Survey held at Hiap Hong.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Sompo.
	RECEIVED 27 FEB 2019
	MV :
	PV :
	Nett :

Date/Time, File Pass to?	Date/Time, File Return to?
1) 27/2 Typist	2)
3)	4)
5)	6)

Preli. Report:

Final Report:

Part Prices Check:

IN	OUT

Survey Fee:	Date:
Basic & Add.	250
__ S + RS, __ SI	10
Photos	
Others	
TOTAL	260

Relat Hosp Brian

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKT91B. Yr Regn: 2015, May.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mazda 3 c.c 1496

Colour Black. Blue A/C: Insured / Std / NI / NA

Sp.Reading 52405 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BM42A8G0309055

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16.

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	28/01/19.

Survey held at Hiap Hong.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Sempa.
	RECEIVED 27 FEB 2019
	MV :
	PV :
	Nett :

Date/Time, File Pass to?	Date/Time, File Return to?
1) 27/2 Typist	2)
3)	4)
5)	6)

Preli. Report:

Final Report:

Part Prices Check:

IN	OUT

Survey Fee:	Date:
Basic & Add.	250
__ S + RS, __ SI	10
Photos	
Others	
TOTAL	260