

ASS. REC. BY:

REF:

CS3 / ALG19001854 / Bcd5⁵²

Special Instruction:

Surveyor
Melman

Mr. Lim

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

29/1/19 @ 10:01am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 3311Z

Insured:

SME 841J

at Workshop m/s

Hup Jey Huat

Tel:

9677 2832

of

Blk1, Kaki Bukit Ave 6 #01-35

Policy No:

0999994322

Claim No:

936635707286

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:32am @ 29/1/19

Person Contacted:

Mr. Tan

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLH 3311Z - X
	SME 841J - X
	Dismantle : 30/1/19

AIG

TOTAL

Your password will expire in 14 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 29/1/2019 10:01:02 AM
Attachments:  90089.PRS.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

Sent: Monday, January 28, 2019 3:03 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Hor, Yinrul; Kaur, Baljit

Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SME841J AND SLH3311Z ON 25/01/2019

Dear Sirs,

We refer to the above matter and to your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your said email.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- 1) Fong Kok Heng
- 2) Danny Yap
- 3) Willy Goh
- 4) Francis Ng
- 5) Dennis Yap
- 6) Louis Ng
- 7) Michael Yap
- 8) LimYong Tian

- 9) Patrick Ng
- 10) Philip Foo

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey of our client's vehicle SLG 3311 Z at our client's repairer workshop as follows :-

Hup Ley Huat Motor Spray Painting Services
Blk 1 Kaki Bukit Avenue 6 #01-35
Singapore 417883

Person to contact : Mr Tan Boon Seng (contact no. 96773832)

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

Our Ref: LCH.ct/2KB02-90089.19

25.01.19

BY FAX NO. 68357416 AND BY HAND
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

BY CERTIFICATE OF POSTING
Bis Motoring Pte Ltd
20 Bendemeer Road #03-13/14
Singapore 339914

BY CERTIFICATE OF POSTING

Dear Sirs

We are instructed by Dave Lim Chong Kok to notify you of a road traffic accident on 25.01.19 at about 7:30 am at Blk 750 Pasir Ris Street 71 involving our client's vehicle registration number SLH 3311 Z and vehicle registration number SME 841 J driven by your insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encls:

This is a computer-generated document and requires no signature

cc: client (via e-mail/fax only) - SLH 3311 Z

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/01/2019 09:58
 Date Of Accident 25/01/2019 07:30
 Exact Location Of Accident BLK750 PASIR RIS ST71
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH3311Z
Insured/Policyholder
 Name Of Registered Owner DAVE LIM CHONG KOK
 NRIC No S1347655A
 Email Address 13TOPE@GMAIL.COM
 Mobile Phone No (LOCAL) +65-93833311
 Alternative Phone No OFFICE-93833311

Vehicle Particulars

Manufacturer TOYOTA
 Model HARRIER
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number P10021533R01
 Cover Note Number

Driver

Name of Driver DAVE LIM CHONG KOK
 NRIC No S1347655A
 Date Of Birth 28/06/1959
 Occupation INDOOR
 Date Of Driving Pass 19/09/1978
 Driving Experience 40 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93833311
 Fax Number
 Contact Number OFFICE-93833311
 EMail Address 13TOPE@GMAIL.COM

Address	BLK751 PASIR RIS ST71 #12-74
Postcode	510751
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YATI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG THE WAY, SUDDENLY VEHICLE B DROVE OUT FROM THE LOADING AND UNLOADING LOT AND HIT ONTO MY LEFT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME841J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA):

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along the way, suddenly vehicle B drove out from the loading and unloading lot and hit onto my left portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7655A

Vehicle Details

Vehicle No.: SLH3311Z
Vehicle to be Exported: No
Intended Deregistration Date: 08 Apr 2019
Vehicle Make: TOYOTA
Vehicle Model: HARRIER ELEGANCE 2.0 A
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: 3ZRB837006
Chassis No.: ZSU600084355
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$30,575.00
Original Registration Date: 07 Oct 2016
First Registration Date: 07 Oct 2016
Transfer Count: 0
Actual ARF Paid: \$29,805.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 06 Oct 2026
PARF Rebate Amount: \$22,353.00

Intended COE Rebate Details

COE Expiry Date: 06 Oct 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$53,001.00
COE Rebate Amount: \$39,718.00
Total Rebate Amount: \$62,071.00

The information contained herein is correct as at 08 Apr 2019

OK

MV 93,000 / =
PV 62,071 / =
NV 30,929 / 2

[Signature]
8/4/19

**Panoramic**

Lowest Mileage. Almost New, 1 Owner Only. Very Well Maintained Highest ARFI Original Elegant Pearl White Paintwork With Highest Spec, Full Panoramic Roof, Black Quilted Leather Interior. Accident Free...

Car Empire Automobiles Pte Ltd

Posted: 12-Mar-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

PREMIUM JD

**Toyota Harrier 2.0A Premium Panoramic**

-

N.A

20-Oct-2016

1,986 cc

-

SUV

SOLD

High ARF \$47,800. Low Depreciation. Low Mileage. 17,000 Km. One Owner. Reverse Camera. Panoramic Roof. V Cool. Full Service Records Accident Free.

Posted: 15-Feb-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Elegance**

\$92,800

\$10,440 /yr

04-Oct-2016

1,986 cc

-

SUV

Available

Excellent, Good Condition, Well Kept, Selling Because Upgrading, Beautiful Black Pearl Model, Loan Available, Welcome Viewing And Enquiry.

Posted: 21-Mar-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

CONSIGNMENT

**Toyota Harrier 2.0A Elegance**

-

N.A

29-Sep-2016

1,986 cc

-

SUV

SOLD

1 Owner, New Arrival, Nice Bitted Number, 6 Months Workshop Warranty. Very Nice Maintained Just Like New Car, 100% Accident-Free, Trade In Welcomed, Bank/High In House Finance Available, Call Or Drop B...

Posted: 08-Mar-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

PREMIUM JD

**Don't be fooled by these car insurance myths!**

Is it true that my NCD will still be affected even if the accident is not my fault?
Let's find out what is true and false about car insurance in Singapore.

Find out more!

**Toyota Harrier 2.0A Elegance**

-

N.A

29-Sep-2016

1,986 cc

-

SUV

SOLD

Accident Free, Original Paintwork, Very Well Kept! Must View. Bank And In House Financing Available. Call For Viewing/Test Drive Today.

Posted: 28-Feb-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Elegance**

\$96,000

\$10,950 /yr

29-Sep-2016

1,986 cc

24,200 km

SUV

Available

Excellent, Like New Condition, Accident-Free And Low Mileage. Selling Due Upgrading. Beautiful Black Pearl Model, Parked Under Cover. Whatsapp/Email To Make Offer Or Arrange Viewing, No Consignment Ag...

Posted: 07-Feb-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

GREAT OWNER

**Toyota Harrier 2.0A Premium Panoramic**

\$95,998

\$10,810 /yr

20-Sep-2016

1,986 cc

50,000 km

SUV

Available

Be Our Next Happy Client To Owned This Quality Pre-Owned Vehicle At Most Reasonable And Affordable Price! Very Well Kept Interior And Exterior! Owner Upgrading. Family 5th Car. Low Fuel Consumption! F...

Posted: 06-Apr-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Elegance**

-

N.A

16-Sep-2016

1,986 cc

-

SUV

SOLD

High Loan Available With High Approval Rate. Balloon Scheme Available. All Vehicles Are Inspected By Our Professional Team For Highest Quality. Extended Warranty Available. Call To Arrange For Viewing...

Posted: 18-Feb-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Elegance Panoramic**

-

N.A

16-Sep-2016

1,986 cc

-

SUV

SOLD

Up To 95% Loan Package Available. High Approval Rate. Balloon Scheme To Lessen Your Monthly Installment Burden. All Vehicles Are Inspected By Our Professional Team For Highest Quality. Extended Warranty...

Avant Automobile Pte Ltd

Posted: 07-Feb-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Premium**

-

N.A

13-Sep-2016

1,986 cc

-

SUV

SOLD

Unbelievable Flexible In House Loan, One Year Warranty Provided. Full Modellista Bodykit. 160 Points Check Done. One Owner. Massive Savings From Brand New Unit! No Repair Needed. Original Paint Work S...

Inchcape Pre-Owned

Posted: 01-Feb-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

PREMIUM JD

**Toyota Harrier 2.0A Premium Panoramic**

-

N.A

08-Sep-2016

1,986 cc

-

SUV

SOLD

Elegant Brown SUV, With Panoramic Sunroof And Navigation System, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan Packages Available.

Posted: 04-Mar-2019

Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

MOTOR CAR (LH)**Left Portion**

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	BT	✓	
1256	995140	Frt LH Door Protector	BT	✓	
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding	NEC	✓	
1261	991588	Frt LH Door Glass Inner Moulding	NEC	✓	
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator	BT	✓	
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber	BT	✓	
1266	991636	Frt LH Door Outer Handle	BT	✓	
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key	BT	✓	
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Vehicle No: SLH 3311Z

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door	BT	✓	
1290	993282	Rear LH Door Protector	BT	✓	
1291	995194	Rear LH Door Hinge	BT	✓	
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding	NEC	✓	
1294	993231	Rear LH Door Glass Inner Moulding	NEC	✓	
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator	BT	✓	
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber	BT	✓	
1299	993275	Rear LH Door Outer Handle	BT	✓	
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock	BT	✓	
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

No of Items: 15Assessor: Torin

8/4/09

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2019 Edit Reg		29 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BIS MOTORING PTE LTD , Co. Reg. No.: 201735055D		
Main Claimant:	DAVE LIM CHONG KOK , ID: S1347655A		
Vehicle Reg. No.:	SLH3311Z	Date of Loss:	25/01/2019 07:00 - :59 [27 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9366357072SG	Policy/Cover Note No.:	0999994322 (Comprehensive)
Vehicle Reg. No. (Insured):	SME841J	Policy No. (Claimant):	
		Excess:	
Repairer:	Hup Ley Huat Motor Spray Painting Services () BLK 1 KAKI BUKIT AVE 6 #01-35, 409793 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 11/02/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (30/01/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLH3311Z (9366357072SG)
[SME841J]**




































TP











































DAVE LIM CHONG KOK

Jan 25 2019 7:00AM

[BIS MOTORING PTE LTD]

Hup Ley Huat Motor Spray Painting Services

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
2	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
3	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
4	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
5	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
6	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
14	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
15	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
16	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
17	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
18	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
19	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
20	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
21	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
22	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
23	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
24	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
25	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
26	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
27	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
28	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
29	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
30	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
31	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
32	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
33	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
34	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
48	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
49	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
50	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
51	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
52	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
53	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
54	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
55	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
56	08/04/19 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
57	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	08/04/19 16:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	08/04/19 16:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001854/BCD3S2

Date: 11/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994322

Claimant Vehicle No : SLH3311Z

Insured Vehicle No : SME841J

Date of Loss: 25/01/2019

Nature of Claim: TP

Claim No: 9366357072SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH3311Z

Make & Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 3ZRB837006

Reg. Date: 07/10/2016 (Man. Year: 2016)

Chassis No: ZSU600084355

Colour: Black

Odometer: 29539 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65R17

Rear Tyre Size: 225/65R17

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/01/2019

Date Inspected: 29/01/2019 Inspected At:

Hup Ley Huat Motor Spray Painting Services
BLK 1 KAKI BUKIT AVE 6 #01-35
Singapore 409793

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Dented	0.00 F	*- F
2	1		*FRT LH DOOR PROTECTOR	Dented	0.00 F	*- F
3	1		*FRT LH DOOR GLASS OUTER MOULDING	Necessary	0.00 F	*- F
4	1		*FRT LH DOOR GLASS INNER MOULDING	Necessary	0.00 F	*- F
5	1		*FRT LH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
6	1		*FRT LH DOOR RUBBER	Cut	0.00 F	*- F
7	1		*FRT LH DOOR OUTER HANDLE	Cut	0.00 F	*- F
8	1		*FRT LH DOOR LOCK W/KEY	Bent	0.00 F	*- F
9	1		*REAR LH DOOR	Dented	0.00 F	*- F
10	1		*REAR LH DOOR PROTECTOR	Dented	0.00 F	*- F
11	1		*REAR LH DOOR HINGE	Bent	0.00 F	*- F
12	1		*REAR LH DOOR GLASS OUTER MOULDING	Necessary	0.00 F	*- F
13	1		*REAR LH DOOR GLASS INNER MOULDING	Necessary	0.00 F	*- F
14	1		*REAR LH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
15	1		*REAR LH DOOR RUBBER	Cut	0.00 F	*- F
16	1		*REAR LH DOOR OUTER HANDLE	Cut	0.00 F	*- F
17	1		*REAR LH DOOR LOCK	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >