

ASS. REC. BY:

REF:

CS3/17419001855/Ucd362

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Mehman

Chin lee Ying

of

AIG

Date/Time:

29/1/19 @ 10:04am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 810X

Insured:

SMA 735D

at Workshop m/s

Bluwel Automotive

Tel:

G745 2088

of

No. 1, kaki Bulkit Ave 6 #01-55

Policy No:

1800056017

Claim No:

987280860586

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

26/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:28am @ 29/1/19

Person Contacted:

Sally

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SLC 810X - (33/CT18022015 / Ucd2
	SMA 735D - x
	Dismantle: 29/1/2019
	After repair: 30/1/2019

DA: 03/22018

11/13) wof

REF:

S. REC. BY: Morfas

ASSIGNMENT

om: _____ Date: _____

Estimated Cost: _____

D / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No: SLC 810X

Workshop m/s am

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

0015H
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC 810X Yr Regn: 5, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: KIA Cerato K3 c.c. 1591

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 21035 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAFJ41MJS765102

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or next

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 26/1/19

Survey held at _____

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 29/1/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>No. set up. KIA 44327</u>

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format : DAR

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: 180

Transportation: _____

S + RS, SI

Photos


Others 10

TOTAL

190

Your password will expire in 14 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 29/1/2019 10:04:54 AM
Attachments:  [tmp741A.TIF](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

M NEDUMARAN & COAdvocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Please reply to our Branch Office for this matterNedumaran Muthukrishnan
LLB (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)⇒ **Branch Office:** 11 Sin Ming Road
#B2-09 (Unit 2) Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : igene.lim@mneduco.com.sg
serene.tan@mneduco.com.sgOur Reference : MN/IG/B1/1912891/st
Your Reference : SMA 735DDate : 28th January 2019AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claims Department

BY FAX 6835-7416 ONLY

Dear Sirs,

1. NOTICE OF ACCIDENT TO INSURERS AND PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)
2. ACCIDENT ON 26/1/2019 INVOLVING VEHICLE NOS. SLC 810X & SMA 735D ALONG SENGKANG EAST WAY EXIT TPE.

We are instructed by HONG JIAWEI (owner of motor vehicle no. SLC 810X) and/or BLUWEL AUTOMOTIVE SERVICE PTE LTD (the motor workshop for SLC 810X) to notify you of a road traffic accident on 26/1/2019 at about 0830 hours along SENGKANG EAST WAY EXIT TPE involving our client's vehicle registration number [SLC 810X] and [SMA 735D] driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you with the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

M NEDUMARAN & CO

Nedumaran Muthukrishnan - (Branch Office)

Encl

c.c. 1) PHEE PING HO

(Vehicle : SMA 735D)

- 2) NAME OF WORKSHOP :
Bluwel Automotive Service Pte Ltd
No. 1 Kaki Bukit Avenue 6
#01-55, Blk C Autobay @ Kaki Bukit
Singapore 417883

(Vehicle : SLC 810X)

Telephone : 6745-2088
Facsimile : 6841-2088

(Attention : Ms Sally)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	0015H

Vehicle Details

Vehicle No.:	SLC810X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jan 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	G4FGJH695444
Chassis No.:	KNAFJ411MJ5765102
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$11,400.00
Original Registration Date:	16 May 2018
First Registration Date:	16 May 2018
Transfer Count:	0
Actual ARF Paid:	\$11,400.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 May 2028
PARF Rebate Amount:	\$8,550.00

Intended COE Rebate Details

COE Expiry Date:	15 May 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,510.00
COE Rebate Amount:	\$35,777.00
Total Rebate Amount:	\$44,327.00

The information contained herein is correct as at 30 Jan 2019

OK

28/01/2019 MON 15:06 FAX

001/004

MSME19013148 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 28/01/2019 15:14
SUBMITTED BY: Chio Pui Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 28/01/2019 15:14
Date Of Accident 26/01/2019 08:30
Exact Location Of Accident SENGKANG EAST WAY EXIY TPE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLC810X
Insured/Policyholder
Name Of Registered Owner HONG JIAWEI
NRIC No S8810015H
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-98433995
Alternative Phone No OFFICE-98433995
Vehicle Particulars
Manufacturer KIA
Model FORTE K3
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 1800054804
Cover Note Number
Driver
Name of Driver HO WEI JIE
NRIC No S8822261Z
Date Of Birth 26/06/1988
Occupation INDOOR
Date Of Driving Pass 11/01/2008
Driving Experience 11 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91511688
Fax Number
Contact Number
Email Address NOEMAIL

28/01/2019 MON 15:06 FAX

002/004

Address BLK 298C COMPASSVALE STREET #16-88
 Postcode 543298
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured FRIEND
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 26/01/2019 AT ABOUT 8.30AM, I WAS WAITING TO EXIT SENGKANG EAST ROAD TO TPE WHEN SUDDENLY I FELT A HIT BEHIND MY CAR A. VEHICLE BEARING (SMA735D) HAS HIT THE REAR OF MY CAR A.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMA735D
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver PHEE PING HO
 NRIC/Passport Number S1486058I
 Contact Number 94774849
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (including Driver)

28/01/2019 MON 15:05 FAX

003/004

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 28/1/19, 12:00 am

Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/1/19, 11:30 am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

CLAIMS SKETCH PLAN - V3

Eduwan

28/01 2019 MON 15:07 PAX

004/004

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28/1/19 at about 830am, I was waiting to exit Sengkang East Road TO TPE when suddenly I felt a hit behind my car (A). Vehicle bearing no. SMA735D has hit the rear of my car (A)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28/1/19, 1130am

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/1/19, 1130am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SLC FLOW

Date

No.

	Rear bumper	DD/De
	Rear bumper lower	De
	Rear bumper reflector	ALS cracked
1 set	Rear bumper reverse sensor	shorted
	Rear bumper reinforcement	cracked
5 PCS	Rear bumper reinforcement retainers	Twisted
	Rear bumper bracket	Repair
	tail lamp	ALS cracked
	Rear end panel	Repair
	Boot lid	Repair
1 set	Rear bumper clips	OK

Ydr.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2019 Edit Reg		29 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	PHEE PING HO, ID: S14960581								
Main Claimant:	-								
Vehicle Reg. No.:	SLC810X	Date of Loss:	26/01/2019 15:00 - :59 [8 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9872808605SG	Policy/Cover Note No.:	1800056017 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMA735D	Policy No. (Claimant):							
		Excess:							
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 11/02/2019]								
Claimant's Solicitor:	M NEDUMARAN & CO - Tel: 65098480								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (30/01/2019): No OI GIA Report AIG_SG (30/01/2019): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLC810X (9872808605SG)
[SMA735D]**





































TP

Jan 26 2019 3:30PM

[PHEE PING HO]

Bluwel Automotive Service Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		▼
Photos/Images															3 per page		▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
2	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
3	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
4	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
5	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
6	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
7	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
8	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
9	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
10	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
11	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
12	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
13	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
14	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
15	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
16	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
17	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
18	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
19	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
20	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
21	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
22	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
23	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
24	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
25	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
26	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
27	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
28	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
29	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
30	23/02/19 11:21	General View														Load JPG	<input checked="" type="checkbox"/>		
31	23/02/19 11:22	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
32	23/02/19 11:22	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
33	23/02/19 11:22	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
34	23/02/19 11:22	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
35	23/02/19 11:22	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
36	23/02/19 11:22	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
37	23/02/19 11:22	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	23/02/19 11:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	23/02/19 11:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/02/19 14:18	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001855/UCD3E2

Date: 27/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800056017

Claimant Vehicle
No : SLC810X

Insured Vehicle No : SMA735D

Date of Loss: 26/01/2019

Nature of Claim:

TP

Claim No: 9872808605SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC810X

Make & Model: KIA FORTE K3, 1.6 (A)

Engine No: G4FGJH695444

Reg. Date: 16/05/2018 (Man. Year: 2017)

Chassis No: KNAFJ411MJ5765102

Colour: Grey

Odometer: 21035 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Nexen 7 mm

Rear Left Side:

Nexen 7 mm

Front Right Side: Nexen 7 mm

Rear Right Side:

Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/01/2019

Date Inspected: 29/01/2019 Inspected At:

Bluwell Automotive Service Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER REFLECTOR N/S	Cracked	0.00 F	*- F
4	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Cracked	0.00 F	*- F
6	5		*REAR BUMPER REINFORCEMENT RETAINER	Twisted	0.00 F	*- F
7	1		*REAR BUMPER BRACKET	Repair	0.00 F	*- F
8	1		*TAILLAMP N/S	Cracked	0.00 F	*- F
9	1		*REAR END PANEL	Repair	0.00 F	*- F
10	1		*BOOTLID	Repair	0.00 F	*- F
11	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >