

ASS. REC. BY:

REF: CS3 / A1519001866 / Bed34

Special Instruction:

Surveyor: Mr. Jim

ASSIGNMENT (Office)

From (Person): ^{Muhammad} chin lee ying

of AIG

Date/Time: 29/1/19 @ 9-49am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 7121H

Insured:

SIF 3913H

at Workshop m/s

M.S. panel Beating

Tel:

9143 6086

of

2 kaki Bukit Ave 2 # 02-17

Policy No:

Claim No:

350313136186

Sum Insured:

Excess:

Make of Veh:

D.O.A.

08/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{cup}

H.O.D. Endorsement:

Date/Time: 10-45am @ 29/1/19

Person Contacted:

Mr. Joh

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

PC 7121H - X

SIF 3913H - X

Your password will expire in 14 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments, Admin A

Cc: Fong, Andy-SY

Sent: 29/1/2019 9:49:03 AM

Attachments:  tmp71B5.tif

Hi LKK,

Kindly assist to survey, owner will leave vehicle this morning.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Oracle Law Corporation

• Advocates & Solicitors • UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Facsimile: 6538 1860
Email: mail@oraclelaw.sg

FACSIMILE TRANSMISSION

To	: AIG Asia Pacific Insurance Pte Ltd	Date	: 28 th January 2019
Attention	: Motor Claims	From	: Mr Stanley Bay / Miss Pauline Ong
Your Ref.	: Insurer of SLF 3913Y	Our Ref.	: SB/PO/Acc/2019-8909
Facsimile	: 6835-7416	No. of Pages	: 5 (including this page)

IMMEDIATE ATTENTION

Dear Sirs

PRE-REPAIR INSPECTION

ACCIDENT INVOLVING PC 7121H & SLF 3913Y ALONG LAVENDER STREET ON 08-01-2019 @ 9.00 A.M.

We act for the owners of vehicle registration no. PC 7121H.

We are instructed by our clients to notify you of the above accident involving our clients' said vehicle and your insured's vehicle registration no. **SLF 3913Y** driven at the material time. A copy of our clients' motor accident report is enclosed herein.

As a result of the above accident, our clients' said vehicle was damaged. Before our clients proceed to repair their damaged vehicle, please let us know within the next (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair their said vehicle without further reference to you.

Please note that this notification does not in any way prejudice our clients' right nor shall it be deemed as a waiver of any of their rights, as such our clients' rights are expressly reserved.

Yours faithfully



Mr Stanley Bay / Miss Pauline Ong
Enc

Details of Repairers

M.S. Panel Beating Workshop
2 Kaki Bukit Ave 2
#02-17 Singapore 417921
Tel No.: 9143-6036 (Mr. Loh) ; Fax No. 6747-8306

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9161W
Vehicle Details	
Vehicle No.:	PC7121H
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1GD8278312
Chassis No.:	GDH2232000319
Maximum Power Output:	-
Open Market Value:	\$43,467.00
Original Registration Date:	25 Jun 2018
First Registration Date:	25 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$2,174.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$16,151.00
COE Rebate Amount:	\$15,132.00
Total Rebate Amount:	\$15,132.00

The information contained herein is correct as at 11 Feb 2019

OK

Dep 8720/yr

MV 80,000/2
 FV 15,132/2
 NV 65,868/2


 11/2/19



Fuel Type: Diesel
 Newly Registered! Totally Legit, GST/ARF/COE All In! Toyota Hiace 5 Doors Diesel. Borneo Motors 3 Years Or 100k Km Warranty! Cheap! Hurry Call Now! 24 Hours Serving You!

ABWIN (1994) Pte Ltd

Posted: 31-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter **\$91,800** **\$9,330 /yr** **12-Dec-2018** **2,982 cc** **-** **Bus** **Available**

Fuel Type: Diesel
 CNY PROMO! Newly Registered Toyota Commuter Hi-Roof Model! Includes 6 Months Road Tax, And Lots Of Accessories! High Loan And High Trade In Available! Can Register Excursion Private Hire Or Private Bu...

Net Link Partners Pte Ltd

Posted: 31-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace **\$69,800** **\$7,240 /yr** **02-Oct-2018** **2,982 cc** **1 km** **Van** **Available**

Fuel Type: Diesel
 Newly Registered! Totally Legit, GST/ARF/COE All In! Toyota Hiace 4 Doors Auto Diesel. Borneo Motors 3 Years Or 100k Km Warranty! Cheap! Hurry Call Now! 24 Hours Serving You!

ABWIN (1994) Pte Ltd

Posted: 31-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter **\$95,800** **\$10,560 /yr** **06-Mar-2018** **2,982 cc** **-** **Bus** **Available**

Fuel Type: Diesel
 14 Seaters Euro 6 Mini Bus For Sales! Ready Stock, 3 Years Or 100000km Warranty Whichever Come First, Include 6 Months Road Tax, And Lots Of Accessories, High Loan And High Trade In. Can Register Excu...

KSL Automotive Pte Ltd

Posted: 31-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace **\$67,800** **\$6,910 /yr** **30-Nov-2018** **2,982 cc** **-** **Van** **Available**

Fuel Type: Diesel
 New Toyota Hiace From Borneo Motor, Guarantee COE And Cheapest In The Market! Ready Stock! 3 Years Warranty By Borneo Motors. New Improve Diesel Engine By Toyota With Low Fuel Consumption, Most Reliab...

KSL Automotive Pte Ltd

Posted: 30-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace **\$68,800** **\$7,120 /yr** **09-Oct-2018** **2,982 cc** **1 km** **Van** **Available**

Fuel Type: Diesel
 Ready Stock. 100% Loan, Warranty And Servicing Included. GST, Admin Fee And Miscellaneous All Included. Many Free Accessories In This Deal. Don't Miss Out On This Special Deal. Full Cash Welcome. Chea...

Car (S) Pte Ltd

Posted: 30-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

PREMIUM AD



Toyota Hiace Commuter **\$81,800** **\$8,720 /yr** **28-Jun-2018** **2,982 cc** **188 km** **Bus** **Available**

Fuel Type: Diesel
 Like New 14 Seaters Mini Bus For Sales! 3 Years Or 100000km Warranty Whichever Come First, High Loan And High Trade In. Can Register Excursion, Private Hire, Or Private Bus, Call Our Friendly Sales Ex...

Tai Huat Automobile

Posted: 30-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0A DX **\$68,800** **\$7,380 /yr** **08-Jun-2018** **2,982 cc** **-** **Van** **Available**

Fuel Type: Diesel
 Toyota Hiace Original 5 Door Glass Panel, Original Rear Aircon, Original LED Head Lamp System, Original Retractable Side Mirrors, Original Security Key System, Nice Bidded Number Plate To Go Along.

Posted: 30-Jan-2019

Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

DIRECT OWNER



Toyota Hiace **\$68,800** **\$7,140 /yr** **28-Sep-2018** **2,982 cc** **1 km** **Van** **Available**

Fuel Type: Diesel
 Newly Registered! Totally Legit, GST/ARF/COE All In! Toyota Hiace 5 Doors Diesel. Borneo Motors 3 Years Or 100k Km Warranty! Cheap! Hurry Call Now! 24 Hours Serving You!

ABWIN (1994) Pte Ltd

Posted: 30-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter **\$89,300** **\$9,110 /yr** **29-Nov-2018** **2,754 cc** **-** **Bus** **Available**

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 30-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace **\$66,800** **\$6,870 /yr** **31-Oct-2018** **2,982 cc** **-** **Van** **Available**

Fuel Type: Diesel
 Low Interest Rate, Easy Approval. 100% Available. \$3k Drive Away, Immediate Stock For Delivery. Best Selling Panel Van For Your Commercial Use.

Think One Automobile & Trading

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/01/2019 10:37
Date Of Accident	08/01/2019 09:00
Exact Location Of Accident	LAVENDER STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC7121H
Insured/Policyholder	
Name Of Registered Owner	TRANS-JAAP EXPRESS
Co Reg No	52919161W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88239033
Alternative Phone No	OFFICE-88239033
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE-3.0 D GL HIGH-ROOF COMMUTER (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101677128
Cover Note Number	25/06/2018 - 24/06/2019
Driver	
Name of Driver	TAMIZUDIN S/O ABDUL RAHIM
NRIC No	S8412345E
Date Of Birth	25/04/1984
Occupation	INDOOR
Date Of Driving Pass	30/05/2008
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91248727
Fax Number	
Contact Number	
E Mail Address	TAMIZUDIN63@GMAIL.COM

Address BLK 178C RIVERVALE CRESCENT #14-425
 Postcode 543178
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY VEHICLE WAS STOPPED STATIONARY ON THE RIGHT LANE OF LAVENDER STREET, WAITING TO TURN RIGHT AHEAD ONTO BENDEMEER ROAD. TRAFFIC WAS HEAVY. THERE WAS ONE LORRY AHEAD OF ME WAITING TO TURN RIGHT TOO. SUDDENLY, I FELT AN IMPACT ON MY VEHICLE REAR LEFT PORTION. VEHICLE B WAS TRYING TO CHANGE LANE TO THE SECOND RIGHT LANE BUT FAILS TO DO AS THERE WAS ONE APPROACHING TRUCK GOING STRAIGHT ON THE SECOND RIGHT LANE. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLF3913Y
 Vehicle Make/Model/Colour VOLVO S60
 Details Of Properties RIGHT PORTION
 Vehicle Category PRIVATE CAR
 Name of Driver HOW TI HWEI
 NRIC/Passport Number S7018956I
 Contact Number 96706784
 Address 3 WEST COAST WALK
 Postcode 127140
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

Sketch Plan Pg. 1

TUC Income Motor Service Centre

8/1/19

Vehicle No:

PC7121H
7/HIACE

Report Date: 1/8/2019 Start Time: 10:51 AM

Report No. MT

D.O.A:

Make / Model:

Reporting Type: TP

End Time:

IMPORTANT NOTICE

SKETCH PLAN

Please report **correctly** the details of the accident to speed up the claims process.

This Form must be **completed by the Policyholder and/or the Authorised Driver.**

Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies **to repudiate policy liability.**

The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.

e) the information so collected under (d) above may be shared / disclosed:

(i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated, or


(ii) for complying with requirements under any regulations, law or court orders.


Policyholder's Signature
& Title:
1/8/2019 10:51


Driver's Signature (If driver is not the policyholder)
Date & Time: 1/8/2019 10:51


Reporting Centre Personnel's Signature
Name: Chen JunLiang
NRIC/ Fin No: S990765

SKETCH PLAN



Vehicle A: PC7121H

Vehicle B: SLF3913Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


MY VEHICLE WAS STOPPED STATIONARY ON THE RIGHT LANE OF LAVENDER STREET, WAITING TO TURN RIGHT HEAD ONTO BENDEMEER ROAD. TRAFFIC WAS HEAVY. THERE WAS ONE LORRY AHEAD OF ME WAITING TO TURN RIGHT TOO. SUDDENLY, I FELT AN IMPACT ON MY VEHICLE REAR LEFT PORTION. VEHICLE B WAS TRYING TO CHANGE LANE TO THE SECOND RIGHT LANE BUT FAILS TO DO AS THERE WAS ONE APPROACHING TRUCK GOING STRAIGHT ON THE SECOND RIGHT LANE. NO ONE WAS INJURED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 1/8/2019 10:51


 Driver's Signature (If driver is not the policyholder)
 Date & Time: 1/8/2019 10:51


 Reporting Centre Personnel's Signature
 Name: Chen JunLiang
 NRIC / Fin No: S990765

VAN / LORRY (Rear)

Vehicle No: PC 71214

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	SCR	X R	
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp	BR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

Handwritten notes:
 13/2/15
 (circled around item 1166)

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel	NG	SCR	Y R
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2019 Edit Reg		29 Jan 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	PC7121H	Date of Loss:	08/01/2019 00:00 - :59 [6 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3503131361SG	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SLF3913H	Policy No. (Claimant):							
		Excess:							
Repairer:	M.s Panel Beating Workshop (HQ) 2 KAKI BUKIT AVE 6, # 02 . 17 AUTOHUB @ KAKI BUKIT, 417921 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 11/02/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (30/01/2019): No Policy Found 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC7121H (3503131361SG)
[SLF3913H]

TP

-

Jan 8 2019 12:00AM

[-]

M.s Panel Beating Workshop

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
2	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
3	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
4	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
5	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
6	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
7	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
8	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
9	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
10	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
11	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
12	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
13	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
14	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
15	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
16	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
17	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
18	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
19	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
20	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
21	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
22	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
23	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
24	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
25	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
26	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
27	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
28	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
29	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
30	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
31	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
32	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>
33	11/02/19 13:38	General View		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset | Save | Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001866/BCD3E2

Date: 14/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : PC7121H

Insured Vehicle No : SLF3913H

Date of Loss: 08/01/2019

Nature of Claim: TP

Claim No: 3503131361SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC7121H**

Make & Model: TOYOTA HIACE, 2.8 D GL (A)

Engine No: 1GD8278312

Reg. Date: 25/06/2018 (Man. Year: 2018)

Chassis No: GDH2232000319

Colour: Silver

Odometer: 44662 km

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/01/2019

Date Inspected: 29/01/2019 Inspected At:

M.s Panel Beating Workshop (HQ)
2 KAKI BUKIT AVE 6, # 02 . 17 AUTOHUB
@ KAKI BUKIT
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	0.00 F	*- F
2	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
3	1		*REAR BODY PANEL N/S	Repair	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >