

Stone

REF: ASM(CAXA)

ASSIGNMENT

From: Date: 20/2/19

Veh No: SMO 2381L Regn: 8/08/18

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: SMO 2381L
at Workshop n/s: Performance
of: 303 Alexandra Road

Make: BMW X1 C.C. 1499

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 9093 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.:

C/No: WBAJG120603 G 76289

Claims No.:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: Yaguel


Mod: Nil / SRim / STD AIRim or

Tyre Size: F: 225/50R18

R: 11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRELLI

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 8 mm R/Bal. 8 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 8 mm L/Bal. 8 mm

Est. Repairs: days Res.: Yes or No

D.O.A. 25/1/19 D.O.I. 20/1/19

Lum Sum: % 3 Val.: Yes or No

Survey held at Performance Motors

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

: Preli. Report

Days Of Repair:

1)

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

2)

Add Fee:

Site Insp (\$)

) S + RS \$

Interview (\$)

) Photos

Tech. Invs (\$)

) Other

Weekend (\$)

)

Report Format :

Lump Sum / I.B.I. (\$)

PTA