

ASS. REC. BY:

REF:

08/MSG19001926/195 d301

Special Instruction:

Surveyor

Minimen

ASSIGNMENT (Office)

From (Person):

Jumyn Tay

of

MSIG

Date/Time:

29/1/19 @ 4:10pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8003J

Insured:

GBA 541B

at Workshop m/s

Premier Taxis

Tel:

6544 6689

of

23 Cheng South Ave 2 #03-02

Policy No:

2909 5521MKC

Claim No:

583596

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/01/2019

CA / REV / REP. / REV 24 HRS

lup

30/01/2019

H.O.D. Endorsement:

Date/Time:

4:47pm @ 29/1/19

Person Contacted:

Vincent

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SHB 8003J -x

GBA 541B - NS/INC16004466/K/vbn2

DOA: 5/3/16

31/01/19

@ 16:49 p.m. revised IA to Jumyn Tay via minimen


Xml.

REF: MSIG

C4975H

ASSIGNMENT

From: Date: 30/01/2019
Estimated Cost:
OD: ☒ WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: 8HB 8003J
at Workshop m/s: Premier Taxis
of: 23 Cheng south Ave 2# 03-02
Insured:
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:
(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value:
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 1 days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS ^{hup}
Date: Person Contacted: Vehicle: IN / OUT



Veh No: SHB 8003J Yr Regn: 28-Sep-2016
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Hyundai i30 C.C. 1582
Colour: silver A/C Insured / Std / NI / NA
Sp. Reading: 103999 T/Radio Insured / Std / NI / NA
Eng/No:
C/No: TMAD 28/UVHJ121525
Gen Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: ☒ S/Rim / STD / ☒ or
Tyre Size: F: 195/65 R15
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or MAXXIS
Front: Rear
R/Bal: 5 mm R/Bal: 5 mm
L/Bal: 5 mm L/Bal: 5 mm
D.O.A.: D.O.I. 30-01-19
Survey held at: w/s 3:35pm
Des. of Damages: Frt / Rear / ☒ S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
03/04/19 Confirmed P/P \$532.62 @ 1 day with XGA
(0 Red - 0%)

RECEIVED 04 APR 2019

3/4/19

Date/Time File Pass to? 04/04/19
1) Typist ☐ : Preli. Report
☒ : Final Report
Date/Time File Return to?

Days Of Repair: 1
Resurvey No. of Trip: /

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee: 150
Transportation: 5 + RS \$1
Photos:
Other:
TOTAL: 160

Report Format :
Lump Sum / I.B.I. (\$) 532.62 p/p

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2019		29 Jan 2019 16:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LAO SICHUAN PTE LTD, Co. Reg. No.: 201203367R		
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H		
Vehicle Reg. No.:	SHB8003J	Date of Loss:	27/01/2019 14:00 - :59 [27 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 583596	Policy/Cover Note No.:	29095521MKC (TP, Fire & Theft) Coverage: 24/11/2018 - 23/11/2019
Vehicle Reg. No. (Insured):	GBA541B	Policy No. (Claimant):	
		Excess:	
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/01/2019]		
Adj Asg. Remarks:	SJE : AGREED / LIABILITY NOT CLEAR (NON REPORTING) Please appoint LKK AUTO to conduct the survey . Kindly contact MR VINCENT CHUA @ 6544 6689 or 6214 8880 to arrange for survey .		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHB8003J
Previous Vehicle No.: -
Effective Date of Ownership: 28 Sep 2016
Original Regn Date: 28 Sep 2016
Registration Date: 28 Sep 2016
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ121525
Engine No.: D4FBGZ105493
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$20,131.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Sep 2024
Minimum PARF Benefit: \$7,610.00
No. of Transfers: 0
IU Label No.: 1050681064
COE No.: 2016092801004227N
COE Expiry Date: 27 Sep 2024
COE Category: A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))
Quota Premium (QP) / Prevailing Quota Premium: - / \$53,339.00
PQP Paid: \$42,672.00
QP (Regn Cat): -
OPC Cash Rebate Eligibility: No

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4975H
Vehicle Details	
Vehicle No.:	SHB8003J
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	I30 GDH 1.6 TCI 5DR DCT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	D4FBGZ105493
Chassis No.:	TMAD281UVHJ121525
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,131.00
Original Registration Date:	28 Sep 2016
First Registration Date:	28 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$12,684.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2024
PARF Rebate Amount:	\$9,513.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$42,672.00
COE Rebate Amount:	\$30,181.00
Total Rebate Amount:	\$39,694.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 31 Jan 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 4 April 2019 9:41 AM
To: 'Goh Wee Dek'; SUR
Cc: 'Gary Shi'
Subject: RE: SHB8003J- FINALIZE

Dear Wee Dek,

Confirmed final fig \$532.62 @ 1 day of repairs before GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek [mailto:weedek.goh@premiertaxi.com]
Sent: Wednesday, 20 March 2019 10:23 AM
To: SUR <sur@lkkauto.com>
Cc: Gary Shi <gary.shi@premiertaxi.com>
Subject: SHB8003J- FINALIZE

Dear Guo Qiang

Please confirm repair \$532.62 & 1 day

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 31 Jan 2019

Preliminary Advice

Insured Vehicle No	: GBA541B	Accident Date	: 27/01/2019
TP Vehicle No	: SHB8003J	Assignment Date	: 29/01/2019
Make	: HYUNDAI I30 GDH	Est. Duration of Repair	: 1 Day
Date of Inspection	: 30/01/2019		
Inspection At	: Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02 Singapore 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	532.62
Revised Amount	:S\$	532.62
Check Items (Estimated)	:S\$	0.00
Total	:S\$	532.62

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/01/2019 17:14
Date Of Accident	27/01/2019 14:00
Exact Location Of Accident	CHIN SWEE ROAD TWDS OUTRAM
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHB8003J
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	
Driver	
Name of Driver	TOH TIONG KHENG
NRIC No	S7107400E
Date Of Birth	03/03/1971
Occupation	OUTDOOR
Date Of Driving Pass	19/02/2014
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91222823
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 442B #10-853 BT BATOK WEST AVE 8
Postcode	652442
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PAX IN THE REAR SEAT GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - 1 PAX VEH. B - NO PAX

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA541B
Vehicle Make/Model/Colour	LORRY
Details Of Properties	VEH. B
Vehicle Category	GOODS VEHICLE
Name of Driver	MALE CHINESE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 7107400E

X *[Signature]*


[Signature]
SHB 8003 J

29 JAN 2013

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Signature]

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHB 8003J

B: GBA 5X1 B

[A large diagonal line is drawn across the remaining lines of this section.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten signature]
57107400E

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

29 JAN 2013

[Handwritten signature]

Describe Circumstance of the Accident.

ON 27/01/2019 @ 1400HRS, I WAS DRIVING MY TAXI (SHB 8003 J), TRAVELLING ALONG CHIN SWEE ROAD TOWARDS OUTRAM ROAD WITH A PASSENGER ONBOARD, IN LANE 3.


WHILE MOVING AHEAD, VEHICLE B (GBA 541 B – LORRY) WHICH WAS FROM LANE 2 – ENCROACHED ONTO MY PATH ON RIGHT ABRUPTLY & COLLIDED ONTO THE RIGHT WING MIRROR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE RIGHT WING MIRROR AND NO DAMAGES TO VEHICLE B.

NO INJURY INVOLVED.
NO PASSENGERS ONBOARD VEHICLE B.

*VIDEO FOOTAGE CAPTURED.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



Driver's Signature & NRIC Number
@ 5:22:01 PM

(attended by)

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
Assessment number: SHB8003J
Version: 1810
Date calculated: 01/30/2019 12:20 PM

Full Report
Registration: SHB8003J
Printed: 30/01/2019 12:23 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-27
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HYUNDAI
Model:	I30 (PD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 82 01
Registration:	SHB8003J
VIN number:	
Odometer:	
Model Specs	
5-DOOR	

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
 Assessment number: SHB8003J
 Version: 1810
 Date calculated: 01/30/2019 12:20 PM

Full Report
 Registration: SHB8003J
 Printed: 30/01/2019 12:23 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection: 2019-01-30

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NN	R/DOOR MIRROR R&R / NEW PARTS		10.0*	50.00
	Labour Cost		Hrs	WU
	Panel / Mechanical Labour		1.00	10.0
	Total of Labour			50.00

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01
				Price SGD
1738	R/DOOR MIRROR	87620G4270	/ Big.	742.49
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			742.49
u: Used parts	Subtotal Discount(+35.00%)			-259.87

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHB8003J

Version: 1810

Date calculated: 01/30/2019 12:20 PM

Full Report

Registration: SHB8003J

Printed: 30/01/2019 12:23 PM

Total	482.62
-------	--------

Final Calculation

	SGD	SGD
Parts	742.49	
Total Discount(+35.00%)	-259.87	
Total Parts		482.62
Labour Time Base 10 WU/h		
Total 10.0 WU X 50.00 SGD/h	50.00	
Total of Labour		50.00
Repair Cost Excludes GST		532.62
GST (+7.0%)		37.28
Repair Cost Included GST		569.90

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

1 Day.
After repair photos.
part by part.
Gua Qian - 82880282
30/1/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: SHB8003J
Version: 1810
Date calculated: 04/03/2019 09:08 AM

Full Report
Registration: SHB8003J
Printed: 03/04/2019 9:08 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-27
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HYUNDAI
Model:	I30 (PD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 82 01
Registration:	SHB8003J
VIN number:	
Odometer:	
Model Specs	
5-DOOR	

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: SHB8003J
 Version: 1810
 Date calculated: 04/03/2019 09:08 AM

Full Report
 Registration: SHB8003J
 Printed: 03/04/2019 9:08 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection: 2019-01-30

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NN	R/DOOR MIRROR R&R / NEW PARTS		10.0*	50.00
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	1.00	10.0	50.00
	Total of Labour			50.00

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01
				Price SGD
1738	R/DOOR MIRROR	87620G4270		742.49
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			742.49
u: Used parts	Subtotal Discount(+35.00%)			-259.87

LKK Auto Consultants

#01-25 Paya Ubi Industrial Park,

51 Ubi Avenue 1

408933

Claim Reference:

Assessment number: SHB8003J

Version: 1810

Date calculated: 04/03/2019 09:08 AM

Full Report

Registration: SHB8003J

Printed: 03/04/2019 9:08 AM

Total	482.62
-------	--------

Final Calculation

	SGD	SGD
Parts	742.49	
Total Discount(+35.00%)	-259.87	
Total Parts		482.62
Labour Time Base 10 WU/h		
Total 10.0 WU X 50.00 SGD/h	50.00	
Total of Labour		50.00
Repair Cost Excludes GST		532.62
GST (+7.0%)		37.28
Repair Cost Included GST		569.90

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2019		29 Jan 2019 16:10 Edit Adj Rpt	S\$532.62 Edit Estimates	S\$532.62 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LAO SICHUAN PTE LTD, Co. Reg. No.: 201203367R								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHB8003J	Date of Loss:	27/01/2019 14:00 - :59 [27 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 583596	Policy/Cover Note No.:	29095521MKC (TP, Fire & Theft) Coverage: 24/11/2018 - 23/11/2019						
Vehicle Reg. No. (Insured):	GBA541B	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Taxis Pte Ltd - Changi (HQ) 23 Changi South Ave 2 #03-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 28/02/2019]								
Adj Asg. Remarks:	SJE : AGREED / LIABILITY NOT CLEAR (NON REPORTING) Please appoint LKK AUTO to conduct the survey . Kindly contact MR VINCENT CHUA @ 6544 6689 or 6214 8880 to arrange for survey .								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB8003J (583596)
 [GBA541B]
 TP
 PREMIER TAXIS PTE LTD
 Jan 27 2019 2:00PM
 [LAO SICHUAN PTE LTD]
 Premier Taxis Pte Ltd - Changi

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Letters/Correspondences						1 per page 1	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	29/01/19 15:39	Non Reporting Letter to OI			Load HTM		
Assessment Reports						1 per page 1	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	31/01/19 16:49	Adjuster Immediate Advice			Load HTM		
Photos/Images						3 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	03/04/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>	
2	03/04/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>	
3	03/04/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>	
4	03/04/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>	
5	03/04/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>	
6	03/04/19 09:09	Odometer Reading			Load JPG	<input checked="" type="checkbox"/>	
7	03/04/19 09:09	Chassis Number			Load JPG	<input checked="" type="checkbox"/>	
8	03/04/19 09:10	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
9	03/04/19 09:10	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
10	03/04/19 09:10	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
11	03/04/19 09:10	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>	
Documentation						1 per page 1	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	29/01/19 15:33	TPD SHB8003J - PRI & GIA REPORT			Load PDF		
2	29/01/19 15:38	Reply email from TP workshop & appoint LKK AUTO			Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	03/04/19 09:19	SHB 8003J AUDATEX.pdf			Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG19001926/GSD3E2**Date:** 16/04/2019REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29095521MKC

Claimant Vehicle No : SHB8003J**Insured Vehicle No :** GBA541B

Date of Loss: 27/01/2019

Nature of Claim: TP

Claim No: 583596

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHB8003J**

Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)

Engine No: D4FBGZ105493

Reg. Date: 28/09/2016 (Man. Year: 2016)

Chassis No: TMAD281UVHJ121525

Colour: Silver

Odometer: 103999 km

Engine Capacity: 1582 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: Maxxis 5 mm

Rear Right Side: Maxxis 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	482.62	482.62	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	50.00	50.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	532.62	532.62	0.00	0.00
+ GST 7.00/7.00% (S\$)	37.28	37.28	0.00	0.00
Nett Amount (S\$)	569.90	569.90	0.00	0.00

INSPECTION

Date of Assignment: 29/01/2019

Date Inspected: 30/01/2019 Inspected At:

Premier Taxis Pte Ltd - Changi (HQ)
23 Changi South Ave 2 #03-02
Singapore 486443

Estimated Period of Repair: 1.0 days

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Apr 2019)	
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB8003J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/DOOR MIRROR	Distorted	742.49 FL	*742.49 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					742.49	742.49
- List Item Discount on L Items 35.00/35.00% (S\$)					259.87	259.87
Total Parts (S\$)					482.62	482.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	10.0 WU X 50.00 SGD/H	New	50.00	50.00
Gross Labour Cost (S\$)			50.00	50.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >