

ASS. REC. BY

REF:

CS/MSG19001927/Jtd39

Special Instruction:

Surveyor
Menimen

ASSIGNMENT (Office)

From (Person):

Janyu Tay

of

MS/G

Date/Time:

29/1/19 @ 10am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 6921Y

Insured:

XD 42812

at Workshop m/s

The One Holdings

Tel

9748 0340

of

8 woodlands Ind. Park C3

Policy No:

MSD/VCC/19-000006

Claim No:

MSC/V/19-000116

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/01/2019

CA / REV / REP. / REV 24 HRS

up

30/1/19 3:15pm-3:30pm

H.O.D. Endorsement:

Date/Time:

4pm-29/1/19

Person Contacted:

Hilmi

Vehic' - IN /

OUT

Date/Time	Action/Instruction (✓) Estimate
	PC 6921Y-X
	XD 42812-C03/MSG17007137/Arbe2
1/2-	Revised preli advise via menimen

D.O.A. 8/1/17

Hwee Jie

REF: MSIG

PRS

SINGAPORE

From: Date: 30/4/2019

Estimated Cost

OD: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No

PC 6921 Y

at Workshop no

The One Holdings

at 8 woodlands Ind. park E3

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

3:15pm-3:30pm

Hilmi @ 9748 0340

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repair: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: PC 6921 Y Yr Began: 16 Aug 2010

Type: M.Car / M.Cycle / ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Golden dragon

CC 6693

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 773357

C/Radio: Insured / Std / NI / NA

Eng/No:

ChNo: LL3BEC0H1AA011105

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/70 R22-5

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Sumitomo

Front

Rear

R/Bal: 7 mm

R/Bal: 7 mm

L/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 24/1/19

D.O.I: 30/1/19

Survey held at The One Holdings

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/4/19 Confirmed L/S \$1000 3days of repair with Hilmi. (Red: 1200:54%)

RECEIVED 23 APR 2019

26/4/2019

Date/Time, File Pass to:

26/4 Typist ☐ Preli. Report ☒ Final Report

Date/Time, File Return to:

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Registration:

Taxes:

Fees:

Fees:

Fees:

Fees:

TOTAL

Report Format:

TP

Lump Sum / LB 1:15

1000/-

Add Fee: ☐ Site Insp. 1\$☐ Interp. 1\$☐ Tech. Insp. 1\$☐ Workshop 1\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Est Audited	Status
Main	28 Jan 2019		29 Jan 2019 10:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	UNION SERVICES (S'PORE) PTE LTD, Co. Reg. No.: 198001961M		
Main Claimant:	SAM BUS LLP, Co. Reg. No.: T18LL1197E		
Vehicle Reg. No.:	PC6921Y	Date of Loss:	24/01/2019 18:00 - :59 [101 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/19-000116	Policy/Cover Note No.:	MSD/VCC/19-000006 (Comprehensive) Coverage: 01/01/2019 - 31/12/2019
Vehicle Reg. No. (Insured):	XD4281Z	Policy No. (Claimant):	
		Excess:	
Repairer:	The One Holdings Pte Ltd (HQ) 8 Woodlands Industrial Park E3, 757786 Woodlands - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/01/2019]		
Adj Asg. Remarks:	SJE AGREED / LIABILITY NOT CLEAR (NON REPORTING) Please appoint LKK AUTO to conduct the survey . Kindly contact MR MUHD HILMI @ 9748 0340 or 6755 8810 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/01/2019 16:50
Date Of Accident	24/01/2019 18:50
Exact Location Of Accident	JURONG ISLAND PASS OFFICE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC6921Y
Insured/Policyholder	
Name Of Registered Owner	SAM BUS LLP
Co Reg No	T18LL1197E
Email Address	SAMBBUS@AOL.COM
Mobile Phone No	(LOCAL) +65-93299902
Alternative Phone No	OFFICE-69880458

Vehicle Particulars

Manufacturer	GOLDEN DRAGON
Model	XML6957J14-6.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	FERRYING PASSENGER TO TOWARDS JALAN PAPAN
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company


Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D18MTSCBU000578
Cover Note Number	

Driver

Name of Driver	MOHAMAD NASIR BIN N K IBRAHIM
NRIC No	S1163274B
Date Of Birth	09/12/1958
Occupation	OUTDOOR
Date Of Driving Pass	13/08/1979
Driving Experience	39 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92397858
Fax Number	
Contact Number	OFFICE-69880458
Email Address	SAMBBUS@AOL.COM

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24th of January 2019 at around 6:50pm I was at Juvang Island checkpoint to exit out. I was actually stopping for a while on the 2nd lane to check on my right side, where suddenly a prime mover XD42812 from my left side came and grazed onto my front portion left hand side over. I then stopped my bus engine and came down. The driver was a PRC. I only managed to get his hp number and took some scene photos. We then moved on.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time




25.1.19

Reporting Centre Personnel's Signature
Name: Kulmi
NRIC/ID No: 8702912162



Sketch Plan Pg. 3



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

		EFFECTIVE DATE
Class 2B	Motorcycles >= 250 cc	15 Jul 1983
Class 2A	Motorcycles between 201 cc and 400 cc	15 Jul 1983
Class 3	Motor cars with unladen weight >= 3000kg with >= 7 passengers, exclusive of driver, and other motor vehicles with unladen weight >= 2500kg	13 Aug 1979
Class 4	Motor vehicles which are constructed to carry load or passengers and the unladen weight >= 2500kg	28 Sep 1986
Class 5	Motor vehicles which are not constructed to carry load or passengers and the unladen weight >= 7250kg	15 Jun 1981
	and the unladen weight >= 7250kg	



NP 4294

Annex A

Transaction ref : 20180914144915696473

The owner and vehicle particulars for Vehicle No. PC6921Y as at 14 Sep 2018 are as follows:

27. Maximum Laden Weight(kg)	: 13200
28. Open Market Value	: \$91,995.00
29. PARF Eligibility	: No
30. PARF Eligibility Expiry Date	: -
31. Minimum PARF Benefit	: \$0.00
32. No. of Transfers	: 2
33. IU Label No.	: 2050082442
34. COE No.	: 2010080105000350N
35. COE Expiry Date	: 15 Aug 2020
36. COE Category	: C - Goods Vehicle & Bus
37. Quota Premium/Prevailing Quota Premium	: \$30,601.00 / -
38. Actual Quota Premium/PQP Paid	: \$30,601.00
39. Actual ARF Paid	: \$4,600.00
40. CO2 Emission(g/km)	: -
41. CO Emission(g/km)	: -
42. HC Emission(g/km)	: -
43. NOx Emission(g/km)	: -
44. PM Emission(mg/km)	: -
45. Actual CEVS/VES Rebate Utilised	: -
46. CEVS/VES Surcharge Paid	: -
47. Actual Green Vehicle Rebate Utilised	: -
48. Vehicle Lifespan Expiry Date	: 15 Aug 2030
49. Road Tax Amount	: -
50. Road Tax Start Date	: -
51. Road Tax End Date	: -
52. Remarks	: This is a public service vehicle.



The One Holdings Pte Ltd
Office : 8 Woodlands Industrial Park E3 (S757786)
Reg :201704052Z
Phone: 67558810 Fax: 67558809

Our Ref: TP/PC6921Y/0002

Date : 28/01/2019

QUOTATION

Dear Sir,


DOA :24/01/2019

Cost of Repair to Vehicle PC6921Y

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	To supply labour and material to dismantle the necessary attached item, repair and patch fiber the LHS corner front cap and front bumper, Install back these items and adjust alignment.	1	1,200.00	1,200.00 650
2.	To supply labour and material to spray paint the whole front cap and front bumper, complete with clear coat. and complete with spray paint & clear coat	1	1,000.00	1,000.00 600
			SUB-TOTAL	S\$2,200.00

Thanks you.
Yours faithfully,


Vincent Yeo
Claims Executive

LOU = 4 days.


1/2/19

Total - \$1000

Hwee Jie - LKK

30/1/19

L/S 3 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2019		29 Jan 2019 10:00 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	UNION SERVICES (S'PORE) PTE LTD , Co. Reg. No.: 198001961M								
Main Claimant:	SAM BUS LLP , Co. Reg. No.: T18LL1197E								
Vehicle Reg. No.:	PC6921Y	Date of Loss:	24/01/2019 18:00 - :59 [101 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-000116	Policy/Cover Note No.:	MSD/VCC/19-000006 (Comprehensive) Coverage: 01/01/2019 - 31/12/2019						
Vehicle Reg. No. (Insured):	XD4281Z	Policy No. (Claimant):							
		Excess:							
Repairer:	The One Holdings Pte Ltd (HQ) 8 Woodlands Industrial Park E3, 757786 Woodlands - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 28/02/2019]								
Adj Asg. Remarks:	SJE AGREED / LIABILITY NOT CLEAR (NON REPORTING) Please appoint LKK AUTO to conduct the survey . Kindly contact MR MUHD HILMI @ 9748 0340 or 6755 8810 to arrange for survey .								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC6921Y (MSC/V/19-000116)
[XD4281Z]
TP
SAM BUS LLP
Jan 24 2019 6:00PM
[UNION SERVICES (S'PORE) PTE LTD]
The One Holdings Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences				
			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/01/19 14:47	Non Reporting Letter to OI	Load HTM	
Assessment Reports				
			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/19 17:37	Adjuster Immediate Advice	Load HTM	
Photos/Images				
			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/19 16:31	General View	Load JPG	☒
2	31/01/19 16:31	General View	Load JPG	☒
3	31/01/19 16:31	General View	Load JPG	☒
4	31/01/19 16:31	General View	Load JPG	☒
5	31/01/19 16:31	General View	Load JPG	☒
6	31/01/19 16:31	General View	Load JPG	☒
7	31/01/19 16:31	General View	Load JPG	☒
8	31/01/19 16:31	General View	Load JPG	☒
9	31/01/19 16:31	General View	Load JPG	☒
10	31/01/19 16:31	General View	Load JPG	☒
11	31/01/19 16:31	General View	Load JPG	☒
12	31/01/19 16:31	General View	Load JPG	☒
13	31/01/19 16:31	General View	Load JPG	☒
14	31/01/19 16:31	General View	Load JPG	☒
15	31/01/19 16:31	General View	Load JPG	☒
16	31/01/19 16:31	General View	Load JPG	☒
Documentation				
			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/01/19 14:40	TPD PC6921Y GIA REPORT	Load PDF	
2	28/01/19 14:40	TPD PC6921Y - PRI	Load PDF	
3	28/01/19 16:26	Reply email from TP Workshop & appoint LKK AUTO	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

	^ v
--	--------

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19001927/JTD3Q2

Date: 06/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCC/19-000006		
Claimant Vehicle No :	PC6921Y	Insured Vehicle No :	XD4281Z		
Date of Loss:	24/01/2019	Nature of Claim:	TP	Claim No:	MSC/V/19-000116

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6921Y	Engine No:	ISBE422521838614
Make & Model:	GOLDEN DRAGON XML6957J14, 6.7 D (A)	Chassis No:	LL3BECDH1AA011105
Reg. Date:	16/08/2010 (Man. Year: 2010)	Odometer:	773357 km
Colour:	Blue		
Engine Capacity:	6693 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/70 R22.5	Rear Tyre Size:	255/70 R22.5
Front Left Side:	Sumitomo 7 mm	Rear Left Side:	Sumitomo 7 mm
Front Right Side:	Sumitomo 7 mm	Rear Right Side:	Sumitomo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,250.00	950.00	43.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,200.00	1,250.00	950.00	43.18
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	2,200.00	1,000.00	1,200.00	54.55
+ GST 7.00/7.00% (S\$)	154.00	70.00	84.00	54.55
Nett Amount (S\$)	2,354.00	1,070.00	1,284.00	54.55

INSPECTION

Date of Assignment:	29/01/2019		
Date Inspected:	30/01/2019	Inspected At:	The One Holdings Pte Ltd (HQ) 8 Woodlands Industrial Park E3 Singapore 757786
Estimated Period of Repair:	3.0 days		

Adjuster: ONG HWEE JIE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 May 2019)

Parts: N/A GOLDEN DRAGON XML6957J14 6.7 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC6921Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY LABOUR AND MATERIAL TO DISMANTLE THE NECESSARY ATTACHED ITEM ,REPAIR AND PATCH FIBER THE LHS CORNER FRONT CAP AND FRONT BUMPER,INSTALL BACK THESE ITEMS AND ADJUST ALIGNMENT	New	1,200.00	650.00
2	TO SUPPLY LABOUR AND MATERIAL TO SPRAY PAINT THE WHOLE FRONT CAP AND FRONT BUMPER,COMPLETE WITH CLEAR COAT.AND COMPLETE WITH SPRAY PAINT & CLEAR COAT	New	1,000.00	600.00
Gross Labour Cost (S\$)			2,200.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >