

22/03/2012

ASS. REC. BY:

REF: CSB/FWD 19001929/100302 Special Instruction:

Supervisor:
Menmen

ASSIGNMENT (Office)

From (Person):

Lionel fun

of

FWD

Date/Time

29/1/2019 @ 11:17am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 7103E

Insured:

SLP 4121G

at Workshop m/s

Black Eagles Auto

Tel:

9647 8331

of

25 Kaki Bkt Rd # 05-80 Synergy

Policy No:

PNP 2018-00012280

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/01/2019

After 12:30pm @ 30/01/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS ^{kup}

Date/Time:

3:53pm @ 29/1/19

Person Contacted:

Mr. Ng

Vehicle: IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKA 7103E - X

SLP 4121G - X

XRL

REF: FWD

PRS

ASSIGNMENT

From: _____ Date: 30/1/19

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: SKA 7103E

at Workshop m/s Black Eagles Auto

of 25 kaki Bkt Rd 4 # 05-80

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

After 12:30pm
Mr. Ng @ 9647 8331

N/S	O/S

Veh No: SKA 7103E Yr Regn: -

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota wish c.c. 1797

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 157153 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 86E 20 000 8634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/65 R15
R: //

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/TOYO/YOKO or

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. _____ D.O.I. 30-1-19

Survey held at: w/s 4:25pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$400 - \$500

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: PRS

Lump Sum / I.B.I.: \$ _____

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee: _____

Transportation: _____

5 + PS: \$ _____

Photos: _____

Other: _____

ADD Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech Invs (\$ _____)

Weekend (\$ _____)

TOTAL: _____

Catherine Chong (LKK Auto)

From: lionel.tan@fwd.com
Sent: Tuesday, 29 January, 2019 11:17 AM
To: assignments@lkkauto.com; sur@lkkauto.com
Cc: josey.loh@fwd.com
Subject: FW: 2nd Notice to Conduct Pre-repair Survey - Your Ref: SLP 4121G (Policy No. PNPV2018-00012280) Our Ref: SKA 7103E/BE/ca/ps
Attachments: 2nd PRS (FWD).pdf

Please find attached pre-repair notice for your attention.

Regards,
Lionel

From: Motor Claims SG - SG Common
Sent: Tuesday, January 29, 2019 11:13 AM
To: 'Accident@kscgp.com'
Cc: motor@kscgp.com
Subject: RE: 2nd Notice to Conduct Pre-repair Survey - Your Ref: SLP 4121G (Policy No. PNPV2018-00012280) Our Ref: SKA 7103E/BE/ca/ps

WITHOUT PREJUDICE

Dear Sir/ Madam

We regret that we are objecting to your proposed list of surveyors.

We will be appointing **LKK AUTO CONSULTANTS PTE LTD** to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

Regards,
Lionel

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: Tuesday, January 29, 2019 10:37 AM
To: Motor Claims SG - SG Common
Cc: motor@kscgp.com
Subject: 2nd Notice to Conduct Pre-repair Survey - Your Ref: SLP 4121G Our Ref: SKA 7103E/BE/ca/ps

Dear Lionel,

We refer to your email below and subject above.

Please find the enclosed 2nd Notice to Conduct Pre-repair Survey herewith.

Thank you.

Regards,
Sampu
for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: motorclaims.sg@fwd.com [<mailto:motorclaims.sg@fwd.com>]

To: Accident@kscgp.com

Cc: motor@kscgp.com

Sent: Tue, 29 Jan 2019 02:16:37 +0000

Subject:

Without Prejudice

Dear Sir/ Madam

Please select one of our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. VICOM LTD
5. APPRAISALS ASSOCIATES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

Lionel

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]

Sent: Tuesday, January 29, 2019 9:32 AM

To: Motor Claims SG - SG Common

Cc: motor@kscgp.com

Subject: Notice to Conduct Pre-repair Survey - Your Ref: SLP 4121G Our Ref: SKA 7103E/BE/ca/ps

Dear Sirs,

We refer to the subject matter.

Please find the enclosed Notice to Conduct Pre-repair Survey herewith.

Thank you.

Regards,
Sampu
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Your Ref : SLP 4121G
Our Ref : SKA 7103E/BE/ca/ps
Date : 29 January 2019

Fax : 6538 3708
Tel : 3152 0989
Email : accident@kscgp.com

FWD Singapore Pte Ltd

By Email Only

DATE OF ACCIDENT: 25 JANUARY 2019
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email dated 29 January 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/No.	Name of Surveyor	Company Name
1.	William Ng	Allied Auto

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Black Eagles Auto Pte Ltd
25 Kaki Bukit Road, #05-80,
Synergy Building,
Singapore 417800

Contact Person/Tel : Mr Ng Yuze (h/p: 9647 8331)

Yours faithfully,

PS

Your Ref : SLP 4121G

Our Ref : SKA 7103E/BE/ca/ps

Date : 29 January 2019

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Vehicle Details	
Vehicle No.:	SKA7103E
Vehicle Type:	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Chassis No.:	ZGE200008634
Propellant:	Petrol
Engine No.:	2ZR0428472
Engine Capacity:	1797 cc
Maximum Power Output:	106.0 kW (142 bhp)
Maximum Laden Weight:	1725 kg
Unladen Weight:	1340 kg
Year Of Manufacture:	2009
Original Registration Date:	25 Mar 2011
Lifespan Expiry Date:	-
COE Category:	E - Open Category
Quota Premium:	\$76,102.00
COE Expiry Date:	24 Mar 2021
Road Tax Expiry Date:	24 Mar 2019
PARF Eligibility Expiry Date:	24 Mar 2021
Inspection Due Date:	24 Mar 2020
Intended Transfer Date:	11 Feb 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 24 Mar 2019. You may renew the road tax from 25 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 24 Mar 2019, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 25 Mar 2019 to 24 Sep 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	487.00	-	487.00
Total Amount Payable:			512.00

Amount Payable (From 25 Mar 2019 to 24 Mar 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	974.00	-	974.00
Total Amount Payable:			999.00

You may print this page for reference.

OK

Print

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Limited Liability Partnership
Owner ID:	1043L
Vehicle Details	
Vehicle No.:	SKA7103E
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	2ZR0428472
Chassis No.:	ZGE200008634
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,925.00
Original Registration Date:	25 Mar 2011
First Registration Date:	25 Mar 2011
Transfer Count:	2
Actual ARF Paid:	\$21,925.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2021
PARF Rebate Amount:	\$13,155.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,102.00
COE Rebate Amount:	\$15,251.00
Total Rebate Amount:	\$28,406.00

The information contained herein is correct as at 11 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/01/2019 09:20
Date Of Accident	25/01/2019 14:25
Exact Location Of Accident	NEW BRIDGE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA7103E
Insured/Policyholder	
Name Of Registered Owner	BLACK EAGLE RENTAL LLP
Co Reg No	T17LL1043L
Email Address	NAIMOTA19912@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-90107743

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5098750063
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	SAFEN BIN SAFIE
NRIC No	S1537007F
Date Of Birth	13/02/1962
Occupation	OUTDOOR
Date Of Driving Pass	02/06/1984
Driving Experience	34 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94563589
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 161 #02-292 SIMEI ROAD
Postcode	520161
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE HEADQUARTERS
Police Station Address	ROAD: 10 UBI AVENUE 3 SINGAPORE , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to police report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO BIG TO BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP4121G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

INCOME MOTOR SERVICE CENTRE

Report Date & Start Time: 26-01-2019 / 09:38

Report No: MT/

D.O.A: 25-01-2019

Vehicle No: SKA7103E

Reporting Type:

Time: 14:25 hrs

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under [d] above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



26-01-19 / 9:38

Policyholder's Signature / Date & Time

26-01-19 / 9:38


Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

[Empty space for describing the accident circumstances]

Declaration

I/We declare the foregoing particulars are true in every respect.


26-01-19 / 9:38

Policyholder's Signature / Date & Time


26-01-19 / 9:38

Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre


Witnessed by Reporting Centre Personnel

Police Report Pg. 2



**SINGAPORE
POLICE FORCE**



T/20190125/7019

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20190125/7019

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SAFEN BIN SAFIE	ID No.	S1537007F
Related Vehicle	SKA7103E (Car)	Contact No.	94563589
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3,3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

At about 1425hrs, I was driving alone in my car bearing plate SKA7103E, a black Toyota Wish, along New Bridge Road towards People's Park Complex taxi stand on the way to pick up a passenger. While driving along the four-lane road on the 3rd lane, I signaled and changed to the 2nd lane to make a right turn in front of Chinatown MRT Station. while driving in my lane, a blue Honda Vezel bearing plate 'SLP4121G' changed lane into the 2nd lane from the 1st lane and hit me on my rear right passenger door. I immediately stopped the car as I did not want to cause more damage to the car. I then looked at the driver of the car and gestured to the driver to stop at the side. The driver, a Chinese male in his mid twenties, was with 2 passengers, a male Chinese in his late fifties in the front seat and a female Chinese in her late fifties.

Upon gesturing to the driver to stop at the side, the driver looked at me and turned away while the male passenger gestured to the driver to keep going forward. The driver then drove forward causing a longer scratch on the side of the car. I then followed the driver along Upper Cross Street but the driver continued to drive, seemingly without an intention to stop. At Park Crescent, the driver of the car turned into a multi storey carpark.

The collision caused my car to sustain damages, multiple scratches ranging from 10cm - 70cm on my right rear passenger door and a 45cm scratch on my side skirt.
I have a front dashboard camera and it has recorded the whole incident.



**SINGAPORE
POLICE FORCE**



T/20190125/7019

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3
Report No. T/20190125/7019

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
IRMAN BIN MOHAMAD SAID
Contact No.: 65476145

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
25/01/2019 23:12

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2019 14:20 Edit Reg		29 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	-, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SKA7103E	Date of Loss:	25/01/2019 00:00 - :59 [94 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SLP4121G	Policy No. (Claimant):							
		Excess:							
Repairer:	Black Eagles Auto Pte Ltd (HQ) 25 Kaki Bukit Road, #05-80 Synergy Building, 417800 Kaki Bukit - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/02/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKA7103E
[SLP4121G]
TP

Jan 25 2019 12:00AM

[-]

Black Eagles Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/02/19 12:41	General View		Load JPG	<input checked="" type="checkbox"/>
2	11/02/19 12:41	General View		Load JPG	<input checked="" type="checkbox"/>
3	11/02/19 12:41	General View		Load JPG	<input checked="" type="checkbox"/>
4	11/02/19 12:41	General View		Load JPG	<input checked="" type="checkbox"/>
5	11/02/19 12:41	General View		Load JPG	<input checked="" type="checkbox"/>
6	11/02/19 12:41	General View		Load JPG	<input checked="" type="checkbox"/>
7	11/02/19 12:41	General View		Load JPG	<input checked="" type="checkbox"/>
8	11/02/19 12:41	General View		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19001929/GCD3E2

Date: 11/02/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SKA7103E

Insured Vehicle No : SLP4121G

Date of Loss: 25/01/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA7103E**

Make & Model: TOYOTA WISH, 1.8 X (A)

Engine No: 2ZR0428472

Reg. Date: 25/03/2011 (Man. Year: 2009)

Chassis No: ZGE200008634

Colour: Black

Odometer: 157153 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/01/2019

Date Inspected: 30/01/2019 Inspected At:

Black Eagles Auto Pte Ltd (HQ)
25 Kaki Bukit Road, #05-80 Synergy
Building
Singapore 417800

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$400.00 -\$500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2019)
Parts: M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA7103E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >