

REF: NTUC NS/INCA001955/Jgd3er

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLM 8509L

Policy No. 5099697038

13042018 - 12042019

Claims No. MT/1016992-002

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No. SMB 42P

Yr Regn: 28 Nov 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes OC500 c.c 11967

Colour: multi colour A/C: Insured / Std / NI / NA

Sp. Reading: 739524 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W2663442021000114

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70 R22.5

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firenze

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 11/10/2018 D.O.I. 29/1/19

Survey held at Smart

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LA \$700, 2 days (led \$601.30, 46%)

RECEIVED 20 MAR 2019

Date/Time. File Pass to?

☐ : Preli. Report

Days Of Repair: 2

11/2/13 harris

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time. File Return to?

Survey Fee:

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)

) \$ + RS. \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format :

Lump Sum / I.B.L. (\$) 700

TOTAL

160
160

Shiau Chan (LKKAUTO)

From: MTCL@income.com.sg
Sent: Wednesday, 20 March 2019 10:59 AM
To: Shiau Chan (LKKAUTO)
Subject: RE: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

Junainah
Senior Admin Assistant
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, 19 March 2019 5:54 PM
To: MTCL@income.com.sg
Subject: RE: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Please refer to the below email.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 14 March 2019 2:16 PM
To: 'mtreg@income.com.sg' <mtreg@income.com.sg>
Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Please refer to the below:

TP Claims against NTUC Income: Follow-Through Survey

Date : 14/03/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D:
1	MT/1016992-002	SMRT BUSES LTD	SMB 42P	SLM 8509L	

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

eBaoTech

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

General Claim

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="11/10/2018 11:40"/>
Vehicle No. (For Motor)	<input type="text" value="SLM8509L"/>	Certificate Number	<input type="text"/>
<input type="button" value="Search"/>			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="checkbox"/>	5099697038		TING MOOI LING	S6866423C	GPC	drive PREMIUM	SLM8509L	SLM8509L	13/04/2018	12/04/2019
<input type="button" value="Continue"/>										

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2292D
Vehicle Details	
Vehicle No.:	SMB42P
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	OC500LE1830H
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	45796600148588
Chassis No.:	WEB63442021000114
Maximum Power Output:	-
Open Market Value:	\$319,952.00
Original Registration Date:	28 Nov 2008
First Registration Date:	28 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$15,998.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 20 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/10/2018 16:20
Date Of Accident	11/10/2018 09:45
Exact Location Of Accident	ALONG PAN ISLAND EXPRESSWAY (PIE)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMB42P
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	OC500LE1830H-12.0 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090224MFBP
Cover Note Number	
Driver	
Name of Driver	CHRISTOPHER DANIEL
NRIC No	G2636348P
Date Of Birth	02/03/1988
Occupation	OUTDOOR
Date Of Driving Pass	15/06/2015
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	10

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

While traveling along PIE towards Geylang Lor 1 Terminal (before Lornie Exit), a private car (SLM8509L) cut into my path as such i stepped on the brakes to avoid collision but was unable to stop on time hence my bus left front portion collided onto the right rear portion of the pte car. No injuries reported.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM8509L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"). The Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be stated outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: BALQISH
NRIC/IN No.: S83403252

SKETCH PLAN

① 8mB42P
② 5LM8509L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO REPORT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signat
Date & Time:



Driver's signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: BALQISH
NIC/FIN No.: SB340325Z





Case Details

Case Reference Number : BUS/10/18/5020

Type of Repair : Accident Repair

Vehicle Registration Number : SMB42P

Company Type : SMRT Buses Ltd

Estimation ID : EST-5543-ID

Assigned By : Audrey Woo Yee Shin

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 11/10/2018 01:46 AM

Vehicle Age(In Months) : 119

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Ren
Standard	Main	VE	6009700	LAMP,BLINKER:FRONT,LEFT,FOR MB OC 500 LE	1	155.30	155.30	10.00	139.77	Replace	1	139.7	Replace	CRA
Total Spare Part Cost									139.77	Surveyor Total		139.77		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									111.82	Final Sur Total		111.82		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	530.00	265	
Total:			530.00	265.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	616.00	446	
Total:			616.00	446.00	




Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

Estimator Assesment(\$)

Surveyor Assesment(\$)

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	111.82	111.82
Total Labour Cost	530.00	265.00
Total Spray Painting	616.00	446.00
Other	0.00	0.00
Overall Total	1,257.82	822.82
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	1,250.00	800.00
Surveyor Approved Amount		800.00
No of Repair Days*	3	2
Remarks	-	L/S REPAIR PHOTO AFTER PAINT.
Surveyor Name		Hwee Jie
Signature		  30/1/19
Survey Date	29/01/2019	<input type="button" value="Save"/> <input type="button" value="Clear"/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 13/03/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB42P
Case Reference Number	BUS/10/18/5020
Registration Date	28/11/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Christopher Daniel
Type of Accident	Side Swipe
Accident Date and Time	11/10/2018 9:46 AM
Accident Reported Date and Time	11/10/2018 1:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100563
Special Instruction to ARC, if any	SMB42P - LEFT FRONT PORTION SLM8509L (TP) - INSURED WITH NTUC
Prepared Date and Time	29/1/2019 4:07 PM
Chassis Number	WEB63442021000114
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$616.00	\$446.00
Total Spare Part Cost	\$111.82	\$111.82
Total Other Cost	\$0.00	(\$142.20)
TOTAL COST	\$1,257.82	\$680.62
Lump Sum Total	\$1,250.00	\$700.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Hwee Jie
ARC / Surveyor Sign Off Date	29/01/2019 4:20 PM	29/01/2019 5:57 PM
Signature		
Remarks		U/S REPAIR PHOTO AFTER PAINT.

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

1301.30



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/03/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$616.00	\$446.00
Total Spray Painting & Panel Beating	\$616.00	\$446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$142.20)
Total Other Costs	\$0.00	(\$142.20)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009700	VE		LAMP,BLINKER:FRONT, LEFT, FOR MB OC 500 LE	1.00	\$155.30	10.00	\$139.77	Replace	Replace
Total					\$155.30		\$139.77		

CRA

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1301-30

Finalized U/s \$700/- 2days.

Three Jie - CLK

g



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19001955/Jqd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 22-03-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLM 8509L	Veh. Inspected	SMB 42P	
Policy No.	5099697038	Coverage (\$)	0.00	
Claim No.	MT/1016992-002	Excess (\$)	0.00	
Assign From		Assign Date	29/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ OC500LE1830H	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WEB63442021000114	Colour	MULTI COLOUR	
Odometer	739524	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	FIRENZA	7 mm	
L/H Front Tyre	275/70 R22.5	FIRENZA	7 mm	
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	7/7 mm	
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/10/2018	Inspection Date	29/01/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 42P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	CRACKED		
	LAMP, BLINKER;FRONT, LEFT, FOR MB OC 500 LE		155.30	155.30
	LESS 10% DISCOUNT		-	-15.53
			155.30	139.77
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		530.00	265.00
	TO PUTTY & RESPRAY.		616.00	446.00
			1,146.00	711.00
GRAND TOTAL			1,301.30	850.77

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			700.00
---	--	--	---------------

Report Ref No. NS/INC19001955/Jqd3e2

ONG HWEE JIE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.