

ASS. REC. BY:

REP: 083/ICR19001962/Gcd3⁵² Special Instruction

Supervisor: CWO Chiang

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of ICR

Date/Time: 30/1/19@10:52am

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFH 9090S Insured: SLM 4539B

at Workshop m/s: Auto Assist Tel: 9746 9644

of 2 Kaki Bukit Ave 2 # 01-33

Policy No: 0999994774 Claim No: 4940415371SG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/01/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{up} H.O.D. Endorsement: _____

Date/Time: 12:17pm@30/1/19 Person Contacted: Randy Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate
	SFH 9090S-C8 / MSG19001958 / Dvd3 DVA: 26/1/19
	SLM 4539B - x

Your password will expire in 13 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 30/1/2019 10:52:02 AM
Attachments:  20190129200028681.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S • A. RAVIDASS

Our ref: SFH 9090 S (iz)

Your ref: SLM 4539 B

29 January 2019

AIG Asia Pacific Insurance Pte Ltd
Singapore

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION
PROTOCOL FOR NIMA CASE
ACCIDENT ON INVOLVING MOTOR VEHICLES SFH 9090 S AND SLM 4539 B
ALONG CTE ON 26 JANUARY 2019**

We act for Ho Wan Sing, the owner of motor vehicle SFH 9090 S who has appointed us to act on his behalf to claim against your insured's vehicle no. SLM 4539 B in regards to the road traffic accident on 26 January 2019.


Please be informed that the said motor vehicle can be inspected at:-

**Auto Assist
2 Kaki Bukit Avenue 2
#01-33 Kaki Bukit AutoHub
Singapore 417212**

Kindly contact Mr Randy at 9746 9644 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,


MR ARULCHELVAN S

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN201330709H

ARULCHELVAN S • A. RAVIDASS

Our ref: SFH 9090 S (iz)

Your ref: SLM 4539 B

29 January 2019

AIG Asia Pacific Insurance Pte Ltd
Singapore

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION
PROTOCOL FOR NIMA CASE
ACCIDENT ON INVOLVING MOTOR VEHICLES SFH 9090 S AND SLM 4539 B
ALONG CTE ON 26 JANUARY 2019**

We act for Ho Wan Sing, the owner of motor vehicle SFH 9090 S who has appointed us to act on his behalf to claim against your insured's vehicle no. SLM 4539 B in regards to the road traffic accident on 26 January 2019.


Please be informed that the said motor vehicle can be inspected at:-

**Auto Assist
2 Kaki Bukit Avenue 2
#01-33 Kaki Bukit AutoHub
Singapore 417212**

Kindly contact Mr Randy at 9746 9644 to make the necessary arrangements.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,


MR ARULCHELVAN S

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/01/2019 14:46
Date Of Accident	26/01/2019 15:45
Exact Location Of Accident	ALONG CTE TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFH9090S
Insured/Policyholder	
Name Of Registered Owner	HO WAN SING
NRIC No	S1301150H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98163867
Alternative Phone No	OFFICE-98163867

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200-1.8 SPORTS COUPE (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P28959017DMA
Cover Note Number	

Driver

Name of Driver	HO SHEN AN CHRISTOPHER
NRIC No	S9490463C
Date Of Birth	14/11/1994
Occupation	INDOOR
Date Of Driving Pass	27/03/2015
Driving Experience	3 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98163867
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	452 SIN MING AVENUE #01-541
Postcode	570452
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to police report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD6724D
Vehicle Make/Model/Colour	TOYOTA ALLION
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM ZHAN KANG
NRIC/Passport Number	S9422751H
Contact Number	91502568
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC8919L
Vehicle Make/Model/Colour HYUNDAI I40
Details Of Properties
Vehicle Category TAXI
Name of Driver TAN CHIA WEI
NRIC/Passport Number S8515623C
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLM4539B
Vehicle Make/Model/Colour TOYOTA PRIUS
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHUA MENG LEE
NRIC/Passport Number S7215489D
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

A = SFH 9090S
B = SLM 4539B
C = SKD 6724D
D = SHC 8915L

The diagram shows four vehicles, labeled A, B, C, and D, positioned in a horizontal line. Each vehicle is represented by a simple rectangular shape with a triangle at the front, indicating its direction of travel. All four vehicles have arrows pointing to the right, suggesting they are moving in the same direction.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A large rectangular area with horizontal lines for describing the accident circumstances.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NIBC/FIN No.:

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SFH9090S		
Vehicle Type:	P10 - Passenger Motor Car		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	MERCEDES BENZ		
Vehicle Model:	C 180		
Chassis No.:	WDD2043312G132358		
Propellant:	Petrol		
Engine No.:	27491030061670		
Engine Capacity:	1595 cc		
Maximum Power Output:	115.0 kW (154 bhp)		
Maximum Laden Weight:	1975 kg		
Unladen Weight:	1505 kg		
Year Of Manufacture:	2013		
Original Registration Date:	26 Nov 2013		
Lifespan Expiry Date:	-		
COE Category:	A - Car (1600cc & below)		
Quota Premium:	\$72,609.00		
COE Expiry Date:	25 Nov 2023		
Road Tax Expiry Date:	25 May 2019		
PARF Eligibility Expiry Date:	25 Nov 2023		
Inspection Due Date:	25 May 2020		
Intended Transfer Date:	11 Feb 2019		
CO2 Emission:	142.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$5,000.00		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1150H
Vehicle Details	
Vehicle No.:	SFH9090S
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	27491030061670
Chassis No.:	WDD2043312G132358
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$33,921.00
Original Registration Date:	26 Nov 2013
First Registration Date:	26 Nov 2013
Transfer Count:	1
Actual ARF Paid:	\$34,490.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2023
PARF Rebate Amount:	\$24,143.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$72,609.00
COE Rebate Amount:	\$34,771.00
Total Rebate Amount:	\$58,914.00

The information contained herein is correct as at 11 Feb 2019

OK

Condition (CQ) (1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched (7) Deformed (8) Shifted (9) Duckled (10) Broken (11) Necessary (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

ACTION (AC)
 (1) Replace (✓) (2) Repair (R) (3) Check (C)
 (4) Not Consistent (NC)

182
 Aug 2005

Rear Portion

Vehicle No: SFH-90905

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper	DD	✓	
1143	993017	Rear Bumper Lower	DD	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	CPV	✓	
1146	992341	Rear Bumper Clips	NET	✓	
1147	992976	Rear Bumper Bracket	CPV	✓	
1148	993068	Rear Bumper Side Retainer	RR	✓	
1149	993045	Rear Bumper Reinforcement	RR	✓	2
1150	992970	Rear Bumper Beam	RT	✓	
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper	CPV	✓	
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	CPV	✓	3
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	RR	✓	4
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim	CPV	✓	
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	RR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	RR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NET	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber	BT	✓	
1179	990382	Bootlid Hinge	CPV	✓	
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel (Fibre)	RR	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe	BT	✓	
1214	993361	Rear Exhaust Mounting	BT	✓	
1215	993358	Rear Exhaust Heat Shield	TN	✓	
1216	995223	Rear LH Chassis Member	BT	✓	
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

Handwritten signature and date: 13/2/09

(10)Shifter (11)Washer (12)Washer (13)Washer (14)Washer (15)Washer (16)Washer (17)Washer (18)Washer (19)Washer (20)Washer

MOTOR CAR (Frt)

ACORN 2015
 (1) Replace (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20)

282

Front Portion

Vehicle No. SFH 99905

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base	GR	✓	
1003	991889	Frt Number Plate Garnish	GR	✓	
1004	991300	Frt Bumper	GR	✓	
1005	992341	Frt Bumper Clips	GR	✓	
1006	991325	Frt Bumper Bracket	ALC	✓	
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	GR	✓	2
1009	991318	Frt Bumper Beam Reinforcement	GR	✓	2
1010	991468	Frt Bumper Sponge	GR	✓	
1011	991427	Frt Bumper Protector	GR	✓	
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille lower			
1014	991301	Frt Bumper Moulding	GR	✓	
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	GR	✓	2
1018	991355	Frt RH Bumper Fog Lamp Cover	GR	✓	
1019	995079	Frt LH Bumper Fog Lamp	GR	✓	
1020	995080	Frt RH Bumper Fog Lamp	GR	✓	
1021	991793	Frt Grille	GR	✓	
1022	991328	Frt Grille Emblem	GR	✓	
1023	991799	Frt Grille Chrome Moulding	GR	✓	
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover	GR	✓	
1027	992416	Horn	GR	✓	
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	GR	✓	
1031	995088	Frt LH Side Lamp	GR	✓	
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem	NO	✓	
1035	990287	Bonnet Lock	ALC	✓	
1036	990285	Bonnet Insulator	BT	✓	
1037	990273	Bonnet Hinge	CR9	✓	
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable	TAI	✓	
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy	BT	✓	
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990123	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling	BT	✓	
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch	GR	✓	
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator	CRU	✓	
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990719	Battery			
1068	990234	Battery Cover			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel	BT	✓	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel	BT	✓	
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991890	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sucker			

RH Headlamp panel
 LH " "

BT ✓
 BT ✓

[Signature]
 13/2/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jan 2019 Edit Reg		30 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	-		
Vehicle Reg. No.:	SFH9090S	Date of Loss:	26/01/2019 00:00 - :59 [62 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4940415371SG	Policy/Cover Note No.:	0999994774 (Comprehensive)
Vehicle Reg. No. (Insured):	SLM4539B	Policy No. (Claimant):	
		Excess:	
Repairer:	Auto Assist Sg () 2 Kakit Bukit Ave 2, #01-33/#02-29, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Jeffrey-SK] Jeffreyayklat.Ng@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/02/2019]		
Claimant's Solicitor:	CHIA S ARUL & LLC - Tel: 67334647		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (31/01/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFH9090S (4940415371SG)
[SLM4539B]
TP**

**Jan 26 2019 12:00AM
[LCRF PTE LTD]
Auto Assist Sg**

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser ▼
Photos/Images						3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
2	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
3	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
4	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
5	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
6	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
7	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
8	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
9	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
10	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
11	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
12	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
13	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
14	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
15	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
16	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
17	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
18	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
19	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
20	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
21	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
22	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
23	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
24	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
25	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
26	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
27	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
28	11/02/19 14:09	General View				Load JPG	<input checked="" type="checkbox"/>
Documentation						1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)				Thumbnail	Print
1	31/01/19 10:22	OI GIA REPORT				Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR19001962/GCD3S2
Date: 14/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994774
Claimant Vehicle No : SFH9090S **Insured Vehicle No :** SLM4539B
 Date of Loss: 26/01/2019 Nature of Claim: TP Claim No: 4940415371SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFH9090S**
 Make & Model: MERCEDES-BENZ C180, 1.8 (A) Engine No: 27491030061670
 Reg. Date: 26/11/2013 (Man. Year: 2013) Chassis No: WDD2043312G132358
 Colour: Grey Odometer: 0 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/01/2019
 Date Inspected: 30/01/2019 Inspected At: Auto Assist Sg
 2 Kakit Bukit Ave 2, #01-33/#02-29
 Singapore 417921
 Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*-F
2	1		*REAR BUMPER LOWER	Dented	0.00 F	*-F
3	1		*REAR BUMPER TOW COVER	Crushed	0.00 F	*-F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
5	1		*REAR BUMPER BRACKET CENTRE	Broken	0.00 F	*-F
6	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*-F
7	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*-F
8	1		*REAR BUMPER SPONGE	Crushed	0.00 F	*-F
9	3		*REAR BUMPER MOULDING	Cut	0.00 F	*-F
10	4		*REVERSE SENSOR	Broken	0.00 F	*-F
11	1		*REAR END PANEL	Dented	0.00 F	*-F
12	1		*REAR END PANEL INNER TRIM	Crushed	0.00 F	*-F
13	1		*REAR LH TAILLAMP	Broken	0.00 F	*-F
14	1		*REAR RH TAILLAMP	Broken	0.00 F	*-F
15	1		*BOOTLID	Dented	0.00 F	*-F
16	1		*BOOTLID EMBLEM	Necessary	0.00 F	*-F
17	1		*BOOTLID LOCK	Bent	0.00 F	*-F
18	1		*BOOTLID RUBBER	Crushed	0.00 F	*-F
19	1		*SPARE TYRE PANEL (FIBRE)	Broken	0.00 F	*-F
20	1		*REAR EXHAUST PIPE	Bent	0.00 F	*-F
21	1		*REAR EXHAUST CHROME PIPE	Bent	0.00 F	*-F
22	1		*REAR EXHAUST MOUNTING	Torn	0.00 F	*-F
23	1		*REAR EXHAUST HEAT SHIELD	Bent	0.00 F	*-F
24	1		*FRT NUMBER PLATE	Broken	0.00 F	*-F
25	1		*FRT NUMBER PLATE BASE	Broken	0.00 F	*-F
26	1		*FRT NUMBER PLATE GARNISH	Broken	0.00 F	*-F
27	1		*FRT BUMPER	Broken	0.00 F	*-F
28	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
29	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*-F
30	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*-F
31	2		*FRT BUMPER REINFORCEMENT BRACKET	Bent	0.00 F	*-F
32	1		*FRT BUMPER SPONGE	Broken	0.00 F	*-F
33	1		*FRT BUMPER GRILLE LOWER	Broken	0.00 F	*-F
34	2		*FRT BUMPER SENSOR	Broken	0.00 F	*-F
35	1		*FRT LH BUMPER FOG LAMP COVER	Broken	0.00 F	*-F
36	1		*FRT RH BUMPER FOG LAMP COVER	Broken	0.00 F	*-F
37	1		*FRT LH BUMPER FOG LAMP	Broken	0.00 F	*-F
38	1		*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*-F
39	1		*FRT GRILLE	Broken	0.00 F	*-F
40	1		*FRT GRILLE EMBLEM	Broken	0.00 F	*-F
41	1		*FRT SUPPORT PANEL CENTRE	Bent	0.00 F	*-F
42	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Broken	0.00 F	*-F
43	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*-F
44	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*-F
45	1		*BONNET	Dented	0.00 F	*-F
46	1		*BONNET EMBLEM	Necessary	0.00 F	*-F
47	1		*BONNET LOCK	Bent	0.00 F	*-F
48	1		*BONNET INSULATOR	Crushed	0.00 F	*-F
49	1		*BONNET RUBBER	Torn	0.00 F	*-F
50	1		*AIR CON CONDENSER	Bent	0.00 F	*-F
51	1		*RADIATOR	Bent	0.00 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
52	1		*RADIATOR FAN ASSY	Broken	0.00 F	*-F	
53	1		*AIR CLEANER HOSE	Crushed	0.00 F	*-F	
54	1		*RH HEADLAMP PANEL	Bent	0.00 F	*-F	
55	1		*LH HEADLAMP PANEL	Bent	0.00 F	*-F	
56	1		*FRT LH FENDER	Bent	0.00 F	*-F	
57	1		*FRT RH FENDER	Bent	0.00 F	*-F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >