

ASS. REP. BY:

REF:

CS3/AIG19001963/Gcd301

Special Instruction:

Surveyor: Chin Lee Yung

ASSIGNMENT (Office)

From (Person): Meimen

Chin Lee Yung

of

AIG

Date/Time:

30/11/19 @ 9.42am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFT 8398Z

Insured:

SKM 5845Y

at Workshop m/s

Y-S Automobile

Tel:

9662 7598

of

Blk 5 Defu Lane 10 # 01-580

Policy No:

2100368254

Claim No:

5072662604SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/01/2019

CA / REV / REP. / REV 24 HRS ^(up)

H.O.D. Endorsement:

Date/Time:

10am @ 30/11/19

Person Contacted:

Peter

Vehicle

IN OUT

Date/Time	Action/Instruction (x) Estimate
	<u>SFT 8398Z - X</u>
	<u>SKM 5845Y - X</u>
	<u>Dismantle: 31/1/2019</u>
	<u>After repair: 4/2/2019</u>

Your password will expire in 13 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: 30/1/2019 9:42:19 AM
Attachments:  SKMBT_C364e19012816380.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Tuesday, January 29, 2019 12:24 PM
To: Md Ishak, Mohd Imran
Cc: Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Azlan, Syazairdina; Mithoosingh, Aashweenjeetkaur; Hor, Yinrul
Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKM5845Y AND SFT8398Z ON 28/01/2019

Dear Sirs,

We refer to the above matter and to your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) William Ng (Allied Auto Appraisal)
- (2) Lee Kok Weng - (Lee Automobile Appraiser Services)
- (3) Lek Boon Hwee (Auto Performance Appraisal)
- (4) Patrick Ng Kong Beng - (Carlink Consultancy)
- (5) Ang Guea Kiang - (CA Appraisal)
- (6) How Andrew - (Prominent Appraiser Service)
- (7) Chang Fuh Keong - (Sincere Appraisal Services)

- (8) Ong Poh Meng - (Aeon Auto Consultants LLP)
- (9) Ng Soon Aik Francis - (Prestige Appraiser Services)
- (10) Ng Soon Chuan Louis - (Prestige Appraiser Services)

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey and kindly contact Mr Peter Yong of Y S Automobile Service, Blk 5 Defu Lane 10 #01-580 Singapore 539186 at mobile no. 9662 7598 for the said arrangement of SFT 8398 Z.

Kindly proceed to do the needful.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 29 Jan 2019, at 11:56 AM, Md Ishak, Mohd Imran <Imran.Ishak@aig.com> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-02-05 11:56 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

<SecureMessageAtt.html>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7168D
Vehicle Details	
Vehicle No.:	SFT8398Z
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 2.0 AUTO
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	3ZRA512882
Chassis No.:	JTDGJ20W205003044
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,003.00
Original Registration Date:	19 Aug 2010
First Registration Date:	19 Aug 2010
Transfer Count:	1
Actual ARF Paid:	\$22,003.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Aug 2020
PARF Rebate Amount:	\$12,101.00
Intended COE Rebate Details	
COE Expiry Date:	18 Aug 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$41,006.00
COE Rebate Amount:	\$6,179.00
Total Rebate Amount:	\$18,280.00

The information contained herein is correct as at 31 Jan 2019

OK

► Wish Used Vehicle List (12 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Toyota Wish 1.8A X	\$29,800	\$12,370 /yr	13-Aug-2010	1,797 cc	-	88 Motor Trading	Availal

S Pass, EP Or LTV Pass Welcome To Loan! In House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approv We Are sgCarMart Premium Dealer! Viewing And Test Drive Availab...

Office No. - 62911187

Mr Ho - 96811390 | Ben - 90913551 | Jeremy - 97625070 | Lek - 87555787

Toyota Wish 2.0A	\$35,800	\$15,160 /yr	20-Sep-2010	1,987 cc	117,200 km	Providence Automobile	Availal
-------------------------	-----------------	--------------	-------------	----------	------------	-----------------------	----------------

Agent Unit! Loan Up To 95%! Meticulously And Diligently Maintained. Absolutely No Repairs Needed. 6 Months Warranty And 1 Free Major Servicing! Witness Firsthand For Yourself How We Perform Major Serv...

Office No. - 67433559

Aizat - 92319670 | Ken - 96353046

Toyota Wish 2.0A (New 10-yr \$57,800 COE)	\$5,780 /yr	27-Jan-2010	1,987 cc	129,247 km	Rexy Motor Trading Company	Availal
--	-------------	-------------	----------	------------	----------------------------	----------------

One Owner. Most Popular Japanese MPV For All Family. BORNEO Unit. Beautiful Paintwork. Ideal For Daily Family Drives Comfortable And Spacious, Perfect For New Coe Renewal. Priced To Sell, See To Believe...

Office No. - 64680082

Yeo - 97482688 | Wayne - 93210015 | David Koh - 94551891 | Desmond - 97323670

Toyota Wish 1.8A X (New 10-yr \$58,800 COE)	\$5,880 /yr	07-Jan-2010	1,797 cc	101,000 km	MS Carz	Availal
--	-------------	-------------	----------	------------	---------	----------------

Option For Without Renew COE Or Renew 5 Years COE. One Of The Most Popular MVP, Known For Reliability And Fuel Efficiency! Clean And Tidy Interior. Trade In Welcome! Bank And In-House Finance Availabl...

Office No. - -

William - 83186606 | Jack - 98506880 | CK - 96920330

Toyota Wish 2.0A (New 10-yr \$58,800 COE)	\$5,880 /yr	14-Jan-2010	1,987 cc	145,000 km	Tim Bock Enterprise	Availal
--	-------------	-------------	----------	------------	---------------------	----------------

1 Owner! Up To 90% Loan. Most Popular Japanese Mpv For All Family. 1 Owner. Borneo Unit. Nice Paintwork And Very Well Maintained. Call Now Before It's Gone.

Office No. - 64595611

Richard - 98197977 | Raymond - 91596282

Toyota Wish 2.0A (New 10-yr \$58,800 COE)	\$5,880 /yr	26-Feb-2010	1,987 cc	83,000 km	Latitude Auto Trading	Availal
--	-------------	-------------	----------	-----------	-----------------------	----------------

Owned By A Careful Lady Teacher Owner. Very Well Maintained. Low Usage. 100% Accident-Free. All Wear And Tear Parts Replaced. No Repairs Needed! Borneo Motors Unit. This 2.0L Is Way More Powerful Than...

Office No. - 67410286

Zac Chua - 96665544 | Dave Lee - 92229955

Toyota Wish 2.0A (New 10-yr \$59,800 COE)	\$5,980 /yr	18-Mar-2010	1,987 cc	106,909 km		Availal
--	-------------	-------------	----------	------------	--	----------------

Most Popular Japanese MPV For All Family. 1 Owner. BORNEO Unit. Beautiful Paintwork. Very Well Serviced And Maintained, Perfect For New Coe Renewal, Viewing By Appointment Only.

Office No. - -

Mr Teo - 91070316

Toyota Wish 2.0A (New 10-yr \$60,800 COE)	\$6,080 /yr	15-Jan-2010	1,987 cc	-	Universe Motoring	Availal
--	-------------	-------------	----------	---	-------------------	----------------

Office No. - 64632929

Andy Ng - 92980877 | Alan Ang - 90476234 | John Wong - 82684836

Toyota Wish 1.8A X (New 10-yr \$61,700 COE)	\$6,160 /yr	08-Jan-2010	1,797 cc	108,588 km	EU Automobile Pte Ltd	Availal
--	-------------	-------------	----------	------------	-----------------------	----------------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/01/2019 15:00
Date Of Accident	28/01/2019 13:30
Exact Location Of Accident	JUNCTION OF YISHUN AVE 2/LENTOR AVE/YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFT8398Z
Insured/Policyholder	
Name Of Registered Owner	PEH ENG HENG
NRIC No	S7127168D
Email Address	ERICPEH71@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98427156
Alternative Phone No	OTHERS-98427156

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MY004307-R05
Cover Note Number	19/08/2018 TO 18/08/2019

Driver

Name of Driver	PEH ENG HENG
NRIC No	S7127168D
Date Of Birth	06/08/1971
Occupation	INDOOR
Date Of Driving Pass	12/07/1991
Driving Experience	27 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98427156
Fax Number	
Contact Number	OTHERS-98427156
EEmail Address	ERICPEH71@GMAIL.COM

Address APT BLK 334 HOUGANG AVE 5 #05-264 (S) 530334
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions AFTER RAIN
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : RYAN PEH
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER WITH ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKM5845Y
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver JULIE ZHENG LIXIA
 NRIC/Passport Number
 Contact Number 94513086
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 2

Passenger 1

NAME: : PASSENGER

GENDER: : FEMALE

DETAILS OF INJURED PERSON 1

Name	FEMALE PASSENGER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKM5845Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	


SKETCH PLAN

A: SFT8398Z

B: SKM5845Y



Yishu ave 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car SFT8398Z was stationary at the slip road of Lenta ave waiting for the incoming traffic to clear.

Suddenly I felt an impact from my rear then realized was hit by a car SKM5845Y. There was female passenger from SKM5845Y looks like not feeling well & I advise her bring her to hospital to check.

Insurance Co. Tatiao Motor

Vehicle No. SFT8398Z Date of Accident 28/1/19

Reporting Only

Own Damage Claim

Third Party Claim

Other Workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28/1/19
15:20PM

Driver's Signature

(If driver is not the policyholder)
Date & Time: 28/1/19
15:20PM



Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

(1)Used (2)Denied (3)Distorted (4)Cracked (5)Cut (6)Scratched
 (7)Deformed (8)Shifted (9)Buckled (10)Broken (11)Necessary
 (12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

ACTION(AC)
 (1)Replace (✓) (2)Repair(X) (3)Check (0)
 (4)Not Consistent (NC)

Aug 2005

Rear Portion

Vehicle No: **SFT 8398Z**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	UP	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	KR	✓	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	UP	✓	
1159	993327	Rear End Panel	UP	✓	
1160	993339	Rear End Panel Top Garnish	UP	✓	
1161	993333	Rear End Panel Inner Trim	UP	✓	
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	KR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem	DD	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector	RP	✓	
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock	NEC	✓	
1198	994651	Tailgate Rubber	BT	✓	
1199	994611	Tailgate Hinge	RU	✓	
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
993069	990247	Sticker			

[Signature]
 11/3/2009

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2019 Edit Reg		30 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIN YONG , ID: S7484521E								
Main Claimant:	PEH ENG HENG								
Vehicle Reg. No.:	SFT8398Z	Date of Loss:	28/01/2019 13:00 - :59 [101 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5072662604SG	Policy/Cover Note No.:	2100368254 (Comprehensive) Coverage: 20/03/2018 - 19/03/2019						
Vehicle Reg. No. (Insured):	SKM5845Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Ys Automobiles Services (HQ) Blk 5 Defu Lane 10 #01-580, 539186 Defu Lane - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (31/01/2019): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFT8398Z (5072662604SG)
[SKM5845Y]
TP
PEH ENG HENG
Jan 28 2019 1:00PM
[LIN YONG]
Ys Automobiles Services

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
2	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
3	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
4	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
5	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
6	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
7	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
8	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
9	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
10	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
11	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
12	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
13	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
14	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
15	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
16	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
17	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
18	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
19	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
20	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
21	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
22	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
23	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
24	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
25	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
26	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
27	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
28	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
29	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
30	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
31	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
32	11/02/19 15:06	General View							Load JPG <input checked="" type="checkbox"/>		
33	11/02/19 15:07	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
34	11/02/19 15:07	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
35	11/02/19 15:07	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
36	11/02/19 15:07	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		
37	11/02/19 15:07	Photographs of Damaged Parts							Load JPG <input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	11/02/19 15:07	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	13/02/19 18:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/01/19 10:16	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19001963/GCD3E2

Date: 14/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100368254
Claimant Vehicle No : SFT8398Z	Insured Vehicle No : SKM5845Y
Date of Loss: 28/01/2019	Nature of Claim: TP Claim No: 5072662604SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFT8398Z	Engine No: 3ZRA512882
Make & Model: TOYOTA WISH, 2.0 (A)	Chassis No: JTDGJ20W205003044
Reg. Date: 19/08/2010 (Man. Year: 2010)	Odometer: 245978 km
Colour: Brown	Engine Capacity: 1987 cc
Market Value/New Car Price: N/A	Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No
	Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15	Rear Tyre Size: 195/65 R15
Front Left Side: Toyo 6 mm	Rear Left Side: Toyo 6 mm
Front Right Side: Toyo 6 mm	Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/01/2019	Inspected At: Ys Automobiles Services (HQ)
Date Inspected: 30/01/2019	Blk 5 Defu Lane 10 #01-580
	Singapore 539186
Estimated Period of Repair: 6.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REVERSE SENSOR	Broken	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Crumpled	0.00 F	*- F
7	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
8	1		*TAILGATE	Dented	0.00 F	*- F
9	1		*TAILGATE LAMP	Broken	0.00 F	*- F
10	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
11	1		*TAILGATE LOCK	Bent	0.00 F	*- F
12	1		*TAILGATE RUBBER	Crumpled	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >