

REF: 193/MSL/1801672/T14d3-1
 ASSIGNMENT (Office)
 From (Person): **Taufikah Jasmine Lok** of **MSL** Date/Time: **28/01/2019**
 Estimated Cost: **USD 0**

OD / (P) / WS / TP / RES / OD RES / EVA / INV / MV / CS
 To Impact Vehicle No: **XD 147E** Insured: **AGB 8744A**
 at Workplace: **Yee Keng Motor** Tel: **9780 8928**
 of: **No 14 Penjuru Rd**
 Policy No: **A28806552mkt** Claim No: **570042**
 Sum Insured: **Excise**
 Make of Veh: **D.O.A** **044092016**
 (Client's Record)
 CA / REV / REP / REV 24 HRS Wp: **Mr. Hiew** Vehicle: **IN/OUT**
 Date/Time: **13/05/2018 11:47am** Person Conducted:

Date/Time	Action/Instruction (X) Estimate
	13/05/2018 11:47am 11/05/2018 11/05/2018
	13/05/2018
	Demanded: 15/9/2018
	Submit.
	lump sum \$4800/- (Red. 2250; 31%) 4days
	4/5 \$4600, 4days


5/3/2019

ASSOCIATION

24/9/2018

10

Lump Sum / I.B. 11.5

Intercept	S
1.000	0.000
0.999	0.000
0.998	0.000
0.997	0.000
0.996	0.000
0.995	0.000
0.994	0.000
0.993	0.000
0.992	0.000
0.991	0.000
0.990	0.000
0.989	0.000
0.988	0.000
0.987	0.000
0.986	0.000
0.985	0.000
0.984	0.000
0.983	0.000
0.982	0.000
0.981	0.000
0.980	0.000
0.979	0.000
0.978	0.000
0.977	0.000
0.976	0.000
0.975	0.000
0.974	0.000
0.973	0.000
0.972	0.000
0.971	0.000
0.970	0.000
0.969	0.000
0.968	0.000
0.967	0.000
0.966	0.000
0.965	0.000
0.964	0.000
0.963	0.000
0.962	0.000
0.961	0.000
0.960	0.000
0.959	0.000
0.958	0.000
0.957	0.000
0.956	0.000
0.955	0.000
0.954	0.000
0.953	0.000
0.952	0.000
0.951	0.000
0.950	0.000
0.949	0.000
0.948	0.000
0.947	0.000
0.946	0.000
0.945	0.000
0.944	0.000
0.943	0.000
0.942	0.000
0.941	0.000
0.940	0.000
0.939	0.000
0.938	0.000
0.937	0.000
0.936	0.000
0.935	0.000
0.934	0.000
0.933	0.000
0.932	0.000
0.931	0.000
0.930	0.000
0.929	0.000
0.928	0.000
0.927	0.000
0.926	0.000
0.925	0.000
0.924	0.000
0.923	0.000
0.922	0.000
0.921	0.000
0.920	0.000
0.919	0.000
0.918	0.000
0.917	0.000
0.916	0.000
0.915	0.000
0.914	0.000
0.913	0.000
0.912	0.000
0.911	0.000
0.910	0.000
0.909	0.000
0.908	0.000
0.907	0.000
0.906	0.000
0.905	0.000
0.904	0.000
0.903	0.000
0.902	0.000
0.901	0.000
0.900	0.000
0.899	0.000
0.898	0.000
0.897	0.000
0.896	0.000
0.895	0.000
0.894	0.000
0.893	0.000
0.892	0.000
0.891	0.000
0.890	0.000
0.889	0.000
0.888	0.000
0.887	0.000
0.886	0.000
0.885	0.000
0.884	0.000
0.883	0.000
0.882	0.000
0.881	0.000
0.880	0.000
0.879	0.000
0.878	0.000
0.877	0.000
0.876	0.000
0.875	0.000
0.874	0.000
0.873	0.000
0.872	0.000
0.871	0.000
0.870	0.000
0.869	0.000
0.868	0.000
0.867	0.000
0.866	0.000
0.865	0.000
0.864	0.000
0.863	0.000
0.862	0.000
0.861	0.000

GURDEEP SINGH SIKHON
CHIA KOK SENG
REY FOO JONG HAN
GOH LAM CHIAN
NAVINDER SINGH
P. PADMAN
KWEH SOON HAN
PRADEEP KUMAR GOBIND
HUE JAPET
MUNIRAH BINTE MYDIN
LIM YUN HENG
SHANEN SIO NANDO SIVA DAS

KSCGP
J U R I S L L P

*Celebrating 25 Years of
Professional and Personalised
Legal Service*

REG / CS / PAY / FA

07 JAN 2019

MAIN OFFICE:

10 Hoe Chiang Road, #13-03A
Keppel Towers,
Singapore 089315
Tel: 6538 3611
Fax: 6538 3708

Website: www.kscgp.com

(Fax/Email not for service of court documents)

Registered in Singapore with limited liability

as a Limited Liability Partnership

Registration Number T10LL1855L

DID: 3152 0987

Email: motor@kscgp.com

Your Ref : GBB 8744A

Our Ref : GS/18/4897/YK/sy/cl

Date : 4 January 2019

MSIG Insurance (Singapore) Pte. Ltd.
16 Raffles Quay
#24-01 Hong Leong Building.
Singapore 048581

BY HAND

Dear Sirs,

HENG LIM SERVICES PTE. LTD.

C/o 10 Hoe Chiang Road #13-03A Keppel Towers Singapore 089315

ACCIDENT INVOLVING XD 147E AND GBB 8744A OUTSIDE 20 GUL WAY ON
04.09.2018

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 04 September 2018 outside 20 Gul Way, involving our client's motor vehicle bearing registration number XD 147E and the motor vehicle bearing registration number GBB 8744A, which was insured by you at the material time.

We are instructed that the accident was caused by the negligent driving and/or management of the authorised driver of GBB 8744A. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

(1)	Cost of repairs	-	\$	7,050.00
(2)	Loss of use (\$300 per day x 8 days)	-	\$	2,400.00
(3)	Survey fees	-	\$	700.00
(4)	LTA search	-	\$	10.00
(5)	GIA search	-	\$	29.00
(6)	Incidentals	-	\$	100.00
(7)	Costs	-	\$	900.00
(8)	GST on items (6) & (7)	-	\$	70.00
				\$ 11,259.00

BRANCH: PRIVATE PROPERTY CONVEYANCING

490 Lorong 6 Toa Payoh Biz 3 Lobby 2
#09-18 HDB Hub
Singapore 310490
Tel: 6591 7696 Fax: 6256 1825

BRANCH: HDB CONVEYANCING

490 Lorong 6 Toa Payoh Biz 3 Lobby 2
#09-18 HDB Hub
Singapore 310490
Tel: 6591 7696 Fax: 6256 1409

BRANCH: SHIPPING, ADMIRALTY & COMMERCIAL

62 Arab Street #03-01 & #03-02
Singapore 199768
Tel: 6634 1348 Fax: 6634 1358

BRANCH: CORPORATE & LITIGATION

81 Robinson Road
#15-02 Robinson Centre
Singapore 068893
Tel: 6817 8795 Fax: 6224 1612

The information contained in this letter / facsimile message is CONFIDENTIAL and may also be LEGALLY PRIVILEGED, intended only for the individual or entity named above. If you are not the intended recipient, you are hereby notified that any use, revelation, dissemination, distribution or copying of this document is strictly prohibited. If you have received this document in error, please notify us immediately by telephone (call the number above) and destroy the original message.

Mr
See Puyland does in
Kumar
26/1/19

A copy each of the supporting documents are enclosed.

S/NO.	AVAILABLE DOCS	PARTICULARS
<u>Client's Documents</u>		
1.	05.09.2018, 04.09.2018	GIA Statement / Traffic Police report
2.		Witness(es)-Statement
3.		Accident-site photographs
4.		Video footage / CCTV / CD recording
5.	30.11.2018	Repair bill / invoice / Excess Tax invoice
6.		Rental bill / invoice and agreement / receipt
7.		Vehicle Entry Permit receipt / E-day license for off-peak vehicle
8.		Towing fees / receipt (Singapore / Malaysia)
9.		Client sold off vehicle and produce letter from LTA
10.		Spare Part Ordering Form
11.		Levy at Custom / receipts
12.	30.11.2018	Survey invoice and surveyor's report
13.	30.11.2018	32 Original / Copies of damage photographs
14.		Enquire PARF / GOE Rebate for Registered Vehicle
15.		Enquire Transfer fee
16.		Certificate of Insurance / Motor Cover Note / New Policy Schedule / Registration Card / Grant / Road Tax
17.	11.09.2018, 12.09.2018	Pre-repair Inspection Notices
18.		Traffic Police investigation results
19.		Estimated agreement between surveyor and repairer
20.	02.01.2019, 03.01.2019	Tax invoices and search results from General Insurance Association of Singapore (GIA) and Traffic Police search fees
<u>Third Party's Documents</u>		
21.	07.09.2018, 05.09.2018	GIA Statement / Traffic Police report
22.		Admission Note
23.	10.09.2018	LTA search / receipt / tax invoice
24.		Malaysia Vehicles Searches / service
25.		RCB / ACRA search
26.		Enhanced Individual search / receipt
27.		Property tax search / receipt
<u>Others (Apply only in chain collisions and/or any other documents)</u>		
28.		

We have, on 11 September 2018 and 12 September 2018, notified you of the accident and a pre-repair inspection of our client's motor vehicle was carried out by the appointed surveyors.

Subject to our client's instructions, please confirm in writing within 7 days hereof if you or your insured wish to inspect our client's vehicle or conduct a second re-inspection.

Please note that you or your insured should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no

alternative but to commence proceedings against your insured without further notice to you or your insured. In this event, you will be liable for any and all legal costs incurred.

Please also note that if your insured has a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter, which we will then forward to our client and/or the insurers for consideration on a without prejudice basis.

For avoidance of doubt, kindly note that this claim is made without prejudice to our client's personal injury claim.

Yours faithfully,



(Main Office)

Enc.

Cc client

Cc owner – Harvest Building Products Pte. Ltd.

Cc driver – Lim Jit Seng

YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road, Singapore 609125
TEL/FAX: 62620218 | MOBILE: 97808928

Date:

PROFORMA INVOICE

DATE: 30 November 2018

VEHICLE NO.: XD 147 E

MAKE/MODEL:

NISSAN CKB45ABTN2

HENG LIM SERVICES PTE LTD
C/O 14 Penjuru Road
Singapore 609125

FINAL REPAIR BILL FOR VEHICLE NO. XD 147 E

Lump sum repair \$7,050.00nett.

Your Ref : GBB 8744A
Our Ref : XD147E/YK/sy/wl
Date : 11 September 2018

Fax : 6538 3708
Tel : 3152 0979
Email : accident@kscgp.com

MSIG Insurance (Singapore) Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 4 SEPTEMBER 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We are instructed by the owner of XD 147E to notify you of a road traffic accident on 4 September 2018 at about 11.05am along Road 1 Gul Way involving our client's vehicle registration number XD 147E and vehicle registration number **GBB 8744A** which was insured by you at the material time. A copy of the Singapore accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

NB. Any settlement or offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude client's driver/passenger from claiming injury-related damages arising from this accident.

Yours faithfully,

f. SY

Enc.

Your Ref : GBB 8744A
Our Ref : XD147E/YK/sy/wl
Date : 12 September 2018

Fax : 6538 3708
Tel : 3152 0979
Email : accident@kscgp.com

MSIG Insurance (Singapore) Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 4 SEPTEMBER 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email on 12 September 2018.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Foo Philip	Precision Appraisal Services
2.	Ronald Ng	Precision Appraisal Services
3.	Lee Kok Weng	Lee Automobile Appraisals Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Yee Keong Motor Engineering
No. 14 Penjuru Road
Singapore 609125

Contact Person/Tel : Mr Hiew (H/p: 9780 8928)

Yours faithfully,

f. SY

Your Ref : GBB 8744A

Our Ref : XD147E/YK/sy/wl

Date : 12 September 2018

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of
_____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post - Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-19-000795

Date of Request: 02/01/2019

Your Ref No: GS/18/4897/YK/SY/CL

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 04/09/2018
Place of Accident: OUTSIDE 20 GUL WAY
Client Vehicle No: XD147E

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
GBB8744A	GUL WAY	04/09/2018 11:10

Thank You,

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-000795

Date of Request: 02/01/2019

Your Ref No: GS/18/4897/YK/SY/CL

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:Date of Accident: 04/09/2018
Place of Accident: OUTSIDE 20 GUL WAY
Client Vehicle No: XD147E

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-000883

Date of Request: 03/01/2019

Your Ref No: GS/18/4897/YK/SY/CL

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Date of Accident: 04/09/2018
Vehicle No: XD147E
Place of Accident: OUTSIDE 20 GUL WAY
Involving Vehicle No: GBB8744A

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GBB8744A	OUTSIDE 20 GUL WAY	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Enquire Vehicle & Owner Information (Vehicle No. GBB8744A As At 04 Sep 2018 / 11:05:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: XD147E/YK/SY

Current Owner Details

Owner ID Type: Company

Owner ID: 200914S31R

Owner Name: HARVEST BUILDING PRODUCTS PTE. LTD.

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House No.: 61

Registered Street Name: WOODLANDS INDUSTRIAL PARK E9

Registered Unit No.: # 06 - 05

Registered Building Name: E9 PREMIUM

Registered Postal Code: 757047

Current Vehicle Details

Vehicle No.: GBB8744A

Make Description/Model: TOYOTA / DYNA 150 MANUAL 3SEATER

Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

PRECISION APPRAISAL SERVICES



Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 6444 4886 Company Registration No. 53139926E

To:

HENG LIM SERVICES PTE LTD

C/O 14 Penjuru Road

Singapore 609125

Invoice No.: 181119

DATE : 30 November 2018

<u>DESCRIPTION</u>		AMOUNT
Vehicle Registration No. : XD 147 E		\$700.00
Type of Claims : Third Party Claims		
Our Reference No. : PAS/YK/181119/TP		
Your Reference No. : -		
Inspection Report Fees : (including transportation charges & photographs)		
Reinspection Report Fees : -		
Transportation Charges : -		
Additional Photographs : -		
Others (Specify) : -		
DOLLARS	SEVEN HUNDRED ONLY	TOTAL: \$700.00



PRECISION APPRAISAL SERVICES

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

HENG LIM SERVICES PTE LTD
C/O 14 Penjuru Road
Singapore 609125

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As above
Accident Date : 04 September 2018
Assignment Date : 13 September 2018
Inspection Date : 13 September 2018
Our Reference No. : PAS/YK/181119/TP

Inspection Report Date : 30 November 2018

Workshop Name :

YEE KEONG MOTOR ENGINEERING

Inspection Address :

14 Penjuru Road Singapore 609125

PARTICULARS OF VEHICLE

Registration No. : XD 147 E
Make/Model : NISSAN CKB45ABTN2
Yr of Manuf/Regn : 2005 / 2006
Carrying Capacity : -
Chassis No. : CKB45ABT00647
Engine No. : PF6169755C
Colour : Metallic Blue
Class : Goods (Prime Mover)

Mileage : 7171722 Km/h
Radio/Cassette : Fitted
CD Disc Player : Fitted
Air Conditioner : Fitted
Clock : Fitted
Seat Belt : Fitted
Wing Mirror Other : Fitted
Accessories : Fitted

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent : None
Eng Modifications

VEHICLE VALUE

Market Value : -

Wreck Value (Part) : -

TYRE SIZE & CONDITION

Front N/s Size : 295/80R22.5 80 %
Make : Falken
Rear N/s size : 295/80R22.5 80 %
Make : Akina
Spare Size : 295/80R22.5 80 %
Make : Akina

Front O/s Size : 295/80R22.5 80 %
Make : Falken
Rear O/s Size : 295/80R22.5 80 %
Make : Akina
Spare Size :
Make :

Jack & Tools : Intact/Missing

Type of Wheel Rims: Standard

Note: The above percentage % represent the estimated remaining tyre threads.

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/Adjusters Cargo Surveyors & Licensed Appraisers




VEHICLE REGISTRATION NO. : XD 147 E **APPENDIX A**

POINT OF IMPACT

Direction of impact/damage marked (→) (X)

The vehicle sustained impact on its O/s Front Portion. (see Diagram B)



GENERAL DESCRIPTION OF DAMAGES

Parts damaged were :

The front o/s door and wheel arch garnish, front o/s wheel rim and arch, front o/s step panel were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 13/09/2018 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s Yee Keong Motor Engineering as per attached Appraisal Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$ 7,050.00 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Spares Parts	: 8814	38	6291	19
Towing Charges	: -	-	-	-
PB Labour Charges	: 1400	00	980	00
Others Misc Charges	: 510	00	350	00
Paintwork	: 1600	00	1200	00
Total	: \$ 12324	38	\$ 8821	19

Under normal circumstances, the duration of repairs should not exceed Four (04) days excluding Pre - Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame & Public Holidays

Attached photographs taken during inspection Thirty - Two (32) Photographs

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 14/09/2018, we examined the extent of damages
3. On 18/09/2018, we examined the repaired vehicle.

Yours Faithfully



TF NG PHILIP FOO
ACII CAE, AMIMI
AIAME, AMSAE-A
Licensed Appraiser/Adjuster

Inspection Report Date: 30 November 2018

VEHICLE REGN NO : XD 147 E
 OUR REFERENCE : PAS/YK/181119/TP
 INSPECTION REPORT DATE: 30-Nov-18

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO: 1

S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
		PARTS SUPPLY - LIST ITEMS		\$ cts	\$ cts
1	1pc	Front o/s step panel	Badly Dented	684.05	684.05
2	1pc	Front o/s step alloy lower	Cracked	275.50	275.50
3	1pc	Front o/s lower step garnish	Torn	295.00	295.00
4	1pc	Front o/s door	Badly Dented	4720.20	4720.20
5	2pcs	Front o/s door hinge@\$206	Serviceable	412.00	-
			5 11470	6386.75	5974.75
		Less:30% discount	2129	-	1792.42
				6386.75	4182.33
		NETT ITEMS			
1	1pc	Front o/s door rubber	Torn	228.00	228.00
2	1pc	Front o/s door lamp	Serviceable	84.45	-
3	1pc	Front o/s door 'UD' lamp	Cracked	88.20	88.20
4	1pc	Front o/s door inner lock	Bent	338.24	338.24
5	1pc	Front o/s door wheel arch garnish	Cracked	422.18	422.18
6	1pc	Front o/s wheel rim	Badly Dented	848.22	848.22
7	1pc	Front o/s wheel rim cap	Dented	102.12	102.12
8	1pc	Front o/s wheel mudflap	Defaced	248.22	248.22
9	1pc	Front o/s door 'UD' emblem	Necessary	68.00	68.00
			840.52	2427.63	2343.18
		Less:10% discount	756.47	-	234.32
				2427.63	2108.86
		Total Spare Parts		8814.38	6291.19
		LABOUR & MISC. CHARGES			
1		Remove the necessary affected parts, straighten front o/s wheel arch panel and replace parts		1400.00	980.00
2		Putty & Spraypaint		1600.00	1200.00
3		Check electrical		80.00	50.00
4		Rewrite door lettering		80.00	50.00
5		Tuff Kote		100.00	60.00
6		Remove and refit front o/s door parts		100.00	80.00
7		Reset wheel alignment		100.00	80.00
8		Replace front o/s wheel rim & tyre and balancing		50.00	30.00
		Note: Recommended lump sum repair at \$7,050.00nett			1280
SUB / GRAND TOTAL				12324.38	8821.19

PRECISION APPRAISAL SERVICES



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	05/09/2018 16:13
Date Of Accident	04/09/2018 11:05
Exact Location Of Accident	OUTSIDE 20 GUL WAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XD147E
Insured/Policyholder	
Name Of Registered Owner	HENG LIM SERVICES PTE LTD
Co Reg No	200802401H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81616722
Alternative Phone No	OFFICE-62696878
Vehicle Particulars	
Manufacturer	NISSAN
Model	CKB45ABTN2-12.5 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27450516TMV
Cover Note Number	
Driver	
Name of Driver	TONG LIXIN
Passport No/FIN	G2437433K
Date Of Birth	25/03/1985
Occupation	OUTDOOR
Date Of Driving Pass	15/08/2014
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86788986
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	N/A
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE HEADQUARTERS
Police Station Address	ROAD: 10 UBI AVENUE 3 SINGAPORE , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT NO: T/20180904/2089

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB8744A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN DRIVER

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBB8744A

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Document: SKETCHPLANFORM_V3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report No: 7/20180904/2019.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☐ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other works hop
☒ For record purpose
 Policy No. _____
 Insurer MSIG Veh.No. XD147E



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1967 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1995 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.S.301

COMMERCIAL VEHICLE - TP

Goods Carrying Vehicle - Sch II

Third Party

Certificate No. B 27450516 TMV

1. Index Mark and Registration Number of Vehicle

XD147E

2. Name of Policyholder

Heng Lim Services Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act

13/02/2018

4. Date of Expiry of Insurance

12/02/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use in connection with the Policyholder's business.
Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
Use for social domestic and pleasure purposes.

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.
- (3) Use for the carriage of passengers for hire or reward.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence No. **G 2437 433 K**

Name: **TONG LIXIN**

Date of Birth: **25 Mar 1985**

Issue Date: **09 Jul 2014**

Valid Till: **08 Jul 2019**

002323193H



WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer: **HENG LIM SERVICES PTE. LTD.**

Sector: **MANUFACTURING**

Name: **TONG LIXIN**

Occupation: **DRIVER**

Work Permit No.: **0 78107327**


Date of Application: **03-12-2017**

Date of Issue: **14-12-2017**

Date of Expiry: **03-12-2019**

0 78107327

L8513543



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

EFFECTIVE DATE

Class 3 - Motor vehicle < 3500 kg with not more than 7 passengers, exclusive of the driver, and motor tractors < 3500 kg **09 Jul 2014**

Class 4 - Heavy motor cars and motor tractors > 3500 kg **18 Apr 2014**

G2437433K

S / No. 9000208155

Licence No: G2437433K

NP 438A



VISIT PASS
Immigration Regulations

Name: **TONG LIXIN**

Date of Birth: **25-03-1985** Sex: **M** Nationality: **CHINESE**

Pass: **G2437433K** Date of Issue: **14-12-2017** Date of Expiry: **03-12-2019**

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



05-09-18;16:19 ;

1/ 2



**SINGAPORE
POLICE FORCE**



T/20180904/2089

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180904/2089

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/09/2018 15:52	Vide Report No.: J/20180904/0086	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: TONG LIXIN			Address: 77A JOO KOON CIRCLE SINGAPORE 629098		
ID Type / ID No.: FIN NO / G2437433K			Contact No.: Home/Office: Mobile: 86788986		
Nationality:			Email:		
Sex: Male	Age: 33	Date of Birth: 25/03/1985	Type of Informant: Driver		
Race:			Language:		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: 3,4 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/09/2018 11:10	Type of Location: T-Junction
Location: Along Road-1 GUL WAY BLK 19 GUL WAY SINGAPORE 629195				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBB8744A	Lorry					0
XD147E	PRIME MOVER					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

05-09-18;16:54 ;

1/ 1


**SINGAPORE
POLICE FORCE**


T/20180904/2089

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180904/2089

CONTINUATION OF REPORT

Driver			
Name	TONG LIXIN	ID No.	G2437433K
Related Vehicle	XD147E (PRIME MOVER)	Contact No.	86788986
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE DATE, TIME AND LOCATION MENTION ABOVE

THE ROAD SURFACE WAS WET AND THE TRAFFIC FLOW WAS NORMAL, I WAS DRIVING ALONG GUL WAY. I WAS EXITING FROM A MINOR LANE FROM THE SIDE OF THE ROAD. BEFORE ENTERING INTO THE MAJOR LANE, I STOP MY VEHICLE AND CHECK FOR ONCOMING VEHICLE. THERE WAS 2 VEHICLE IN A STATIONARY POSITION, THAT I PROCCED FORWARD INTO THE LANE. WHEN I WAS ENTERING INTO THE 2 LANE SUDDENLY THE LORRY FROM MY RIGHT SIDE COLLIDED ON MY VEHICLE. THE IMPACT WAS NEA R TO THE FRONT RIGHT TIRE AREA. I EXITED MY VEHICLE AND CHECKED ON THE DRIVER AND HE INFROM ME THAT HE INJURED LEFT LEG PAIN. I CALLED FOR THE AMBULANCE AND INFORM MY COMPANY. WE WAITED FOR THE AMBULANCE AND TRAFFIC POLICE.

THAT'S ALL

05-09-18:16:19 ;

2/ 2



**SINGAPORE
POLICE FORCE**



T/20180904/2089

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180904/2089

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
KHALED AMR HASSAN MOHSEN

Signature Of Interpreter:
SC/CPL MARCUS /
S9409296E

Officer In Charge Of Case:
TP / GIT /
Staff Sgt MOHAMED SUFIAN BIN SUDIN
Contact No.: 65476367

Authentication Stamp
NP188

Signature Of Informant:

Date/Time:
04/09/2018 15:52



**SINGAPORE
POLICE FORCE**

Classification Of Case:



Signature:

**SINGAPORE
POLICE FORCE**

Signature:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 07/09/2018 10:39
Date Of Accident 04/09/2018 11:10
Exact Location Of Accident GUL WAY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBB8744A
Insured/Policyholder
Name Of Registered Owner HARVEST BUILDING PRODUCTS PTE LTD
Co Reg No 200914531R
Email Address LILIAN.FOO@HBP.COM.SG
Mobile Phone No (LOCAL) +65-96447794
Alternative Phone No Office-63622608

Vehicle Particulars

Manufacturer TOYOTA
Model DYNA 150 MANUAL 3SEATER-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number A28806552MKC
Cover Note Number

Driver

Name of Driver LIM JIT SENG
NRIC No S6822975H
Date Of Birth 17/06/1968
Occupation INDOOR
Date Of Driving Pass 18/08/1988
Driving Experience 30 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-94874026

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 417 ANG MO KIO AVE 10 #09-1011
Postcode	560417
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	AFTER RAIN
Road Surface	DAMP

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : WORKER Gender: : Male

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD147E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LIM JIT SENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBB8744A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

(X)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Shuman

7/9 @ 10:40

SKETCH PLAN



A: GBB 8744A

B: XD 147E

Gul Way

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

(X)

Policyholder's Signature
Date & Time:

Company Chop (if applicable)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Shuman



7/9 @ 10 AM

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20180905/2110

1 of 3

Report No. T/20180905/2110

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/09/2018 16:21	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: LIM JIT SENG			Address: 417 ANG MO KIO AVENUE 10 #09-1011 TECK GHEE HEARTLANDS SINGAPORE 560417		
ID Type / ID No.: NRIC NO / S6822975H			Contact No.: Home/Office: Mobile: 94874026		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 50	Date of Birth: 17/06/1968	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 04/09/2018 11:10	Type of Location:
Location: Along Road 1 GUL WAY				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBB8744A	Lorry					1
XD147E						0



**SINGAPORE
POLICE FORCE**



T/20180905/2110

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180905/2110

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE TIME AND LOCATION

I WAS GOING STRAIGHT ON THE 2-LANE 2-WAY ROAD WITH 1 PASSENGER. I WAS GOING STRAIGHT WHEN SUDDENLY A LORRY(XD147E) CAME OUT FROM A FACTORY ON MY LEFT. THE LORRY WANTED TO TURN RIGHT. I COULD NOT STOP IN TIME AND COLLIDED INTO THE RIGHT SIDE OF THE LORRY. POLICE AND AMBULANCE CAME. MY PASSENGER AND I WAS CONVEYED TO NG TENG FONG GENERAL HOSPITAL WHERE I WAS DISCHARGED THE SAME DAY AND RECEIVED 6-DAYS MC.



**SINGAPORE
POLICE FORCE**



T/20180905/2110

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180905/2110

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
MUHAMMAD SYUKRI BIN ABU BAKAR

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
05/09/2018 16:21

Officer In Charge Of Case:
TP / GIT /
Staff Sgt MOHAMED SUFIAN BIN SUDIN
Contact No.: 65476367

Classification Of Case:

Authentication Stamp
NP168



Accident Photo



Accident Photo



Accident Photo

GNASSIS NO : JTFAT35Y50-K25-0001
ULW : 3500 KG
M.L.W. : 3500 KG
PASS.CAP : 02
TYRE SIZE : F.195/75R.15
: R.155R.12.8(D)

Accident Photo



Accident Photo



Accident Photo



Accident Photo



































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Sep 2018		13 Sep 2018 10:37 Edit Adj Rpt	S\$4,800.00 Edit Estimates	S\$4,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HARVEST BUILDING PRODUCTS PTE LTD, Co. Reg. No.: 200914531R								
Main Claimant:	HENG LIM SERVICES PTE LTD, Co. Reg. No.: 200802401H								
Vehicle Reg. No.:	XD147E	Date of Loss:	04/09/2018 11:00 - :59 [150 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 570042	Policy/Cover Note No.:	A28806552MKC (Comprehensive) Coverage: 26/08/2018 - 25/08/2019						
Vehicle Reg. No. (Insured):	GBB8744A	Policy No. (Claimant):							
		Excess:							
Repairer:	Yee Keong Motor Engineering (HQ) No. 14 Penjuru Road, 609125 Jurong West - Tel: 97808928								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/01/2019]								
Driver/Custodian (Insured):	LIM JIT SENG () , NRIC: S6822975H, Tel: +6594874026 Email:								
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP reject SJE, please assign LKK to survey. Liability : not clear Contact : Mr Hiew @ 9780 8928								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (28/01/2019): Report Send Back Alerts - XD147E (TP) MSIG_SG (28/01/2019): < No subject > 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD147E (570042)
 [GBB8744A]
 TP
 HENG LIM SERVICES PTE LTD
 Sep 4 2018 11:00AM
 [HARVEST BUILDING PRODUCTS PTE LTD]
 Yee Keong Motor Engineering

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/09/18 18:52	Accident Statement From: SC - Reg. No: GBB8744A, Claimant: HARVEST BUILDING PRODUCTS PTE LTD	 Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/09/18 14:38	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
19	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
20	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	24/09/18 14:38	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/09/18 18:52	E-FILE REPORT (XD147E)	 Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
		From: SC - Reg. No: G888744A, Claimant: HARVEST BUILDING PRODUCTS PTE LTD		
2	12/09/18 18:53	TP PRI		Load PDF
3	12/09/18 19:10	TP REJECTION REPLY ON OUR SJE		Load PDF
4	12/09/18 19:12	OUR REJECTION REPLY & WE NOMINATED LKK TO BE OUR SJE		Load PDF
5	07/01/19 19:28	TP LOD & DOCS		Load PDF
6	07/01/19 19:29	TP SURVEY REPORT		Load PDF
7	31/01/19 15:36	EMAL CORRESPONDENCES ZHNNG HANYANG & RICHARD (CANOPY INS AGY)		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/19 17:18	PRS Invoice		Load PDF
2	05/03/19 17:19	Colour Photo		Load PDF
3	05/03/19 17:19	PRS Invoice		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18016722/T1TD3E2-1

Date: 06/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28806552MKC

Claimant Vehicle
No : XD147E

Insured Vehicle No : GBB8744A

Date of Loss: 04/09/2018

Nature of Claim: TP

Claim No: 570042

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD147E

Make & Model: NISSAN CKB45ABTN2, 12.5 D (M)

Engine No: PF6169755C

Reg. Date: 13/02/2006 (Man. Year: 2005)

Chassis No: CKB45ABT00647

Colour: Blue

Odometer: 717172 km

Engine Capacity: 12503 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Falken 8 mm

Rear Left Side: Falken 8/8 mm

Front Right Side: Falken 8 mm

Rear Right Side: Falken 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,814.38	4,091.02	4,723.36	53.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,880.00	1,630.00	46.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,324.38	5,971.02	6,353.36	51.55
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	12,324.38	4,800.00	7,524.38	61.05

INSPECTION

Date of Assignment: 13/09/2018

Date Inspected: 13/09/2018 Inspected At:

Yee Keong Motor Engineering (HQ)
No. 14 Penjuru Road
Singapore 609125

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Mar 2019)	
Parts:	N/A	NISSAN CKB45ABTN2 12.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD147E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S STEP PANEL	Not Necessary	684.05 F	*- FL
2	1		*FRONT O/S STEP ALLOY LOWER	Cracked	275.50 F	*275.50 FL
3	1		*FRONT O/S LOWER STEP GARNISH	Torn	295.00 F	*295.00 FL
4	1		*FRONT O/S DOOR	Badly Dented	4,720.20 F	*3,900.00 FL
5	2		*FRONT O/S DOOR HINGE	Serviceable	412.00 F	*- FL
6	1		*FRONT O/S DOOR RUBBER	Torn	228.00 F	*228.00 FN
7	1		*FRONT O/S DOOR LAMP	Serviceable	84.45 F	*- FN
8	1		*FRONT O/S DOOR UD LAMP	Not Necessary	88.20 F	*- FN
9	1		*FRONT O/S DOOR INNER LOCK	Not Necessary	338.24 F	*- FN
10	1		*FRONT O/S DOOR WHEEL ARCH GARNISH	Cracked	422.18 F	*422.18 FN
11	1		*FRONT O/S WHEEL RIM	Repair	848.22 F	*- FN
12	1		*FRONT O/S WHEEL RIM CAP	Dented	102.12 F	*102.12 FN
13	1		*FRONT O/S WHEEL MUDFLAP	Defaced	248.22 F	*248.22 FN
14	1		*FRONT O/S DOOR UD EMBLEM	Necessary	68.00 F	*68.00 FN

F=Franchise part. L=ListItemDisc. N=NetItemDisc.

Sub Total (\$\$)	8,814.38	5,539.02
- List Item Discount on L Items 0.00/30.00% (\$\$)	0.00	1,341.15
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	106.85
Total Parts (\$\$)	8,814.38	4,091.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN FRONT O/S WHEEL ARCH PANEL AND REPLACE PARTS	New	1,400.00	800.00
2	PUTTY & SPRAYPAINT	New	1,600.00	800.00
3	CHECK ELECTRICAL	New	80.00	30.00
4	REWRITE DOOR LETTERING	New	80.00	50.00
5	TUFF KOTE	New	100.00	30.00
6	REMOVE AND REFIT FRONT O/S DOOR PARTS	New	100.00	60.00
7	RESET WHEEL ALIGNMENT	New	100.00	80.00
8	REPLACE FRONT O/S WHEEL RIM & TYRE AND BALANCING	New	50.00	30.00
Gross Labour Cost (\$\$)			3,510.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >