



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III18017051/R1vd3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 15-02-2019



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFF 8583D	Veh. Inspected	SGW 5509M
Policy No.		Coverage (\$)	0.00
Claim No.	MC2018/2782	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	29/01/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA S2000 2.2 M	c.c	2156
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	AP21001878	Colour	WHITE
Odometer	119234	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	MICHELIN	6 mm
L/H Front Tyre	215/45 R17	MICHELIN	6 mm
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/09/2018	Inspection Date	12/12/2018
Survey held at	MIRACLE WORKZ PTE LTD 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**