

2/03/2002

ASS. REC. BY:

REF:

083/CTI 19001996/Gcd3d

Special Instruction:

Surveyor:

GD

ASSIGNMENT (Office)

From (Person):

Elaine Cheung

of

CTI

Date/Time:

30/11/19 @ 12:03pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGQ 9747Y

Insured:

XD5565Z

at Workshop m/s

SAT Motor

Tel:

98599677

of

24 Defn Lane 12

Policy No:

DMCVSN17628118011

Claim No:

SNM19D200476C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/1/19

CA / REV / REP. / REV 24 HRS

Wup

H.O.D. Endorsement:

Date/Time:

2:50pm @ 30/11/19

Person Contacted:

Jessie

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SGQ 9747Y - NA / CTI 19001683 / 24 DOA: 24/01/19
	XD5565Z - NA / CTI 19001683 / 24 DOA: 24/1/2019
	Diamond: 31/1/2019

PRS  
KML

REF: CFF

19788

(2022)

ASSIGNMENT

From: \_\_\_\_\_ Date: 31/1/19

Estimated Cost: \_\_\_\_\_

OD:  TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGQ 9747Y

at Workshop n/s: SAT Motor

of: 24 Defu June 12

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Mowing

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$54k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS<sup>up</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SGQ9747Y Yr Regn: 29 Jan 2007

Type:  M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Merced E200k C.C. 1796

Colour: silver A/C Insured / Std / NI / NA

Sp. Reading: 167697 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDB2110412B049442

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD  R/Rim or

Tyre Size: F: 225/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA /  MIC DOHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front		Rear
R/Bal. 6 mm		R/Bal. 6 mm
L/Bal. 6 mm		L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 31-01-19

Survey held at: W/S 11:15

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction

\$3000 - \$4000

Date/Time, File Pass to?  Preli. Report

1)  Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:	150
Transportation:	
_____ S + RS _____ SI	
Photos	
Other	
TOTAL	150

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: PRE

Lump Sum / I.B.F. (\$) \_\_\_\_\_

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

**►Nivitha (LKK Auto)**

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Wednesday, 30 January 2019 12:03 PM  
**To:** kkrishna; 'assignments'  
**Cc:** pak >> Jessie Ong; jonathan@satmotors.com; sean@satmotors.com  
**Subject:** RE: PRE-REPAIR INSPECTION - YOUR REF: SGQ9747Y / OUR REF: SNM19D200476C02/5

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Sir,

We refer to your email of 29.01.19.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



---

**From:** kkrishna [mailto:kkrishna@singnet.com.sg]  
**Sent:** Tuesday, 29 January, 2019 5:32 PM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Cc: pak >> Jessie Ong <pakweng@satmotors.com>; jonathan@satmotors.com; sean@satmotors.com  
Subject: Fwd: PRE-REPAIR INSPECTION - YOUR REF: SGQ9747Y / OUR REF: SNM19D200476C02/5

Dear Elaine,

We refer to your letter of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead our client proposes that you choose a surveyor from the list of surveyors as appended below:

- 1) Lim Chang Lian
- 2) Lim Yong Tian, Sebastian
- 3) Philip Foo
- 4) Ho Joo Loong, Danny
- 5) Kelvin, Teo Hoon Tong
- 6) Lee Kok Weng
- 7) Lim Yong Tian, Sebastian
- 8) Ong Ah Keng, Kent
- 9) Ong Poh Meng
- 10) Allin

As our client's workshop, i.e. the workshop he sent his car for repairs, is a small workshop, our client is unable to provide you with more than the above listed motor surveyors. We trust you will be able to choose a surveyor from above.

Please be informed that if we do not hear from you **within two (2) working days from the date hereof**, our client shall assume, as per the Protocol, that you have no objections to the list of motor surveyors above and you shall be deemed to have agreed to the any of the above motor surveyors as a "single joint expert".

We will accordingly inform you who the "single joint expert" is to facilitate your conduct of a pre-repair survey.

Regards.

Yours faithfully,  
K. Krishna & Partners  
Advocates & Solicitors  
Tel: 6323 3038  
Fax: 6323 2120

----- Forwarded Message -----

Subject: PRI - YOUR REF: SGQ9747Y / OUR REF: SNM19D200476C02/5

Date: Tue, 29 Jan 2019 06:52:53 +0000

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

To: kkrishna@singnet.com.sg <kkrishna@singnet.com.sg>

**WITHOUT PREJUDICE**

Dear Farida,

We refer to your fax of 28.01.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1978Z
Vehicle Details	
Vehicle No.:	SGQ9747Y
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Feb 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200K
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	27195630827432
Chassis No.:	WDB2110412B049442
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$52,574.00
Original Registration Date:	29 Jan 2007
First Registration Date:	29 Jan 2007
Transfer Count:	0
Actual ARF Paid:	\$57,832.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,330.00
COE Rebate Amount:	\$15,741.00
<b>Total Rebate Amount:</b>	<b>\$15,741.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Feb 2019

OK

## ▶ Mercedes-Benz e200k Used Vehicle List (6 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
<b>Mercedes-Benz E-Class E200K (COE till 06/2021)</b>	<b>\$25,800</b>	\$10,700 /yr	05-Jul-2001	1,998 cc	107,000 km	I Care Auto Pte Ltd	Availab

Well Maintained, Car In Original Condition, Must View To Appreciate, Please Call For Viewing.

Office No. - -

Francis - 97892698

<b>Mercedes-Benz E-Class E200K (COE till 07/2026)</b>	<b>\$58,800</b>	\$7,840 /yr	21-Sep-2006	1,796 cc	162,000 km	Juzt Carz Auto	Availab
---	-----------------	-------------	-------------	----------	------------	----------------	---------

New Arrival The E200 Provide You Luxury, Comfort, Stylish Drive And Spacious To Fit Your Family Size. Owned By A Careful Non Smoker Owner. New Paint Will Be Provided. Condition To Good To Scrap! View ...

Office No. - 63383813

James Li - 88588866 | Shawn Zheng - 97520620 | Joey Lim - 97892877 | Philip Koh - 82338484

<b>Mercedes-Benz E-Class E200K (COE till 12/2026)</b>	<b>\$53,800</b>	\$6,820 /yr	20-Dec-2006	1,796 cc	164,000 km	Auto Zoom Enterprise Pte Ltd	Availab
---	-----------------	-------------	-------------	----------	------------	------------------------------	---------

C&C Facelifted Model E200K With 181Bhp Not The E200ML With 160Bhp, Only \$6800 Deprecation, Cheapest In Market With Only 2 Owners . Low Mileage Of 13000km Average A Year, Road Tax Till 19 June 2019, ...

Office No. - 63421000

Jeffrey - 90041167 | Stanley Chua - 96813489

<b>Mercedes-Benz E-Class E200K (COE till 08/2027)</b>	<b>\$55,999</b>	\$6,530 /yr	30-Aug-2007	1,796 cc	-	Kao Lian Enterprise	Availab
---	-----------------	-------------	-------------	----------	---	---------------------	---------

New Arrival! Beautiful Silver In Grey E200K Model. Luxurious, Elegant Drive. Spacious And Comfortable. Well Maintained By Careful Owner A 100% Accident-Free! Road Tax Till Aug 2019! Loan/Trade In We...

Office No. - -

Shu Yi - 91445626 | Ben - 82020820 | Desmond - 97467781

<b>Mercedes-Benz E-Class E200K (New 10-yr COE)</b>	<b>\$62,000</b>	\$6,190 /yr	09-Sep-2008	1,796 cc	-	Prem Roy Motoring	Availab
--	-----------------	-------------	-------------	----------	---	-------------------	---------

C&C Unit, One Of The Best Merc Models, Super Elegant, Does Not Feel Like A 10 Year Old Car, Original Stock Condition. Guaranteed Acciden Free. No More Repairs Needed. All Wear And Tear Done Up With R...

Office No. - 66028046

Kana - 96435365 | Mark - 98896985

<b>Mercedes-Benz E-Class E200K (COE till 01/2024)</b>	<b>\$43,800</b>	\$8,810 /yr	22-Jan-2009	1,796 cc	149,000 km	Hamilton Autohub Pte Ltd	Availab
---	-----------------	-------------	-------------	----------	------------	--------------------------	---------

Office No. - 62979001

Andy Ang - 92366391

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/01/2019 17:32
Date Of Accident	24/01/2019 17:10
Exact Location Of Accident	ALONG MARINE PARADE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGQ9747Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ESTATE OF NARANJAN SINGH S/O BACHAN SINGH
NRIC No	S1071978Z
Email Address	SINGHSARBRINDER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93899934
Alternative Phone No	OTHERS-93899934

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5069676905-03
Cover Note Number	

### Driver

Name of Driver	JAGIR KAUR W/O NARINJAN SINGH
NRIC No	S2078851H
Date Of Birth	25/08/1947
Occupation	INDOOR
Date Of Driving Pass	09/01/1973
Driving Experience	46 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93899934
Fax Number	
Contact Number	
EMail Address	SINGHSARBRINDER@GMAIL.COM

Address 17 GREENFIELD DRIVE  
SINGAPORE

Postcode 457930

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : GURVEEN KAUR  
GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ

Police Station Address **ROAD:** 10 UBI AVENUE 3 , **POSTCODE:** 408865 , **COUNTRY:** SINGAPORE

Police Station Contact **TEL NO:** 65470000 - **FAX NO:**

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number XD5565Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name JAGIR KAUR W/O NARINJAN SINGH

Approximate Age

Injuries Sustain REFER POLICE REPORT

Injured person in which vehicle? SGQ9747Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reudate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/Jan/2019 @ 5.10 p.m I was driving my motorcar SGR 9747J along the extreme left lane of Marine Parade Road with my <sup>grandmother</sup> (Gurveenkar) as the front seat passenger heading home to my house at Frankel Avenue. I brought my motorcar SGR 9747J to a stop along the extreme left lane of Marine Parade Road at the traffic lights ahead were red in colour. There were a few cars that stopped in front of me also due to red traffic light whilst my car was stationary waiting for the traffic light to turn green, suddenly without any warning or indication a white motor-lorry - XD 5565Z came out from construction site from the left side of Road into Marine Parade Road and just collided into the right-side ~~of~~ rear of my stationary vehicle. The driver of XD 5565Z came out of construction site without checking and made a left turn into Marine Parade Road and hit the rear of my stationary vehicle. I was injured and ambulance and police came to the scene. Ambulance bring me to hospital hospital and I given MC 8 days

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

↓ Jagir Kaur.  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190125/7006

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408665  
Tel No: 65470000

1 of 3

Report No. T/20190125/7006

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 25/01/2019 13:52	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

**Informant's Particulars**

Name of Informant: JAGIR KAUR W/O NARINJAN SINGH		Address: 17 GREENFIELD DRIVE SINGAPORE 457930	
ID Type / ID No.: NRIC NO / S2078851H		Contact No.:	Mobile: 93899934
Nationality:		Email: singhsarbrinder@gmail.com	
Sex:	Age:	Date of Birth:	Type of Informant: Driver
Race:		Language: English	Institution / School Name:
Occupation: DIRECTOR		Driving Licence Information: Class: Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 24/01/2019 17:10	Type of Location: Straight Road
Location:  MARINE PARADE ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGQ9747Y	Car	MERCEDES BENZ	E200	Grey	Slightly Damaged	2
XD5565Z	Lorry				Slightly Damaged	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGQ9747Y	NTUC Income Insurance Co-Operative Limited			

Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190125/7006

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3  
Report No. T/20190125/7006

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	JAGIR KAUR W/O NARINJAN SINGH	ID No.	S2078851H
Related Vehicle	SGQ9747Y (Car)	Contact No.	93899934
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	24/01/2019	Date Discharge	25/01/2019
No. of Days granted Medical Leave	08	Degree of Injury	Serious

Brief Details.

ON 24/01/2019, AT 5:10PM I WAS DRIVING MY MOTOR CAR SGQ9747Y ALONG EXTREME LEFT LANE OF MARINE PARADE WITH MY GRAND DAUGHTER AS FRONT SEAT PASSENGER HEADING HOME AT FRANKEL AVE. I BROUGHT MY MOTOR CAR TO A STOP AT THE LEFT LANE AS TRAFFIC LIGHT AHEAD IS RED COLOUR, THERE A FEW CARS IN FRONT ALSO STOP AS RED TRAFFIC LIGHT. WHILE MY CAR STATIONARY WAITING FOR TRAFFIC TO TURN GREEN, SUDDENLY WITHOUT ANY WARNING OR INDICATION A WHITE MOTOR LORRY XD5565Z CAME OUT OF THE CONSTRUCTION SITE FROM THE LEFT SIDE OF THE ROAD INTO MARINE PARADE ROAD AND JUST COLLIDED INTO THE RIGHT REAR SIDE OF MY STATIONARY VEHICLE. THE DRIVER OF MOTOR LORRY COME OUT OF CONSTRUCTION SITE WITHOUT CHECKING AND MADE LEFT TURN INTO MARINE PARADE ROAD AND HIT THE REAR OF MY STATIONARY VEHICLE. I WAS INJURED AND AMBULANCE AND POLICE CAME TO THE SCENE. AMBULANCE BRING ME TO HOSPITAL AND WAS GIVEN 8 DAYS OF MC.

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 May 2019		10 May 2019 10:17	<b>S\$0.00</b>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	ESTATE OF NARANJAN SINGH S/O BACHAN SINGH, ID: S1071978Z		
Vehicle Reg. No.:	SGQ9747Y	Date of Loss:	24/01/2019 17:00 - :59 [143 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200476C02	Policy/Cover Note No.:	DMCVSN17628118011
Vehicle Reg. No. (Insured):	XD5565Z	Policy No. (Claimant):	5069676905-03
		Excess:	S\$0.00
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/05/2019]		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b> <b>Subject</b> <b>Handler</b> <b>Assigned By</b> <b>Completed On</b> <b>Created On</b> <b>Done?</b>
No results.			

### Claim Documents

**\*SGQ9747Y (SNM19D200476C02)  
[XD5565Z]**

**TP  
ESTATE OF NARANJAN SINGH S/O BACHAN SINGH  
Jan 24 2019 5:00PM  
[-]  
Sat Motors**

Upload Documents		Upload Photos		Compose New Letter		<b>View</b> View in Browser	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print		
1	25/01/19 17:44	<b>Accident Statement</b>		 Load HTM	<input checked="" type="checkbox"/>		
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print		
1	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
2	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
3	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
4	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
5	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
6	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
7	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
8	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
9	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
10	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
11	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
12	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
13	25/01/19 17:38	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		 Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
2	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
3	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
4	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
5	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
6	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
7	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
8	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
9	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
10	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
11	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
12	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
13	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
14	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		
15	10/05/19 10:49	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
16	10/05/19 10:49	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
18	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
19	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
20	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
21	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
22	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
23	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
24	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
25	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
26	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
27	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
28	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
29	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
30	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
31	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
32	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
33	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
34	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>
35	10/05/19 10:50	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/05/19 10:18	<b>pri contact</b>	 Load PDF	

No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	25/01/19 17:40	<b>Sketch Plan</b> [Linked Accident Report Documents]	 Load TIF	
2	25/01/19 17:40	<b>Sketch Plan #2</b> [Linked Accident Report Documents]	 Load TIF	
3	25/01/19 17:40	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]	 Load TIF	
4	25/01/19 17:40	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]	 Load TIF	
5	25/01/19 17:40	<b>Accident Sketch Plan</b> [Linked Accident Report Documents]	 Load TIF	

### Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	25/01/19 17:44	<b>Accident Statement</b>	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
2	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
3	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
4	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
5	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
6	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
7	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
8	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
9	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
10	25/01/19 17:38	<b>Accident Photo</b>	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
11	25/01/19 17:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	25/01/19 17:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	25/01/19 17:38	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	25/01/19 17:40	Sketch Plan	Load TIF	
2	25/01/19 17:40	Sketch Plan #2	Load TIF	
3	25/01/19 17:40	Accident Sketch Plan	Load TIF	
4	25/01/19 17:40	Accident Sketch Plan	Load TIF	
5	25/01/19 17:40	Accident Sketch Plan	Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119001996/GCD3E2  
Date: 10/05/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17628118011
Claimant Vehicle No :	SGQ9747Y	Insured Vehicle No :	XD5565Z
Date of Loss:	24/01/2019	Nature of Claim:	TP
		Claim No:	SNM19D200476C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGQ9747Y		
Make & Model:	MERCEDES-BENZ E200, 1.8 (A)	Engine No:	27195630827432
Reg. Date:	29/01/2007 (Man. Year: 2006)	Chassis No:	WDB2110412B049442
Colour:	Silver	Odometer:	167697 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	10/05/2019	Inspected At:	Sat Motors (HQ) 24 Defu Lane 12 Singapore 539131
Date Inspected:	31/01/2019		
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2019)
<b>Parts:</b> 143	MERCEDES-BENZ E200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGQ9747Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >