

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China Taping
(4S) LKK -

Date: 29.01.2019

Time: 15:27:31

Page: 1/3

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305264515
 REGN NO : SHC2041H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : SONATA
 DATE OF REGN : 31.05.2012
 DATE/TIME IN : 29.01.2019 11:40
 ACCIDENT DATE : 29.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0101-0003-A	FRT BUMPER	1	538.80	20.00	431.04	/CRK
0002	04-01-0101-0066-G	FRT BUMPER LIP	1	59.90	20.00	47.92	?
0003	04-01-0101-0084-G	FRT BUMPER GRILLE LH	1	17.60	20.00	14.08	X SUL
0004	04-01-0101-0029-G	FRT BUMPER UPR BRKT LH	1	20.10	20.00	16.08	?
0005	04-01-0101-0023-G	FRT BUMPER PROTECTOR LH	1	29.20	20.00	23.36	/CRK
0006	04-01-0101-0045-G	FRT BUMPER MTG LH	1	14.30	20.00	11.44	?
0007	04-01-0101-0074-G	FRT FENDER RETAINER LH	1	9.20	20.00	7.36	?
0008	04-01-0101-0027-A	HEADLAMP LH	1	797.90	20.00	638.32	/CRK
0009	04-01-0101-0012-G	RADIATOR GRILLE	1	282.10	20.00	225.68	X SUL
0010	04-01-0101-0009-G	U-MOULDING	1	108.90	20.00	87.12	?
0011	04-01-0101-0013-A	BONNET	1	1,151.80	20.00	921.44	/BUC
0012	04-01-0101-0016-A	FRT FENDER LH	1	593.80	20.00	475.04	/DEF
0013	03-01-0101-0005-G	FRT FENDER SHIELD LH	1	86.00	20.00	68.80	/TN

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China Taiping
CL5)

Date: 29.01.2019

Time: 15:27:31

Page: 2

LKK-

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305264515
REGN NO : SHC2041H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 31.05.2012
DATE/TIME IN : 29.01.2019 11:40
ACCIDENT DATE : 29.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0101-0015-G HEADLAMP SUPPORT PANEL 1 1,023.00 20.00 818.40 ?

SUB-TOTAL : 3,786.08

JOB NATURE

0000 L PANEL BEATING
0001 23-502 SPRAYPAINT ON AFFECTED AREA
0002 17-01 CHECK ALL LIGHTING
0003 20-00 TUFF COAT ON AFFECTED PARTS.
0004 L R/I AIR CON CONDENSER ETC

~~480.00~~ 400~~600.00~~ 600 /~~50.00~~ 30

40.00 /

150.00 X NN

SUB-TOTAL : 1,320.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 29.01.2019

REPAIR ESTIMATE

China Taiping (LKS)

Time: 15:27:31

Page: 3

13

TS

LKK-

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305264515
REGN NO : SHC2041H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 31.05.2012
DATE/TIME IN : 29.01.2019 11:40
ACCIDENT DATE : 29.01.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

LWS

TOTAL : 5,106.08

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NAZ LKK

29/1/19 1615

LIS

4 DAYS

CHECK ITEMS PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: