

149220

INS. CASE OWNER:

CC 3 / III1900 2004, T1 1/23

LKK: IDAC:

Surveyor:

TAMBUKH

DOI:

ASSIGNMENT

20/02/19

Date / Time:

20/1/19

Registered in Merimen:

20/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH 710YB

Claim No.:

MJ19010821

Name of Insured:

LTPK

Policy No.:

M L 00005

Insured Tel No.:

HP:

29/1/19

Make / Model:

Toyota

Excess Sec II :SS

D.O.A.:

29/1/19

Place of Accident:

1/2 FARMER RA TUMS TAMBUKH

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

um fany LI RONNIE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L YES / NO)

Insured Liability: %

Final ? Yes / No

SKR 210219

SH 710YB

SLS 186YS

SBC 055T



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS: 01



INSRS: WSP: Tel: Liability: RMKS: TP



INSRS: WSP: Tel: Liability: RMKS:

| Date/Time | STAGE                           | DATE / PIC     |
|-----------|---------------------------------|----------------|
| 12/02/19  | Non-Reporting Ir (1st)          |                |
|           | Non-Reporting Ir (2nd)          |                |
|           | Non-Reporting Ir (Final)        |                |
|           | Notification Ir (if non-pickup) |                |
|           | Call OI:                        |                |
|           | After call Ir to OI:            |                |
| 10/01/19  | Documentation Check List:       | Handler Typist |
|           | Notification Ir (if non-pickup) |                |
|           | After call Ir to OI:            |                |
|           | Authorisation To Act:           |                |
|           | Release Voucher:                |                |
|           | Final Repair Bill:              |                |
|           | Car Rental Invoice:             |                |
|           | Towing Invoice:                 |                |
|           | LTA / GIA:                      |                |
|           | Medical Bill:                   |                |
|           | PIR:                            |                |
|           | Mutate/Reject Instruction:      |                |
|           | LOD:                            |                |
|           | Payment Breakdown Form:         |                |
|           | Post-Repair Photos:             |                |
|           | Others:                         |                |

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: P/P \$5 3,808.00 4 days) Reduction: % Email  Call

FINAL SETTLEMENT Date/Time: 19/2/19 Confirm with: TAMBUX Email  Call

Final Liability: % 100 Agreed / Assessed BOLA S/N No.: 28 If NO, B 28, Ass. Lia: 0%

Repair Cost: W/P \$5 3745-W (4 Veh. C.C., Old 3rd car)

Loss of Rental (LOR): \$5 ( days)

Loss of Use (LOU): \$5 4W-W (S 1W x 4)

Loss of Income (LOI): \$5 (S x days)

LOR only  LOU only  LOR + LOU  LOR + LO  [Tick only one]

GIA/LTA Search: \$5

Medical: \$5

Disbursement: \$5 (e.g. Tow/Independent)

Legal Cost: \$5

Total: \$5 4145-W Global Sum \$5:

FINAL PAYMENT Date/Time: Confirm with: Email  Call

Payee 1: \$5 4145.00 Name 1: Performance Motors Ltd

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                           |   |
|--|--|---------------------------|---|
| INDIA INTERNATIONAL INSURANCE PL   |  | Ref : CC3/III19002004/hb3 |   |
| 64 CECIL STREET<br>#05-02 IOB BUILDING SINGAPORE 049711  |  | Date : 30-01-2019         |  |
|  |  | Code : III2               |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |                           |   |
| Insured Veh.   | SH 7102B   | Veh. Inspected            | SLS 1867S   |
| Policy No.   |  | Coverage (\$)             | 0.00  |
| Claim No.  |  | Excess (\$)               | 0.00  |
| Assign From  |  | Assign Date               | 30/01/2019  |
| 2. Vehicle Particulars & Condition   |  |                           |   |
| Make & Model   |  | c.c                       | 0   |
| Engine No.   | HIDDEN   | Year of Reg.              |   |
| Chassis No.  |  | Colour                    |   |
| Odometer   | -  | Steering                  |   |
| Brakes   |  | Modification              |   |
| General  |  |                           |   |
| 3. Conditions of Tyres   |  |                           |   |
|  | Size   | Make                      | Balance   |
| R/H Front Tyre   |  |                           | mm  |
| L/H Front Tyre   |  |                           | mm  |
| R/H Rear Tyre  |  |                           | mm  |
| L/H Rear Tyre  |  |                           | mm  |
| 4. Description of Damages  |  |                           |   |
|  |  |                           |   |
| 5. General Information   |  |                           |   |
| Accident Date  | 27/01/2019   | Inspection Date           |   |
| Survey held at   | PERFORMANCE MOTORS LTD<br>303 ALEXANDRA ROAD<br>SINGAPORE 159941 |                           |   |
| 5a. Remarks  |  |                           |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                           |   |

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

101, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Seapong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

119, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190228 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796224 (Motorrad)



GST REG. NO : M2 - 0020081 - X

30 JAN 2019

## ESTIMATE

Estimate No. : **b1 49951**  
Date Estimated : **29/01/2019**  
Prepared By : **Joseph Yaguel**

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ow Chio Kiat  
40B Nassim Road

Singapore 258427

- ACCOUNT - 40000

Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL  | MILEAGE |
|-----------|-------------|------------|--------|---------|
| SLS1867S  | PZ85208     | 30/09/2009 | 3351-C | 0       |

### DESCRIPTION

Replacing rear bumper panel and attachments, reworking front bumper panel, tail panel and to knock out dents caused by the accident

1700 2,550.00

Spray rear bumper, tail panel, front bumper

1868 2,819.00

To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.

250 295.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 ? photo 271.00 X

Sundries

? 80 150.00

Total Labour 1: 6,085.00

### DESCRIPTION

| DESCRIPTION                         | QTY | PRIC     | VALUE    |
|-------------------------------------|-----|----------|----------|
| RR BUMPER LH GUIDE                  | 1   | 39.30    | 39.30    |
| RR BUMPER RH GUIDE                  | 1   | 39.30    | 39.30    |
| RR BUMPER CTR GUIDE                 | 1   | 47.95    | 47.95    |
| RR BUMPER CARRIER                   | 1   | 458.55   | 458.55   |
| RR BUMPER (M/PDC)                   | 1   | 1,320.90 | 1,320.90 |
| DECOUPLING RING PDC TORQUE CONVERTE | 4   | 5.05     | 20.20    |

Total Parts : 1,926.20

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401999M GST Reg. No M2-0020081-X



105, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax: 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motocorr)  
Fax. 64796601 (AfterSales)  
64796624 (Motocorr)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : **b1 49951**  
Date Estimated : **29/01/2019**  
Prepared By : **Joseph Yaguel**

Page No. : **2 of 5**

| REGN. NO.       | CHASSIS NO.    | REGN. DATE        | MODEL         | MILEAGE  |
|-----------------|----------------|-------------------|---------------|----------|
| <b>SLS1867S</b> | <b>PZ85208</b> | <b>30/09/2009</b> | <b>3351-C</b> | <b>0</b> |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before bar spray painting
- To display damage after survey
- Parts prices are subject to confirmation
- Third party surveys on a 'Without Prejudice' basis
- No illegal modifications
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Reg No: \_\_\_\_\_ Claim No: \_\_\_\_\_  
 Used Time: **26/2/19 @ 1120** Excess \$: \_\_\_\_\_  
 Surveyor's Name: **Tan Jia** Sign: **Tan Jia**  
 Surveyor's Tel: **97495747** Authorized: Yes / No  
 Authorized Date: \_\_\_\_\_  
 SURVEYOR'S PHOTO BY SURVEYOR: **Tan Jia @ lkkauto.com** / No PMS. res. re: \_\_\_\_\_  
**04 days**



SUN, 20

|                    |   |                 |
|--------------------|---|-----------------|
| Labour 1           | : | <b>6,085.00</b> |
| Parts              | : | <b>1,926.20</b> |
| Labour 2           | : | <b>0.00</b>     |
| Excess             | : | <b>0.00</b>     |
| Total GST @ 7%     | : | <b>560.78</b>   |
| <b>Grand Total</b> | : | <b>8,571.98</b> |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M3-002081-X



## FINAL REPORT

Estimate No. : b1 49951  
Date Estimated : 29/01/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
Ow Chio Kiat  
40B Nassim Road

- ACCOUNT - 219  
India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

Singapore 258427

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL  | MILEAGE |
|-----------|-------------|------------|--------|---------|
| SLS1867S  | P285208     | 30/09/2009 | 335i-C | 0       |

| DESCRIPTION  | ORIGINAL PRICE | DISC. % | NETT     |
|--|----------------|---------|----------|
| To make good the front/rear bumpers include removing attachments to facilitate repairs and knocking out dents caused by the accident | 1700.00        |         | 1,700.00 |
| To spray paint rear bumper and front bumper  | 1868.00        |         | 1,868.00 |
| To check electrical wiring system and lightings at the front and rear sections for proper function                                   | 250.00         |         | 250.00   |
| Sundries   | 80.00          |         | 80.00    |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|-------------|------------|-----|---------|------|
|-------------|------------|-----|---------|------|

### # SUPPLEMENTARY ITEMS

|                                 |          |
|---------------------------------|----------|
| Total Labour :                  | 3,898.00 |
| Total Parts :                   | 0.00     |
| Total Labour & Parts :          | 3,898.00 |
| Deduction for Excess :          | 0.00     |
| Total Repair Costs less Excess: | 3,898.00 |
| GST @7%:                        | 272.86   |
| Grand Total :                   | 4,170.86 |

## Hsiao Tong (LKKAuto)

---

**From:** Taufikh (LKKAuto)  
**Sent:** Friday, 14 June 2019 6:20 PM  
**To:** 'PBSP'  
**Cc:** Vic (LKKAuto)  
**Subject:** RE: LIMIT REPAIR: FINAL REPORT/ SLS1867E

Hi Caroline,

COR \$3500 , 4 days.

Regards  
Taufikh  
Lkk AUTO

---

**From:** PBSP [mailto:pml-pbsp@simedarby.com.sg]  
**Sent:** Thursday, 13 June 2019 10:39 AM  
**To:** vicalpeh@lkkauto.com; taufikh@lkkauto.com  
**Subject:** Fw: LIMIT REPAIR: FINAL REPORT/ SLS1867E  
**Importance:** High

Dear Vic and Taufikh

Please assist to confirm limit repair at \$3500 before GST.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Yaguel Renan Joseph Estoria  
**Sent:** Thursday, 13 June 2019 9:52 AM  
**To:** PBSP  
**Subject:** FW: LIMIT REPAIR: FINAL REPORT/ SLS1867E

Hi Caroline,

As per discussion with Taufikh this morning, having the repair limit given to us after proceeding repairs.  
We agreed to settle @ \$3500.00

Best Regards,

**Joseph Yaguel**  
*Customer Service Adviser*  
*Performance Motors Limited*  
*Body & Paint Department*

Mobile: 91165199  
DID : 63190149  
Fax : 64743229



**From:** PBSP  
**Sent:** Monday, 10 June, 2019 4:00 PM  
**To:** taufikh@lkkauto.com; Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>; Teng Wai Khan <teng.wai.khan@simedarby.com.sg>  
**Cc:** vicalpeh@lkkauto.com  
**Subject:** LIMIT REPAIR: FINAL REPORT/ SLS1867E  
**Importance:** High

Dear Teng

Please assist to check if there is a limit repair on this.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>  
**Sent:** Tuesday, 28 May 2019 9:50 AM  
**To:** PBSP; Taufikh (LKKAuto)  
**Cc:** 甯琿 ©; Vic (LKKAuto)  
**Subject:** RE: FINAL REPORT/ SLS1867E

Without Prejudice

Dear Caroline,

We refer to the below email and to our telephone conversation earlier.

Kindly put on hold, we would like to withdraw confirmation on COR.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK**

Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**CERTIFICATE OF INSURANCE**

ORIGINAL

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Type of Policy. : PRIVATE MOTOR CAR INSURANCE  
Type of Cover. : Comprehensive  
Certificate No. : D-18091600MVPC  
Vehicle No / Chassis No : SLS1867S / WBAWL720X0PZ85208  
Name of Insured : OW CHIO KIAT  
Period Of Insurance : 30.09.2018 To 29.09.2019  
Insured Estimated Value : Market Value At Time Of Loss

**Excess :**

SGD1,500.00 SECTION I FOR NAMED DRIVERS

**Authorised Driver\***

OW CHIO KIAT, LIM SIEW FENG KATHERINE MRS C K OW, OW YEW HENG, KIERSTEN OW YILING, LAMAT BIN HARON, MOHAMMED SUHAIMI BIN TAIB, MOHAMAD RAIMI BIN SULAM AND RAHIM BIN KOMING

**Persons or classes of persons entitled to drive\***

\* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**Limitations as to use\***

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or reward, racing, pacemaking, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

MS First Capital Insurance Limited  
(Approved Insurers)

LILIA/B0188/MX3

Issued at Singapore on 16.08.2018

  
\_\_\_\_\_  
Authorised Signature

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S0799657H



Name

OW CHIO KIAT



歐石吉

Race

CHINESE

Date of Birth

Sex

28-03-1945

M

Country of Birth

SINGAPORE

1300461



NRIC No: S0799657H



Blood Group Date of issue

O-

05-01-1994

40B NASSIM ROAD  
SINGAPORE 258427

NRIC No: S0799657H

Date: 24/12/2007

No: 6841704

ID

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. **S8118351A**



Name  
**KIERSTEN OW YILING**  
**(OU YILING)**  
**歐伊玲**

Race  
**CHINESE**

Date of Birth  
**20-08-1981**

Country of Birth  
**SINGAPORE**



REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. **S8118351A**



Name  
**OW YILING**  
**(OU YILING)**

Date of Birth  
**20 Jun 1981**

Valid From  
**18 Mar 2004**



001187981C



10 COVE DRIVE #04-11  
SINGAPORE 060079

Identity Card No. **S8118351A**

Date of Birth  
**19-08-2006**

Valid From  
**23-10-2015 (R)**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS (S)

Class 7 Motor Cars and Motor Tractors the weight of which exceeds three ton or over 3000 kilograms

Valid From  
**18 Mar 2004**



## Claim Audit

| AUDIT TRAIL |                      |                              |   |                                      |
|-------------|----------------------|------------------------------|---|--------------------------------------|
| No.         | On                   | Audit                        | Remarks   | By                                   |
| 1           | 30 Jan 2019<br>17:44 | <b>Cim Veh Model Changed</b> | (201436) BMW 335I 3.0 (A).  | [A] Lau<br>Shu Pei                   |
| 2           | 30 Jan 2019<br>17:44 | <b>Cim Created</b>           | Reg No: SLS1867S. Acct Date: 2019/01/27. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: MS First Capital Insurance Ltd (HQ). Workshop: Performance Motors Limited (Alexandra)           | [A] Lau<br>Shu Pei                   |
| 3           | 30 Jan 2019<br>17:44 | <b>Adj Co Assigned</b>       | LKK Auto Consultants Pte Ltd (HQ);  | [A] Lau<br>Shu Pei                   |
| 4           | 30 Jan 2019<br>17:44 | <b>Adj Next Rpt Changed</b>  | Next Rpt:Final Rpt.Due Date:2019/02/12  | [A] Lau<br>Shu Pei                   |
| 5           | 30 Jan 2019<br>17:44 | <b>Adj Mandate Set</b>       | Approved:0.00.Reinsp:Adj decides.   | [A] Lau<br>Shu Pei                   |
| 6           | 30 Jan 2019<br>17:44 | <b>Label Added</b>           | (30653):Direct Settlement.  | [A] Lau<br>Shu Pei                   |
| 7           | 30 Jan 2019<br>17:44 | <b>Adj Adjuster Assigned</b> | [None] -> MOHD TAUFIKH BIN HAMID  | [A] Lau<br>Shu Pei                   |
| 8           | 12 Feb 2019<br>08:53 | <b>Adj Mandate Request</b>   | Cur.Reg:0.00:PODS LIABILITY: 100% REMARKS: BOLA 28 - 4 veh.c.c.; OID 3rd car  | [A] VIC<br>ALPEH                     |
| 9           | 12 Feb 2019<br>09:33 | <b>Adj Next Rpt Changed</b>  | Next Rpt:Final Rpt.Due Date:2019/02/12. Mandate Remarks: Please note that our insured is the 2nd vehicle in line of 3 vehicles. Kindly check n revert   | [I]<br>Lalitha<br>Krishnan           |
| 10          | 12 Feb 2019<br>09:33 | <b>Adj Mandate Set</b>       | Maintained:Please note that our insured is the 2nd vehicle in line of 3 vehicles. Kindly check n revert   | [I]<br>Lalitha<br>Krishnan           |
| 11          | 12 Feb 2019<br>19:49 | <b>Cim Dtl Modified</b>      | Insured Name: -> COMFORT TRANSPORTATION PTE LTD.  | [A] Lau<br>Shu Pei                   |
| 12          | 12 Feb 2019<br>19:49 | <b>Cim Dtl Modified</b>      | Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.   | [A] Lau<br>Shu Pei                   |
| 13          | 15 Feb 2019<br>11:03 | <b>Adj Mandate Request</b>   | Cur.Reg:0.00:PODS LIABILITY: 100% (4 veh.c.c.; OID 3rd car) REMARKS: TP REPORTED AND CONFIRMED 1ST VEHICLE SBC 555T.  | [A] VIC<br>ALPEH                     |
| 14          | 15 Feb 2019<br>14:45 | <b>Adj Next Rpt Changed</b>  | Cur Rpt:Final Rpt. Cur Due Date:2019/02/12. Mandate Remarks: Please note that our insured is the 2nd vehicle in line of 3 vehicles. Kindly check n revert   | [I]<br>Lalitha<br>Krishnan           |
| 15          | 15 Feb 2019<br>14:45 | <b>Adj Mandate Set</b>       | Approved:0.00:Please note that our insured is the 2nd vehicle in line of 3 vehicles. Kindly check n revert  | [I]<br>Lalitha<br>Krishnan           |
| 16          | 19 Jul 2019<br>17:20 | <b>Adj Rpt Initiated</b>     |   | [A]<br>JOANNE<br>LEE<br>KHANG<br>MIN |
| 17          | 19 Jul 2019<br>17:20 | <b>Cim Dtl Modified</b>      | Insured ID: -> -.   | [A]<br>JOANNE<br>LEE<br>KHANG<br>MIN |
| 18          | 19 Jul 2019<br>17:20 | <b>Cim Dtl Modified</b>      | JPJ Reg. Date: -> 2009/09/30.   | [A]<br>JOANNE<br>LEE<br>KHANG<br>MIN |
| 19          | 19 Jul 2019<br>17:20 | <b>Cim Details Notified</b>  |   | [A]<br>JOANNE<br>LEE<br>KHANG<br>MIN |
| 20          | 29 Jul 2019<br>11:43 | <b>Adj Mandate Request</b>   | Cur.Reg:4145.00:PODS Liability: 100% Quantum: (a)CORw/GST: \$3,745.00 + (b)LOU (4days x \$100.00): \$400.00 = Total: \$4,145.00 Vehicle Model: BMW 335I (2979cc) 4 r recommendation repair days For your approval please. | [A]<br>CHEW<br>HSIAO<br>TONG         |

Date From



Date To



Audit Type None

Go

### ACTIVITY

[15/02/2019 16:20] VIC ALPEH:  
Alert - Adj Mandate Approved (S\$0.00) - SLS1867S - Claim Handler: Sherini Pillai  
Approved:0.00:Please note that our insured is the 2nd vehicle in line of 3 vehicles. Kindly check n revert  
[15/02/2019 11:44] VIC ALPEH:  
TP NO VIDEO FOOTAGE, ONLY SCENE PHOTOS  
[12/02/2019 08:55] VIC ALPEH:

Adj Mandate Request Cur.Req:0.00;PODS LIABILITY: 100% REMARKS: BOLA 28 - 4 veh.c.c.; OID 3rd car  
 [12/02/2019 08:54] VIC ALPEH:

FILE REVIEWED. OID Mr Lim Feng Ci Ronnie reported that he was involved in a 3 veh.c.c. and was the 2nd car, TP 1st car. TP reported that this is a 4 veh.c.c. and there is 1 more car in front of him involved. Seek liability mandate to III by merimen

**Merimen Billing for this case - Transaction History**

| Bill Ref No | Bill Date           | Acc Type | Acc Name                           | Co Name (Branch)                        | Ref 1    | Ref 2   | Amount |
|-------------|---------------------|----------|------------------------------------|---|----------|---------|--------|
| 2218879     | 19/07/2019<br>17:20 | Motor    | LKK Auto<br>Consultants Pte<br>Ltd | LKK Auto<br>Consultants Pte<br>Ltd (HQ) | SLS1867S | SH7102B | 11.77  |

# Print Received Message

This mail is associated with :

**\*SLS1867S (MCT19010811)**  
**[SH7102B]**  
TP  
OW CHIO KIAT  
Jan 27 2019 12:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Performance Motors Limited

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 29/07/2019 12:10 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$4145.00) - SLS1867S - Claim Handler: Sherini Pillai

Approved:4145.00:Please note that our insured is the 2nd vehicle in line of 3 vehicles. Kindly check n revert

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Saturday, 10 August 2019 11:34 AM  
**To:** PBSP  
**Cc:** Admin A  
**Subject:** Your ref: SLS1867S \*Our ref: CC3/III19002004/T1pb3 [ACCIDENT INVOLVING SH 7102B(III) / SLS 1867S/ OTHERS ON 27/01/2019]

Your ref: **SLS1867S** Without Prejudice  
Our ref: CC3/III19002004/T1pb3

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SH 7102B(III) / SLS 1867S/ OTHERS ON 27/01/2019**

We refer to the above matter and your LOD dated 27/06/2019.

We confirm settlement at \$4,145.00(all-in).

We will proceed to close file.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*W5100 T17*

India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
Attention: Motor Claims

**"Without Prejudice"**

Your Ref :

Our Ref :

Date : 27 June 2019

Subject : **ACCIDENT INVOLVING VEHICLES SLS1867S & SH7102B ON 27.01.2019**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

|                |   |     |                             |
|----------------|---|-----|-----------------------------|
| Cost of repair | : | S\$ | 3745.00                     |
| Loss of use    | : | S\$ | 400.00 (S\$100.00 x 4 days) |
| Total          | : | S\$ | 4145.00                     |

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & Certificate of Insurance
3. Copy of Identification Card & Driving License
4. Copy of Letter of Authorisation & Discharge Voucher

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-269)  
[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel Aftersales:  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel Aftersales  
6319 0527  
Fax 6479 6624

290  
Kampong Arang Rd  
East Coast Centre  
Singapore 438180  
Tel Aftersales  
6319 0888  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No:  
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to [pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg).

Yours sincerely

**Cresendo Lagman**  
Customer Service Manager, Body & Paint

# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLS 1867S & SH7102B ON 27-01-19.

I, OW CHIO KIAT owner of Vehicle Registration No. SLS1867S hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Name: OW CHIO KIAT (Date) 31-01-2019  
NRIC No.: S079965TH

In the presence of:

Name: RENAN JOSEPH YAGUEL (Date)  
NRIC No. PERFORMANCE MOTORS LIMITED

303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
TEL: 63190100 (Sales)  
63190111 (After sales)

FORM B1 VERSION 1 - SEPT 2017

## EXPRESS SETTLEMENT

### DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCM010811  
Claimant Ref: SLS18675

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 3745.00 (repair cost), S\$ 400.00 (loss of use/rental), S\$ Nil (search fee), vehicle no. SLS18675 that was damaged pursuant to the accident which occurred on 27/1/19 (date) at Along Grange Road (location) involving vehicle no. 3H7102B (insured vehicle). This is pursuant to the inspection conducted on 26/2/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Qu Chio Kiat ("the third party claimant") of vehicle no. SLS18675 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLS18675 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4145.00 to Performance Motors Ltd.

Dated this 14 day of Aug 20 19

**CLAIMANT:**

Signature:

  
Signed by "the workshop" (with chop)

Name:

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

NRIC:

Address:

Nationality:

Occupation:

**WITNESS:**

Signature:



Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

1996071982

Address:

51 Ubi Ave 1 A 01-25

Paya Ubi Industrial Park (S) 408973

Nationality:

Occupation:

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, East Coast Road  
East Coast Centre  
Singapore 412180  
Tel. 63190688 (AfterSales)  
Fax. 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796401 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1340461

Date IN : 26/02/2019

Motor Claim Advisor: Joseph Yaguel

Page No. : 1 of 1

Invoice Number : 2112574 / WSB

Invoice Date : 18/06/2019

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

### - CUSTOMER INFORMATION -

Mr Ow Chio Kiat  
40B Nassim Road

Singapore 258427

### - INVOICE TO - 219

India Int'L Insurance Pte Ltd  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL  | MILEAGE |
|-----------|-------------|------------|--------|---------|
| SLS1867S  | PZ85208     | 30/09/2009 | 335I-C | 41844   |

### --- LABOUR 1 ---

Labour charge to R & R, renew and/or repair affected parts and attachments, chassis pulling-alignment-measurement, panel beats and spray paint affected area including additional discount for LIMIT REPAIR.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 27.01.2019. 3RD PARTY CAR : SH7102B.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON 26.02.2019 AT 11:20AM. AUTHORISED REPAIR BY MS VIC ALPEH FROM LKK AUTO ON 15.02.2019 VIA EMAIL.

PROPOSE LOSS OF USE = \$100x4. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

Total Labour 1: 3,500.00

|                  |          |                                    |              |
|------------------|----------|------------------------------------|--------------|
| Labour Charges : | 3,500.00 | Total Labour & Parts Charges :     | S\$ 3,500.00 |
| Parts Charges :  | 0.00     | Less Insurance Excess :            | S\$ 0.00     |
| Lubricant/Misc : | 0.00     | Invoice Total Amount Exclude GST : | S\$ 3,500.00 |
|                  |          | GST @ 7% :                         | S\$ 245.00   |
|                  |          | Invoice Total Amount Include GST : | S\$ 3,745.00 |

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 3,745.00

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |             |   |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 30 Jan 2019<br><a href="#">Edit Reg</a> |               | 26 Feb 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$3,500.00</b><br><a href="#">Edit Estimates</a> | <b>S\$3,500.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference  | Claim Details          | Documents   | <a href="#">Show All</a> |         |             |              |            |       |
|---|--|------------------------|---|--------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>   |  |                        |   |                          |         |             |              |            |       |
| Insured:  | <b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: -  |                        |   |                          |         |             |              |            |       |
| Main Claimant:  | <b>OW CHIO KIAT</b> , ID: S0799657H  |                        |   |                          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SLS1867S</b>  | Date of Loss:          | 27/01/2019 12:00 - :59<br>[111 Months and 28 Days From LTA Reg Date (Man Yr)] |                          |         |             |              |            |       |
| Claim Type:   | <b>TP / MCT19010811</b>  | Policy/Cover Note No.: | MCOM0015  |                          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>SH7102B</b>   | Policy No. (Claimant): | D-18091600MVPC  |                          |         |             |              |            |       |
|   |  | Excess:                |   |                          |         |             |              |            |       |
| Repairer:   | <b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 |                        |   |                          |         |             |              |            |       |
| Handling Insurer:   | <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sherini Pillai</b> ]                                  |                        |   |                          |         |             |              |            |       |
| Claimant's Insurer:   | <b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311   |                        |   |                          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 12/02/2019]   |                        |   |                          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a>   <a href="#">Compose Case Mail</a></span>   |  |                        |   |                          |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>• III_SG (29/07/2019): Alert - Adj Mandate Approved (S\$4145.00) - SLS1867S - Claim Handler: Sherini Pillai</li> <li>• III_SG (15/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SLS1867S - Claim Handler: Sherini Pillai</li> <li>• III_SG (12/02/2019): Alert - Adj Mandate Maintained - SLS1867S - Claim Handler: Sherini Pillai</li> </ul> |  |                        |   |                          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a></span>   |  |                        |   |                          |         |             |              |            |       |
| Due Date  | Priority   | Type                   | Task Group  | Subject                  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |  |                        |   |                          |         |             |              |            |       |

## Claim Documents

\*SLS1867S (MCT19010811)  
 [SH7102B]  
 TP  
 OW CHIO KIAT  
 Jan 27 2019 12:00PM  
 [COMFORT TRANSPORTATION PTE LTD]  
 Performance Motors Limited

| <a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a> |                 |  | View   | View in Browser                     |
|---|-----------------|--|--|-------------------------------------|
| <b>Photos/Images</b>  |                 |  | 3 per page   | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | Thumbnail  | Print                               |
| 1   | 28/05/19 09:45  | <b>Odometer Reading</b>                    |  Load JPG   | <input checked="" type="checkbox"/> |
| 2   | 28/05/19 09:45  | <b>Chassis Number</b>                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 3   | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 4   | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 5   | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 6   | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 7   | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 8   | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 9   | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 10  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG  | <input checked="" type="checkbox"/> |
| 11  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 12  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 13  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 14  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 15  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 16  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 17  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 18  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 19  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 20  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 21  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 22  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 23  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 24  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 25  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 26  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 27  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| 28  | 28/05/19 09:45  | <b>General View</b>                        |  Load JPG | <input checked="" type="checkbox"/> |
| <b>Documentation</b>  |                 |  | 1 per page   | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          | Thumbnail  | Print                               |
| 1   | 30/01/19 17:45  | <b>TP GIA REPORT</b>                       |  Load PDF |                                     |
| 2   | 15/02/19 11:44  | <b>TP SCENE PHOTOS</b>                     |  Load PDF |                                     |
| 3   | 27/02/19 15:28  | <b>TP ESTIMATE- MARKED</b>                 |  Load PDF |                                     |
| 4   | 22/07/19 10:55  | <b>WORKSHOP INVOICE</b>                    |  Load PDF |                                     |
| 5   | 22/07/19 10:55  | <b>LOD</b>                                 |  Load PDF |                                     |
| 6   | 19/08/19 08:38  | <b>AUTHORISATION TO ACT FORM</b>           |  Load PDF |                                     |
| 7   | 19/08/19 08:38  | <b>DISCHARGE VOUCHER</b>                   |  Load PDF |                                     |
| No  | Finalized On    | India International Insurance Pte Ltd (HQ) | Thumbnail  | Print                               |

| Photos/Images |                 |                                   | 3 per page   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1             | 31/01/19 08:50  | Singapore Accident Statement      |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |

| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)  |
|--|
|  |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III19002004/T1PB3Q2

**Date:** 19/08/2019

#### REFERENCE

|   |                     |          |                       |
|---|---------------------|----------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No:          | MCOM0015 |                       |
| Claimant Vehicle No: SLS1867S                           | Insured Vehicle No: | SH7102B  |                       |
| Date of Loss: 27/01/2019                                | Nature of Claim:    | TP       | Claim No: MCT19010811 |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SLS1867S                     | Engine No:  | HIDDEN            |
| Make & Model:               | BMW 335i, 3.0 (A)            | Chassis No: | WBAWL720X0PZ85208 |
| Reg. Date:                  | 30/09/2009 (Man. Year: 2009) | Odometer:   | 41844 km          |
| Colour:                     | Black                        |             |                   |
| Engine Capacity:            | 2979 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 225/40 R18   | Rear Tyre Size:  | 225/40 R18   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                   | Repairer's                  | Adjuster's      | Difference      | Diff %       |
|--|-----------------------------|-----------------|-----------------|--------------|
| Parts  | 2,076.20                    | 80.00           | 1,996.20        | 96.15        |
| Miscellaneous Items                              | 0.00                        | 0.00            | 0.00            |              |
| Labour   | 5,935.00                    | 3,818.00        | 2,117.00        | 35.67        |
| Paintwork Labour                                 | 0.00                        | 0.00            | 0.00            |              |
| Towing   | 0.00                        | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>              | <b>8,011.20</b>             | <b>3,898.00</b> | <b>4,113.20</b> | <b>51.34</b> |
| <b>Approved Total (Overridden) (S\$)</b>         |                             | <b>3,500.00</b> |                 |              |
|  | (S\$)                       | 8,011.20        | 3,500.00        | 4,511.20     |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 560.78                      | 245.00          | 315.78          | 56.31        |
| <b>Nett Amount (S\$)</b>                         | <b>8,571.98</b>             | <b>3,745.00</b> | <b>4,826.98</b> | <b>56.31</b> |
| <b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b> |                             | 400.00          |                 |              |
|  | <b>Nett Liability (S\$)</b> | <b>4,145.00</b> |                 |              |

#### INSPECTION

|                     |                          |  |
|---------------------|--------------------------|--|
| Date of Assignment: | 26/02/2019               |  |
| Date Inspected:     | 26/02/2019 Inspected At: | Performance Motors Limited (Alexandra)<br>303 Alexandra Road, Sime Darby<br>Performance Centre<br>Singapore 159941 |

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

SPECIAL REMARKS

Market Value: \$43,000.00(est)  
less LTA Rebate:\$39,394.00(est)  
Nett Value: \$3,606.00(est)

## REPAIR DETAILS

### Reference

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 22 Jul 2019)   |  |
| <b>Parts:</b>        | N/A  | BMW 335i 3.0 (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLS1867S)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

### Recommended Parts

| No.                      | Qty | Part No. | Particulars                          | Condition     | Repairer's      | Amount       |
|--------------------------|-----|----------|--------------------------------------|---------------|-----------------|--------------|
| 1                        | 1   |          | *SUNDRIES                            | Necessary     | 150.00 FS       | *80.00 FS    |
| 2                        | 1   |          | *RR BUMPER LH GUIDE                  | Not Necessary | 39.30 FS        | *- FS        |
| 3                        | 1   |          | *RR BUMPER RH GUIDE                  | Not Necessary | 39.30 FS        | *- FS        |
| 4                        | 1   |          | *RR BUMPER CTR GUIDE                 | Not Necessary | 47.95 FS        | *- FS        |
| 5                        | 1   |          | *RR BUMPER CARRIER                   | Not Necessary | 458.55 FS       | *- FS        |
| 6                        | 1   |          | *RR BUMPER (M/PDC)                   | Repair        | 1,320.90 FS     | *- FS        |
| 7                        | 4   |          | *DECOUPLING RING PDC TORQUE CONVERTE | Not Necessary | 20.20 FS        | *- FS        |
| <b>Total Parts (S\$)</b> |     |          |                                      |               | <b>2,076.20</b> | <b>80.00</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | REPLACING REAR BUMPER PANEL AND ATTACHMENTS ,REWORKING FRONT BUMPER PANEL, TAIL PANEL AND TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT | New      | 2,550.00        | 1,700.00        |
| 2                               | SPRAY REAR BUMPER ,TAIL PANEL ,FRONT BUMPER   | New      | 2,819.00        | 1,868.00        |
| 3                               | TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS             | New      | 295.00          | 250.00          |
| 4                               | TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS   | New      | 271.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>5,935.00</b> | <b>3,818.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >