

ASS. REC. BY:

REF:

es/c7119002006/Ttd3

n2

Special Instruction:

Surveyor

\*Mennen

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time:

30/11/19 @ 4:32pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8JL 5151H

Insured:

PA 3Y

at Workshop m/s

Mora

Tel:

62723892

of

Blk 1008 Blk Meruh June 3 #01-04

Policy No:

Claim No:

8NM19D200535

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

5:43pm @ 30/11/19

Person Contacted:

Mora

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	8JL 5151H-CS/DAI 12019162/Akn DOA: 5/10/2012
	PA 3Y-X
	lump sum \$850/- (Red: 581.76; 40%)

Tunji

REF: CTL

ASSIGNMENT

CoE 2023 Nov.

2008 Nov.

From: Date: 3.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: S3L 5151H

at Workshop m/s: Nova Automotive

of BIK 1008 Bukit Merah Lane 3 # 01-04/06/06

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: Itava-m owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

mp"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: S3L5151H

Vr Reg:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make:

Honda Fit

CC

1339

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading:

167563

T/Radio:

Insured / Std / NI / NA

Eng/No:

GE61092904

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

3/9/19 2115

Survey held at

Mova BM.

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 06 OCT 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 8/10 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS: \$

) Photos

) Others

)

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

850

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2019		30 Jan 2019 16:32 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	
Main Claimant:	LIM YUEH SHYAN
Vehicle Reg. No.:	SJL5151H
Claim Type:	TP / SNM19D200535
Vehicle Reg. No. (Insured):	PA3Y
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/02/2019]

<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>
There are no mail for this case.		

<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>
Due Date	Priority	Type
Task Group	Subject	Handler
Assigned By	Completed On	Created On
Done?		

No results.

This vehicle cannot close

## Nivitha (LKK Auto)

---

**From:** Catherine Thia <catherine.thia@sg.cntaiping.com>  
**Sent:** Wednesday, 30 January 2019 4:29 PM  
**To:** assignments  
**Cc:** nitha@moa.com.sg  
**Subject:** FW: TP CLAIMS - SJL5151H AGAINST PA3Y DOA 18/01/2019 AT LOWER DELTA ROAD  
**Attachments:** RPT.pdf; EST.pdf

Dear LKK oic,

Please attend to the PRI assignment. We will create in Merimen shortly

Thanks

### Catherine Thia

Senior Executive  
Motor Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6193  
[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



#### Disclaimer :

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Claims Dept of CTI  
**Sent:** Wednesday, 30 January, 2019 4:27 PM  
**To:** Catherine Thia <catherine.thia@sg.cntaiping.com>  
**Subject:** TP CLAIMS - SJL5151H AGAINST PA3Y DOA 18/01/2019 AT LOWER DELTA ROAD

From: Nitha [mailto:nitha@nova.com.sg]

Sent: Monday, 28 January, 2019 4:30 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: ongbobo@nova.com.sg; 'ann' <suann@nova.com.sg>

Subject: TP CLAIMS - SJL5151H AGAINST PA3Y DOA 18/01/2019 AT LOWER DELTA ROAD

Dear Sir/Madam,  
Good day

REF : PA3Y

Kindly assist revert officer in charge and liability and arrange survey for the above mention case.

Thank you,

Best Regards,

*Nitha*

Claims Officer

Nova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Denise Tay (LKKAuto)

---

**From:** Bobo Ong <ongbobo@mova.com.sg>  
**Sent:** Tuesday, 8 October 2019 2:28 PM  
**To:** Denise Tay (LKKAuto); SUR  
**Cc:** 'Jacelyn'  
**Subject:** RE: SJL5151H FINALISATION

Dear Denise

Confirmed, thanks.

Best Regards,

Bo Bo

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

---

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Tuesday, 8 October 2019 11:21 AM  
**To:** Bobo Ong; SUR  
**Cc:** 'Jacelyn'  
**Subject:** RE: SJL5151H FINALISATION

Dear Bobo,

Lump sum \$850, 2 Days.

Please check and confirm

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Bobo Ong <ongbobo@mova.com.sg>  
**Sent:** Tuesday, 8 October 2019 9:36 AM  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Jacelyn' <[jacelyn@mova.com.sg](mailto:jacelyn@mova.com.sg)>  
**Subject:** FW: SJL5151H FINALISATION

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Foreign Identification Number
Owner ID:	5679L

**Vehicle Details**

Vehicle No.:	SJL5151H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A4102899
Chassis No.:	GE61092904
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,965.00
Original Registration Date:	28 Nov 2008
First Registration Date:	28 Nov 2008
Transfer Count:	3
Actual ARF Paid:	\$12,965.00

**Intended PARF Rebate Details**

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	27 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$14,365.00
<b>Total Rebate Amount:</b>	<b>\$14,365.00</b>

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Jan 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/01/2019 14:52
Date Of Accident	18/01/2019 19:40
Exact Location Of Accident	LOWER DELTA ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL5151H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM YUEH SHYAN
Passport No/FIN	G3095679L
Email Address	YUEHSHYAN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91060921
Alternative Phone No	OFFICE-91060921

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT-1.3 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA412526
Cover Note Number	

### Driver

Name of Driver	LIM YUEH SHYAN
Passport No/FIN	G3095679L
Date Of Birth	01/11/1990
Occupation	INDOOR
Date Of Driving Pass	26/02/2018
Driving Experience	0 YEAR AND 10 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-91060921
Fax Number	
Contact Number	OFFICE-91060921
EMail Address	YUEHSHYAN@HOTMAIL.COM



Address	NCH SINGAPORE PTE LTD
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA3Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time: 24 / 01 / 2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SJL 5151H	ACCIDENT DATE & TIME: 18/01/2019 19:40
CONTACT NUMBER: 9106 0921	E-MAIL ADDRESS: yuehshyan@hotmail.com
LOCATION: Lower Delta Road	
<p>Driving along Lower Delta Road travelling to Sentosa. I came into a traffic light and stopped. There was a bus in front, vehicle number registered PA3Y, stopping and waiting for the traffic light also. Then realised that the bus have slowly moving backward &amp; came nearer to my car. I had honked a few times before the bus hit my car head. The bus showed no sign of stopping &amp; hit into my car. The driver ran away from the incident.</p> <p style="text-align: center;">bus</p>	
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>	
Please state:	
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only	

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 24/01/2019

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

## Sketch Plan Pg. 3



**SINGAPORE  
POLICE FORCE**



T/20190118/7023

1 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190118/7023

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/01/2019 21:17		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: LIM YUEH SHYAN			Address: APT BLK 94 HAVELOCK ROAD #04-577 HAVELOCK HEIGHTS SINGAPORE 160094		
ID Type / ID No.: FIN NO / G3095679L			Contact No.: Home/Office: Mobile: 91060921		
Nationality: MALAYSIAN			Email: yuehshyan@hotmail.com		
Sex: Female	Age: 28	Date of Birth: 01/11/1990	Type of Informant: Vehicle Owner		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Other chemical engineers			Driving Licence Information: Class: Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 18/01/2019 19:40	Type of Location: Straight Road
Location:  Lower Delta Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
P A 3 Y	Bus/Coach/Mi nibus			Black		0
SJL 5151 H	Car			White	Slightly Damaged	1

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Sketch Plan Pg. 4



**SINGAPORE  
POLICE FORCE**



T/20190118/7023

2 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190118/7023

## CONTINUATION OF REPORT

Vehicle Owner			
Name	LIM YUEH SHYAN	ID No.	G3095679L
Related Vehicle	NIL	Contact No.	91060921
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

## Brief Details.

I was driving along Lower Delta Road travelling to Sentosa. I came into a traffic light and stopped. There was a bus in front, vehicle number registered PA3Y, stopping and waiting for the traffic light also. Then I realised that the bus have slowly moving backward and came nearer to my car. I had honked a few times before the bus hit my car head. However, the bus showed no sign of stopping and hit into my car, while I was honking continuously. After the bus hit, I pulled off my handbrake, expecting the driver would come down, however, the bus straight away moving forward when the traffic light turned green, as if nothing had happened. I was able to follow the bus from behind until the bus had turned into AYE (Tuas), at which, we got separated as I continuously driving along Lower Delta Road.

I have the whole video of incident being recorded down with dashboard camera installed in my car, however, I could not able to upload as attachment. I have saved copies of the related videos.

It happened at traffic light along Lower Delta Road, opposite of Cendex Centre.

I was travelling along Lower Delta Road, from my house Block 94 Havelock Road moving towards Sentosa.

No, the incident did not take place at a pedestrian crossing.

Sketch Plan Pg. 5



**SINGAPORE  
POLICE FORCE**



T/20190118/7023

3 of 3

Report No. T/20190118/7023

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
ESTHER CHONG  
Contact No.: 65476368

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
18/01/2019 21:17

Classification Of Case:

**Main Office:**  
Mova Building  
No. 22, Jalan Klang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

25/01/2019

CHINA TAIPING INSURANCE (S) PTE LTD  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909.

Page # :- 1  
Veh # :- SJL5151H  
Veh Model :- HONDA FIT  
Estimate# :- CK418626  
Claim # :-  
ACC. Date :- 18/01/19  
Terms :- C.O.D Days  
Remarks :-

Attention :- XA017

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	FRONT GRILLE (AFTER MARKET)	1 PC	156.00	156.00
2.	FRONT GRILLE LOGO	1 PC	45.00	45.00
3.	FRONT REINFORCEMENT	1 PC	231.20	231.20
4.	FRONT BUMPER CLIPS	10 PC	5.00	50.00
5.	HEADLAMP RH	1 PC	620.00	620.00
6.	BRACE PANEL - CHECK	1 PC		
LIST TOTAL S\$				1,102.20
20% DISCOUNT S\$				-220.44
				881.76
<b>LABOUR :</b>				
TO REMOVE & REPLACE DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS				200 300.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				200 250.00
LABOUR TOTAL S\$				550.00

E. & O.E

NON-TAX AMOUNT S  
AMOUNT S\$ 1,431.76  
GST @ 7 % 100.22  
AMOUNT DUE S\$ 1,531.98

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Parts = \$851.00  
20% = \$168.00  
Labour = \$400.00  
\$1080.00  
Lumpsum 20% = \$864.64  
\$850.00  
# 2 Repair days

Twighan 9749544  
wp  
3/1/19 11:15  
Repair after repair  
2 days  
surellmova.com

# Estimate

25/01/2019

**CHINA TAIPING INSURANCE (S) PTE LTD**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909.**

Attention :- **XA017**

Page # :- 1  
 Veh # :- SJL5151H  
 Veh Model :- HONDA FIT  
 Estimate# :- CK418626  
 Claim # :-  
 ACC. Date :- 18/01/19  
 Terms :- C.O.D Days  
 Remarks :-

**Main Office:**  
 Mova Building  
 No. 22, Jalan Kilang,  
 Singapore 159419  
 Tel : (65) 6476 3333  
 Fax : (65) 6271 5891  
 www.mova.com.sg  
**Workshop Dept:**  
 Block 1008,  
 Bukit Merah Lane 3,  
 #01-04/06/08/94  
 Singapore 159722  
 Tel : (65) 6272 3892  
 Fax : (65) 6270 8314  
 Co. Reg. 198904033G  
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	FRONT GRILLE (AFTER MARKET)	1 PC	156.00	156.00
2.	FRONT GRILLE LOGO	1 PC	45.00	45.00
3.	FRONT REINFORCEMENT	1 PC	231.20	231.20
4.	FRONT BUMPER CLIPS	10 PC	5.00	50.00
5.	HEADLAMP RH	1 PC	620.00	620.00
6.	BRACE PANEL - CHECK	1 PC	?	620.00
LIST TOTAL S\$				1,102.20
20% DISCOUNT S\$				-220.44
				881.76
<b>LABOUR :</b>				
TO REMOVE & REPLACE DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS				200 300.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				200 250.00
LABOUR TOTAL S\$				550.00

E. & O.E

NON-TAX AMOUNT S  
 AMOUNT S\$ 1,431.76  
 GST @ 7 % 100.22  
 AMOUNT DUE S\$ 1,531.98

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

*[Signature]*  
 5/9/19

Tanjong 97495449  
 WP.  
 3/9/19 1115  
 Repairing after repair  
 2 days  
 surellhanda.com



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19002006/T1TD3N2

Date: 10/10/2019

**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: NA  
 Claimant Vehicle No : SJL5151H Insured Vehicle No : PA3Y  
 Date of Loss: 18/01/2019 Nature of Claim: TP Claim No: SNM19D200535

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: SJL5151H  
 Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A4102899  
 Reg. Date: 28/11/2008 (Man. Year: 2008) Chassis No: GE61092904  
 Colour: White Odometer: 167563 km  
 Engine Capacity: 1339 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	881.76	680.80	200.96	22.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	400.00	150.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>1,431.76</b>	<b>1,080.80</b>	<b>350.96</b>	<b>24.51</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>850.00</b>		
<b>(\$\$)</b>	1,431.76	850.00	581.76	40.63
<b>+ GST 7.00/7.00% (\$\$)</b>	100.22	59.50	40.72	40.63
<b>Nett Amount (\$\$)</b>	<b>1,531.98</b>	<b>909.50</b>	<b>622.48</b>	<b>40.63</b>

**INSPECTION**

Date of Assignment: 30/01/2019  
 Date Inspected: 03/09/2019 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)  
 Blk 1008, #01-04/06/08/94, Bukit Merah  
 Lane 3  
 Singapore 159722

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2019)
<b>Parts:</b> 144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJL5151H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE (AFTER MARKET)	Cracked	156.00 FL	*156.00 FL
2	1		*FRONT GRILLE LOGO	Necessary	45.00 FL	*45.00 FL
3	1		*FRONT REINFORCEMENT	Not Necessary	231.20 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
5	1		*HEADLAMP RH	Cracked	620.00 FL	*620.00 FL
6	1		*BRACE PANEL (NPA)	Not Necessary	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,102.20</b>	<b>851.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	220.44	170.20
<b>Total Parts (\$\$)</b>	<b>881.76</b>	<b>680.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE DAMAGED PARTS,STRAIGHTEN & REALIGN AFFECTED AREAS	New	300.00	200.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	250.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>550.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >