



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002011/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 09-04-2020



ATTN:PETER

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 318D	Veh. Inspected	SLR 9690L
Policy No.	VFX/P1582555	Coverage (\$)	0.00
Claim No.	S9M01CD4	Excess (\$)	0.00
Assign From		Assign Date	30/01/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C350 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2050472F423647	Colour	METALLIC BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/35Z R19	MICHELIN	8 mm
L/H Front Tyre	245/35Z R19	MICHELIN	8 mm
R/H Rear Tyre	275/30Z R19	MICHELIN	8 mm
L/H Rear Tyre	275/30Z R19	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/01/2019	Inspection Date	31/01/2019
Survey held at	160 SIN MING DRIVE		
Repairer	MBM WHEELPOWER PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------