



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 29/01/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SMB1346G
Case Reference Number	BUS/01/19/1069
Registration Date	15/4/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Rahmad Bin Abdul Majid
Type of Accident	Side Swipe
Accident Date and Time	25/1/2019 12:00 PM
Accident Reported Date and Time	25/1/2019 1:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1346G - left front portion EL202L (TP) - INSURED WITH AIG. right rear portion
Prepared Date and Time	29/1/2019 11:33 AM
Chassis Number	WMAA22ZZ4D7001793
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$446.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$976.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days		
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date		
Signature	<input type="text"/>	<input type="text"/>
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/01/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$530.00 265	
Total Labour	\$530.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$446.00 324	
Total Spray Painting & Panel Beating	\$446.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	F01001-CW264	COVER, HEADLAMP-FRT LH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair X NN	
Total					\$974.70		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Hwee Jie-LKK
29/1/19
L/S 1 days
g:
Photo after paint