

ASS. REC. BY:

REF:

CS/CT19002021/Kvd327

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Catherine Pina

of CTI

Date/Time: 30/1/2019

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR5828H

Insured: GY 2501T

at Workshop m/s Cheng Hoo Motor

Tel: 67556142

of BIK1019 Yehum Ind Pk #01-37H

Policy No:

Claim No: 8NM19D200507

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SJR5828H-X
	GY2501T-NA/CT19001714/z4 SOA: 26/1/2019
14/5/19	LS \$900 confirmed by email (Real 524.55, 37%)

ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: B13k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STR 582814 Yr Regn: 06, 09Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Syiphy C.C. 1498Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 147537 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BAA 41180110051Gen. Cond: Good Fair / Poor / BurntSteering: In order Jammed / Leaked / Burnt orBrake: In order Jammed / Leaked / Burnt orModl: NI S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 26/1/19

Survey held at

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 26/2/19Des. of Damages: Front Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 14 MAY 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 14/5 - typist

Report Format:

Lump Sum / I.B.I. (\$

merimen

900/-

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

: Fuel

: Others

TOTAL

220

220

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2019 Sendback Est	26 Feb 2019 13:16 S\$1,424.55	31 Jan 2019 12:58 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	SHAHRL IZWAN BIN SUBOH								
Vehicle Reg. No.:	SJR5828H	Date of Loss:	26/01/2019 00:00 - :59 [114 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200507	Policy/Cover Note No.:	NA						
Vehicle Reg. No. (Insured):	GY2501T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 13/02/2019]								
Driver/Custodian (Insured):	RAMASAMY VIDUTHALAIPULI (/ Male) , Tel: +6593974927 Email:								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Thursday, 31 January 2019 12:04 PM
To: assignments
Cc: shujuan@automotiverepaircentre.com.sg
Subject: PRI request (TPV SJR5828H) (OIV GY2501T)
Attachments: 20190131115424.pdf

Dear LKK oic

Please attend to the PRI assignment. We will create in Merimen shortly

Thanks

Catherine Thia

Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6193

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: slnx@sg.chinataiping.com [mailto:slnx@sg.chinataiping.com]
Sent: Thursday, 31 January, 2019 11:55 AM
To: Catherine Thia <catherine.thia@sg.cntaiping.com>
Subject:

at ①

Evon Char

From: Lin Shu Juan <shujuan@automotiverepaircentre.com.sg>
Sent: Tuesday, January 29, 2019 1:56 PM
To: Claims Dept of CTI
Cc: raymond@automotiverepaircentre.com.sg
Subject: SJR5828H - TP Claim against GY2501T - PRS
Attachments: SAS2543298.PDF; EST1901-008 SJR5828H.pdf

D4CUSN
1605548022
Shm 190200507

Dear Person-in-charge,

Our client's vehicle SJR5828H wants to make a third party claim against GY2501T which is insured by China Taiping Insurance Pte. Ltd.

Kindly let us know the Claim officer in-charge for liability / settlement of our client's claim.

T 16934

E.g. your principle's advice on the validity of the policy holder.

*Please send us your top 10 surveyor companies for survey.

Thank you.

LH.

Best Regards,
Lin Shu Juan

Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18
Singapore 757700
Tel: +65 6468 8834
Fax: +65 6462 2278

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	0206E

Vehicle Details

Vehicle No.:	SJR5828H
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	HR15155511B
Chassis No.:	JN1BAAG11Z0110051
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$19,528.00
Original Registration Date:	30 Jun 2009
First Registration Date:	30 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$19,528.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2019
PARF Rebate Amount:	\$9,764.00

Intended COE Rebate Details

COE Expiry Date:	29 Jun 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$8,501.00
COE Rebate Amount:	\$306.00
Total Rebate Amount:	\$10,070.00

The information contained herein is correct as at 19 Feb 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/01/2019 12:41
Date Of Accident	26/01/2019 16:10
Exact Location Of Accident	OUTSIDE GSC AUTOMOTIVE (NORTHLINK BUILDING)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR5828H
Insured/Policyholder	
Name Of Registered Owner	SHHRUL IZWAN BIN SUBOH
NRIC No	S7700206E
Email Address	BABY_TULIPS13@YAHOO.COM
Mobile Phone No	(LOCAL) +65-90905908
Alternative Phone No	OTHERS-83667389

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00395395/01
Cover Note Number	

Driver

Name of Driver	SHHRUL IZWAN BIN SUBOH
NRIC No	S7700206E
Date Of Birth	06/01/1977
Occupation	OUTDOOR
Date Of Driving Pass	29/11/2011
Driving Experience	7 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90905908
Fax Number	
Contact Number	OTHERS-83667389
EMail Address	BABY_TULIPS13@YAHOO.COM

Address	BLK 583 WOODLANDS DRIVE 16 #03-454
Postcode	730583
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MARWIYAH BINTE MOHAMED RAWI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MRS SOH
Phone Number	94520288
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	GY2501T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	RAMASAMY VIDUTHALAIPULI
NRIC/Passport Number	G8327084K
Contact Number	93974927
Address	



Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The car is in stationary position when the lorry hit the car while reversing. The incident happened during outside ASC Auto at Northline Building. The driver has stopped the car in order to allow his passenger to alight. His passenger needs to remove her seatbelt and take her handbag before alighting. The moment she steps out of the car and closed the door, the driver had reversed and hit the car. This should allow the lorry driver ample time to check his blind spot.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28/01/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/ID No:

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 28/01/2019

1229 HRS

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

-

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA
Policy No:	NA	Date of Loss:	26/01/2019
Vehicle Reg. No.:	SJR5828H	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	SHHRUL IZWAN BIN SUBOH	Driver (Insured):	RAMASAMY VIDUTHALAIPULI
Make/Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Vehicle Reg. Date:	30/06/2009
Vehicle Colour:	GREY		
Engine No:	HR15155511B	Chassis No:	JN1BAAG11Z0110051
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS	Amount
Parts	588.00
Miscellaneous Items	300.00
Labour	536.55
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,424.55
+ GST 7.00% (S\$)	99.72
Nett Amount (S\$)	1,524.27

This claim is handled by: EFEEDA BINTE MOHAMED OTHMAN*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2019)**Parts:** 143 NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SJR5828H/26/02/2019 13:16**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*L/R BUMPER BRACKET	0.00	0.00	*23.00 F
2	1	NA	*L/R LAMP	0.00	0.00	*200.00 F
3	1	NA	*REAR BUMPER	0.00	0.00	*280.00 F
4	1	NA	*REAR BUMPER MOULDING	0.00	0.00	*85.00 F

F=Franchise part.

Total Parts (S\$) **588.00**

Cheng Hoe Motor Pte Ltd/SJR5828H/26/02/2019 13:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	REVERSE SENSOR	200.00
2	1	SUNDRY	100.00
Sub Total (S\$)			300.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	281.40
2	Total Paint Materials	New	103.95
3	Total Panel/Mechanical Labour	New	151.20
Gross Labour Cost (S\$)			536.55

Cheng Hoe Motor Pte Ltd/SJR5828H/26/02/2019 13:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SJR5828H
TP/china

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference:
Assessment number: A0013
Version: 1810
Date calculated: 02/26/2019 01:08 PM

Full Report
Registration: SJR5828H
Printed: 26/02/2019 1:10 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-26
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	SYLPHY
Sub Model:	BASE MODEL
Model Sheet Number:	71 BL 01
Registration:	SJR5828H
VIN number:	JN1BAAG11Z0110051
Odometer:	

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference:
 Assessment number: A0013
 Version: 1810
 Date calculated: 02/26/2019 01:08 PM

Full Report
 Registration: SJR5828H
 Printed: 26/02/2019 1:10 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☒
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
UC10A1	R + R REAR BUMPER INCLUDES: R + R TAILLAMPS		11.0	46.20
UC12A1)	RENEW REAR BUMPER		1.0	4.20
NO NUMBER	R + R REAR BUMPER CARRIER		1.0	4.20
NO NUMBER	R + R REAR BUMPER MOULDING		1.0	4.20
VB34A1	R + R REAR END PANEL TRIM		2.0	8.40
2711	REAR PANEL REPAIR		10.0*	42.00
3481	L/R SIDE PANEL REPAIR		10.0*	42.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		3.60	36.0	151.20
Total of Labour				151.20

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference:
 Assessment number: A0013
 Version: 1810
 Date calculated: 02/26/2019 01:08 PM

Full Report
 Registration: SJR5828H
 Printed: 26/02/2019 1:10 PM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		9.0	
	REAR PANEL REPAIR PAINTING >50%		17.0	
	L/R SIDE PANEL REPAIR PAINTING >50%		21.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	37.69
2711	REAR PANEL REPAIR PAINTING >50%	15.73
3481	L/R SIDE PANEL REPAIR PAINTING >50%	23.43

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			47.0	
Preparation Main Work Metal		1.70	17.0	71.40
Preparation Comp. Work Plastic		0.30	3.0	12.60
Total	10 WU/h	6.70	67.0	281.40

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	37.69
Repair Painting	39.16
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	103.95

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Supplier	Price SGD	
2583	REAR BUMPER	85022 EW025		280.00	✓
2611	REAR BUMPER	85072 EW000		85.00	✓
	MOULDING				
2617	L/R BUMPER BRACKET	85227 EW000		23.00	✗
3291	L/R LAMP	26559 EW00B		200.00	✓
Savings				0.00	

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference:
 Assessment number: A0013
 Version: 1810
 Date calculated: 02/26/2019 01:08 PM

Full Report
Registration: SJR5828H
Printed: 26/02/2019 1:10 PM

Subtotal	588.00
Fixed Sundry Parts Price	100.00
Total	688.00

Extras

Code	Description	Price SGD
1001	REVERSE SENSOR	200.00*
	Total Extras	200.00

Final Calculation

	SGD	SGD
Parts	588.00	
Fixed Sundry Parts Price	100.00	
Total Parts		688.00
Labour Time Base 10 WU/h		
Total 36.0 WU X 42.00 SGD/h	151.20	
Total of Labour		151.20
Total Of Extras		200.00
Paint Work Time Base 10 WU/h		
Labour Cost 67.0 WU X 42.00 SGD/h	281.40	
Material Cost	103.95	
Total Paint Including Material		385.35
Repair Cost Excludes GST		1,424.55
GST (+7.0%)		99.72
Repair Cost Included GST		1,524.27

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after any painting
- To display damaged section during survey
- Parts photo are to be taken immediately
- Third party survey with a witness (Inspector) to be
- No illegal modification is allowed
- Supplemental work to be approved and is subject to the approval from Insurance Company

Acknowledged by:
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd
#01-374/382,Blk 1019, Yishun
Industrial Park A
768761

Claim Reference:
Assessment number: A0013
Version: 1810
Date calculated: 11/05/2019 2:27 PM

Full Report
Registration: SJR5828H
Printed: 11/05/2019 2:37 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:		Date of Incident:	26/01/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	SYLPHY
Sub Model:	BASE MODEL
Model Sheet Number:	71 BL 01
Registration:	SJR5828H
VIN number:	JN1BAAG11Z0110051
Odometer:	

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference:
Assessment number: A0013
Version: 1810
Date calculated: 11/05/2019 2:27 PM

Full Report
Registration: SJR5828H
Printed: 11/05/2019 2:37 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
UC10A1	R + R REAR BUMPER INCLUDES: R + R TAILLAMPS		11.0	46.20
UC12A1)	RENEW REAR BUMPER		1.0	4.20
NO NUMBER	R + R REAR BUMPER MOULDING		1.0	4.20
VB34A1	R + R REAR END PANEL TRIM		2.0	8.40
2711	REAR PANEL REPAIR		5.0*	21.00
3481	L/R SIDE PANEL REPAIR		5.0*	21.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.50	25.0	105.00
Total of Labour				105.00

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference:
 Assessment number: A0013
 Version: 1810
 Date calculated: 11/05/2019 2:27 PM

Full Report
 Registration: SJR5828H
 Printed: 11/05/2019 2:37 PM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		9.0	
	REAR PANEL REPAIR PAINTING >50%		17.0	
	L/R SIDE PANEL REPAIR PAINTING >50%		21.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	37.69
2711	REAR PANEL REPAIR PAINTING >50%	15.73
3481	L/R SIDE PANEL REPAIR PAINTING >50%	23.43

Labour Cost - Paint

		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			47.0	
Preparation Main Work Metal		1.70	17.0	71.40
Preparation Comp. Work Plastic		0.30	3.0	12.60
Total	10 WU/h	6.70	67.0	281.40

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	37.69
Repair Painting	39.16
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	103.95

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	85022 EW025		280.00
2611	REAR BUMPER	85072 EW000		85.00
	MOULDING			
3291	L/R LAMP	26559 EW00B		200.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			565.00
u: Used parts				

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Claim Reference:
 Assessment number: A0013
 Version: 1810
 Date calculated: 11/05/2019 2:27 PM

Full Report
 Registration: SJR5828H
 Printed: 11/05/2019 2:37 PM

Fixed Sundry Parts Price	100.00
Total	665.00

Final Calculation

	SGD	SGD
Parts	565.00	
Fixed Sundry Parts Price	100.00	
Total Parts		665.00
Labour Time Base 10 WU/h		
Total 25.0 WU X 42.00 SGD/h	105.00	
Total of Labour		105.00
Paint Work Time Base 10 WU/h		
Labour Cost 67.0 WU X 42.00 SGD/h	281.40	
Material Cost	103.95	
Total Paint Including Material		385.35
Repair Cost Excludes GST		1,155.35
GST (+7.0%)		80.87
Repair Cost Included GST		1,236.22

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
Assessment number: A0013
Version: 1810
Date calculated: 13/05/2019 11:00 AM

Full Report
Registration: SJR5828H
Printed: 13/05/2019 11:00 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	26/01/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	NISSAN
Model:	SYLPHY
Sub Model:	BASE MODEL
Model Sheet Number:	71 BL 01
Registration:	SJR5828H
VIN number:	JN1BAAG11Z0110051
Odometer:	

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: A0013
 Version: 1810
 Date calculated: 13/05/2019 11:00 AM

Full Report
 Registration: SJR5828H
 Printed: 13/05/2019 11:00 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☒
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
UC10A1	R + R REAR BUMPER INCLUDES: R + R TAILLAMPS		11.0	46.20
UC12A1)	RENEW REAR BUMPER		1.0	4.20
NO NUMBER	R + R REAR BUMPER MOULDING		1.0	4.20
VB34A1	R + R REAR END PANEL TRIM		2.0	8.40
2711	REAR PANEL REPAIR		5.0*	21.00
3481	L/R SIDE PANEL REPAIR		5.0*	21.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.50	25.0	105.00
Total of Labour				105.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: A0013
 Version: 1810
 Date calculated: 13/05/2019 11:00 AM

Full Report
 Registration: SJR5828H
 Printed: 13/05/2019 11:00 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		9.0	
	REAR PANEL REPAIR PAINTING >50%		17.0	
	L/R SIDE PANEL REPAIR PAINTING >50%		21.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	37.69
2711	REAR PANEL REPAIR PAINTING >50%	15.73
3481	L/R SIDE PANEL REPAIR PAINTING >50%	23.43

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			47.0	
Preparation Main Work Metal		1.70	17.0	71.40
Preparation Comp. Work Plastic		0.30	3.0	12.60
Total	10 WU/h	6.70	67.0	281.40

Material Cost - Paint		Price SGD
New Part Painting - Plastic K1R		37.69
Repair Painting		39.16
Material-constant Metal		18.10
Material-constant Plastic		9.00
Total		103.95

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	85022 EW025		280.00
2611	REAR BUMPER MOULDING	85072 EW000		85.00
3291	L/R LAMP	26559 EW00B		200.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			565.00
u: Used parts				

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: A0013
 Version: 1810
 Date calculated: 13/05/2019 11:00 AM

Full Report
Registration: SJR5828H
Printed: 13/05/2019 11:00 AM

Fixed Sundry Parts Price	100.00
Total	665.00

Final Calculation

	SGD	SGD
Parts	565.00	
Fixed Sundry Parts Price	100.00	
Total Parts		665.00
Labour Time Base 10 WU/h		
Total 25.0 WU X 42.00 SGD/h	105.00	
Total of Labour		105.00
Paint Work Time Base 10 WU/h		
Labour Cost 67.0 WU X 42.00 SGD/h	281.40	
Material Cost	103.95	
Total Paint Including Material		385.35
Repair Cost Excludes GST		1,155.35
GST (+7.0%)		80.87
Repair Cost Included GST		1,236.22

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 14 May 2019 12:23 PM
To: Efeeda (Cheng Hoe -Yishun)
Cc: SUR
Subject: RE: SJR5828H DOA:26/1/19 TP/CHINA

Dear Efeeda,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>
Sent: Tuesday, 14 May 2019 12:05 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: SJR5828H DOA:26/1/19 TP/CHINA

Hi Veron,

Confirmed as below.

Thank u.

Rgds
Efeeda
Cheng Hoe Motor PL
Tel:67556142
Fax:67557719

From: Veron Chen (LKKAUTO)
Sent: Monday, May 13, 2019 11:07 AM
To: Efeeda (Cheng Hoe -Yishun) ; Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: RE: SJR5828H DOA:26/1/19 TP/CHINA

Dear Efeeda,

WITHOUT PREJUDICE

Offer Lump Sum \$900 @ 2 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Efeeda (Cheng Hoe -Yishun) <chmotor@singnet.com.sg>

Sent: Saturday, 11 May 2019 2:46 PM

To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>

Subject: SJR5828H DOA:26/1/19 TP/CHINA

Hi Kenneth,

Photos and finalization list as attached.

Please let us have your confirmation on the final sum – **\$1155.35 / 3 DAYS** via reply email.

Thank you.

Rgds
Efeeda
Cheng Hoe Motor PL
Tel:67556142
Fax:67557719

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2019 Sendback Est	26 Feb 2019 13:16 S\$1,424.55	31 Jan 2019 12:58 Edit Adj Rpt	S\$900.00 Edit Estimates	S\$900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: -, Co. Reg. No.: -									
Main Claimant: SHAHROL IZWAN BIN SUBOH									
Vehicle Reg. No.: SJR5828H		Date of Loss: 26/01/2019 00:00 - :59 [114 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D200507		Policy/Cover Note No.: NA							
Vehicle Reg. No. (Insured): GY2501T		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/02/2019]									
Driver/Custodian (Insured): RAMASAMY VIDUTHALAI PULI (/ Male) , Tel: +6593974927 Email:									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJR5828H (SNM19D200507)
[GY2501T]

TP

SHAHRUL IZWAN BIN SUBOH

Jan 26 2019 12:00AM

[-]

Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print		
1	26/02/19 13:16	Repairer Estimates		Load HTML			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	13/05/19 10:51	General View		Load PDF			
2	13/05/19 10:52	Reinspection Photo		Load PDF			
Documentation						1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print		
1	26/02/19 13:14	E-filed GIA report		Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19002021/KVD3E2

Date: 15/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: NA

Claimant Vehicle No: SJR5828H

Insured Vehicle No: GY2501T

Date of Loss: 26/01/2019

Nature of Claim: TP

Claim No: SNM19D200507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR5828H

Make & Model: NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A) Engine No: HR15155511B

Reg. Date: 30/06/2009 (Man. Year: 2009)

Chassis No: JN1BAAG11Z0110051

Colour: Metallic Grey

Odometer: 147537 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Nexen 8 mm

Rear Left Side: Nexen 8 mm

Front Right Side: Nexen 8 mm

Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	588.00	565.00	23.00	3.91
Miscellaneous Items	300.00	100.00	200.00	66.67
Labour	536.55	490.35	46.20	8.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,424.55	1,155.35	269.20	18.90
Approved Total (Overridden) (S\$)		900.00		
(S\$)	1,424.55	900.00	524.55	36.82
+ GST 7.00/7.00% (S\$)	99.72	63.00	36.72	36.82
Nett Amount (S\$)	1,524.27	963.00	561.27	36.82

INSPECTION

Date of Assignment: 31/01/2019 Present Location:

Date Inspected: 26/02/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2019)
Parts:	143	NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR5828H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/R BUMPER BRACKET	Repair	23.00 F	*. F
2	1	NA	*L/R LAMP	Cracked	200.00 F	*200.00 F
3	1	NA	*REAR BUMPER	Bent	280.00 F	*280.00 F
4	1	NA	*REAR BUMPER MOULDING	Necessary	85.00 F	*85.00 F
Total Parts (S\$)					588.00	565.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REVERSE SENSOR (SERVICEABLE)	200.00	0.00
2	1	SUNDRY (NECESSARY)	100.00	100.00
Sub Total (S\$)			300.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	281.40	281.40
2	Total Paint Materials	New	103.95	103.95
3	Total Panel/Mechanical Labour	New	151.20	105.00
Gross Labour Cost (S\$)			536.55	490.35

Report was unsubmitted during this print-out.

< END OF ESTIMATES >