

ASS. REC. BY:

REF: CS3/SM019002042/Gcd301

Special Instruction:

Surveyor:  
menmen

(Auto direct)

ASSIGNMENT (Office)

From (Person): chen shu hui aghes

of

SMO

Date/Time:

30/11/19 @ 4.17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 3885X

Insured:

YN 753R

at Workshop m/s

MI Motoring

Tel:

6266 7030 / 97988118

of

34 tuh Guen Rd East # 01-29

Policy No:

D18M74CVC 002627

Claim No:

CM7D1900652

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/01/2019

CA / REV / REP. / REV 24 HRS

'up

H.O.D. Endorsement:

Date/Time: 1030am @ 31/1/19

Person Contacted:

Albert

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate	Insp: 411 chengji Road
	FBN 3885X-X	
	YN 753R-NS/INC14023367/14/vbk3	DOA: 16/12/2014

08/11/15  
Surveyor

PRS  
Xhd.


REF: SMO

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s M1 Motoring  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FBN 3885 X Yr Regn: Sep / 18  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Yamaha TMAX530cc 530  
Colour: Black A/C: Insured / Std / NI / NA  
Sp.Reading: - T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: -  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: M / S/Rim / STD A/Rim or  
Tyre Size: F: 120/70R15  
R: 160/60R15  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front Rear  
R/Bal. 5 mm R/Bal. 5 mm  
L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm  
D.O.A. \_\_\_\_\_ D.O.I. 31-01-19  
Survey held at w/s 12/15  
Des. of Damages: Frt / Rear / O/S / M/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation: \_\_\_\_\_ S + RS. \_\_\_\_\_ SI

Photos

Others

TOTAL

Report Format : PRQ

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

100
10
110

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2019		30 Jan 2019 16:17 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PECK TIONG CHOON LEASING PTE LTD, Co. Reg. No.: 199204891W		
Main Claimant:	MUHAMMAD FARHAN BIN AMAN, ID: S8627100A		
Vehicle Reg. No.:	FBN3885X	Date of Loss:	27/01/2019 23:00 - :59
Claim Type:	TP / CMTD1900652	Policy/Cover Note No.:	D18MTHCVE002627 (Third Party Only)
Vehicle Reg. No. (Insured):	YN753R	Policy No. (Claimant):	
		Excess:	
Repairer:	M1 Motoring ( ) 34 Toh Guan Road East, #01-29, 608579 Jurong East - Tel: 62667030		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/02/2019]		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7100A
<b>Vehicle Details</b>	
Vehicle No.:	FBN3885X
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	YAMAHA
Vehicle Model:	TMAX530(DX)
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	J415E024435
Chassis No.:	JYASJ145000013519
Maximum Power Output:	-
Open Market Value:	\$9,541.00
Original Registration Date:	21 Sep 2018
First Registration Date:	21 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$3,021.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	20 Sep 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,214.00
COE Rebate Amount:	\$4,048.00
<b>Total Rebate Amount:</b>	<b>\$4,048.00</b>

The information contained herein is correct as at 11 Feb 2019

OK

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jan 2019		30 Jan 2019 16:17 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>











  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;"><a href="#">[Created by insurer]</a></span>									
Insured: <b>PECK TIONG CHOON LEASING PTE LTD</b> , Co. Reg. No.: 199204891W									
Main Claimant: <b>MUHAMMAD FARHAN BIN AMAN</b> , ID: S8627100A									
Vehicle Reg. No.: <b>FBN3885X</b>		Date of Loss: 27/01/2019 23:00 - :59 [4 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / CMTD1900652</b>		Policy/Cover Note No.: D18MTHCVE002627 (Third Party Only)							
Vehicle Reg. No. (Insured): <b>YN753R</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>M1 Motoring (HQ)</b> 411 Changi Road, 419860 Changi - Tel:									
Handling Insurer: <b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>CHAN SHU HUI AGNES</b> - 6329 5327]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 12/02/2019]</b>									
Adj Asg. Remarks: -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBN3885X (CMTD1900652)  
[YN753R]  
TP  
MUHAMMAD FARHAN BIN AMAN  
Jan 27 2019 11:00PM  
[PECK TIONG CHOON LEASING PTE LTD]  
M1 Motoring

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
2	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
3	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
4	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
5	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
6	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
7	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
8	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
9	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
10	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
11	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
12	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
13	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
14	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
15	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
16	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
17	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
18	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
19	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
20	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
21	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
22	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
23	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
24	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
25	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
26	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
27	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
28	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
29	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
30	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
31	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
32	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
33	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
34	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
35	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
36	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	
37	11/02/19 14:16	General View						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/02/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/02/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/02/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/02/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/02/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/02/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/02/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/02/19 14:16	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	30/01/19 14:13	Certificate Schedule	 Load PDF	
2	01/02/19 11:16	FAX FR GOH JP & WONG LLC - FBN3885X	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19002042/GCD3E2

Date: 12/02/2019

### REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE002627
Claimant Vehicle No :	FBN3885X	Insured Vehicle No :	YN753R
Date of Loss:	27/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900652

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBN3885X</b>	Engine No:	J415E024435
Make & Model:	YAMAHA TMAX530, 530cc (DX)	Chassis No:	JYASJ145000013519
Reg. Date:	21/09/2018 (Man. Year: 2017)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	530 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	160/60 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	30/01/2019		
Date Inspected:	31/01/2019	Inspected At:	34 Toh Guan Rd East #01-29 Repairer : M1 Motoring (HQ)
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 12 Feb 2019)

**Parts:** N/A YAMAHA TMAX530 530cc (DX) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBN3885X)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >