*	V2	Λ
24	KC 1 200 Km 2068 :6	NO STILKK
15/5/2010	CCY (AXA1900 70 0 0 /9	DAC:
INS. CASE OWNER		
	EGD ASSIGNMENT	milita.
Surveyor:	DOI: 17/10.	Date / Time :
	and the second s	Registered in Merimen:
Pre-assign / CCU	/FTE	01 2012/01/0
<u> </u>	SUF JA60 (Claim No.	SAMULCI & 16400
Insured Vehicle No	- my 0 copy contractor & DNOTO	11788806-
Name of Insured	MANY PROF WING MAR C 1. Policy No.	
Insured Tel No.	: HP: Make / Model	
Excess Sec II :SS	D.O.A: 2011 19 Place of Acciden	1188 LIMPASEVAVE BUN
Is driver the owner	(YES / NO) Nature of Accident	
L'AITE ALC VIIII		T: YES) NO : TP GIA REPORT: Y)S / NO
Driver Tel	No.: (VIL. (ES) NO.) Insuled Linsuity	
gent 65	(N)	
	Niene.	INSRS:
INSRS: WSP: Jeach	INSRS: INSRS: WSP:	WSP:
U Tel	La Tel: Tel:	Tel:
Liability: VMO	Liability: Liability:	Liability:
RMKS	RMKS: RMKS:	RMKS:
Date/ Time		
	GINT 649112-4 SUF7 60T-	STAGE DATE/PIC
	(1 2 ~	Non-Reporting ltr (1st):
		Non-Reporting ltr (2nd): Non-Reporting ltr (Final):
	ENGLISH CONTROL OF THE CONTROL OF TH	Notification ltr (if non-pickup):
	N. C. Allalan	Call OI: Young 2777
	* Gunt dam	After call ltr to OI:
	0 . N/P	Documentation Check List: Handler Typist
,	+01,161.	Notification ltr (if non-pickup)
20 12610	Col. A CID BILL LINE	After call lir to OI:
1414 -	Called CID, PII su vius	Authorisation To Act:
26/2/19 -	AXA V DS. All Claim ercesc: \$26.	Final Repair Bill:
10/1/1/	THE VIS. MICHINIA COSC. +	Car Rental Invoice:
	offer TP \$1850.11 (Olk mardall of	Towing Invoice
	\$1800.11)	LTA/GIA:
114119 -	- Offer email to TP. (Pending reply on counting)	Medical Bill:
5419 -	- DV send to TP Pandine DV Veturn.	PIR:
10/4/191 -	- By in - KIN repards to wrong DV from AXA	Mandate/Reject Instruction:
12/4/19 -	Selved Div to tp.	LOD
1015 -	DV IVI , FILE pass to CHT.	Payment Breakdown Form:
PRELIMINARY ADVICE	B Date/Time: Sent By:	Post-Repair Photos:
		Others:
FINALIZATION	Date/Time: Confirm with:	Confirm by:
Repair Cost:	Date/Time:51919 5 & Sp. Confirm with Millin Utw	Email Cal Cal
FINAL SETTLEMENT	% (Agreed / Assessed) BOLA S/N No.: 7	If NO or B 28, Ass. Lia
Final Liability: Repair Cost:	SS 1698 - 1 PROCESSED BOLA STANO.	The state of the s
Loss of Rental (LOR):	SS (days)	COMPA CENT
Loss of Use (LOU):	ss (50) (s 50 x 3 days)	14 6 19
Loss of Income (LOI):	SS — (S x days)	
LOR only LOU only		V
GIA/LTA Search	ss 2.00	n contract of the contract of
Medical:	SS -	1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS — (e.g. Tow/ Independent) SS —	2) Report Format: 13) Survey fee: 1550 - 150
Legal Cost Total:	SS Global Sum SS:	and the second second
FINAL PAYMENT	Date/Time; Confirm with:	Email Cal
Payce 1:	SS 1850.11 Name 1: KAN Motor Lo. Solm.	end
Payee 2: (Strike if N.A.)	SS Name 2:	and. Un 12/11
Payee 3: (Strike if N.A.)	S\$ Name 3:	/~
Carried State of the Control of the		

Report Format :

Lump Sum / LBJ: (\$

XIN	[[[[[[[[[[[[[[[[[[[[(10)11
Neo	<u>A50</u>	GNMENT	
	Date 01 00 309	Volt 16 SME 6593 1	k village 10 oct 2018
Estroled Cost	Date	Type MC / M.Cycle / Bus / Van /	
(1)	OD RESTEVATINY/MV	Truck / Trailer or	•
To Inspect Vehicle No.	SME 6543K	Make Umoda J	a22 00 1318
at Workshop m/s	Kah Mita	Colour VILLONI	A/C Insured / Std / NI / NA
of	15 Ubi Rd 4	Make: Hanela J Colour Yellow Sp.Reading 02259	T/Radio: Insured / Std / NI / NA
Insured	101 1(4)	Eng/No:	
Policy No.		CINO: THUGK	3850 JX 227014
Claims No.		Gen. Cond: God / Fair / Poor / Bur	
Sum Insured:	Excess	Steering: Inor@r / Jammed / Leake	ed / Burnt or •
(Client's Record)		Brake: Ino Ger / Jammed / Leake	ed / Burnt or
Make of Veh:	Mr.Lim	Modi: Nil / S/Rin / STD A/Rim	
	30m	Tyre Size: F: 205	150 RHG
(Policy Condition)	34"1	R:	11
Remark: The veh had o		BS / DUN / EXNOVA / GY / FS / LIZ	(A / MIC / OHTSU / PIR / SUMI /
repair at the t	time of inspection.	TOYO / YOKO OF	
Bal, or Market Value:		<u>Front</u>	Rear
IDAG Accident Rport:	Consistent?: Yes or No	R/Bal. 7 mm	R/Bal. mm
GIA / PR Seen:	Consistent? ; Yes or No	L/Bal. 9 mm	L/Bal. 7 mm
Est. Repairs	days Res.: Yes or No	D.O.A.	01-02-19
Lum Sum:	- % 3 Val.: Yes or No	Survey held at	5pm
GA / REV / REP.	/ 24 HRS	Des. of Damages Frth Rear / O.	IS I NIS I UIC I ROOROP OF 1
Date	Vehicle: IN / OUT Person Contacted:		ody Structure affected due to collision.
	on / Instruction		
3			
Þ	P = \$1587.02		
		- h.s	1/PE / FO - 12/CO
	-	1501 11	\-\/-\/-
Date/Time, File Pass to?	: Preli. Report	Days Of Repair:	
1)	: Final Report	Resurvey No. of Trip:	Survey Fee
Date/Time, File Return to?			Transportation
	Add F∈	Revisioned .) _ S+RS _ SI
	100	Interview (\$) Photos

Tech thys (\$

Weskend I\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AXA INSURANCE PTE LTD Ref : CC4/ASM		Ref: CC4/ASM1900	2068/Gpb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 31-01-2019 Code: ASM		
1.		Policy Part	ticulars :- THIRD PARTY CLA	IM
	Insured Veh.	SGF 7960T	Veh. Inspected	SME 6593K
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	31/01/2019
2.		Vehic	le Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	92	Steering	
	Brakes		Modification	
	General			
3.			Conditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		D	escription of Damages	
5.			General Information	
	Accident Date	30/01/2019	Inspection Date	01/02/2019
	Survey held at	KAH MOTOR CO SDN	Annual Contract of the Contrac	SOSTILLA METACHIDATIA
		15 UBI ROAD 4 SINGAPORE 408610		
5a.			Remarks	



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

EMBLEM H 7

NUTPUSH 3MM

HEADLIGHT ASSY,R.

75700-T5A-000

90301-ST0-003

33100-T5A-J81

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

Kindly Help to arrange Surveyor to Survey this Velvicle thanks

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

12.04

3.37

384.95

1,603.59

11.25

3.15

359.77

1498.69

25

25

25

Sum Item

15.00

2.10

479.70

0.79

0.22

25.18

104.90

For 24-hours Roadsi	de Assistance, Call 98203838						
Customer Registration No Chassis No Model Owner's Name	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811 : SME6593K : JHMGK3850JX227014 : JAZZ 1.3LXR CVT 18YM (EURO 6) : LOH EE LING	Date Cus Svc Eng Date Sun	ument No. tomer No. Advisor ine No Time veyor Name	: 30. : WZ : LIN	T19000515 Jan 2019 ZA006 1 CHOU SIG 3B1103129 Jan 2019 3	DNG 2	Page 1
Ins Policy No.	:		horisation Da	te ·			
Date of Accident	: 30/1/2019	Aut				0% GST	Amount
Item	Description	Qty	Unit Price	Disc %	Amount	Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: LOH EE LING						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 30/1/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: SGF7960T						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	N 1	45.00		45.00	3.15	48.15
71145-TAR-T50	BASE,FR.LICENCE PLATE X	1	49.00	25	36.75	2.57	39.32
04711-T5A-J50ZZ	FACE, FR. BUMPER / CL . ~~	1	504.60 678	25	378.45	26.49	404.94
71102-T5L-T50	LOWER GRILLE ASSY, FR. X	1	137.90	25	103.42	7.24	110.66
71103-T5A-J50	GARNISH,R.FR.BUMPER 7 \ /	-1	29.00	25	21.75	1.52	23.27
71104-T5A-J50ZA	COVER, FR. TOWING H ?	1	15.50	25	11.62	0.81	12.43
71106-T5A-J50	DUCT,R.FR.BUMPER SIDE	NI	13.20	25	9.90	0.69	10.59
71114-T5A-J50	GARNISH,R.FR.LOWER GRI INT	1	8.70	25	6.52	0.46	6.98
71130-T5A-J50ZZ	BEAM COMP, FR. BUMPER ?	1	213.00	25	159.75	11.18	170.93
71140-T5A-J50	BEAM UPPER,R.FR.BUMPER ?	1	27.70	25	20.77	1.45	22.22
71193-T5A-000	SPACERR.FR.BUMPER / /	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER - SALC .	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER /	19	2.30	25	32.77	2.29	35.06
71121-T5A-J50	BASE, FR. GRILLE HOOK 7	1	227.40	25	170.55	11.94	182.49
71122-T5A-J50	MOLDING LOWER, FR. GRILLE ?	A 1 1	148.90	25	111.67	7.82	119.49
	Aura-control and the control of the	/ / /					



QUOTATION

GST Reg No.: M200050223

Page

2

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

068811

For 24-hours Roadside Assistance, Call 98203838

Customer

: AXA INSURANCE S'PORE PTE LTD

8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE

: SME6593K

Registration No. Chassis No

: JHMGK3850JX227014

Model

: JAZZ 1.3LXR CVT 18YM (EURO 6) : LOH EE LING

Owner's Name Ins Policy No.

Date of Accident

: 30/1/2019

Document No.

: SQT19000515

: 30. Jan 2019

: WZA006

Customer No. : LIM CHOU SIONG

Svc Advisor

Date

: L13B11031292

Engine No Date | Time

: 30. Jan 2019 3:20:26 PM

Surveyor Name

Survey Date

Authorisation Date

2.50	1
3.50	53.50
7.00	107.00
84.00	1284.00
70.00	1070.00
164.50	2,514.50
	84.00 70.00

Survey By

Date & Time

Excess

81006303(48)

3,848.69 269.40 4,118.09

Total (Inclusive of GST)

4,118.09

Status

Signature

2978.89

Ways. Defair part photos.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Printed on 30/1/2019 7:25:06 PM

Date:

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

31017019@ 1024cm

Menu



Service Request Details

Claim

S9M01CIZ

Reference

None 🥒

Loss Date

January 30, 2019

Request Date

January 31, 2019

Due Date

February 11, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions Next Step Agree to perform service Decline Work Accept Work

Vehicle Information

Incident Vehicle Registration #

SME6593K

Make

TPVD HONDA

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu

Service Address

Primary Contact/Insured

MANO FREE LANCE VIDEO & PHOTO BLK 223 BISHAN STREET 23, #08-133, 570223, Singapore 96245100

Claim Handler

CHAN Kian Chuan 6568804269 kianchuan.chan@axa.com.sg

Additional Instructions
INSURED NOT REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

Catherine Chong (LKK Auto)

From:

Lim Chou Siong <cslim@honda.com.sg> Wednesday, 30 January, 2019 7:31 PM

Sent: To:

SG AXA Insurance SM AXA SGP - Motor Survey

Subject:

DIRECT SETTLEMENT OF VEHICLE NO. SME6593K AGAINST SGF7960T

Attachments:

3934_001.pdf

Categories:

Mateen

To Officer In Charge,

The Above Attachment For Your Reference.

Kindly Help To Arrange Surveyor To Survey This Vehicle SME6593K,

Your Insure Vehicle Number SGF7960T, Accident Date 30/01/19,

Thank for your help.

Best Regards,

Lim Chou Siong Bodyshop Service Advisor Kah motor Co. Sdn Bhd 15, Ubi Road 4 Singapore 408610

E-mail: cslim@honda.com.sg<mailto:cslim@honda.com.sg>

Fax: 67480770 DID: 68465671 H/P: 81006303

From: Printer Service <printservice@honda.com.sg>

Sent: Wednesday, 30 January, 2019 7:27 PM To: Lim Chou Siong <cslim@honda.com.sg>

Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Menu



RE: DS

Type

Q Question

Message

Hi KC, OID(G Manokaran) is the owner of the company. We have uploaded a copy of OI ACRA in Smartclaims. Kindly advise if there is any policy issue and whether we can proceed DS. Thank you. Hsiao Tong - 25 Feb 2019

Reply

LKK AUTO CONSULTANTS PTE LTD (TP) +

Menu



Re:RE: DS

Type

Question

Message

PLS PROCEED DS WITH QUANTUM TO BE AGREED, ALL CLAIM EXCESS AT \$2,000.00

Reply

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Wednesday, 27 February 2019 7:52 AM

To:

'Lim Chou Siong'

Cc:

Liew Thye Wui; Admin A

Subject:

RE: DIRECT SETTLEMENT OF VEHICLE NO. SME6593K AGAINST SGF7960T *LKK REF:

CC4/ASM19002068/Gpb3

WITHOUT PREJUDICE

Dear Sirs/Mdm.

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Chou Siong <cslim@honda.com.sg>

Sent: Friday, 22 February 2019 2:04 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>

Subject: DIRECT SETTLEMENT OF VEHICLE NO. SME6593K AGAINST SGF7960T *LKK REF:

CC4/ASM19002068/Gpb3

Hi Hsiao Tong,

Ok, Thanks.

Best Regards,

Lim Chou Siong Bodyshop Service Advisor Kah motor Co. Sdn Bhd 15, Ubi Road 4 Singapore 408610

E-mail: cslim@honda.com.sg

Fax: 67480770 DID: 68465671 H/P: 81006303

From: Lim Chou Siong

Sent: Friday, 22 February, 2019 1:56 PM

To: 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>

Subject: DIRECT SETTLEMENT OF VEHICLE NO. SME6593K AGAINST SGF7960T *LKK REF:

CC4/ASM19002068/Gpb3

Hi Hsiao Tong,

Ok, Thanks.

Best Regards,

Lim Chou Siong Bodyshop Service Advisor Kah motor Co. Sdn Bhd 15, Ubi Road 4 Singapore 408610

E-mail: cslim@honda.com.sg

Fax: 67480770 DID: 68465671 H/P: 81006303

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Friday, 22 February, 2019 12:09 PM
To: Lim Chou Siong cslim@honda.com.sg>

Cc: Liew Thye Wui < twliew@honda.com.sg>; Admin A < admin-a@lkkauto.com>

Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO. SME6593K AGAINST SGF7960T *LKK REF:

CC4/ASM19002068/Gpb3


Without Prejudice

Dear Mr Lim,

We refer to your below email.

We are currently pending for relevant documents from our insured. Therefore, we are unable to comment DS at this moment. You may advise your client to do OD.

Attached is a copy of our insured accident report for your easy reference.



- V1) SGF7960T (Complainant's vehicle)
- V2) SME6593K (Other party's vehicle)

On 30/01/2019, at about 8.24am, I picked up a passenger from Br 278B Compassivale Bow. As I was turning right, the passenger told me to turn left suddenly. So I reversed my car a little, I did not notice a car SME 6593K which was behind and ton close to my car. My car hit onto the bonner of that car and was slightly dented. I did not take down the other party particulars.

There was no injury on anyone.

If this accident was reported to the Poilee within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: SSSgt Azmi Bin Mohamed Hamzah

Date: 30/01/2019 Time: 1618hrs

S/D Ref: eSD 122

Police Post/Unit: Bishan NPC

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim Chou Siong < cslim@honda.com.sg>

Sent: Friday, 22 February 2019 9:12 AM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Cc: Liew Thye Wui < twliew@honda.com.sg>

Subject: DIRECT SETTLEMENT OF VEHICLE NO. SME6593K AGAINST SGF7960T

Hi Hsiao Tong,

Your Surveyor Has Survey This Vehicle SME6593K On 30/01/19 At 15:00PM,

May I Know Is The Liability Clear, How Much Is The Rental Or LOU Per Day,

Your Insure Vehicle Number Is SGF7960T, Accident Date 30/01/19, Thanks.

Best Regards,

Lim Chou Siong Bodyshop Service Advisor Kah motor Co. Sdn Bhd 15, Ubi Road 4 Singapore 408610

E-mail: cslim@honda.com.sg<mailto:cslim@honda.com.sg>

Fax: 67480770 DID: 68465671 H/P: 81006303

From: Lim Chou Siong

Sent: Friday, 15 February, 2019 10:26 AM

To: 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>

Subject: DIRECT SETTLEMENT OF VEHICLE NO. SME6593K AGAINST SGF7960T

Hi Hsiao Tong,

Your Surveyor Has Survey This Vehicle SME6593K On 30/01/19 At 15:00PM,

May I Know Is The Liability Clear, How Much Is The Rental Or LOU Per Day,

Your Insure Vehicle Number Is SGF7960T, Accident Date 30/01/19, Thanks.

Best Regards,

Lim Chou Siong Bodyshop Service Advisor Kah motor Co. Sdn Bhd 15, Ubi Road 4 Singapore 408610

E-mail: cslim@honda.com.sg<mailto:cslim@honda.com.sg>

Fax: 67480770 DID: 68465671 H/P: 81006303

From: Lim Chou Siong

Sent: Wednesday, 30 January, 2019 7:31 PM

To: 'motor.survey@axa.com.sg' < motor.survey@axa.com.sg >

Subject: DIRECT SETTLEMENT OF VEHICLE NO. SME6593K AGAINST SGF7960T

To Officer In Charge,

The Above Attachment For Your Reference,

Kindly Help To Arrange Surveyor To Survey This Vehicle SME6593K,

Your Insure Vehicle Number SGF7960T, Accident Date 30/01/19,

Thank for your help.

Best Regards,

Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4
Singapore 408610


E-mail: cslim@honda.com.sg<mailto:cslim@honda.com.sg>

Fax: 67480770 DID: 68465671 H/P: 81006303


From: Printer Service <pri>printservice@honda.com.sg>

Sent: Wednesday, 30 January, 2019 7:27 PM To: Lim Chou Siong <<u>cslim@honda.com.sg</u>>

Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Cecilia Chong (LKK Auto)

From:

Cecilia Chong (LKK Auto)

Sent:

Tuesday, 2 April 2019 3:01 PM

To:

'cslim@honda.com.sg'

Cc:

Hsiao Tong (LKKAuto); Admin A

Subject:

Your Ref: SME 6593K *Our Ref: CC4/ASM19002068/Gpb3 [ACCIDENT INVOLVING SGF

7960T(AXA) & SME 6593K ON 30/01/20191

Your Ref: SME 6593K

Without Prejudice

Our Ref: CC4/ASM19002068/Gpb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SGF 7960T(AXA) & SME 6593K ON 30/01/2019

We refer to the above matter.

We propose settlement as follow:

Cost of repair	\$1,698.11	
Loss of Use (\$50 x 3 days)	\$ 150.00	
LTA fee	\$ 2.00	
Total	\$1,850.11	

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 28/03/2019

Survey Details:

Date of loss	30.01.2019
Date of appointment	31.01.2019
Date of survey	01.02.2019
Location of survey	KAH MOTOR CO. SDN. BHD.

Vehicle Details:

Claim Type:	Third party
Vehicle number	SME 6593K
Make and Model	HONDA JAZZ - 1318CC
Date of registration	10.10.2018
Excess	
Market Value	\$80,000
Parf Rebate	\$30,000
Nett Loss	\$50,000

Repair details:

Initial Estimate	\$ 3,848.69

Proposed/Revised repair cost:

Parts	\$ 557.02
Check items (estimate)	\$ 8
Labour	\$ 1,030.00
Total	\$ 1,587.02
Lump Sum(if applicable)	-

Number of days for repair	3
---------------------------	---



51 UBLAVE 1, #02-25 PAVA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

	_	

Remarks:

Mandate:

Liability(TP)	100%	-	
Proposed repair cost (W/GST)	\$ 1,698.11	\$	
Loss of use (3days x \$50)	\$ 150.00	\$	
Loss of rental		\$	
Loss of income		\$	-
LTA search fees	\$ 2.00	\$	
Others		\$	
Proposed Total	\$ 1,850.11	\$	

Menu



<SEEK MANDATE> OUR REF: CC4/ASM19002068/Gpb3 ACCIDENT INVOLVING SGF 7960T & SME 6593K ON 30/01/2019

Type

Q Question

Message

LIABILITY 100% BOLA S27 - COR 1698.11(W/GST) LOU \$150 LTA SEARCH FEE \$2 = \$1850.11

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGF 7960T (Insd veh)		Model:	HONDA JAZZ	
	SME 6593K (TP veh)			
Date of Accident:	of Accident: 30/01/2019				
Global Sum Settlen	nent [] Yes	T	[X] No	9	
Repair Estimate	100 200	: \$	4,257.41		
Final Repair Cost		: \$	1,698.11		
Loss of Use		: \$	150.00	3 days at \$50.00 per day	
Rental (if any)		: \$	2.00	days	
LTA / GIA Search F	ee	: \$			
Others:		: \$			
		: \$			
Final Settlement Su	ım	: \$	1,850.11		
oelow) A) For Non GIA R	egistered Workshop:		Agreed Liability _	(%)	
B) For GIA Regis	For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No27				
BOLA Liability:	100(%)		Assessed Liability	/ (*):(%)	
* Assessed Lia	bility to be filled only fo	r chain	collisions and for ca	ses where BOLA does not apply.	
Remarks					
Payment Instruction	on: Payee's Breakdow	vn .			
1) KAH MOTOR	CO. SDN. BHD.		: \$	1,850.1	
			10.00		
	ILAH BTE ABDOL VAHAB		29/05/2019		
(90)			Date		

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Autom	nobile	
AXA	INSURANCE PTE	LTD	Ref : CC4/ASM1900	2068/Ggb3s2	
T-10 (T-10)	HENTON WAY #24 TOWERSINGAPO	N (1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Date: 29-05-2019		
ATTN: KIAN CHUAN			Code: ASM		
1.		Policy Particul	ars :- THIRD PARTY CLA	IM	
	Insured Veh.	SGF 7960T	Veh. Inspected	SME 6593K	
	Policy No.	P/17858106	Coverage (\$)	0.00	
	Claim No.	S9M01CIZ	Excess (\$)	0.00	
	Assign From	KIAN CHUAN	Assign Date	31/01/2019	
2.		Vehicle P	articulars & Condition		
	Make & Model	HONDA JAZZ	c.c	1318	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	JHMGK3850JX227014	Colour	YELLOW	
	Odometer	002259	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Con	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	205/50R16	YOKOHAMA	9 mm	
	L/H Front Tyre	205/50R16	YOKOHAMA	9 mm	
	R/H Rear Tyre	205/50R16	YOKOHAMA	9 mm	
	L/H Rear Tyre	205/50R16	YOKOHAMA	9 mm	
4.			iption of Damages		
	DAMAGES SEE D	STAINED DAMAGES AT THE ETAILS.	FRONT PORTION.		
5.		Gen	eral Information		
	Accident Date	30/01/2019	Inspection Date	01/02/2019	
	Survey held at	KAH MOTOR CO SDN BER	HAD		
		15 UBI ROAD 4 SINGAPORE 408610			
5a.			Remarks		
		ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS			
5b.		Estim	ate Days of Repair		
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Day	/s	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 6593K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NUMBER PLATE WITH CASING (SN) (CONSISTENT)	NOT NECESSARY	45.00	
1	BASE, FR.LICENCE PLATE (SN) (CONSISTENT)	NOT NECESSARY	36.75	
1	FACE,FR.BUMPER (SN) (CONSISTENT)	DEFORMED	508.65	508.65
-1	LOWER GRILLE ASSY, FR. (SN) (CONSISTENT)	NOT NECESSARY	103.42	
1	GARNISH,R.FR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	21.75	
1	COVER,FR.TOWING H (SN) (CONSISTENT)	NOT NECESSARY	11.62	
1	DUCT,R.FR.BUMPER SIDE (SN) (CONSISTENT)	NOT NECESSARY	9.90	
-1	GARNISH, R. FR. LOWER GR INT (SN) (CONSISTENT)	NOT NECESSARY	6.52	
1	BEAM COMP, FR. BUMPER (SN) (CONSISTENT)	NOT NECESSARY	159.75	
1	BEAM UPPER,R.FR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	20.77	
1	SPACERR FR.BUMPER (SN) (CONSISTENT)	NECESSARY	7.80	7.80
1	SPACERL FR. BUMPER (SN) (CONSISTENT)	NECESSARY	7.80	7.80
19	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	32.77	32.77
1	BASE,FR.GRILLE HOOK (SN) (CONSISTENT)	NOT NECESSARY	170.55	
1	MOLDING LOWER, FR. GRILLE (SN) (CONSISTENT)	NOT NECESSARY	111.67	
1	EMBLEM H (SN) (CONSISTENT)	NOT NECESSARY	11.25	
2	NUTPUSH 3MM (SN) (CONSISTENT)	NOT NECESSARY	3.15	
1	HEADLIGHT ASSY,R. (SN) (CONSISTENT)	NOT NECESSARY	359.77	
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			1,678.89	577.02
	LABOUR			
	INSPECT FR LIGHTING MECHANISMS & FOCUS.	NOT NECESSARY	100.00	
	REPLACE FR BUMPER, REPAIR BULKHEAD & OTHER DAMAGE.		1,200.00	560.00
	SPRAY PAINTING ON FR BUMPER & BULKHEAD.		1,000.00	450.00
			2,300.00	1,010.00
	GRAND TOTAL		3,978.89	1,587.02

Report Ref No. CC4/ASM19002068/Ggb3s2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 1,587.02

Report Ref No. CC4/ASM19002068/Ggb3s2

8

XING GUO QIANG

M.MATAI, AMSAE-A

Simont

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.