

ASS. REC. BY:

REF

es|SMO19002069/Asd3n2|Special Instruction:

Surveyor:

Mentmen

From (Person):

Adrian
Thelma Choo

ASSIGNMENT (Office)

of SMO

Date/Time 31/11/19 @ 2.48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 9923T

Insured:

SLF 2868B

at Workshop m/s:

New Hock Teck

Tel:

6747 9241

of

1 kaki Blk Ave 6 # 01-43

Policy No:

DI9 MTPV01001143

Claim No:

CMTD1900665

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/01/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

3:36pm @ 31/11/19

Person Contacted:

Sukyi

Vehicle

☒ IN

OUT

Date/Time

Action/Instruction (✓) Estimate

SJV 9923T-X

SLF 2868B-X

01/02/19

@ 15:04 p.m. revert pending estimate from repairer to
Thelma via mentmen.

ASSIGNMENT

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SJV9923T Yr Regn: 2010, Feb.Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c. 1987Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 151125 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDGJ20W603002138Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 195/65 R15R: 195/65 R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 31/01/19.Survey held at NHT.Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sample

26/03/19 Confirmed L/S \$10k @ 14 days with Adrian
(C\$ 22,004.25 Red - 69%)

MV: 25K

PV: 14.7K

Nett: 10.3K

RECEIVED 26 MAR 2019

Review No. of Trip - 1

Date/Time, File Pass to?

Date/Time, File Return to?

1) 26/03/19

2) _____

3) Typ

4) _____

5) _____

6) _____

Prel. Report:

Final Report: L/S \$10k

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, St

Photos

Others

TOTAL

450

10

460

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2019		31 Jan 2019 14:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LOU JIE, ID: S7880940Z, Tel: +6598328687, Email: NOEMAIL		
Main Claimant:	SU SHIDONG, ID: S7887035D		
Vehicle Reg. No.:	SJV9923T	Date of Loss:	30/01/2019 19:00 - :59
Claim Type:	TP / CMTD1900665	Policy/Cover Note No.:	D19MTPV01001143 (Comprehensive)
Vehicle Reg. No. (Insured):	SLF2868B	Policy No. (Claimant):	
		Excess:	
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/02/2019]		
Driver/Custodian (Insured):	LOU JIE (40 / Male), NRIC: S7880940Z, Tel: +6598328687		
Adj Asg. Remarks:	-NO TP SAS SUBMITTED		

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**RENEW
YOUR
COE**



**1.99%*P.A
ONLY**

MONEYMAX
LEASING
MEMBER OF MONEYMAX FINANCIAL SERVICES LTD.

SEARCH

Used Car Comparison

--- Comparing 4 Vehicles ---

Toyota Wish 1.8A X

Toyota Wish 1.8A X

Toyota Wish 2.0A

Toyota Wish 1.8A



Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Back to search result

CAR DETAILS

	Toyota Wish 1.8A X	Toyota Wish 1.8A X	Toyota Wish 2.0A	Toyota Wish 1.8A
Price	\$25,800	\$29,800	\$35,800	\$34,800
Instalment	\$3,055	\$1,211	\$1,381	\$997
Registration Date	14-Aug-2009	13-Aug-2010	20-Sep-2010	04-Apr-2011
Manufactured	2009	2009	2010	2011
Mileage	-	-	117,200 km	-
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,797 cc	1,797 cc	1,987 cc	1,798 cc
Road Tax	\$974 /yr	\$974 /yr	\$1,198 /yr	\$976 /yr
Power	106.0 kW (142 bhp)	106.0 kW (142 bhp)	106.0 kW (142 bhp)	106.0 kW (142 bhp)
Curb Weight	1,340 kg	1,340 kg	1,380 kg	1,360 kg
Features	-	-	Powerful And Fuel Efficient Dual VVTI DOHC Engine, CVT Transmission, Digital Climate Aircon, 6 SRS Airbags, ABS, Traction Control, Retractable Mirror.	1.8L DOHC VVTI Engine, Speed CVT Steptronic Transmission, SRS Entry, Reverse Sensors.
Accessories	-	-	Leather Seats, Arm Rest, Solar Film, Sports Rims, Reverse Sensors, Retractable Mirrors, Fog Lamps.	Leather Seats, Original Film, Climatic Aircon Sensors, Retractable
Description	New Facelift, Option For COE POP 10yrs At \$57,800, New Paintwork, High Loan And Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.	S Pass, EP Or LTV Pass Welcome To Loan! In House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Viewing And Test Drive Available Daily From 10.30 A.M. To 6.30 P.M. All Our Vehicles Has Undergone A 120 Points Check By Our In House Workshop!	Agent Unit! Loan Up To 95%! Meticulously And Diligently Maintained. Absolutely No Repairs Needed. 6 Months Warranty And 1 Free Major Servicing! Witness Firsthand For Yourself How We Perform Major Servicing At Our In House Workshop! Purchase With Assurance And Peace Of Mind. Call Now For More Detail!	Elegant Toyota Wish Maintained. Up To We Provide Lowest Flexible Loan And Interest Available. Package Warranty Complete Test Report. Check Now. Meet Our Friendly Staff. An Non Obligation
COE	\$18,189	\$23,180	\$42,901	\$62,001
OMV	\$21,924	\$21,698	\$22,003	\$21,503
ARF	\$21,924	\$21,698	\$22,003	\$21,503
Depreciation	\$28,060 /yr	\$12,400 /yr	\$15,190 /yr	\$11,080 /yr
No. of Owners	1	2	2	2
Type of Vehicle	MPV	MPV	MPV	MPV
Category	PARF Car	PARF Car, Premium Ad Car	PARF Car	PARF Car.
Availability	Available	Available	Available	Available

SELLER INFORMATION

Seller	Boeki Auto & Marine	88 Motor Trading	Providence Automobile	Classic Credit Pte Ltd
--------	---------------------	------------------	-----------------------	------------------------

View Sent Message

This mail is associated with :

***SJV9923T (CMTD1900665)
[SLF2868B]**

TP

SU SHIDONG

Jan 30 2019 7:00PM

[LOU JIE]

New Hock Teck Motor Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/02/2019 15:04 PM.

To thelma.choo@sompo.com.sg

CC sur@lkkauto.com

Subject SJV9923T (CMTD1900665) [SLF2868B] TP

Dear Thelma,

Please be informed that we have inspected the vehicle SJV 9923T on 31/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 7035D

Vehicle Details

Vehicle No.: SJV9923T
Vehicle to be Exported: No
Intended Deregistration Date: 31 Jan 2019
Vehicle Make: TOYOTA
Vehicle Model: WISH 2.0 AUTO
Primary Colour: Silver
Manufacturing Year: 2010
Engine No.: 3ZRA460955
Chassis No.: JTDGJ20W605002138
Maximum Power Output: 106.0 kW (142 bhp)
Open Market Value: \$22,003.00
Original Registration Date: 26 Feb 2010
First Registration Date: 26 Feb 2010
Transfer Count: 1
Actual ARF Paid: \$22,003.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Feb 2020
PARF Rebate Amount: \$12,101.00

Intended COE Rebate Details

COE Expiry Date: 25 Feb 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$23,889.00
COE Rebate Amount: \$2,560.00
Total Rebate Amount: \$14,661.00

The information contained herein is correct as at 31 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2019 15:50
Date Of Accident	30/01/2019 19:10
Exact Location Of Accident	KPE TUNNEL TWDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV9923T
Insured/Policyholder	
Name Of Registered Owner	SU SHIDONG
NRIC No	S7887035D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81278397
Alternative Phone No	OFFICE-81278397

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA298292
Cover Note Number	

Driver

Name of Driver	SU SHIDONG
NRIC No	S7887035D
Date Of Birth	13/09/1978
Occupation	INDOOR
Date Of Driving Pass	14/05/2012
Driving Experience	6 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81278397
Fax Number	
Contact Number	OFFICE-81278397
Email Address	NOEMAIL

Address BLK 289 TAMPINES ST 22 #12-442
 Postcode 520289
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : CAI JIAN HUA
 GENDER: : MALE
 Passenger 2 NAME: : ED MAR
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG KPE TUNNEL TOWARDS PIE. ALL VEHICLES IN FRONT OF ME STOPPED, I FOLLOWED SUIT. SUDDENLY, I FELT AN IMPACT. VEHICLE B COLLIDED ONTO REAR PORTION OF MY VEHICLE AND CAUSED MY VEHICLE TO SURGE FORWARD AND COLLIDED ONTO VEHICLE C REAR PORTION. I ALIGHTED AND REALISED THERE WERE TOTAL 3 VEHICLES INVOLVED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLF2868B
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLN9901A
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SU SHI DONG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJV9923T
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

	<p>KPE Tunnel Towards FLE</p>	A: SJV993ST
		B: 3LF2868B
		C: SLN9901A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along KPE Tunnel Towards FLE.

All vehicles in front of me stopped, I followed suite.

Suddenly I felt an impact. Vn "B" collided onto rear portion of my vehicle and caused my vehicle surged forward collided onto Vn "C" rear portion.

I alighted and realised there was total 3 vehicles get involved.

Sin Shidong

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Sin Shidong
 Policyholder's Signature
 Date & Time:

Sin Shidong
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #3 Pg. 1

LETTER OF UNDERTAKING

I/We, Su Shidong, the owner of vehicle no. SJV99237

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, New Hock Lock Motor Pte Ltd

Signed and Acknowledge by:

Su Shidong
Nric no. & signature of policyholder

Company stamp

31/1/19
Date


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

	A: 3JV 9923T
	B: 8LF 2866B
	C: SLN 9901A
	KPE Tunnel Towards PIE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along KPE Tunnel Towards PIE.

All vehicles in front of me stopped, I followed suite.

Suddenly I felt an impact. Vth "B" collided onto rear portion of my vehicle and caused my vehicle surged forward collided onto Vth "C" rear portion.

I alighted and realised there was total 3 vehicles get involved.

S. Shindong

DECLARATION

I/We declare the foregoing particulars are true in every respect.

S. Shindong
 Policyholder's Signature
 Date & Time:

S. Shindong
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

31/01/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Sampo
Sturley

JTD GJ20W605002138

Accident date: 30/01/2019

Estimated repair cost for vehicle no: SJV9923T TOYOTA WISH 2.0 A '10

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet		\$804.00
2	2	Front Bonnet Hinge	\$78.10	\$156.20
3	1	Front Bonnet Lock		\$102.10
4	1	Front Bonnet Insulator		\$211.30
5	8	Front Bonnet Insulator Clip	\$6.50	\$52.00
6	1	Front Bonnet Emblem Logo		\$55.60
7	2	Front Head Lamp	\$879.60	\$1,759.20
8	1	Front Grille		\$246.10
9	8	Front Grille Clip	\$6.50	\$52.00
10	1	Front Bumper		\$381.70
11	8	Front Bumper Clip	\$6.50	\$52.00
12	2	Front Bumper Side Retainer	\$81.70	\$163.40
13	1	Front Bumper Inner Sponge		\$97.80
14	1	Front Bumper Reinforcement		\$311.60
15	1	Front Bumper Number Plate		\$50.00
16	2	Front Bumper Fog Lamp	\$287.35	\$574.70
17	2	Front Bumper Fog Lamp Cover	\$86.30	\$172.60
18	2	Front Bumper Fog Lamp Side Cover	\$131.35	\$262.70
19	2	Front Bumper Fog Lamp Chrome	\$181.90	\$363.80
20	1	Front Support Panel		\$1,013.10
21	1	Front Support Panel Top Cover		\$269.20
22	8	Front Support Panel Top Cover Clip	\$6.50	\$52.00
23	1	Front Air-Con Condenser		\$1,130.60
24	1	Front Radiator		\$986.30
25	1	Rear Boot Lid		\$1,415.20
26	2	Rear Boot Lid Hinge	\$141.40	\$282.80
27	2	Rear Boot Lid Shock Absorber	\$371.85	\$743.70
28	1	Rear Boot Lid Emblem Logo		\$51.10
29	2	Rear Boot Lid Side Reflector	\$377.00	\$754.00

12566.8

377

30	1	Rear Boot Lid Center Chrome Moulding	crackd		\$274.45	✓
31	1	Rear Boot Lid Inner Lock	Damaged		\$374.45	✓
32	1	Rear Boot Lid Inner Rubber	Lt		\$381.90	✓
33	1	Rear Boot Lid Inner Trim Board	crackd		\$781.45	✓ 455.10
34	1	Rear Boot Lid Windscreen Seal	gone		\$125.00	✓
35	2	Rear Boot Lid Windscreen Side Moulding		\$108.00	\$216.00	✓
36	1	Rear Boot Lid Camera	new		\$550.00	X
37	1	Rear L/H Tail Lamp	crackd		\$387.40	✓
38	1	Rear L/H Tail Lamp Panel	Dented		\$378.85	X 189
39	1	Rear Bumper	Distorted		\$481.10	✓
40	8	Rear Bumper Clip	new	\$6.50	\$52.00	✓ 30
41	2	Rear Bumper Side Retainer	new	\$132.10	\$264.20	✓
42	1	Rear Bumper Reverse Sensor (special Nett)	Damaged		\$380.00	✓ 200/500
43	1	Rear L/H Bumper Side Reflector	crackd		\$141.45	✓
44	1	Rear L/H Bumper Bracket	Dented		\$88.60	✓
45	1	Rear L/H Bumper Mud Shield	torn		\$172.25	✓
46	1	Rear L/H Fender	Repair		\$972.45	X
47	1	Rear L/H Fender Glass Assy	new		\$396.20	+
48	1	Rear L/H Fender Air Duct	crackd		\$92.80	✓
49	2	Rear Fender Inner Trim Board	Lt crackd	\$972.45	\$1,944.90	✓ 972.45
50	1	Rear End Panel Outer	Dented		\$519.80	✓
51	1	Rear End Panel Inner	Repair		\$780.50	X
52	1	Rear End Panel Top Garnish	crackd		\$374.45	✓
53	1	Rear Spare Tyre Panel	Repair		\$980.30	X
54	1	Rear Spare Tyre Panel Top Cover	Defunct		\$374.30	X
55	1	Rear Spare Tyre Panel & End Panel Sealant	new		\$450.00	X
56	1	Rear Spare Tyre Lock	Dm		\$174.85	✓

Subtotal :- \$24,434.25

11603.95
8702.96

S.V. 200.

131.65

11735.35

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00	X
To remove & refit seat cushion & trim board	\$280.00	80
To remove & refit rear camera & windscreen camera	\$380.00	50
To remove & refit rear exhaust	\$280.00	X
To remove & refit petrol tank	\$280.00	X
To remove & refit reverse sensor	\$100.00	50
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To remove & refit fender glass	\$100.00	X
Gum	\$50.00	X
To check wiring	\$100.00	60
Towing fee	\$100.00	60
Tuff kote	\$150.00	60
Panel beating	\$2,800.00	1800
Spray painting	\$2,400.00	1500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$7,570.00

Total:- \$32,004.25

32246.45

total: 12732.96

L/S: 10K (Nett Value).

10K

14 days.

14 days Chinese New Year.

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002069/ASD3N2

Date: 04/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01001143
Claimant Vehicle No :	SJV9923T	Insured Vehicle No :	SLF2868B
Date of Loss:	30/01/2019	Nature of Claim:	TP
		Claim No:	CMTD1900665

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV9923T	Engine No:	3ZRA460955
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGJ20W605002138
Reg. Date:	26/02/2010 (Man. Year: 2010)	Odometer:	151125 km
Colour:	Silver		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	24,676.45	8,902.96	15,773.49	63.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,570.00	3,830.00	3,740.00	49.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,246.45	12,732.96	19,513.49	60.51
Approved Total (Overridden) (\$\$)		10,000.00		
(\$\$)	32,246.45	10,000.00	22,246.45	68.99
+ GST 7.00/7.00% (\$\$)	2,257.25	700.00	1,557.25	68.99
Nett Amount (\$\$)	34,503.70	10,700.00	23,803.70	68.99

INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 31/01/2019 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV9923T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	804.00 F	*- FL
2	2		*FRONT BONNET HINGE	Not Necessary	156.20 F	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	102.10 F	*- FL
4	1		*FRONT BONNET INSULATOR	Not Necessary	211.30 F	*- FL
5	8		*FRONT BONNET INSULATOR CLIP	Not Necessary	52.00 F	*- FL
6	1		*FRONT BONNET EMBLEM LOGO	Not Necessary	55.60 F	*- FL
7	2		*FRONT HEAD LAMP	Cracked	1,759.20 F	*1,344.00 FL
8	1		*FRONT GRILLE	Cracked	246.10 F	*246.10 FL
9	8		*FRONT GRILLE CLIP	Necessary	52.00 F	*10.00 FL
10	1		*FRONT BUMPER	Deformed	381.70 F	*381.70 FL
11	8		*FRONT BUMPER CLIP	Necessary	52.00 F	*30.00 FL
12	2		*FRONT BUMPER SIDE RETAINER	Necessary	163.40 F	*163.40 FL
13	1		*FRONT BUMPER INNER SPONGE	Cracked	97.80 F	*97.80 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	311.60 F	*311.60 FL
15	1		*FRONT BUMPER NUMBER PLATE	Cut	50.00 F	*50.00 FL
16	2		*FRONT BUMPER FOG LAMP	Cracked	574.70 F	*574.70 FL
17	2		*FRONT BUMPER FOG LAMP COVER	Cracked	172.60 F	*172.60 FL
18	2		*FRONT BUMPER FOG LAMP SIDE COVER	Not Necessary	262.70 F	*- FL
19	2		*FRONT BUMPER FOG LAMP CHROME	Not Necessary	363.80 F	*- FL
20	1		*FRONT SUPPORT PANEL	Repair	1,013.10 F	*- FL
21	1		*FRONT SUPPORT PANEL TOP COVER	Deformed	269.20 F	*269.20 FL
22	8		*FRONT SUPPORT PANEL TOP COVER CLIP	Necessary	52.00 F	*20.00 FL
23	1		*FRONT AIR-CON CONDENSER	Not Necessary	1,130.60 F	*- FL
24	1		*FRONT RADIATOR	Not Necessary	986.30 F	*- FL
25	1		*REAR BOOT LID	Distorted	1,415.20 F	*1,415.20 FL
26	2		*REAR BOOT LID HINGE	Not Necessary	282.80 F	*- FL
27	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	743.70 F	*- FL
28	1		*REAR BOOT LID EMBLEM LOGO	Necessary	51.10 F	*51.10 FL
29	1		*REAR BOOT LID SIDE REFLECTOR	N/S Cracked	754.00 F	*377.00 FL
30	1		*REAR BOOT LID CENTER CHROME MOULDING	Cracked	274.45 F	*274.45 FL
31	1		*REAR BOOT LID INNER LOCK	Damaged	374.45 F	*374.45 FL
32	1		*REAR BOOT LID INNER RUBBER	Cut	381.90 F	*381.90 FL
33	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	781.45 F	*455.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	125.00 F	*125.00 FL
35	2		*REAR BOOT LID WINDSCREEN SIDE MOULDING	Necessary	216.00 F	*216.00 FL
36	1		*REAR BOOT LID CAMERA	Not Necessary	550.00 F	*- FL
37	1		*REAR L/H TAIL LAMP	Cracked	387.40 F	*387.40 FL
38	1		*REAR L/H TAIL LAMP PANEL	Dented	378.85 F	*189.00 FL
39	1		*REAR BUMPER	Distorted	481.10 F	*481.10 FL
40	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
41	2		*REAR BUMPER SIDE RETAINER	Necessary	264.20 F	*264.20 FL
42	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
43	1		*REAR L/H BUMPER SIDE REFLECTOR	Cracked	141.45 F	*141.45 FL
44	1		*REAR L/H BUMPER BRACKET	Dented	88.60 F	*88.60 FL
45	1		*REAR L/H BUMPER MUD SHIELD	Torn	172.25 F	*172.25 FL
46	1		*REAR L/H FENDER	Repair	972.45 F	*- FL
47	1		*REAR L/H FENDER GLASS ASSY	Not Necessary	396.20 F	*- FL
48	1		*REAR L/H FENDER AIR DUCT	Cracked	92.80 F	*92.80 FL
49	1		*REAR FENDER INNER TRIM BOARD	N/S Cracked	1,944.90 F	*972.45 FL
50	1		*REAR END PANEL OUTER	Dented	519.80 F	*519.80 FL
51	1		*REAR END PANEL INNER	Repair	780.50 F	*- FL
52	1		*REAR END PANEL TOP GARNISH	Cracked	374.45 F	*374.45 FL
53	1		*REAR SPARE TYRE PANEL	Repair	980.30 F	*- FL
54	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	374.30 F	*374.30 FL
55	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
56	1		*REAR SPARE TYRE LOCK	Damaged	174.85 F	*174.85 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,676.45	11,803.95
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,900.99
Total Parts (\$\$)	24,676.45	8,902.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR,FAN MOTOR & TOP UP GAS	New	380.00	0.00
2	TO REMOVE & REFIT SEAT CUSHION & TRIM BOARD	New	280.00	80.00
3	TO REMOVE & REFIT REAR CAMERA & WINDSCREEN CAMERA	New	380.00	50.00
4	TO REMOVE & REFIT REAR EXHAUST	New	280.00	0.00
5	TO REMOVE & REFIT PETROL TANK	New	280.00	0.00
6	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
8	GUM	New	50.00	50.00
9	TO REMOVE & REFIT FENDER GLASS	New	100.00	0.00
10	GUM	New	50.00	0.00
11	TO CHECK WIRING	New	100.00	60.00
12	TOWING FEE	New	100.00	60.00
13	TUFF KOTE	New	150.00	60.00
14	PANEL BEATING	New	2,800.00	1,800.00
15	SPRAY PAINTING	New	2,400.00	1,500.00
Gross Labour Cost (S\$)			7,570.00	3,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >