

2/03/2002

ASS. REC. BY:

REF:

CS3/AIG19002071/Rled312

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

31/1/19 @ 3.13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SGY 4455E

Insured:

SLW 1939Y

at Workshop m/s

Motor Intel

Tel:

88383318

of

13 kaki Bukit Rd 4 # 01-20

Policy No.:

1800014795

Claim No.:

379444473SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/01/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

3.42pm @ 31/1/19

Person Contacted:

Wilson

Vehicle:

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SGY 4455E - NS/INC/2014944/HI/kn

Jura: 1/8/2012

SLW 1939Y - X.

*Form*

REF:

6072R  
COE XPR/24: 2020 / Jan

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SGY 44556**

at Workshop m/s: **MOTOR INTL**

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No.: \_\_\_\_\_

Claims No.: \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **21K**

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: **6** days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SGY 44556**

Yr Regn: **2010 Jan**

Type: **C** M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **ALFA ROMEO 2-2** C.C. **2198**

Colour: **WHITE** A/C: Insured / Std / NI / NA

Sp. Reading: **267960** T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **ZAR939 0000 725 8404**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: **8** In order / Jammed / Leaked / Burnt or

Brake: **8** In order / Jammed / Leaked / Burnt or

Modi: **8** Nil / R/Rim / STD A/Rim or

Tyre Size: F: **225/45ZR17**

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **30/01/19** D.O.I. **31/01/19**

Survey held at: **MOTOR INTL**

Des. of Damages: **8** Frt / **8** Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 21,099

PV - 16,331

NV - 4669

*Rasul, pls advise repairer repair limit.*

*[Signature]*  
*11/2*

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair: **6**

Resurvey No. of Trip: **-**

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Other:

)

TOTAL

Report Format: **DAR.**

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

**180**

**10**

**190**

Your password will expire in 11 days. [Click here to change it.](#)

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: 31/1/2019 3:13:48 PM  
Attachments:  tmpAC88.tif

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: SLW 1939Y

Our Ref: AL.INS.2018.SGY4455E

31 January 2019

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**

**BY FAX; 6835 7416**

78, Shenton Way

AIG Building, #08-16

Singapore 079120

Dear Sirs,

**ACCIDENT INVOLVING SJE 7909M, SGY 4455E, SLW 1939Y & SLQ 3187T  
ALONG PIE TOWARDS CHANGI AIRPORT BEFORE JALAN EUNOS ON 30  
JANUARY 2019 AT ABOUT 2045 HOURS**

We act for the owner of vehicle no. SGY 4455E

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

**Motor Intelligence Automo Pte Ltd**

13 Kaki Bukit Road 4

#01-20 Bartley Biz Centre

Singapore 417807


Person In-Charge: Wilson / Tinie

Mobile Number: 8838 3318 / 6281 0087

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jeremy Peh at 6438 3303 or email us at [jeremypeh@alt.sg](mailto:jeremypeh@alt.sg) for future correspondences.

Yours faithfully

  
f ALLISTER LIM

**ALLISTER LIM & THRUMURGAN**

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6072R
Vehicle Details	
Vehicle No.:	SGY4455E
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Feb 2019
Vehicle Make:	ALFA ROMEO
Vehicle Model:	ALFA 159 2.2JTS.SPORTWAGON.SELESPEED
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	939A50001761168
Chassis No.:	ZAR93900007258404
Maximum Power Output:	136.0 kW (182 bhp)
Open Market Value:	\$29,022.00
Original Registration Date:	14 Jan 2010
First Registration Date:	14 Jan 2010
Transfer Count:	2
Actual ARF Paid:	\$29,022.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2020
PARF Rebate Amount:	\$14,511.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,190.00
COE Rebate Amount:	\$1,820.00
<b>Total Rebate Amount:</b>	<b>\$16,331.00</b>

The information contained herein is correct as at 01 Feb 2019

OK

21000  
16331  
-----  
4669

1-

# RENEW YOUR COE



# 1.99%\*P.A ONLY

# MONEYMAX

LEASING  
MEMBER OF MONEYMAX FINANCIAL SERVICES LTD.

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad


Advertiser Login

Ways of Selling

BMW 7 Series 730Li Sunroof.



Cheapest In The Market, Low  
Depreciation, Cheaper Than 3  
Series Or Rental.  
Direct Owner StarAd



Browse by Category ▼



Sort by Date Posted ▼

20 results/page ▼

2 vehicles

Alfa Romeo 159

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>Alfa Romeo 159</b>	Any	Any	<b>2010</b>	Any	Any	Any	<b>Available</b>
	<b>Alfa Romeo 159 2.2A JTS Selespeed</b>	<b>\$23,500</b>	<b>\$9,620 /yr</b>	<b>29-Mar-2010</b>	<b>2,198 cc</b>	<b>167,000 km</b>	<b>Luxury</b>	<b>Available</b>
New Arrival. Don't Miss. Asking For Paper Plus Body. Warranty To Ease Your Worries! Serviced By Agent Genuine Mileage! Fast Deal! Cheapest In The Market! Very Well Maintained! Call Now!								
Car Empire Automobiles Pte Ltd								
Posted: 31-Jan-2019 Tags: 2010 Alfa Romeo 159, 2010 alfa romeo 159, Alfa Romeo 159, alfa romeo 159, Alfa Romeo, 159, Used Alfa Romeo								
	<b>Alfa Romeo 159 2.2 JTS Selespeed</b>	<b>\$29,888</b>	<b>\$10,100 /yr</b>	<b>11-Nov-2010</b>	<b>2,198 cc</b>	<b>157,000 km</b>	<b>Luxury</b>	<b>Available</b>
Low Depreciation. Well Maintained. Flexi In House Loan Available. Car Is Under Consignment. Trade In Welcome. Call For A Test Drive Now!								
Posted: 11-Dec-2018 Tags: 2010 Alfa Romeo 159, 2010 alfa romeo 159, Alfa Romeo 159, alfa romeo 159, Alfa Romeo, 159, Used Alfa Romeo								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view **Expired ads**

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Alfa Romeo 159, Alfa Romeo 159 Singapore, used Alfa Romeo 159 Singapore, used Alfa Romeo 159, used vehicles Singapore or even buy used Alfa Romeo 159 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow **sgCarMart.com**
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

Date of Accident : 30/01/2019 Accident Time: 2045 (24-HR-Format)  
Accident Place : PIE TOWARDS CHANGI AIRPORT BEFORE JALAN EUNOS.  
Vehicle. No. (Car Plate No.) : SGY4455E Make/Model: ALFA ROMEO 159  
Insurance Company : NTUC INCOME Policy No: 5092418913-01  
Owner or Company Name / IC No. : DARES AUTOMOTIVE PTE LTD 201716072R.  
Owner or Company Contact No. : 96670296 Owner's Hp \_\_\_\_\_ Company Tel \_\_\_\_\_  
DRIVER'S Name / IC No. : LIM TIONG KWOK, DAVID 57134019H  
DRIVER'S Date Of Birth : 26/09/1971 DRIVER'S License Pass Date 05/06/1993  
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: \_\_\_\_\_  
DRIVER'S Address : 108C CANBERRA WALK #13-35 S(753108)  
DRIVER'S Contact No./ Alt No. : 1) 96670296 2) \_\_\_\_\_  
DRIVER'S Occupation : INDOOR OUTDOOR (e.g. working inside or outside office)  
Email Address : \_\_\_\_\_ sales@mia.com.sg  
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
Number of Passengers (Including Driver): 2  
Was there any video Captured by car camera: YES NO  
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
Any Injury (If YES, Pls state): \_\_\_\_\_

**Other Party Driver's Particular (if any)**

Vehicle. No: ① SJE7909M  
Vehicle Make\Model: T/AXIO  
Name Driver: \_\_\_\_\_  
IC No. Driver/Contact: \_\_\_\_\_

Vehicle. No: ③ SLW1939Y  
Vehicle Make\Model: MAZDA 3  
Name Driver: \_\_\_\_\_  
IC No. Driver/Contact: \_\_\_\_\_

\* NEW - Passenger's name & gender:

④ SLQ3187T  
H/VEZEL


## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN

PIE TOWARDS CHANGI AIRPORT BEFORE JALAN EUNOS.



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/01/19 @ about 2045 hrs I was travelling along PIE towards Changi Airport on the extreme left lane. The traffic condition was heavy. The vehicle in front of me slow down & stopped I proceed to stop behind the vehicle. Out of sudden I felt a strong impact from the rear of my vehicle & due to the <sup>strong</sup> impact from the rear, my vehicle shift to the front & hit the front vehicle. I alighted my vehicle & found out that I am in a 4 car chain collision. Accident. I wish to state I have 1 passenger on board my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

## MOTOR CAR (Frt)

ACTION (AC)

(1)Replace (✓)

(2)Repair (X)

(3)Recall (7)

(4)Not Constant (4C)

Aug 2005

## Front Portion

Vehicle No:

SGY4455E

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	DD	✓	
1006	991325	Frt Bumper Bracket	NEC	✓	
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	RR	✓	2
1009	991318	Frt Bumper Beam		?	
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem	RR	✓	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy		?	
1030	991821	Frt RH Headlamp Assy		?	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem	DD	✓	
1035	990287	Bonnet Lock	NEC	✓	
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Flange			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990131	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched  
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

## MOTORCAR (Rear)

ACTION (AC)  
 (1) Replace (✓) (2) Repair (X) (3) Check (□)  
 (4) Not Consistent (NC)

Aug 2005

### Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BR	✓	
1138	993627	Rear Number Plate Base	UT	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	BR	✓	
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	BR	✓	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	BR	✓	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	BR	✓	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	RT	✓	
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Vehicle No:

SGY 4455E

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe	CUT	✓	
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2019 <a href="#">Edit Reg</a>		31 Jan 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	LEE YOKE CHOY, ID: S1672054B								
Main Claimant:	-								
Vehicle Reg. No.:	SGY4455E	Date of Loss:	30/01/2019 00:00 - :59 [108 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3794444173SG	Policy/Cover Note No.:	1800014795 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLW1939Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Intel Automo Pte Ltd (HQ) 13 Kaki Bukit Road 4, #01-20, Bartley Biz Centre, 417807 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/02/2019]								
Claimant's Solicitor:	ALLISTER LIM & THRUMURGAN - Tel: 64222187								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (01/02/2019): Request to upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



































## Claim Documents


**\*SGY4455E (3794444173SG)**  
**[SLW1939Y]**

TP

-

**Jan 30 2019 12:00AM**  
**[LEE YOKE CHOY]**  
**Motor Intel Automo Pte Ltd**

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
2	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
3	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
4	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
5	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
6	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
7	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
8	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
9	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
10	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
11	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
12	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
13	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
14	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
15	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
16	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
17	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
18	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
19	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
20	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
21	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
22	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
23	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
24	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
25	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
26	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
27	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
28	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
29	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
30	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
31	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
32	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
33	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
34	01/02/19 17:08	General View										Load JPG	<input checked="" type="checkbox"/>	
Documentation											1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/02/19 09:27	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19002071/R1CD3E2

Date: 12/02/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800014795

Claimant Vehicle No : SGY4455E

Insured Vehicle No : SLW1939Y

Date of Loss: 30/01/2019

Nature of Claim: TP

Claim No: 3794444173SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY4455E**

Make & Model: ALFA ROMEO 159, 2.2 JTS (A)

Engine No: 939A50001761168

Reg. Date: 14/01/2010 (Man. Year: 2009)

Chassis No: ZAR93900007258404

Colour: White

Odometer: 267960 km

Engine Capacity: 2198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45Z R17

Rear Tyre Size: 225/45Z R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 31/01/2019 Inspected At:

Motor Intel Automo Pte Ltd (HQ)  
13 Kaki Bukit Road 4, #01-20, Bartley Biz  
Centre  
Singapore 417807

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
5	1		*FRT GRILLE	Broken	0.00 F	*- F
6	1		*FRT LH HEADLAMP ASSY	* Check	0.00 F	*- F
7	1		*FRT RH HEADLAMP ASSY	* Check	0.00 F	*- F
8	1		*BONNET	Dented	0.00 F	*- F
9	1		*BONNET EMBLEM	Necessary	0.00 F	*- F
10	1		*REAR NUMBER PLATE	Broken	0.00 F	*- F
11	1		*REAR NUMBER PLATE BASE	Cut	0.00 F	*- F
12	1		*REAR NUMBER PLATE LAMP	Broken	0.00 F	*- F
13	1		*REAR BUMPER	Dented	0.00 F	*- F
14	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
15	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
16	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
17	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
18	1		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
19	1		*REVERSE SENSOR	Broken	0.00 F	*- F
20	1		*REAR RH TAILLAMP	* Check	0.00 F	*- F
21	1		*TAILGATE	Dented	0.00 F	*- F
22	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
23	1		*TAILGATE LAMP	* Check	0.00 F	*- F
24	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
25	1		*TAILGATE LOCK	Bent	0.00 F	*- F
26	1		*REAR EXHAUST PIPE	* Check	0.00 F	*- F
27	1		*REAR EXHAUST CHROME PIPE	Cut	0.00 F	*- F
				<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >