

ASS. REC. BY:

REF: 02/AIG14002074/Atb39

Special Instruction:

Surveyor
Mannan

Adnan

ASSIGNMENT (Office)

From (Person):

Azlan Syazairi

AIG

Date/Time:

31/1/19 @ 10:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 6817J

Insured:

S/L 4614X

at Workshop m/s:

Hiap Hong Motor

Tel:

8433 3989

of

2 kaki Bukit Ave 2 # 02-13 Autohub

Policy No:

1800132958

Claim No:

15070360186

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:04am @ 31/1/19

Person Contacted:

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SJM 6817J - 007/AIG11017032/M1p63k2

DUA: 21/8/2011

S/L 4614X -

Lump Sum \$11,200+ (Red: 12541: 52%) , 13 days

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

13 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJM6817J Yr Regn: 2009 / Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C. 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading 141821 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MROS3ZEE106125528Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 31/04/19Survey held at Hip HenryDes. of Damages Fr / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG.

COE Expiry: 12/01/24.

MV: 28K

PV: 12.9K

Nett: 15.1K.

RECEIVED 27 FEB 2019

Date/Time, File Pass to?

1) 27K Typist

3)

5)

Prel. Report:

Final Report:

Date/Time, File Return to?

2)

4)

6)

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

150

Your password will expire in 12 days. [Click here to change it.](#)

- Pre repair inspection request - SJM6817J VS SJL4614X (OI) DOA 29/01/2019

From: Azlan, Syazairdina
To: admin-a@kkauto.com, assignments@kkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Hor, Yinrul, Kaur, Baljit
Sent: 31/1/2019 10:18:16 AM
Attachments:  [tnc5482.tif](#)

Hi,

Please refer to the enclosed request from Tng Soon Chye & Co.

Claim no : 1508083601SG003
Case Owner : CHEE HENG LOH

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOI, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: tsclex@singnet.com.sg [mailto:tsclex@singnet.com.sg]
Sent: Thursday, January 31, 2019 9:58 AM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Hor, Yinrul; Kaur, Baljit; tsclex@singnet.com.sg
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJL4614X AND SJM6817J ON 29/01/2019

IMMEDIATE ATTENTION

Dear Sirs,

We refer to your email dated 31 January 2019.

Our client instructs that he agrees to the appointment of Mr Adrian Ling of LKK Auto Consultants Pte Ltd as a Single Joint Expert for the pre repair inspection of car SJM6817J at Hiap Hong Motor Repair at 2 Kaki Bukit Avenue 2 #02-13 Autohub Singapore 417921 (tel: 67459633).

If we do not receive your reply within the stipulated 2 days, our client shall proceed to repair the car SJM6817J without any reference whatsoever. Our client's rights are hereby expressly reserved.

Thank You & Best Regards,

M/s Tng Soon Chye & Co

From: Azlan, Syazairdina
Sent: Thu, 31 Jan 2019 01:32:48 +0000
To: tsclex@singnet.com.sg
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Hor, Yinrul, Kaur, Baljit
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJL4614X AND SJM6817J ON 29/01/2019

Without Prejudice

Your Reference : TSC SJM6817J.Accid.2019 (HHT)-c
Our Reference : 1508083601SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services

EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Quang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Zhou, Aiping
Sent: Wednesday, January 30, 2019 4:42 PM
To: PRDSG.FNOL
Cc: Azlan, Syazairdina; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Chan, Yoke Shi; Mithoosingh, Aashweenjeetkaur; Chin, Ann; Md Ishak, Mohd Imran; Ho, Choon-Poh; Tan, Lily (AIG); Quek, Joyceline-CH; Hor, Yinrul
Subject: 05# SJL4614X #002,002#DEFAULT

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4629G
Vehicle Details	
Vehicle No.:	SJM6817J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4818011
Chassis No.:	MR053ZEE106125528
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	13 Jan 2009
First Registration Date:	13 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$16,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Details	
COE Expiry Date:	12 Jan 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,024.00
COE Rebate Amount:	\$12,883.00
Total Rebate Amount:	\$12,883.00
Remarks	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Feb 2019.

OK



Triple Crown Winner of the Premium Dealer Award

Save big & enjoy \$800 shopping vouchers with every purchase.

[Learn more](#)**Select**

By Performance Premium Selection



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[i Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A



2.88% P.A. Lowest Interest @ GV
Cars Financing \$2000
Downpayment Monthly From
\$638

GV Credit Pte Ltd StarAd



- Free VICOM evaluation
- Free grooming and 3 months maintenance
- In-house workshop ensures quality service
- Member of SYTA and hire purchase association
- 100% deposit refund for unapproved loan



YONG LEE SENG MOTOR PTE LTD

Browse by Category

[Save Search](#)[Print](#)[Back \(1 2 3 4 5 \) Next >](#)

Sort by Date Posted

20 results/page

91 vehicles

Search **Altis**[Advanced Search](#)[Search](#)[View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection: Altis Any Any 2009 Any Any Any Available



☐ Toyota Corolla Altis 1.6A
(COE till 01/2024)

\$27,800

\$5,620 /yr

14-Jan-2009

1,598 cc

-

Sedan

Available

2.88% P.A. Lowest Interest At \$568 Monthly For Toyota Altis. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available

\$2700 Driveway (inc: 1 Yr Insurance & Adv) 2.88% p.a Monthly \$568 By GV Finance

GV Credit Pte Ltd

☆ Posted: 01-Feb-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM ED



☐ Toyota Corolla Altis 1.6A (New
5-yr COE)

\$32,800

\$6,560 /yr

05-Jan-2009

1,598 cc

85,000 km

Sedan

Available

Well Maintained, Super Low Genuine Mileage Done, Well Groomed Inside Out. No Repairs Needed, Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Pr...

☆ Posted: 28-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM ED



☐ Toyota Corolla Altis 1.6A (COE
till 01/2024)

\$30,800

\$6,250 /yr

06-Jan-2009

1,598 cc

117,900 km

Sedan

Available

New Road Tax, New Paintwork, New Engine Mountings, New Stabilizers, Servicing Done, Receipts To Proof, Bank/In House Loan, Low Down Payment, \$574 Monthly, No Hidden Cost.

☆ Posted: 25-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (New
5-yr COE)

\$32,800

\$6,560 /yr

08-Jan-2009

1,598 cc

92,000 km

Sedan

Available

One Year In House Warranty, "The Only Altis With Factory Full Bodykit" In Resale Market, Full Loan Available, Price Above Stated Is Actual Selling Price, STA Evaluation Are Welcome, Purchase With Off...

Carway

☆ Posted: 31-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ Toyota Corolla Altis 1.6A (COE
till 01/2024)

\$31,800

\$6,440 /yr

08-Jan-2009

1,598 cc

-

Sedan

Available

Good Condition, Well Maintained, All Wear And Tear Parts Had Change. Call/SMS For More Details.

Prime Cars Credit

☆ Posted: 26-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE
till 01/2024)

\$27,800

\$5,620 /yr

12-Jan-2009

1,598 cc

-

Sedan

Available

2.88% P.A. Lowest Interest At \$568 Monthly For Toyota Altis. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

Driveway \$2700 (inc: 1 Year Insurance & Adv) 2.88% p.a Monthly \$568 By Gv Finance

GV Credit Pte Ltd

☆ Posted: 01-Feb-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

PREMIUM ED

SHORTLISTED

REMOVED

[Compare \[4 \]](#)



☐ Toyota Corolla Altis 1.6A (COE till 01/2024) \$29,800 \$6,030 /yr 12-Jan-2009 1,598 cc 102,300 km Sedan Available

Monthly Installment \$600 Plus For 54 Months! Powerful, Comfortable, Reliable And Low Maintenance Cost. Flexible Bank/ In House Loan Package Available. Viewing Is Highly Encouraged. Call Our Sales Team...

Viking Motor Pte Ltd

☆ Posted: 11-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (New 5-yr COE) \$27,800 \$5,560 /yr 12-Jan-2009 1,598 cc - Sedan Available

Monthly Payment Of \$596! New 5 Years COE. Price Include New \$2K Paint/New Leather Seat, Rims, Comes With 6 Months Engine And Gearbox Warranty. All Our Quality Preowned Car Are Selling At Low Depreciat...

Car World Automobile

☆ Posted: 23-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 01/2024) \$29,800 \$6,030 /yr 12-Jan-2009 1,598 cc 128,000 km Sedan Available

Monthly Installment \$600 Plus For 54 Months! Powerful, Comfortable, Reliable And Low Maintenance Cost. Flexible Bank/ In House Loan Package Available. Viewing Is Highly Encouraged. Call Our Sales Team...

Viking Motor Pte Ltd

☆ Posted: 19-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 01/2024) \$29,888 \$6,040 /yr 13-Jan-2009 1,598 cc 115,000 km Sedan Available

Free 1 Servicing Upon Purchase! 1 Year Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Well Maintained, Super Low Genuine Mileage Done. Well Groomed Ins...

PREMIUM #2

☆ Posted: 30-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



That's a fine looking car interior

Customise your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.

Find out more!



☐ Toyota Corolla Altis 1.6A (COE till 01/2024) \$27,800 \$5,620 /yr 13-Jan-2009 1,598 cc - Sedan Available

2.88%P.A Lowest Interest At \$568 Monthly For Toyota Altis. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

GV Credit Pte Ltd

PREMIUM #2

☆ Posted: 20-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 01/2024) \$27,800 \$5,620 /yr 13-Jan-2009 1,598 cc - Sedan Available

2.88%P.A Lowest Interest At \$568 Monthly For Toyota Altis. Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. Add Ons Available.

GV Credit Pte Ltd

PREMIUM #2

☆ Posted: 26-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 01/2024) \$32,800 \$6,630 /yr 13-Jan-2009 1,598 cc 92,000 km Sedan Available

Well Maintained, Cheap And Well Conditioned! Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency. We Provide Loa...

PREMIUM #2

☆ Posted: 27-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (New 5-yr COE) \$32,800 \$6,560 /yr 13-Jan-2009 1,598 cc - Sedan Available

☆ Posted: 27-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (New 5-yr COE) \$33,800 \$6,760 /yr 13-Jan-2009 1,598 cc - Sedan Available

Well Kept Condition. Excellent Condition Interior And Exterior. View To Believe. In House/Bank Loan Available. Call Now For Viewing.

☆ Posted: 15-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



☐ Toyota Corolla Altis 1.6A (COE till 01/2024) \$29,700 \$6,000 /yr 14-Jan-2009 1,598 cc 97,026 km Sedan Available

PREMIUM #2

☆ Posted: 31-Jan-2019 Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Compare [4]

湯順才律師樓
TNG SOON CHYE & CO.

ADVOCATES & SOLICITORS
NOTARY PUBLIC
COMMISSIONER FOR OATHS
UEN NO: 53131141D

150 South Bridge Road #02-19 Fook Hai Building Singapore 058727

Tel: 6438 3133 • Fax: 6438 6066

(Service of Court documents via fax is not acceptable)

Our Ref: TSC.SJM6817J.Accid.2019 (HH)-c

30th January 2019

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

Motor Claim Department

78 Shenton Way

#07-16

Singapore 079120

(Insurer of vehicle no. SJL4614X)

URGENT ATTENTION

By Fax/Certificate of Posting

(Fax: 6835 7416/ 6415 3727 / 6835 3727)

cc. to:

LING JIA YI

488C Choa Chu Kang Avenue 5

#04-167

Singapore 683488

(Owner of vehicle no. SJL4614X)

By Certificate of Posting

Dear Sirs,

**ACCIDENT ON 29th JANUARY 2019 INVOLVING MOTOR-VEHICLES NOS. SGX7525Y
SJM6817J & SJL4614X ALONG PIE TWDS CHANGI AROUND LORNIE**

We are instructed by Chee Beng Hum to notify you of a road traffic accident on 29th January 2019 at about 13:30 hrs along PIE Twds Changi Around Lornie involving our client's vehicle registration number SJM6817J and vehicle registration SJL4614X. Vehicle SJL4614X driven by your insured driver at the material time of the accident. A copy of the Singapore accident statement/ traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle at 2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Yours faithfully,

Tng Soon Chye

Enc.

cc. client – via fax: 6747 8602 only
(ref: SJM6817J)

MSME19014009 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 29/01/2019 17:47
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/01/2019 17:47
Date Of Accident	29/01/2019 13:30
Exact Location Of Accident	PIE TWDS CHANGI AROUND LORNIE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJM6817J
Insured/Policyholder	
Name Of Registered Owner	CHEE BENG HUM
NRIC No	S1184629G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91591755
Alternative Phone No	OFFICE-91591755
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0003112
Cover Note Number	
Driver	
Name of Driver	ISAAC CHEE HAOZHE
NRIC No	S9441345A
Date Of Birth	07/11/1994
Occupation	INDOOR
Date Of Driving Pass	23/07/2015
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96328299
Fax Number	
Contact Number	
Email Address	ISAAC.CHEE@GMAIL.COM

Address	25 WOODLEIGH CLOSE #04-01
Postcode	357920
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL4614X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGX7525Y
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

VEHICLE C

PRIVATE CAR

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/01/2019 17:47
Date Of Accident	29/01/2019 13:30
Exact Location Of Accident	PIE TWDS CHANGI AROUND LORNIE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJM6817J
Insured/Policyholder	
Name Of Registered Owner	CHEE BENG HUM
NRIC No	S1184629G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91591755
Alternative Phone No	OFFICE-91591755
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0003112
Cover Note Number	
Driver	
Name of Driver	ISAAC CHEE HAOZHE
NRIC No	S9441345A
Date Of Birth	07/11/1994
Occupation	INDOOR
Date Of Driving Pass	23/07/2015
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96328299
Fax Number	
Contact Number	
Email Address	ISAAC.CHEE@GMAIL.COM

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

B-SSL4614X
C-SG47525Y



[Signature]

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

~~We were on the~~
Refer to attached.

[Signature]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/SIN No.:

SJM6817J

Date

No.

Toyota Altis 1558cc

MROS3ZEE106125528

Front Number Plate	Bent	30(SN)	✓
Front Number Plate Holder	Crushed	30(SN)	✓
Front Bumper	Distorted	56380	✓
Front Bumper Clips	new	30	✓
Front Bumper Side Holder	x02 new	607x2=12140	✓
Front Bumper Reinforcement	Bent	33970	✓
Front Bumper Lower Grille	2 new	10650	✗
Front Bumper Fog Lamp		279.5x2=559	✗
Front Bumper Fog Lamp Cover		96.3x2=192.60	✗
Front Bumper Undercover	torn	262.20	✗
Front Bumper Undercover Clips	new	30	✓
Front Bumper Logo	new	3280	✓
Front Grille	Crushed	29880	✓
Front Grille Clips	new	20	✓
Headlamp	x02 Crushed	635x2=1270	✓
Front Brace Panel	Bent	11310	✓
Front Support Panel	Crushed	69990	✓
Bonnet	Distorted	89450	✓
Bonnet Lock	Damaged	9850	✓
Bonnet Hinge	x02 Bent	489x2=9780	✓
Bonnet Weatherstripe	at	6850	✓
Bonnet Weatherstripe Clips	new	10	✓
Bonnet Insulation Pad	crushed	26680	✓
Bonnet Insulation Pad Clips	new	30	✓
Front Fender	x02 Crushed	585x2=1170	✓
VVTi Emblem	x02 new	341x2=6820	✓
Wiper Panel Garnish	LH cut	26820	✓
Wiper Panel Garnish Clips	new	20	✓
Air Con Condenser	Bent	129940	✓
Radiator	Not new	168190	✗

SJM6817J.

	Date	No.
Rear Fender Inner Trim x 2 } new	338.7 x 2 = 677.40	x
Rear Fender Inner Trim Clips. } new	60	x
Rear Exhaust Pipe } new	792.10	x
Rear Exhaust Mounting } new	42	x

12321.30
9240.94

S.N: 400

Panel Beating	2200	2000
Spray Painting.	8200	2000.
Wiring	400	60.
To undress	150	50
To remove reverse sensor	400	50
To remove upholstery	4400.	150 60.
To transfer bootlid fittings	150	60
To remove exhaust pipe.	150	x
To remove radiator, condenser and to top up air con gas.	180	120.

total 14040.57

H/s: 11.2K

13 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2019 Edit Reg		31 Jan 2019 00:00 Edit Adj Rpt	\$511,200.00 Edit Estimates	\$511,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LING JIA YI , ID: S9238449G									
Main Claimant: CHEE BENG HUM , ID: S1184629G									
Vehicle Reg. No.: SJM6817J		Date of Loss: 29/01/2019 13:00 - :59 [120 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1508083601SG		Policy/Cover Note No.: 1800132958 (Comprehensive)							
Vehicle Reg. No. (Insured): SJL4614X		Policy No. (Claimant):							
		Excess:							
Repairer: Hiap Hong Motor Repair (HQ) 2 Kaki Bukit Avenue 2, #02-13 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 67459633									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/02/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (01/02/2019): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM6817J (1508083601SG)
[SJL4614X]
TP
CHEE BENG HUM
Jan 29 2019 1:00PM
[LING JIA YI]
Hiap Hong Motor Repair

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	26/02/19 15:39	General View														Load JPG				
2	26/02/19 15:39	General View														Load JPG				
3	26/02/19 15:39	General View														Load JPG				
4	26/02/19 15:39	General View														Load JPG				
5	26/02/19 15:39	General View														Load JPG				
6	26/02/19 15:39	General View														Load JPG				
7	26/02/19 15:39	General View														Load JPG				
8	26/02/19 15:39	General View														Load JPG				
9	26/02/19 15:39	General View														Load JPG				
10	26/02/19 15:39	General View														Load JPG				
11	26/02/19 15:39	General View														Load JPG				
12	26/02/19 15:39	General View														Load JPG				
13	26/02/19 15:39	General View														Load JPG				
14	26/02/19 15:39	General View														Load JPG				
15	26/02/19 15:39	General View														Load JPG				
16	26/02/19 15:39	General View														Load JPG				
17	26/02/19 15:39	General View														Load JPG				
18	26/02/19 15:39	General View														Load JPG				
19	26/02/19 15:39	General View														Load JPG				
20	26/02/19 15:39	General View														Load JPG				
21	26/02/19 15:39	General View														Load JPG				
22	26/02/19 15:39	General View														Load JPG				
23	26/02/19 15:39	General View														Load JPG				
24	26/02/19 15:39	General View														Load JPG				
25	26/02/19 15:39	General View														Load JPG				
26	26/02/19 15:39	General View														Load JPG				
27	26/02/19 15:39	General View														Load JPG				
28	26/02/19 15:39	General View														Load JPG				
29	26/02/19 15:39	General View														Load JPG				
30	26/02/19 15:39	General View														Load JPG				
31	26/02/19 15:39	General View														Load JPG				
32	26/02/19 15:39	General View														Load JPG				
33	26/02/19 15:39	General View														Load JPG				
34	26/02/19 15:39	General View														Load JPG				
35	26/02/19 15:39	General View														Load JPG				
36	26/02/19 15:39	General View														Load JPG				
37	26/02/19 15:39	General View														Load JPG				

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/02/19 15:39	General View	 Load JPG	☒
39	26/02/19 15:39	General View	 Load JPG	☒
40	26/02/19 15:39	General View	 Load JPG	☒
41	26/02/19 15:39	General View	 Load JPG	☒
42	26/02/19 15:39	General View	 Load JPG	☒
43	26/02/19 15:39	General View	 Load JPG	☒
44	26/02/19 15:39	General View	 Load JPG	☒
45	26/02/19 15:39	General View	 Load JPG	☒
46	26/02/19 15:39	General View	 Load JPG	☒
47	26/02/19 15:39	General View	 Load JPG	☒
48	26/02/19 15:39	General View	 Load JPG	☒
49	26/02/19 15:39	General View	 Load JPG	☒
50	26/02/19 15:39	General View	 Load JPG	☒
51	26/02/19 15:39	General View	 Load JPG	☒
52	26/02/19 15:39	General View	 Load JPG	☒
53	26/02/19 15:39	General View	 Load JPG	☒
54	26/02/19 15:39	General View	 Load JPG	☒
55	26/02/19 15:39	General View	 Load JPG	☒
56	26/02/19 15:39	General View	 Load JPG	☒
57	26/02/19 15:39	General View	 Load JPG	☒
58	26/02/19 15:39	General View	 Load JPG	☒
59	26/02/19 15:39	General View	 Load JPG	☒
60	26/02/19 15:39	General View	 Load JPG	☒
61	26/02/19 15:39	General View	 Load JPG	☒
62	26/02/19 15:39	General View	 Load JPG	☒
63	26/02/19 15:39	General View	 Load JPG	☒
64	26/02/19 15:39	General View	 Load JPG	☒
65	26/02/19 15:39	General View	 Load JPG	☒
66	26/02/19 15:39	General View	 Load JPG	☒
67	26/02/19 15:39	General View	 Load JPG	☒
68	26/02/19 15:39	General View	 Load JPG	☒
69	26/02/19 15:39	General View	 Load JPG	☒
70	26/02/19 15:39	General View	 Load JPG	☒
71	26/02/19 15:39	General View	 Load JPG	☒
72	26/02/19 15:39	General View	 Load JPG	☒
73	26/02/19 15:39	General View	 Load JPG	☒
74	26/02/19 15:39	General View	 Load JPG	☒
75	26/02/19 15:39	General View	 Load JPG	☒
76	26/02/19 15:39	General View	 Load JPG	☒
77	26/02/19 15:39	General View	 Load JPG	☒
78	26/02/19 15:39	General View	 Load JPG	☒
79	26/02/19 15:39	General View	 Load JPG	☒
80	26/02/19 15:39	General View	 Load JPG	☒
81	26/02/19 15:39	General View	 Load JPG	☒
82	26/02/19 15:39	General View	 Load JPG	☒
83	26/02/19 15:39	General View	 Load JPG	☒
84	26/02/19 15:39	General View	 Load JPG	☒
85	26/02/19 15:39	General View	 Load JPG	☒
86	26/02/19 15:39	General View	 Load JPG	☒
87	26/02/19 15:39	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	26/02/19 15:39	General View		☒
89	26/02/19 15:39	General View		☒
90	26/02/19 15:39	General View		☒
91	26/02/19 15:39	General View		☒
92	26/02/19 15:39	General View		☒
93	26/02/19 15:39	General View		☒
94	26/02/19 15:39	General View		☒
95	26/02/19 15:39	General View		☒
96	26/02/19 15:39	Reinspection Photo		☒
97	26/02/19 15:39	Reinspection Photo		☒
98	26/02/19 15:39	Reinspection Photo		☒
99	26/02/19 15:39	Reinspection Photo		☒
100	26/02/19 15:39	Reinspection Photo		☒
101	26/02/19 15:39	Reinspection Photo		☒
102	26/02/19 15:39	Reinspection Photo		☒
103	26/02/19 15:39	Reinspection Photo		☒
104	26/02/19 15:39	Reinspection Photo		☒
105	26/02/19 15:39	Reinspection Photo		☒
106	26/02/19 15:39	Reinspection Photo		☒
107	26/02/19 15:39	Reinspection Photo		☒
108	26/02/19 15:39	Reinspection Photo		☒
109	26/02/19 15:39	Reinspection Photo		☒
110	26/02/19 15:39	Reinspection Photo		☒
111	26/02/19 15:39	Reinspection Photo		☒
112	26/02/19 15:39	Reinspection Photo		☒
113	26/02/19 15:39	Reinspection Photo		☒
114	26/02/19 15:39	Reinspection Photo		☒
115	26/02/19 15:39	Reinspection Photo		☒
116	26/02/19 15:39	Reinspection Photo		☒
117	26/02/19 15:39	Reinspection Photo		☒
118	26/02/19 15:39	Reinspection Photo		☒
119	26/02/19 15:39	Reinspection Photo		☒
120	26/02/19 15:39	Reinspection Photo		☒
121	26/02/19 15:39	Reinspection Photo		☒
122	26/02/19 15:39	Reinspection Photo		☒
123	26/02/19 15:39	Reinspection Photo		☒
124	26/02/19 15:39	Reinspection Photo		☒
125	26/02/19 15:39	Reinspection Photo		☒
126	26/02/19 15:39	Reinspection Photo		☒
127	26/02/19 15:39	Reinspection Photo		☒
128	26/02/19 15:39	Reinspection Photo		☒
129	26/02/19 15:39	Reinspection Photo		☒
130	26/02/19 15:39	Reinspection Photo		☒
131	26/02/19 15:39	Reinspection Photo		☒
132	26/02/19 15:39	Reinspection Photo		☒
133	26/02/19 15:39	Reinspection Photo		☒
134	26/02/19 15:39	Reinspection Photo		☒
135	26/02/19 15:39	Reinspection Photo		☒
136	26/02/19 15:39	Reinspection Photo		☒
137	26/02/19 15:39	Reinspection Photo		☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
139	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
140	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
141	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
142	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
143	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
144	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
145	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
146	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
147	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
148	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
149	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
150	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
151	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
152	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
153	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
154	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
155	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
156	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
157	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
158	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
159	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
160	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
161	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
162	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
163	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
164	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
165	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
166	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
167	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
168	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
169	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
170	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
171	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
172	26/02/19 15:39	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/02/19 09:22	OI GIA REPORT	 Load PDF	
2	01/02/19 11:23	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19002074/ATD3Q2

Date: 28/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800132958

Claimant Vehicle No : SJM6817J

Insured Vehicle No : SJL4614X

Date of Loss: 29/01/2019

Nature of Claim:

TP

Claim No: 1508083601SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM6817J**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4818011

Reg. Date: 13/01/2009 (Man. Year: 2008)

Chassis No: MR053ZEE106125528

Colour: Silver

Odometer: 141821 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Toyo 6 mm

Rear Left Side:

Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side:

Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,511.00	9,640.97	8,870.03	47.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	4,400.00	980.00	18.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,891.00	14,040.97	9,850.03	41.23
Approved Total (Overridden) (S\$)		11,200.00		
Nett Amount (S\$)	23,891.00	11,200.00	12,691.00	53.12

INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 31/01/2019 Inspected At:

Hiap Hong Motor Repair (HQ)
2 Kaki Bukit Avenue 2, #02-13 Kaki Bukit
Autohub
Singapore 417921

Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Cracked	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER	Distorted	563.80 F	*563.80 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	2		*FRONT BUMPER SIDE HOLDER	Necessary	121.40 F	*121.40 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	339.70 F	*339.70 FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	106.50 F	*- FL
8	2		*FRONT BUMPER FOG LAMP	Not Necessary	559.00 F	*- FL
9	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	192.60 F	*- FL
10	1		*FRONT BUMPER UNDERCOVER	Torn	262.20 F	*262.20 FL
11	1		*FRONT BUMPER UNDERCOVER CLIPS	Necessary	30.00 F	*30.00 FL
12	1		*FRONT BUMPER LOGO	Necessary	32.80 F	*32.80 FL
13	1		*FRONT BUMPER TOP RUBBER	Cut	69.70 F	*69.70 FL
14	1		*FRONT GRILLE	Cracked	298.80 F	*298.80 FL
15	1		*FRONT GRILLE CLIPS	Necessary	20.00 F	*20.00 FL
16	2		*HEADLAMP	Cracked	1,270.00 F	*1,270.00 FL
17	1		*FRONT BRACE PANEL	Bent	113.10 F	*113.10 FL
18	1		*FRONT SUPPORT PANEL	Buckled	699.90 F	*699.90 FL
19	1		*BONNET	Distorted	894.50 F	*894.50 FL
20	1		*BONNET LOCK	Damaged	98.50 F	*98.50 FL
21	2		*BONNET HINGE	Bent	97.80 F	*97.80 FL
22	1		*BONNET WEATHERSTRIPE	Cut	68.50 F	*68.50 FL
23	1		*BONNET WEATHERSTRIPE CLIPS	Necessary	10.00 F	*10.00 FL
24	1		*BONNET INSULATION PAD	Crumpled	266.80 F	*266.80 FL
25	1		*BONNET INSULATION PAD CLIPS	Necessary	30.00 F	*30.00 FL
26	2		*FRONT FENDER	Buckled	1,170.00 F	*1,170.00 FL
27	2		*VVTI EMBLEM	Necessary	68.20 F	*68.20 FL
28	1		*WIPER PANEL GARNISH LH	Cut	268.20 F	*268.20 FL
29	1		*WIPER PANEL GARNISH CLIPS	Necessary	20.00 F	*20.00 FL
30	1		*AIR CON CONDENSER	Bent	1,299.40 F	*1,299.40 FL
31	1		*RADIATOR	Not Necessary	1,681.90 F	*- FL
32	1		*RADIATOR TOP COVER	Cracked	193.40 F	*193.40 FL
33	1		*RADIATOR FAN COWLING	Not Necessary	232.30 F	*- FL
34	1		*RADIATOR FAN MOTOR	Not Necessary	383.20 F	*- FL
35	1		*RADIATOR FAN BLADE	Not Necessary	96.10 F	*- FL
36	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
37	1		*REAR BUMPER	Deformed	476.20 F	*476.20 FL
38	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
39	2		*REAR BUMPER SIDE HOLDER	Necessary	114.00 F	*114.00 FL
40	2		*REAR BUMPER REFLECTOR	Not Necessary	138.40 F	*- FL
41	2		*REAR BUMPER IMPACT BRACKET	Dented	171.20 F	*171.20 FL
42	1		*REAR BUMPER REINFORCEMENT ROD	Bent	152.60 F	*152.60 FL
43	1		*REAR BUMPER SPONGE	Cracked	80.90 F	*80.90 FL
44	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
45	1		*REAR END PANEL	Distorted	532.80 F	*532.80 FL
46	1		*REAR END PANEL TOP GARNISH	Deformed	192.70 F	*192.70 FL
47	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
48	2		*TAILLAMP	Cracked	684.00 F	*684.00 FL
49	2		*TAILLAMP LOWER BRACKET	Not Necessary	110.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*TAILLAMP SPONGE GASKET	Necessary	40.00 FS	*40.00 FS
51	2		*TAILLAMP PANEL	Repair	228.00 F	*- FL
52	1		*BOOTLID	Buckled	680.00 F	*680.00 FL
53	1		*BOOTLID LOCK	Damaged	121.50 F	*121.50 FL
54	1		*BOOTLID WEATHERSTRIPE	Cut	195.50 F	*195.50 FL
55	2		*BOOTLID REFLECTOR	Not Necessary	390.20 F	*- FL
56	1		*TOYOTA LOGO	Necessary	52.00 F	*52.00 FL
57	1		*1.6 EMBLEM	Necessary	46.00 F	*46.00 FL
58	1		*COROLLA WORDING	Necessary	48.00 F	*48.00 FL
59	1		*ALTIS WORDING	Necessary	48.00 F	*48.00 FL
60	1		*SPARE TYRE PANEL TOP COVER	Deformed	359.20 F	*359.20 FL
61	2		*REAR FENDER INNER TRIM	Not Necessary	677.40 F	*- FL
62	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
63	1		*REAR EXHAUST PIPE	Not Necessary	792.10 F	*- FL
64	1		*REAR EXHAUST MOUNTING	Not Necessary	42.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,511.00	12,721.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	3,080.33
Total Parts (\$\$)	18,511.00	9,640.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	2,000.00
2	SPRAY PAINTING	New	2,200.00	2,000.00
3	WIRING	New	100.00	60.00
4	TO UNDERSEAL	New	150.00	50.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	60.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
8	TO REMOVE EXHAUST PIPE	New	150.00	0.00
9	TO REMOVE RADIATOR ,CONDENSER AND TO TOP UP AIR CON GAS	New	180.00	120.00
Gross Labour Cost (S\$)			5,380.00	4,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >