

ASS. REC. BY:

REF:

CS3/FWD19002077/RICd362 Special Instruction

Survivor
menmen

Rasul

ASSIGNMENT (Office)

From (Person):

Motorclaims

of

FWD

Date/Time

30/1/19 @ 6:17pm

Estimated Cost:

Bill to:

OD/FP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLG 6866A

Insured:

SKK 3165A

at Workshop m/s

T & B Motor Repairs

Tel:

6458 0296

of

Blk 160 Sin Ming Drive # 08-03

Policy No:

PNPV2018-00011797

Claim No:

1201900003564

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/01/2019

CA / REV / REP. / REV 24 HRS

'up'

01/02/19 @ 10-11am

H.O.D. Endorsement:

Date/Time:

10:49am @ 31/1/19

Person Contacted:

judy

Vehicle

IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

SLG 6866A - X

SKK 3165A - X

Pending Gria Report.

REF: FWD

PRS (Merimen)

ASSIGNMENT

From Date 01/02/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

at Workshop n/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Repair large 35K-4K

13/2/2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: PRS

Lump Sum / I.B.I: (\$)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S+RS SI

) Photos

) Collect

) -

TOTAL

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Veh No SLG 6866A

Yr Regn Sep 16

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

HONDA VIZOR

C.C.

1496

Colour

BLACK

A/C

Insured / Std / NI / NA

Sp. Reading

016837

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

R11202118

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ B / STD A/Rim or

Tyre Size: F:

215/50R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/01/19

D.O.I.

01/02/19

Survey held at

T & B Motor

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Nivitha (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Wednesday, 30 January 2019 6:17 PM
To: assignments@lkkauto.com; sur@lkkauto.com
Subject: FW: Notice of Accident - Traffic accident involving SLG 6866 A and SKK 3165 A (FWD // PNPV2018-00011797) on 30 January 2019 at/along the CTE exit towards A.M.K Avenue 1; Our ref: LCH.my/SMTB-90113.19

PRI email below for your attention.

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Wednesday, January 30, 2019 5:25 PM
To: Motor Claims SG - SG Common
Subject: Re: Notice of Accident - Traffic accident involving SLG 6866 A and SKK 3165 A (FWD // PNPV2018-00011797) on 30 January 2019 at/along the CTE exit towards A.M.K Avenue 1; Our ref: LCH.my/SMTB-90113.19

Dear Sir / Madam,

We refer to the above matter and to your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors stated therein.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- | | |
|--------------------------|-------------------------|
| 1) Jayson Liaw Leong San | 6) Hong Fook Choy |
| 2) Lee Kok Weng | 7) Andrew Aw |
| 3) Low Sar Huei | 8) Matthew Ng Yong Chin |
| 4) Patrick Ng Kong Beng | 9) Ong Poh Meng |
| 5) Leslie Lim | 10) Jackson Quek |

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey of our client's vehicle no. SLG 6866 A at our client's repairer workshop as follows:-

T & B Motor Repairs Services Pte Ltd
Blk 160 Sin Ming Drive #08-03
Sin Ming Auto City
Singapore 575722

Person to contact : Mr Tay (contact no. 6458 0296)

Thanks & regards,
Melody

CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05 Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 30 Jan 2019, at 3:58 PM, motorclaims.sg@fwd.com wrote:

Without Prejudice

Dear Sir/ Madam

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. VICOM LTD
5. APPRAISALS ASSOCIATES PTE LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]

Sent: Wednesday, January 30, 2019 1:06 PM

To: Motor Claims SG - SG Common

Subject: Notice of Accident - Traffic accident involving SLG 6866 A and SKK 3165 A (your insured) on 30 January 2019 at/along the CTE exit towards A.M.K Avenue 1; Our ref: LCH.my/SMTB-90113.19

Dear Sir/ Madam,

Please see attached Notice of Accident for your attention and reply.

Thanks & regards,

Melody

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05 Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please

- notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLG6866A		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	VEZEL 1.5X CVT		
Chassis No. :	RU11202118		
Propellant :	Petrol		
Engine No. :	L15B4402117		
Engine Capacity :	1496 cc		
Maximum Power Output :	96.0 kW (128 bhp)		
Maximum Laden Weight :	1465 kg		
Unladen Weight :	1190 kg		
Year Of Manufacture :	2016		
Original Registration Date :	27 Sep 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$50,000.00		
COE Expiry Date :	26 Sep 2026		
Road Tax Expiry Date :	26 Mar 2019		
PARF Eligibility Expiry Date :	26 Sep 2026		
Inspection Due Date :	26 Sep 2019		
Intended Transfer Date :	11 Feb 2019		
CO2 Emission :	117.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 26 Mar 2019. You may renew the road tax from 27 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 26 Mar 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 27 Mar 2019 to 26 Sep 2019)			
	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	341.00	-	341.00
Total Amount Payable :			366.00
Amount Payable (From 27 Mar 2019 to 26 Mar 2020)			
	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	682.00	-	682.00
Total Amount Payable :			707.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8241G
Vehicle Details	
Vehicle No.:	SLG6866A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4402117
Chassis No.:	RU11202118
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,300.00
Original Registration Date:	27 Sep 2016
First Registration Date:	27 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$13,220.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2026
PARF Rebate Amount:	\$9,915.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$38,125.00
Total Rebate Amount:	\$48,040.00

The information contained herein is correct as at 11 Feb 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2019 Edit Reg		30 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN LAY KOON , ID: S7917797J									
Main Claimant: -									
Vehicle Reg. No.: SLG6866A		Date of Loss: 30/01/2019 00:00 - :59 [28 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1201900003564		Policy/Cover Note No.: PNPV2018-00011797							
Vehicle Reg. No. (Insured): SKK3165A		Policy No. (Claimant):							
		Excess:							
Repairer: T& B Motor Repairs Services Pte Ltd (HQ) BLK 20 SIN MING ROAD #01-28, 575678 Sin Ming - Tel:									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/02/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG6866A (1201900003564)






















[SKK3165A]

TP

Jan 30 2019 12:00AM

[TAN LAY KOON]

T& B Motor Repairs Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/02/19 16:11	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	01/02/19 17:05	Insured GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19002077/R1CD3E2

Date: 14/02/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00011797
 Claimant Vehicle No: SLG6866A Insured Vehicle No: SKK3165A
 Date of Loss: 30/01/2019 Nature of Claim: TP Claim No: 1201900003564

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG6866A**
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4402117
 Reg. Date: 27/09/2016 (Man. Year: 2016) Chassis No: RU11202118
 Colour: Black Odometer: 16837 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R16 Rear Tyre Size: 215/50 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/01/2019
 Date Inspected: 01/02/2019 Inspected At: 160 SIN MING DRIVE# 08-03
 Repairer : T & B Motor Repairs Services Pte Ltd (HQ)
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 14 Feb 2019)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG6866A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >