

ASS. REC. BY:

REF:

CSB/FWD19002079/Gcd301

Special Instruction:

Survivor
Mummen

GMO Qisang

ASSIGNMENT (Office)

From (Person):

Lionel Ten

of

FWD

Date/Time:

30/1/19 @ 4:24pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 2502Y

Insured:

SLV 2870J

at Workshop m/s

Bak Heng Motor

Tel:

64816829 / 97888579

of

Blk 5032, Amk Ind. Park 2 #01-201

Policy No:

PNPV2018-00016332

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/01/2019

CA / REV / REP. / REV 24 HRS

sup

H.O.D. Endorsement:

Date/Time:

10:44am @ 31/1/19

Person Contacted:

Kelvin

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction (X) Estimate

SLC 2502Y-CSB/MSG18016066/bxx

D.O.A: 28/8/18

SLV 2870J - x

Nivitha (LKK Auto)

From: lionel.tan@fwd.com
Sent: Wednesday, 30 January 2019 4:29 PM
To: assignments@lkkauto.com; sur@lkkauto.com
Subject: FW: Notice of PRI of vehicle SLC 2502 Y // SLV 2870 J (PNPV2018-00016332)
Attachments: PRI-SLC2502Y-BHM.PDF

PRI email below for your attention.

From: Motor Claims SG - SG Common
Sent: Wednesday, January 30, 2019 4:27 PM
To: 'Mdm Ling'
Cc: Ling Leong Hui
Subject: RE: Notice of PRI of vehicle SLC 2502 Y // SLV 2870 J (PNPV2018-00016332)

WITHOUT PREJUDICE

Dear Sir/ Madam

We regret that we are objecting to your proposed list of surveyors.

We will be appointing **LKK AUTO CONSULTANTS PTE LTD** to conduct the pre-repair survey (PRS) on your client's vehicle. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

Regards,
Lionel

From: Mdm Ling [<mailto:mdmling@tcmg.com.sg>]
Sent: Wednesday, January 30, 2019 4:14 PM
To: Motor Claims SG - SG Common
Cc: Ling Leong Hui
Subject: Notice of PRI of vehicle SLC 2502 Y

WITHOUT PREJUDICE

Dear Sirs,

We refer to the above matter and to your e-mail of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

Yours faithfully,

Mdm Ling
TOMMY CHOO MARK GO LLC

From: motorclaims.sg@fwd.com [mailto:motorclaims.sg@fwd.com]
Sent: Wednesday, January 30, 2019 3:45 PM
To: mdmling@tcmg.com.sg
Subject: [Spam-pop3] RE: Notice of PRI of vehicle SLC 2502 Y

Without Prejudice

Dear Sir/ Madam

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. VICOM LTD
5. APPRAISALS ASSOCIATES PTE LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

From: Mdm Ling [mailto:mdmling@tcmg.com.sg]
Sent: Wednesday, January 30, 2019 12:32 PM
To: Motor Claims SG - SG Common
Subject: Notice of PRI of vehicle SLC 2502 Y

Dear Sir,

We refer to the above matter.

Attach herewith the notice of PRI of vehicle SLC 2502 Y for your attention.

Best Regards,

Mdm Ling
Tommy Choo Mark Go LLC
151 Chin Swee Road
#14-15/16 Manhattan House
Singapore 169876
Tel: (65) 6532 2455
Fax: (65) 6538 9850
Email Address: mdmling@tcmg.com.sg

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16
MANHATTAN HOUSE
SINGAPORE 169876
TEL : (65) 6532 2455
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg;mdmling@tcmg.com.sg

Our Ref: TCMG/SLC2502Y/0119/BHM

Your Ref: SLV 2870 J

30 January 2019

M/S FWD SINGAPORE PTE LTD

6 Temasek Boulevard
#18-01
Suntec Tower 4
Singapore 038986

Attn: Motor Claims Department

BY E-MAIL ONLY
(motorclaims.sg@fwd.com)

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Ong Ah Kee**, the owner and/or driver of motor vehicle no. **SLC 2502 Y**, which was involved in an accident along Old Tampines Road open carpark HG 25 on 27 January 2019 at 13:25 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SLV 2870 J** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s Bak Heng Motor Repairing, (5032 #01-291, AMK Industrial Park 2, Singapore 569535 - Kelvin @ 9788 8579).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,

MR LING LEONG HUI

cc. M/s Bak Heng Motor
(Yref: SLC2502Y)

BY FAX NO. 6481 6820 ONLY

DIRECTOR : LING LEONG HUI

CONSULTANTS : POOTS LAURENCE JAMES

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4567B
Vehicle Details	
Vehicle No.:	SLC2502Y
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4032248
Chassis No.:	RU11112241
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,721.00
Original Registration Date:	06 May 2016
First Registration Date:	06 May 2016
Transfer Count:	0
Actual ARF Paid:	\$9,721.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 May 2026
PARF Rebate Amount:	\$7,290.00
Intended COE Rebate Details	
COE Expiry Date:	05 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,889.00
COE Rebate Amount:	\$34,637.00
Total Rebate Amount:	\$41,927.00

The information contained herein is correct as at 11 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/01/2019 10:40
Date Of Accident	27/01/2019 13:25
Exact Location Of Accident	OLD TAMPINES RD OPEN CP HG25
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC2502Y
Insured/Policyholder	
Name Of Registered Owner	ONG AH KEE
NRIC No	S1414567B
Email Address	AKONG60@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97993332
Alternative Phone No	OFFICE-97993332
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	ONG AH KEE
NRIC No	S1414567B
Date Of Birth	29/01/1960
Occupation	INDOOR
Date Of Driving Pass	11/05/1979
Driving Experience	39 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97993332
Fax Number	
Contact Number	OFFICE-97993332
EMail Address	AKONG60@YAHOO.COM

Address 10 RIVERVALE LINK #10-18 S545044
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : ZHANG FANG
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE SIZE IS TOO LARGE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLV2870J
 Vehicle Make/Model/Colour LEXUS
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver NA
 NRIC/Passport Number
 Contact Number 91160188
 Address NA
 NA
 Postcode
 Insurance Company Name

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 28/1/19
1052

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



AMENDMENT

A: SLC 2502Y

B: SLC 2502Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was just driving along the car park, suddenly
veh B came out of his lot & hit onto
my left side partition

INSURER: NTUC

VEHICLE: SLC 2502Y

DOA: 27/1/19

CLAIM TYPE: Repairing

WORKSHOP: NA

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 28/1/19
10:55

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2019 09:07 Edit Reg		30 Jan 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SLC2502Y	Date of Loss:	27/01/2019 00:00 - :59 [32 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SLV2870J	Policy No. (Claimant):	
		Excess:	
Repairer:	Bak Heng Motor Repairing (HQ) 5032, ANG MO KIO INDUS PARK 2, #01-291, 569535 Ang Mo Kio - Tel: 9788 8579		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/02/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC2502Y
[SLV2870J]

TP

-

Jan 27 2019 12:00AM

[-]

Bak Heng Motor Repairing

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
2	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
3	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
4	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
5	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
6	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
7	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
8	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
9	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
10	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
11	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
12	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
13	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
14	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
15	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
16	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
17	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
18	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
19	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
20	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
21	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
22	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
23	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
24	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
25	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
26	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
27	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	
28	11/02/19 14:52	General View						Load JPG	<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19002079/GCD3E2

Date: 12/02/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No: SLC2502Y

Insured Vehicle No: SLV2870J

Date of Loss: 27/01/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC2502Y

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: L15B4032248

Reg. Date: 06/05/2016 (Man. Year: 2015)

Chassis No: RU11112241

Colour: White

Odometer: 92113 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/01/2019

Date Inspected: 31/01/2019 Inspected At:

Bak Heng Motor Repairing (HQ)
5032, ANG MO KIO INDUS PARK 2, #01-291
Singapore 569535

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC2502Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >