

22/03/2001

ASS. REC. BY:

REF CS/MSG19002091/Bcd32

Special Instruction:

Surveyor  
Menmen

ASSIGNMENT (Office)

From (Person): Irene Tan

of

MSGDate/Time 31/11/19 @ 3:54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 838T

Insured:

SMA 7462U

at Workshop m/s

Yap Lee Motor

Tel:

6844 1555

of

1 Kaki Bukit Ave 6 # 01-26,

Policy No:

804 644 95

Claim No:

5839 07

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

IMP

H.O.D. Endorsement:

Date/Time:

12:23pm @ 31/1/19

Person Contacted:

Ms Shirley

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SKX 838T - NV/INC19001870 / Ka</u>
	<u>SMA 7462U - NA / INC19001870 / Ka</u>
	<u>Dismantle: 14/2/2019</u>
	<u>After repair: 18/2/2019</u>

DUA: 29/1/19DUA: 29/1/19

REF:

MS19

## ASSIGNMENT

From:

Date: 13/2/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKX 838T

at Workshop m/s YAP LEE MOTOR

of 1 KAKI Bukit Ave 6 # 01-26

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKX 838T

Yr Regn: 15/1/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA GROLLA FIELDER C.C. 1406

Colour: WHITE A/C Insured / Std / NI / NA

Sp. Reading 82574 T/Radio: Insured / Std / NI / NA

Eng/No: 2NR 8503566

C/No: NRE1618001461

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/60/15

R: 175/60/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 22/1/19 D.O.I. 13/2/19

Survey held at YAP LEE MOTOR

Des. of Damages: Frt / Rear / O/S / M/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 3,000/2 - 4,000/2

*[Signature]*  
25/2/2019

MV 51,000/2

PV 43,000/2

NV 8,000/2

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + R: \$

) Photos

) Others:

Report Format: PRE.

Lump Sum / I.B.I. (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

TOTAL

120

10

130

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2019		31 Jan 2019 15:54 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM WEI LI, ID: S8602432B, Tel: +6592251586		
Main Claimant:	LECCA CAR LEASING, Co. Reg. No.: 53247626C		
Vehicle Reg. No.:	SKX838T	Date of Loss:	29/01/2019 12:00 - :59 [36 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 583907	Policy/Cover Note No.:	80464495 (Comprehensive) Coverage: 23/11/2018 - 22/11/2019
Vehicle Reg. No. (Insured):	SMA7462U	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/02/2019]		
Driver/Custodian (Insured):	LIM WEI LI (33 / Male), NRIC: S8602432B, Tel: +6592251586		
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY 80% Please appoint LKK AUTO to conduct the survey . Kindly contact MRS CHUA or MS SHIRLEY @ 6844 1555 to arrange for survey .		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7626C
Vehicle Details	
Vehicle No.:	SKX838T
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA FIELDER 1.5G CVT ABS D/AIRBAG 2W
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2NR8503566
Chassis No.:	NRE1618001461
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,489.00
Original Registration Date:	15 Jan 2016
First Registration Date:	15 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$7,489.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jan 2026
PARF Rebate Amount:	\$5,616.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,301.00
COE Rebate Amount:	\$37,456.00
Total Rebate Amount:	\$43,072.00

The information contained herein is correct as at 21 Feb 2019

OK

Dep 8,766/yr  
747/mth

MV 51,000/2  
PV 43,000/2  
NV 8,100/2

Used Cars ([http://www.oneshift.com/used\\_cars/index.php](http://www.oneshift.com/used_cars/index.php)) › Listings

Used Car Make / Model

GO BACK

SHOW FILTER

RESET ([http://www.oneshift.com/used\\_cars](http://www.oneshift.com/used_cars))

3 cars listed

Make

Sort By

⊞ (/used\_c

Save this Search

View Search Alerts ([http://www.oneshift.com/used\\_cars/save](http://www.oneshift.com/used_cars/save))


Model

⊞ (/used\_car

## Toyota Corolla Fielder 1.5 X (A) (New 5-yr COE)

Price

\$35,800

([http://www.oneshift.com/used\\_cars/ads\\_detail.php?adid=237285&make=Toyota&model=FIELDER](http://www.oneshift.com/used_cars/ads_detail.php?adid=237285&make=Toyota&model=FIELDER))


Depre: \$7,160

 27 Jun 2008  
7 mths left

[http://www.oneshift.com/used\\_cars/ads\\_detail.php?adid=237285&make=Toyota&model=FIELDER](http://www.oneshift.com/used_cars/ads_detail.php?adid=237285&make=Toyota&model=FIELDER)

## Toyota Corolla Fielder 1.5 X (A)

\$61,800

([http://www.oneshift.com/used\\_cars/ads\\_detail.php?adid=233223&make=Toyota&model=FIELDER](http://www.oneshift.com/used_cars/ads_detail.php?adid=233223&make=Toyota&model=FIELDER))

Depre: \$8,966

 6 Mar 2015  
6 yrs left

43,100 km

[http://www.oneshift.com/used\\_cars/ads\\_detail.php?adid=233223&make=Toyota&model=FIELDER](http://www.oneshift.com/used_cars/ads_detail.php?adid=233223&make=Toyota&model=FIELDER)

## Toyota Corolla Fielder 1.5 X (A)

SOLD

([http://www.oneshift.com/used\\_cars/ads\\_detail.php?adid=241404&make=Toyota&model=FIELDER](http://www.oneshift.com/used_cars/ads_detail.php?adid=241404&make=Toyota&model=FIELDER))

Workshop

MNA119013736 / National Assessment Centre Services - Ubi  
ENTRY DATE & TIME: 29/01/2019 13:45  
SUBMITTED BY: Krishnasamy s/o Gorindasamy

**SINGAPORE ACCIDENT STATEMENT****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/01/2019 13:45
Date Of Accident	29/01/2019 12:00
Exact Location Of Accident	JUNC OF UBI ROAD 3 AND UBI ROAD 4
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKX838T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LECCA CAR LEASING
Co Reg No	53247626C
Email Address	DARRYL@OCTOPUSGROUP.COM.SG
Mobile Phone No	(LOCAL) +65-93487376
Alternative Phone No	OFFICE-90613717
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	COROLLA FIELDER 1.5G CVT ABS D/AIRBAG 2W
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106699106
Cover Note Number	
<b>Driver</b>	
Name of Driver	SAHA SHAUN
Passport No/FIN	G6574457R
Date Of Birth	28/03/1984
Occupation	OUTDOOR
Date Of Driving Pass	29/08/2016
Driving Experience	2 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93487376
Fax Number	
Contact Number	OTHERS-90613717
Email Address	DARRYL@OCTOPUSGROUP.COM.SG

Address	OCTOPUS GROUP HOLDINGS PTE LTD
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REVERT
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA7462U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM WEI LI
NRIC/Passport Number	S8602432B
Contact Number	92251586
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

29/11/2019




SKETCH PLAN

JUNCTION OF UBI Road 3 and UBI Road 4

A - SKX838T

B - SMA 7462U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A ~~SKX~~ SKX838T was Driving in UBI Road 3 and The vehicle B SMA 7462U was Driving from UBI Road 4 Towards UBI Road 3. Then Hit vehicle A SKX 838T Front left ~~wheel~~ wheel and Front BUMPER and LEFT SIDE FEND including wheel rim -

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

29/1/2019

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Jan 2019		31 Jan 2019 15:54 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>LIM WEI LI</b> , ID: S8602432B, Tel: +6592251586								
Main Claimant:	<b>LECCA CAR LEASING</b> , Co. Reg. No.: 53247626C								
Vehicle Reg. No.:	<b>SKX838T</b>	Date of Loss:	29/01/2019 12:00 - :59 [36 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 583907</b>	Policy/Cover Note No.:	80464495 (Comprehensive) Coverage: 23/11/2018 - 22/11/2019						
Vehicle Reg. No. (Insured):	<b>SMA7462U</b>	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	<b>Yap Lee Motor (HQ)</b> 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Imm.Advice due 01/02/2019]								
Driver/Custodian (Insured):	LIM WEI LI (33 / Male), NRIC: S8602432B, Tel: +6592251586 Email:								
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY 80% Please appoint LKK AUTO to conduct the survey . Kindly contact MRS CHUA or MS SHIRLEY @ 6844 1555 to arrange for survey .								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents


\*SKX838T (583907)  
[SMA7462U]  
TP  
LECCA CAR LEASING  
Jan 29 2019 12:00PM  
[LIM WEI LI]  
Yap Lee Motor

Upload Documents | Upload Photos | Compose New Letter

View View in Browser


































### Assessment Reports




















1 per page 1 ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/01/19 13:19	<b>Accident Statement</b> From: SC - Reg. No: SMA7462U, Claimant: LIM WEI LI	 Load HTM	<input type="checkbox"/>

### Photos/Images

3 per page 3 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 13:23	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 13:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/02/19 13:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/02/19 13:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/02/19 13:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/02/19 13:24	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/02/19 13:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/02/19 13:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	23/02/19 13:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	23/02/19 13:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	23/02/19 13:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	23/02/19 13:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	23/02/19 13:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	23/02/19 13:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	23/02/19 13:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/01/19 13:19	TPD SKX838T GIA REPORT From: SC - Reg. No: SMA7462U, Claimant: LIM WEI LI	 Load PDF	
2	31/01/19 13:27	TPD SKX838T - PRI	 Load PDF	
3	31/01/19 13:27	Reject email to TP Lawyer & appoint LKK AUTO	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19002091/BCD3E2

Date: 26/02/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80464495

Claimant Vehicle No : SKX838T

Insured Vehicle No : SMA7462U

Date of Loss: 29/01/2019

Nature of Claim: TP

Claim No: 583907

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX838T

Make &amp; Model: TOYOTA COROLLA FIELDER, 1.5 (A)

Engine No: 2NR8503566

Reg. Date: 15/01/2016 (Man. Year: 2015)

Chassis No: NRE1618001461

Colour: White

Odometer: 82574 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 13/02/2019 Inspected At:

Yap Lee Motor (HQ)  
1 Kaki Bukit Avenue 6, #01-26 Autobay @  
Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 26 Feb 2019)
Parts:	N/A	TOYOTA COROLLA FIELDER 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKX838T)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >