

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGN8660Kat Workshop m/s: Sp.of SGW 4457K

Insured: \_\_\_\_\_

Policy No: B29080721TMCClaims No: 584279

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 64

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 26454

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date / Time Action / Instruction

Copy LRA 47084 745 3rd Mar 16926 -1/2/19 - Email police report to file20/3/19 4/5 #16500 confirmed with Alan (Red: 25622; 270%)Veh No: SGN8660K Yr Regn: 18/5/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: KA Forte 1.3 c.c. 1591Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 36890 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAF241M65600412Gen. Cond: Good / Fair / Poor / BurntSteering: Insured / Jammed / Leaked / Burnt orBrake: Insured / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/45 R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXONFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 3.1/1/19 D.O.I. 3.1/1/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear & Rf

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 21/3 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prel. Report☒ : Final ReportDays Of Repair: 14Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 16,500)

RECEIVED 21 MAR 2019

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Friday, 1 February 2019 4:37 PM  
**To:** Hasrianah Binte Hassan  
**Cc:** SUR; KKLau; CHIONH Hock San Christopher; Accounts (LKKAUTO)  
**Subject:** FW: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 30/1/2019 ,SGN 8660K (TP VEHICLE), SGW 4457K (OI VEHICLE)  
**Attachments:** POLICE REPORT.pdf

Dear Hasrianah,

Please be informed that we had inspected the vehicle SGN 8660K at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 9/1/2019

Enclosed herewith a copy of police report. The TP's GIA and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAUTO)

**Sent:** Thursday, 10 January 2019 10:50 AM

**To:** Hasrianah Binte Hassan <[hasrianah@sg.msig-asia.com](mailto:hasrianah@sg.msig-asia.com)>

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Accounts (LKKAUTO) <[account@lkkauto.com](mailto:account@lkkauto.com)>; KKLau <[kklau@lkkauto.com](mailto:kklau@lkkauto.com)>

**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 9/1/2019 ,GX 4977X (TP VEHICLE), SJW 77P (OI VEHICLE)

Dear Hasrianah,

Please be informed that we had inspected the vehicle GX 4977X at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 9/1/2019

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

RENEW  
YOUR COE1.99%\*P.A  
ONLY

MEMBER

kia k3

Price Range

Depreciation

2016

Vehicle Type



Home » Used Cars » ValueCars Auto Traders » Kia Forte K3 1.6A EX

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Tyres

DUNLOP www.dunlop.com.sg



## Kia Forte K3 1.6A EX

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

**Price** \$61,800**Depreciation** \$7,590 /yr

View models with similar depreciation

**Reg Date** 18-Apr-2016  
(7yrs 2mths 16days COE left)**Manufactured** 2016**Mileage** 57,118 km (20.5k /yr)**Transmission** Auto**Engine Cap** 1,591 cc**Road Tax** \$738 /yr**Power** 95.3 kW (127 bhp)  
View specs of the Kia Cerato K3 (2013-2018)**Curb Weight** 1,295 kg**Features** Kia Forte K3 1.6L 4 Cylinders Inline 16 Valves DOHC Dual CVT Engine Producing 127 BHP, 6 Speed Auto Transmission, ABS, SRS Airbags.**Accessories** Sports Rims, Reverse Sensors, Factory Fitted Audio System, USB/AUX Port, Rear Aircon, Fog Lamps, Auto Headlights.**Description** 1 Owner! Very Low Installment! April 2016 Sporty Blue Kia Forte K3 1.6A! Come Own This Kia K3 With Flexible Loan For Prosperous CNY 2019 Ahead! Genuine Lowest Mileage Clocked 57,118km! Regularly Agent Maintenance! Come View And We Discuss Further, Thanks!**COE** \$46,009**OMV** \$14,207**ARF** \$14,207**Dereg Value** \$43,832 as of today (change)**No. of Owners** 1**Type of Veh** Mid-Sized Sedan

## Seller Information

<b>Company</b>	Value: » dealer » 42 ve
<b>Address</b>	61 Ubi Search
<b>Location</b>	Automoc
<b>Office No</b>	684101
<b>Contact Person(s)</b>	Audrey Richan

## Useful Services

Afraid of lemm  
this car evali

Compare

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



## CONNECTING CAR BUYERS &amp; SELLERS.

We'll handle your loans, insurance &amp; other paperwork for FREE.

Find out more

kia k3

Price Range

Depreciation

2016

Vehicle Type



Home » Used Cars » Direct Owners » Kia Forte K3 1.6A

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Kia Forte K3 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

**Price** \$65,800**Depreciation** \$7,660 /yr

View models with similar depreciation

**Reg Date** 29-Jul-2016

(7yrs 5mths 26days COE left)

**Manufactured** 2016**Mileage** 29,000 km (11.5k /yr)**Transmission** Auto**Engine Cap** 1,591 cc**Road Tax** \$738 /yr**Power** 95.3 kW (127 bhp)

View specs of the Kia Cerato K3 (2013-2018)

**Curb Weight** 1,295 kg**Features** Ventilated Aircon For Front 2 Seats.**Accessories** -**Description** One Careful Lady Owner Of White K3 And Is Fully Maintained And Serviced By C&C. It Is In Good Condition And Low Mileage. No Major Accident.**COE** \$53,000**OMV** \$16,863**ARF** \$16,863**Dereg Value** \$52,346 as of today (change)**No. of Owners** 1**Type of Veh** Mid-Sized Sedan**Category** PARF Car, Direct Owner Sale**Availability** Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

100% FREE  
PAPERWORK  
SUPPORT FOR  
BOTH BUYER  
& SELLER

## Seller Information

**Contact Person(s)** Chin**Contact No.** 936601**Enquiry** Co

## ESSENTIAL TRANSACTION

» Indemnity form

» Receipt

» Ownership Transfer

GET HELP WITH  
PAPERWORKsgCarMart Connect handles paperwork - send us your car and we'll help with **Car Loan & Ownership Transfer**. FREE Advertised Vehicles.

Upload your

Read our 8 Step Guide for

Compare

Posted on: 25-Jan-2019 | Last Updated on: 01-Feb-2019

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2645A
<b>Vehicle Details</b>	
Vehicle No.:	SGN8660K
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA ELEGANCE (AUTO)
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	2NRX424141
Chassis No.:	MHFZ28H3900062130
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$19,166.00
Original Registration Date:	31 Jan 2019
First Registration Date:	31 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$19,166.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2029
PARF Rebate Amount:	\$14,374.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,501.00
COE Rebate Amount:	\$25,487.00
<b>Total Rebate Amount:</b>	<b>\$39,861.00</b>

The information contained herein is correct as at 01 Feb 2019

OK

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2645A
<b>Vehicle Details</b>	
Vehicle No.:	SMH7054C <i>change vehicle Number</i>
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Feb 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A SX
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	G4FGGH612793
Chassis No.:	KNAFZ411MG5600412
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$16,226.00
Original Registration Date:	18 May 2016
First Registration Date:	18 May 2016
Transfer Count:	0
Actual ARF Paid:	\$16,226.00 <i>\$113</i>
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 May 2026
PARF Rebate Amount:	\$12,169.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,889.00
COE Rebate Amount:	\$34,925.00
<b>Total Rebate Amount:</b>	<b>\$47,094.00</b>

The information contained herein is correct as at 01 Feb 2019

OK



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 31/01/2019 11:50		Vide Report No.: G/20190131/0074		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: HU KAITIAN			Address: APT BLK 102 PUNGGOL WALK #15-08 SINGAPORE 828791		
ID Type / ID No.: NRIC NO / S8134060I			Contact No.: Home/Office: Mobile: 90258052		
Nationality: SINGAPORE CITIZEN			Email: evelynhu@gmail.com		
Sex: Female	Age: 37	Date of Birth: 12/10/1981	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Administration manager			Driving Licence Information: Class: 3 Date of Expiry: 31/01/2019		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 31/01/2019 09:00	Type of Location: Straight Road
Location:  TAMPINES EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGN8660K	Car					0
SGW4457K	Car		Toyota Altis	Silver		0
SLN2477D	Car		Mercedez	Black		0
SLN7222A	Car		Volkwagon	Blue		0
SME5148U	Car		Honda Civic	Black		0



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	HU KAITIAN	ID No.	S8134060I
Related Vehicle	SGN8660K (Car)	Contact No.	90258052
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 31/01/2019
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	Hu Kaitian	ID No.	S8134060I
Related Vehicle	SGN8660K (Car)	Contact No.	90258052
Hospital/Clinic	ETERN MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 31/01/2019
Date Treatment	31/01/2019	Date Discharge	31/01/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight
<b>Driver</b>			
Name	Muhammed Ali Bin Nazir Ahamed	ID No.	S7533508C
Related Vehicle	SGW4457K (Car)	Contact No.	87525744
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 31/01/2019
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 31/1/2019 at around 9am i was driving on the stated venue TPE towards Ecp after Lorong halus Before Tampines Ave 10. I was driving on the straight road at Lane 1. The front vehicle SME5148U stopped and i follow suits. Before my Vehicle SGN 8660K , could come to a complete stop, I Felt a hard impact from the rear of my car & the great impact pushes my car to move forward and hit onto the front vehicle . I stopped my car and i realized Vehicle SGW4457K had hit onto my car & i was involve in a 5 cars chain collison. I was the forth vehicle. 1st vehicle car plate SLN2477D, 2nd vehicle SLL7222A, 3rd Vehicle SME5148U , 4th car SGN8660K and the 5th car (last car) SGW4457K. Someone was injured & was conveyed by ambulance.



**SINGAPORE  
POLICE FORCE**



T/20190131/7004

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 4

Report No. T/20190131/7004

**CONTINUATION OF REPORT**



**SINGAPORE  
POLICE FORCE**



T/20190131/7004

4 of 4

Report No. T/20190131/7004

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
31/01/2019 11:50

Classification Of Case:

Authentication Stamp  
NP168

**FASTECH AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Not Authorized  
Mark  
2/5 16500  
14dy.

Qty	Particular	Amount S\$
<u>List Item:</u>		
1PCS	BOOTLID	Body m \$894.00
1PCS	BOOTLID 'KIA' LOGO	rec \$76.00
1PCS	BOOTLID 'FORTE' EMBLEM	rec \$40.00
1PCS	BOOTLID 'K3' EMBLEM	rec \$36.00
1PCS	BOOTLID C&C LOGO	rec \$42.00
2PCS	BOOTLID REFLECTORS @\$710.00	11 \$1420.00 X
1PCS	BOOTLID INNER LOCK	1 m/sheld \$82.00
1PCS	BOOTLID LOCK STRIKER	11 \$35.00 X
1PCS	BOOTLID TOP SPOILER	11 \$680.00 X
1PCS	BOOTLID WEATHERSTRIP	1 m \$105.00
1PCS	BOOTLID INNER TRIM	11 \$166.00 X
1SET	BOOTLID INNER TRIM CLIPS	rec \$45.00
2PCS	BOOTLID HINGES @\$68.00	3 m \$136.00 X
1PCS	REAR BUMPER	11 \$788.00
1PCS	REAR BUMPER LOWER	11 \$322.00
2PCS	REAR BUMPER SIDE RETAINERS @\$45.00	3 m \$90.00
2PCS	REAR BUMPER REFLECTORS @\$112.00	1 m \$224.00 1 pc
1PCS	REAR BUMPER SPONGE	10 m \$210.00
1PCS	REAR BUMPER REINFORCEMENT	3 m \$360.00
2PCS	REAR BUMPER REINFORCEMENT BRACKETS @\$75.00	3 m \$150.00
2PCS	REAR BUMPER REINFORCEMENT LOWER BRACKETS @\$33.00	1 m \$66.00
1SET	REAR BUMPER CLIPS	rec \$50.00
1PCS	REAR END PANEL	Body m \$335.00

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	REAR END PANEL TOP GARNISH	Two \$85.00 ✓
1PCS	REAR FLOOR PANEL	cramped/Buc \$740.00 ✓
1PCS	REAR FLOOR PANEL TOP BOARD	nope/oe \$365.00 ✓
1PCS	REAR FLOOR PANEL INSULATOR	rec \$150.00 ✓
2PCS	REAR FENDERS @\$1133.00	n \$2266.00 X
2PCS	REAR FENDER INNER TRIMS @\$285.00	als to n \$570.00 1pc
1SET	REAR FENDER INNER TRIM CLIPS	rec \$50.00 ✓
2PCS	TAILLAMPS @\$788.00	one \$1576.00 ✓
2PCS	TAILLAMP HOUSING PANELS @\$125.00	n \$250.00 X
1PCS	REAR EXHAUST	n \$729.00 X
2PCS	REAR EXHAUST MOUNTINGS @\$35.00	11 \$70.00 X
4PCS	REAR REVERSE TRASONIC SENSOR @\$172.00	shuttl \$688.00 2pc 176
1PCS	REAR REVERSE WIRING HARNESS	to n \$173.00 ✓
1PCS	FRONT BUMPER	DD \$688.00 ✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$33.00	but \$66.00 ✓
1PCS	FRONT BUMPER SPONGE	to n \$145.00 ✓
1PCS	FRONT BUMPER REINFORCEMENT 399	but \$410.00 ✓
1PCS	FRONT BUMPER BRACKET N/S	but \$48.00 ✓
1PCS	FRONT BUMPER CENTRE GRILLE	dis \$185.00 ✓
2PCS	FRONT BUMPER FOG LAMPS @\$205.00	one \$410.00 ✓
1SET	FRONT BUMPER CLIPS	rec \$50.00 ✓
1PCS	FRONT GRILLE	but \$256.00 ✓
2PCS	HEADLAMP ASSYS LED @\$1870.00	one \$3740.00 ✓

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty	Particular	Amount S\$
<u>List Item:</u>		
1PCS	FRONT SUPPORT PANEL 458	Bent \$766.00 ✓
1PCS	FRONT SUPPORT PANEL TOP GARNISH	Re/Toin \$235.00 ✓
1PCS	FRONT AIR CON SIDE GARNISH	Toin \$82.00 ✓
1PCS	AIR CON CONDENSER	Bent/Pan \$610.00 ✓
1PCS	RADIATOR ASSY	3uff/cro \$745.00 ✓
1PCS	Radiator fan assy 685.00	cro/jm \$1405.00 ✓
1PCS	front licence plate garnish	D.S. \$155.00 ✓
1PCS	PASSENGER AIR BAG	11 \$1528.00 X
1PCS	AIR BAG CONTROL UNIT	11 \$767.00 X
2PCS	FRONT SAFETY BELTS @\$605.00	11 \$1210.00 X
1PCS	front bumper top rubber 92.30	neu \$1820.00 ✓
1PCS	FRONT bumper top grille 315.00	D.S. \$933.00 ✓
1PCS	FRONT logo 65.00	neu \$81.00 ✓
1PCS	BONNET	3uc \$873.00 ✓
1PC	Bonnet lock 145	YWI \$290.00 ✓
2PCS	FRONT FENDERS @\$335.00	2 \$670.00 X
List Item Total:		\$32,232.00

18998.3  
16378.47

## Special Nett Item:

1PCS	REAR LICENCE PLATE W/HOLDER	11 \$50.00 X
1PCS	REAR END PANEL SEALANT	neu \$50.00 ✓
1PCS	FRONT WINDSCREEN SOLAR FILM	11 \$300.00 X
1PCS	FRONT WINDSCREEN SEALANT	11 \$50.00 X

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty	Particular	Amount S\$
<u>Special Nett Item:</u>		
1PCS	FRONT LICENCE PLATE W/HOLDER	50.00 ✓
<u>Special Nett Total:</u>		\$500.00
<u>Labour Charge:</u>		
	TO CHECK WIRING.	\$100.00 30
	TO DISMANTLE & REPLACING REVERSE SENSOR.	\$100.00 50
	TO TRANSFER BOOTLID MECHANISM.	\$100.00 60
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.	\$180.00 100
	TO DISMANTLE & REPLACING REAR EXHAUST.	\$100.00 60
	TO MOUNT VEHICLE ON CAR-O-LINER.	17 \$380.00 X
	TO SPRAY RUST PROOFING.	\$300.00 120
	TO DISMANTLE & REPLACING FRONT DASHBOARD.	17 \$380.00 X
	TO DISMANTLE & REPLACING FRONT AIR BAG ,RESET S.R.S SYSTEM.	17 \$500.00 X
	TO DISMANTLE & REPLACING FRONT WINDSCREEN.	17 \$150.00 X
	TO REFILL AIR CON GAS.	\$150.00 100
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN	
	& REPLACING PARTS.	\$3800.00 2000
	TO PUTTY & SPRAY PAINTING.	\$3000.00 1800
	TOWING CHARGE.	\$150.00 60
	Labour Charge Total:	\$9390.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$42,122.00

4480

## ...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2019 14:23		07 Feb 2019 14:50 <a href="#">Edit Adj Rpt</a>	<b>S\$16,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$16,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	PREMIER RENT A CAR PTE LTD, Co. Reg. No.: 200612929E								
Main Claimant:	CHIA WEE KEE, ID: S7722645A								
Vehicle Reg. No.:	SGN8660K	Date of Loss:	31/01/2019 08:00 - :59 [32 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 584275	Policy/Cover Note No.:	B29080721TMC (Third Party Only) Coverage: 01/05/2018 - 30/04/2019						
Vehicle Reg. No. (Insured):	SGW4457K	Policy No. (Claimant):							
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 08/02/2019]								
Driver/Custodian (Insured):	MUHAMMED ALI BIN NAZIR AHAMED (), NRIC: S7533508C Email:								
Adj Asg. Remarks:	Direct Survey done on 09/01/2019.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SGN8660K (584275)**  
**[SGW4457K]**  
**TP**  
**CHIA WEE KEE**  
**Jan 31 2019 8:00AM**  
**[PREMIER RENT A CAR PTE LTD]**  
**Fastech Auto Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
2	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
3	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
4	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
5	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
6	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
7	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
8	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
9	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
10	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
11	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
12	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
13	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
14	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
15	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
16	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
17	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
18	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
19	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
20	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
21	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
22	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
23	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
24	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
25	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
26	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
27	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
28	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
29	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
30	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
31	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
59	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
60	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
61	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
62	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
63	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
64	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
65	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
66	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
67	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
68	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
69	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
70	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
71	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
72	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
73	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
74	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
75	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
76	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
77	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
78	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
79	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
80	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
81	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
82	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
83	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
84	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
85	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
86	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
87	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
89	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
90	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
91	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
92	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
93	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
94	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
95	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
96	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
97	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
98	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
99	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
100	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
101	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
102	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
103	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
104	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
105	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
106	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
107	21/03/19 10:44	General View	 Load JPG	<input checked="" type="checkbox"/>
108	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	21/03/19 10:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
138	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
139	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
140	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
141	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
142	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
143	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
144	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
145	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
146	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
147	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
148	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
149	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
150	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
151	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
152	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
153	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
154	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
155	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
156	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
157	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
158	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
159	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
160	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
161	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
162	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
163	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
164	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
165	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
166	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
167	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
168	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
169	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
170	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
171	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
172	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
173	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
174	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
175	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
176	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
177	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
178	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
179	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
180	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
181	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
182	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
183	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
184	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
185	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
186	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
187	21/03/19 10:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
188	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
189	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
190	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
191	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
192	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
193	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
194	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
195	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
196	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
197	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
198	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
199	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
200	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
201	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
202	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
203	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
204	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
205	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
206	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
207	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
208	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
209	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
210	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
211	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
212	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
213	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
214	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
215	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
216	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
217	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
218	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
219	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
220	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
221	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
222	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
223	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
224	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
225	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
226	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
227	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
228	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
229	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
230	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
231	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
232	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
233	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
234	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
235	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
236	21/03/19 10:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
237	21/03/19 10:46	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
238	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
239	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
240	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
241	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
242	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
243	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
244	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
245	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
246	21/03/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/02/19 14:26	SGN8660K GIA Rpt	 Load PDF	
2	07/02/19 14:45	SGW4457K GIA Rpt	 Load PDF	
3	07/02/19 14:45	Direct Survey email frm LKK	 Load PDF	
4	07/02/19 14:45	TP Police Report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19002102/UTD3Q2

Date: 23/04/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B29080721TMC

Claimant Vehicle No : SGN8660K

Insured Vehicle No : SGW4457K

Date of Loss: 31/01/2019

Nature of Claim: TP

Claim No: 584275

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SGN8660K

Make &amp; Model: TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)

Engine No: G4FGGH612793

Reg. Date: 18/05/2016 (Man. Year: 2016)

Chassis No: KNAFZ411MG5600412

Colour: Silver

Odometer: 36890 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Nexen 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,732.00	16,478.47	16,253.53	49.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,390.00	4,380.00	5,010.00	53.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>42,122.00</b>	<b>20,858.47</b>	<b>21,263.53</b>	<b>50.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>16,500.00</b>		
(S\$)	42,122.00	16,500.00	25,622.00	60.83
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,948.54</b>	<b>1,155.00</b>	<b>1,793.54</b>	<b>60.83</b>
<b>Nett Amount (S\$)</b>	<b>45,070.54</b>	<b>17,655.00</b>	<b>27,415.54</b>	<b>60.83</b>

## INSPECTION

Date of Assignment: 07/02/2019

Date Inspected: 31/01/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 14.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2019)
<b>Parts:</b>	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGN8660K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	894.00 F	*894.00 FL
2	1		*BOOTLID KIA LOGO	Necessary	76.00 F	*76.00 FL
3	1		*BOOTLID FORTE EMBLEM	Necessary	40.00 F	*40.00 FL
4	1		*BOOTLID K3 EMBLEM	Necessary	36.00 F	*36.00 FL
5	1		*BOOTLID C&C LOGO	Necessary	42.00 F	*42.00 FL
6	2		*BOOTLID REFLECTORS	Not Necessary	1,420.00 F	*- FL
7	1		*BOOTLID INNER LOCK	Twisted / Shorted	82.00 F	*82.00 FL
8	1		*BOOTLID LOCK STRIKER	Not Necessary	35.00 F	*- FL
9	1		*BOOTLID TOP SPOILER	Not Necessary	680.00 F	*- FL
10	1		*BOOTLID WEATHERSTRIP	Twisted	105.00 F	*105.00 FL
11	1		*BOOTLID INNER TRIM	Not Necessary	166.00 F	*- FL
12	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	45.00 F	*45.00 FL
13	2		*BOOTLID HINGES	Serviceable	136.00 F	*- FL
14	1		*REAR BUMPER	Distorted	788.00 F	*788.00 FL
15	1		*REAR BUMPER LOWER	Distorted	322.00 F	*322.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Bent	90.00 F	*90.00 FL
17	1		*REAR BUMPER REFLECTORS	N/S Cracked	224.00 F	*112.00 FL
18	1		*REAR BUMPER SPONGE	Torn	210.00 F	*210.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	360.00 F	*360.00 FL
20	2		*REAR BUMPER REINFORCEMENT BRACKETS	Bent	150.00 F	*150.00 FL
21	2		*REAR BUMPER REINFORCEMENT LOWER BRACKETS	Twisted	66.00 F	*66.00 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
23	1		*REAR END PANEL	Badly Dented	335.00 F	*335.00 FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	85.00 F	*85.00 FL
25	1		*REAR FLOOR PANEL	Crumpled / Buckled	740.00 F	*740.00 FL
26	1		*REAR FLOOR PANEL TOP BOARD	Warped / Deformed	365.00 F	*365.00 FL
27	1		*REAR FLOOR PANEL INSULATOR	Necessary	150.00 F	*150.00 FL
28	2		*REAR FENDERS	Repair	2,266.00 F	*- FL
29	1		*REAR FENDER INNER TRIMS	N/S Torn	570.00 F	*285.00 FL
30	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 F	*50.00 FL
31	2		*TAILLAMPS	Cracked	1,576.00 F	*1,576.00 FL
32	2		*TAILLAMP HOUSING PANELS	Repair	250.00 F	*- FL
33	1		*REAR EXHAUST	Repair	729.00 F	*- FL
34	2		*REAR EXHAUST MOUNTINGS	Not Necessary	70.00 F	*- FL
35	4		*REAR REVERSE TRASONIC SENSOR	Shorted (3 PCS ONLY)	688.00 F	*516.00 FL
36	1		*REAR REVERSE WIRING HARNESS	Torn	173.00 F	*173.00 FL
37	1		*FRONT BUMPER	Dented	688.00 F	*688.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	2		*FRONT BUMPER SIDE RETAINERS	Bent	66.00 F	*66.00 FL
39	1		*FRONT BUMPER SPONGE	Torn	145.00 F	*145.00 FL
40	1		*FRONT BUMPER REINFORCEMENT	Bent	410.00 F	*399.00 FL
41	1		*FRONT BUMPER BRACKET N/S	Bent	48.00 F	*48.00 FL
42	1		*FRONT BUMPER CENTRE GRILLE	Distorted	185.00 F	*185.00 FL
43	2		*FRONT BUMPER FOG LAMPS	Cracked	410.00 F	*410.00 FL
44	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
45	1		*FRONT GRILLE	Bent	256.00 F	*256.00 FL
46	2		*HEADLAMP ASSYS LED	Cracked	3,740.00 F	*3,740.00 FL
47	1		*FRONT SUPPORT PANEL	Bent	766.00 F	*456.00 FL
48	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed / Torn	235.00 F	*235.00 FL
49	1		*FRONT AIR CON SIDE GARNISH	Torn	82.00 F	*82.00 FL
50	1		*AIR CON CONDENSER	Bent / Punctured	610.00 F	*610.00 FL
51	1		*RADIATOR ASSY	Bent / Cracked	745.00 F	*745.00 FL
52	1		*RADIATOR FAN ASSY	Cracked / Jammed	1,405.00 F	*695.00 FL
53	1		*FRONT LICENCE PLATE GARNISH	Distorted	155.00 F	*155.00 FL
54	1		*PASSENGER AIR BAG	Not Necessary	1,528.00 F	*- FL
55	1		*AIR BAG CONTROL UNIT	Not Necessary	767.00 F	*- FL
56	2		*FRONT SAFETY BELTS	Not Necessary	1,210.00 F	*- FL
57	1		*FRONT BUMPER TOP RUBBER	Necessary	1,820.00 F	*92.30 FL
58	1		*FRONT BUMPER TOP GRILLE	Distorted	933.00 F	*315.00 FL
59	1		*FRONT LOGO	Necessary	81.00 F	*65.00 FL
60	1		*BONNET	Buckled	873.00 F	*873.00 FL
61	1		*BONNET LOCK	Twisted	290.00 F	*145.00 FL
62	2		*FRONT FENDERS	Repair	670.00 F	*- FL
63	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
64	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
65	1		*FRONT WINDSCREEN SOLAR FILM	Not Necessary	300.00 FS	*- FS
66	1		*FRONT WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
67	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$) 32,732.00 18,298.30  
 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00 1,819.83

Total Parts (S\$) 32,732.00 16,478.47

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	100.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	100.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	180.00	100.00
5	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	60.00
6	TO MOUNT VEHICLE ON CAR-O-LINER	New	380.00	0.00
7	TO SPRAY RUST PROOFING	New	300.00	120.00
8	TO DISMANTLE & REPLACING FRONT DASHBOARD	New	380.00	0.00
9	TO DISMANTLE & REPLACING FRONT AIR BAG ,RESET S.R.S SYSTEM	New	500.00	0.00
10	TO DISMANTLE & REPLACING FRONT WINDSCREEN	New	150.00	0.00
11	TO REFILL AIR CON GAS	New	150.00	100.00
12	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS	New	3,800.00	2,000.00
13	TO PUTTY & SPRAY PAINTING	New	3,000.00	1,800.00
14	TOWING CHARGE	New	150.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>9,390.00</b>	<b>4,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >