

Our Ref : 305265038

Date : 31.01.2019

Time of Fax : 1640w

AXA

Via Fax : email

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Your Insured : ET 5333 S

Date of Acc : 30.01.2019

www.cdge.com.sg

Company Registration No: 199506048W

Workshop

Attn : Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO

SHA 5875 J

Loyang
59 Loyang Drive
Singapore 508969
Fax no. 6546 8156

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find :
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Tel no. 62148355 or Hp no. 98240811
Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305
Lim Tien Siong Tel no. 62148398 or Hp no. 96358546
Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006
Fauzy Bin Mokhtar Tel no: 62148319 or Hp no : 81259176
→ Larry Ng Tel: 6214 8316

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

Larry Ng

for Vice President
Crash Repairs & Claims Recovery

REPAIR ESTIMATE*

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper			\$538.80
10	Front Bumper Clips		\$2.20	\$22.00
1	Radiator Grille			\$282.10
	SUB TOTAL			\$842.90
	LESS 20%			\$168.58
	DISCOUNTED TOTAL			\$674.32
1	Front Licence Plate			\$25.00
1	Front Licence Plate Casing			\$20.00
				\$45.00
	Labour Charge			
1	Panel Beating			\$300.00
1	Spray Painting Charge(Fender,2Doors, Mirror)			\$300.00
	TOTAL LABOUR			\$600.00
	ESTIMATE TOTAL			\$1,319.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 5875J

DATE 31/1/2019 16:07

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid			\$ 1,349.50	
	Boot Lid Lock Upper			\$ 132.10	
	Boot Lid Lock Lower			\$ 30.30	
	Boot Lid Sonata Plate			\$ 43.60	
	Boot Lid Hyundai Plate			\$ 24.20	
	Boot Lid 'H' Emblem			\$ 26.10	
	Boot Lid CRDI Plate			\$ 22.70	
	Boot Lid Lamp (LH/RH)		\$ 230.20	\$ 460.40	
	Rear Bumper			\$ 578.40	
	Rear Bumper Reinforcement			\$ 483.30	
	Rear Bumper Clip			\$ 22.00	
	Rear Bumper Sponge			\$ 137.40	
	Rear Bumper Under Cover			\$ 185.80	
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00	
	Tail Lamp (LH/RH)		\$ 344.00	\$ 688.00	
	Rear Panel			\$ 391.80	
	Rear Panel Garnish			\$ 95.80	
	Rear Fender (LH)			\$ 1,935.90	
	Rear Windscreen Moulding			\$ 60.00	
	SUB TOTAL			\$ 6,743.30	
	LESS 20%			\$ 1,348.66	
	DISCOUNTED TOTAL			\$ 5,394.64	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett
	Rear No. Plate			\$ 25.00	Nett
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Windscreen Sealant			\$ 46.00	Nett
				\$ 236.70	
	Labour Charge				
	Panel Beating			\$ 1,200.00	
	Spray Painting Charge			\$ 1,200.00	
	Wiring Charge			\$ 30.00	
	Tuff Kote			\$ 50.00	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	
	Remove/Refix Rear Windscreen Glass			\$ 120.00	
	Remove/Refix Reverse Sensor			\$ 80.00	
	TOTAL LABOUR			\$ 2,830.00	
	ESTIMATE TOTAL			\$ 8,461.34	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2019 13:44
Date Of Accident	30/01/2019 17:35
Exact Location Of Accident	AYE TWDS CITY (NEAR WEST COAST.)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA5875J
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	LIM TEOW LEONG
NRIC No	S1472913E
Date Of Birth	23/05/1961
Occupation	OUTDOOR
Date Of Driving Pass	27/02/1979
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91685062
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 210A COMPASSVALE LANE #06-158
Postcode	541210
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE
Passenger 3	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	ET5333S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMMAD TAUFIQ BIN BORHAN

NRIC/Passport Number	S8316558H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLD8544G
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE HUANG CHUN @ LI FANJUN
NRIC/Passport Number	S7732251E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LIM TEOW LEONG
Approximate Age	
Injuries Sustain	LOWER BACK, SHOULDER, NECK
Injured person in which vehicle?	SHA5875J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	MOONG WAI SHAN (PAX)
Approximate Age	
Injuries Sustain	UNSURE
Injured person in which vehicle?	SHA5875J
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

[Signature]


31/1/19
Jackson Heng
CSO

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/01/2019 at about 17:35 hrs, I, Vehicle A was driving my taxi along HVE toward City (Near West Coast). As a vehicle C in front of me stop. But I also coming to stop, vehicle B came from behind and hit onto vehicle A rear portion. But force vehicle A to move forward and hit vehicle C. No one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

31/1/19
Jackson Heng
CSO

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: