Rasu | REF: ASM(AXA) 2371/19 (F) | 31232

ASSIGNMENT

From: | Date: 15/2/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL 8300B

at Workshop m/s: Trans Eurokars

of: 27A Tanjong Penjum

Insured:

Policy No:

Claims No:

Sum Insured: | Excess:

(Client's Record)

Make of Veh: 4pm owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 378K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SLL 8300 B | Yr Regn: 2016 AUG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: PORSCHE CAYMAN GT4 | c.c: 3800

Colour: BLACK | A/C: Insured / Std / NI / NA

Sp.Reading: 74459 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WP0ZZZ98ZGK189608

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/30ZR20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	26/01/19	D.O.I.	15/02/19

Survey held at: TRANS EUROKARS

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

S + PS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)