

ASS. REC. BY

REF

CS/CT11900755/ R1SD3

Report of Instruction

Surveyor
Merimen

Rogers

ASSIGNMENT (Office)

From (Person):

Catherine Thier

of

CT1

Date/Time:

1/2/19 @ 3.46pm

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL262SR

Insured:

SLL7652S

at Workshop in/s

Weathers Automotive

Tel:

63789370/

of

249 Alexandra Road

Policy No:

DMPCSN18362718000

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

29/01/2019

CA / REV / REP. / REV 24 HRS

'up'

7/2/19 @ 11 am (aw)

H.O.D. Endorsement:

Date/Time:

4.16pm @ 1/2/18

Person Contacted:

patricia

Vehicle IN (DUI)

Date/Time

Action/Instruction (✓) Estimate

SKL262SR - CS/AG19001999/d3

DOA: 29/1/19

SLL7652S - CS/AG19001999/d3

DOA: 29/1/19

Rahul

REF: CTT

81957

ASSIGNMENT

Event: Date: 7/2/19

Estimated Cost:

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKL 2625R

at Workshop no: Weames Automotive

et: 249 Alexandra Road

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: Name owner writing Patricia

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
-----	-----

Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted: Vehicle: IN / OUT

Date / Time Action / Instruction

Yr Regn: 2013 04

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: LAND ROVER RANGE ROVER ²⁻⁰ 1999

Colour: Res A/C Insured / Std / NI / NA

Sp Reading: 022586 T/Eadio: Insured / Std / NI / NA

Eng/No:

C/No: SALVA 2A590H821060

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ R / STD A/Rim or

Tyre Size: F: 235/55R19 R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or CONTINENTAL

Front	Rear
R/Bal: 6 mm	R/Bal: 6 mm
L/Bal: 6 mm	L/Bal: 6 mm
D.O.A: 29/01/19	D.O.I: 02/02/19

Survey held at: Weames

Des. of Damages: Frt / Rear / O/S / ☒ M/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

4/5/19 Confirmed P/P \$ 8,439.28 @ 4 days with Rasul.
(\$ 7,310.92 red - 46%)

RECEIVED 14 MAY 2019

Date/Time, File Pass to:
14/05/19
Typ: SF

☐ : Prelim. Report
☒ : Final Report

Days Of Repair: 4
Resurvey No. of Trip: 1

Survey Fee:
Transportation:

Add Fee: ☐ Site Insp: \$
☐ Interview: \$
☐ Tech. Inv.: \$
☐ Weekend: \$

Report Format:

Lump Sum / I.B.I.: \$ 8,439.28 P/P

DATE

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		01 Feb 2019 15:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	NIE YING			
Vehicle Reg. No.:	SKL2625R	Date of Loss:	29/01/2019 14:00 - :59	
Claim Type:	TP	Policy/Cover Note No.:	DMPCSN18362718000	
Vehicle Reg. No. (Insured):	SLL7652S	Policy No. (Claimant):		
		Excess:	S\$3,500.00	
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/02/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Friday, 10 May 2019 10:23 AM
To: Paul Ong Qing Yong
Cc: Patricia Kueh Anak Slin; Shirley Hiew (LKK Auto)
Subject: RE: SKL2625R Finalise

Sensitivity: Confidential

Hi Paul,

Finalised amount of \$ 8,439.28 before GST 4 days part by part is confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Paul Ong Qing Yong [mailto:paul.ong@wearnes.com]
Sent: Thursday, 9 May, 2019 2:49 PM
To: Rasul (LKKAuto); SUR
Cc: Patricia Kueh Anak Slin
Subject: SKL2625R Finalise
Importance: High
Sensitivity: Confidential

Attached final bill.

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

Nivitha (LKK Auto)

From: Chee So Chow <sochow.chee@sg.cntaiping.com>
Sent: Friday, 1 February 2019 2:52 PM
To: assignments@lkkauto.com
Cc: admin-d@lkkauto.com
Subject: FW: TP CLAIM FOR SKL2625R (OUR INSURED VEHICLE SLL7652S)

Dear Nivitha

Please conduct pre repair survey.

Thank you.

CHEE SO CHOW

Deputy Manager
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02
Springleaf Tower Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6176
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
sochow.chee@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Patricia Kueh Anak Slin [mailto:patricia.kueh@wearnes.com]
Sent: Friday, February 01, 2019 1:22 PM
To: Chee So Chow <sochow.chee@sg.cntaiping.com>
Cc: Catherine Thia <catherine.thia@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: RE: TP CLAIM FOR SKL2625R (OUR INSURED VEHICLE SLL7652S)

Dear Chee,

Please arrange pre-survey repair with LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)- Mohamad Taufikh on 07/02/19 at 10am.

Thank you.

Best Regards,

Patricia Kueh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 9770 4368 D (65) 6378 9336
www.wearnesauto.com patricia.kueh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Chee So Chow <sochow.chee@sg.cntaiping.com>
Sent: Friday, 1 February, 2019 12:57 PM
To: Patricia Kueh Anak Slin <patricia.kueh@wearnes.com>
Cc: Catherine Thia <catherine.thia@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>
Subject: TP CLAIM FOR SKL2625R (OUR INSURED VEHICLE SLL7652S)

Dear Patricia

We refer to your Notice of Accident dated 31.01.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert:

Survey firm	
LBS Auto Consultants Pte Ltd (closed during CYN between 4/2/19 to 10/2/19)	Mohd Fadhilah Bin Osman
LBS Auto Consultants Pte Ltd (closed during CNY between 4/2/19 to 10/2/19)	Stan See Chew Seng
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Kalvin Ang
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Mohamad Taufikh
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Bryan Ang
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Adrian Ling
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Mohammed Rasul
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Marcus Chua
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Kenneth Kong
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Muhammad Nazril Bin Abdullah
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Ong Hwee Jie
LKK Auto Consultants Pte Ltd (closed from 4/2/19 to 6/2/19)	Xing Guo Qiang
STA INSPECTION PTE LTD (closed during CNY between 4/2/19 to 6/2/19)	Low Sar Huei
STA INSPECTION PTE LTD (closed during CNY between 4/2/19 to 6/2/19)	Hong Fook Choy

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards

Chee So Chow (Ms)
Deputy Manager
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6176
Fax (65) 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
sochow.chee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/01/2019 13:50
Date Of Accident	29/01/2019 14:00
Exact Location Of Accident	CTE TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL2625R
Insured/Policyholder	
Name Of Registered Owner	NIE YING
Passport No/FIN	G0729185T
Email Address	NIEYING81@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97260998
Alternative Phone No	OTHERS-97260998

Vehicle Particulars

Manufacturer	LAND ROVER
Model	EVOQUE-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100354428-05
Cover Note Number	

Driver

Name of Driver	NIE RONG
Passport No/FIN	G0848799K
Date Of Birth	18/02/1994
Occupation	INDOOR
Date Of Driving Pass	01/11/2017
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83211378
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	17 CAIRNHILL CIRCLE #16-04
Postcode	229816
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer attachments.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL7652S
Vehicle Make/Model/Colour	LEXUS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MS LIU
NRIC/Passport Number	
Contact Number	81836017
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing w ith my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as w ell as on the external cover of envelopes/mail packages); and/or

(v) complying w ith applicable law in administering, processing, handling and/or dealing w ith my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

N. M. J.
Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (if driver is not the policyholder) / Date
& Time

Kueh
Witnessed by Reporting Centre Personnel

Sketch Plan

SKETCH PLAN

Describe Circumstance of the Accident

I was driving on ECTE Towards PIE. Vehical SLL76RS suddenly hit my car when Vehical SLL76RS trying join ~~my lane~~ ~~lane~~ to come out from slip road into my road.

The owner of Vehical SLL76RS offered the cash settlement on the accident scene and she admitted this accident was her fault.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre Personnel

SERVICE ESTIMATE

75584 - C00001 SL: SERVICE SALES - PC

Ms Nie Nie Ying
532 Upper Cross Street
#20-226

Singapore 050532

Closed by : Patricia Kueh Anak S
Svc Consultant :
Remarks : Ms Nie Ying

GST Reg.No:M28920628X
Inv.No. : B&P 0 Page 1
Inv.date : 30/01/2019
WIP No. : 51657
Veh.In/Out:
*Tel.No. : Mobile: 97260998
Reg.No. : SKL2625R
Reg.date : 18/10/2013
Mileage : 0
Chassis No: SALYA2A690H821060

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE DOOR FRT LH, DOOR REAR LH, DOOR MOULDING LH, ETC	0		3600.00	0		3,600.00 S	1800
800	TO PUTTY SPRAYPAINT ON DOOR FRT LH, DOOR REAR LH, ETC	0		3000.00	0		3,000.00 S	2000
802	TO TRANSFER DOOR FRT LH PART	0		500.00	0		500.00 S	
802	TO TRANSFER DOOR REAR LH PART	0		500.00	0		500.00 S	Xnn
208	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		486.00	0		486.00 S	
	DOOR REAR LH EVO 50 repair	1.0	EA	3125.90			3,125.90 S	
	DOOR PANEL FRT LH EV	1.0	EA	2726.50			2,726.50 S	2453.85
	DOOR SEAL PRIMARY FR	1.0	EA	218.10 218.10	0		218.10 S	218.10 196.19
	DOOR SEAL PRIMARY RE	1.0	EA	229.10			229.10 S	
	DOOR OUTSIDE MOULDIN	1.0	EA	257.30			257.30 S	231.57
	MOULDING - DOOR OUTS	1.0	EA	242.40			242.40 S	212.16

SERVICE ESTIMATE

75584 - C00001

SL: SERVICE SALES - PC

Ms Nie Nie Ying

532 Upper Cross Street
#20-226

Singapore 050532

Closed by : Patricia Kueh anak S

Svc Consultant :

Remarks : Ms Nie Ying

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 30/01/2019

WIP No. : 51657

Veh.In/Out:

*Tel.No. : Mobile: 97260998

Reg.No. : SKL2625R

Reg.date : 18/10/2013

Mileage : 0

Chassis No: SALVA2AG9DH821060

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	SOUND DEADENING PAD	110 EA	250.00			300.00	\$ 225
--	---------------------	--------	--------	--	--	--------	--------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten:
11/2/19
Hp 900 000 Gs
4 days
P/P
01/02/19 @ 1120
Reay 64 part

Labour Total	8,086.00
Parts Total	7,299.30
Package Total	0.00

Gross Total.	15,385.30	15750.20
Net.....	15,385.30	
GST @ 7.0%	1,076.97	
Total.....	16,462.25	
Paid.....	0.00	
Please Pay..	16,462.25	

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Handwritten:
15693
57.2

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date : 09/05/2019
 SINGAPORE 079909 WIP No. : 62476
 Veh.In/Out: 26/04/2019 02/05/2019
 *Tel.No. : 63896111
 Reg.No. : SKL2625R
 Closed by : Paul Ong Qing Yong Reg.date : 18/10/2013
 Svc Consultant : ACC Mileage : 23,885
 Remarks : Ms Nie Ying Chassis No: SALVA2AG9DH821060

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount	G
802	TO REPLACE DOOR FRT LH, DOOR MOULDING LH, REPAIR DOOR REAR LH, ETC	0	1800.00 / 0	1,800.00	S
800	TO PUTTY SPRAYPAINT ON DOOR FRT LH, DOOR REAR LH, ETC	0	2000.00 / 0	2,000.00	S
802	TO TRANSFER DOOR FRT LH PARTS	0	500.00 / 0	500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00 / 0	486.00	S
	DOOR PANEL FRT LH EV	1.0 EA	2726.50 / 10	2,453.85	S
	DOOR SEAL PRIMARY FR	1.0 EA	218.10 / 10	196.29	S
	LLR045546/DOOR OUTSI	1.0 EA	257.30 / 10	231.57	S
	LLR045553/MOULDING -	1.0 EA	242.40 / 10	218.16	S
	SOUND DEADENING PAD	1.0 EA	250.00 / 10	225.00	S
	BUMPER NUT XF <i>supp 1/2"</i>	13.0 EA	4.40 / 10	51.48	S
	MOULDING - DOOR WIND <i>supp sent</i>	1.0 EA	307.70 / 10	276.93	S

Gross Total. 8,439.28

Labour Total 4,786.00
 Parts Total 3,653.28
 Package Total 0.00

Net..... 8,439.28
 GST @ 7.0% 590.75
 Total..... 9,030.03
 Paid..... 0.00
 Please Pay.. 9,030.03

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Supp-

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 09/05/2019
 SINGAPORE 079909 WIP No. . : 62476
 Veh.In/Out: 26/04/2019 02/05/2019
 *Tel.No. . : 63896111
 Reg.No. . : SKL2625R
 Closed by : Paul Ong Qing Yong Reg.date .: 18/10/2013
 Svc Consultant : ACC Mileage ...: 23,885
 Remarks : Ms Nie Ying Chassis No: SALVA2AG9DHB21060

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER NUT XF	13.0 EA	4.40	10		51.48	S
	MOULDING - DOOR WIND	1.0 EA	307.70	10		276.93	S

Gross Total. 328.41

Labour Total 0.00
 Parts Total 328.41
 Package Total 0.00

Net..... 328.41
 GST @ 7.0% 22.99
 Total..... 351.40
 Paid..... 0.00
 Please Pay.. 351.40

GST: S=StdRated; O=OutOfScope; Z=ZeroRated




































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2019		01 Feb 2019 15:46 Edit Adj Rpt	\$48,439.28 Edit Estimates	\$48,439.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: -, ID: -									
Main Claimant: NIE YING									
Vehicle Reg. No.: SKL2625R		Date of Loss: 29/01/2019 14:00 - :59 [63 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D200753C02/2		Policy/Cover Note No.: DMPCSN18362718000							
Vehicle Reg. No. (Insured): SLL7652S		Policy No. (Claimant):							
		Excess: \$43,500.00							
Repairer: Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 14/02/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKL2625R (SNM19D200753C02/2)
[SLL7652S]
TP
NIE YING
Jan 29 2019 2:00PM
[-]
Wearnes Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
2	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
3	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
4	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
5	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
6	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
7	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
8	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
9	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
10	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
11	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
12	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
13	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
14	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
15	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
16	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
17	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
18	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
19	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
20	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
21	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
22	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
23	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
24	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
25	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
26	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
27	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
28	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
29	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
30	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
31	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
32	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
33	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
34	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
35	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
36	14/05/19 14:06	General View								Load JPG	<input checked="" type="checkbox"/>			
37	14/05/19 14:07	Reinspection Photo								Load JPG	<input checked="" type="checkbox"/>			

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	14/05/19 14:07	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	14/05/19 14:07	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	14/05/19 14:07	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	01/02/19 15:44	Pre-Repair Survey	1	Load PDF	
2	01/02/19 15:44	Pre-Repair Survey	1	Load PDF	
3	01/02/19 15:44	Pre-Repair Survey	1	Load PDF	
4	02/04/19 15:44	Singapore Accident Statement	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/05/19 08:13	SUPPLEMENTARY PART	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119002155/R1SD3Q2

Date: 17/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN18362718000
Claimant Vehicle No :	SKL2625R	Insured Vehicle No :	SLL7652S
Date of Loss:	29/01/2019	Nature of Claim:	TP
		Claim No:	SNM19D200753C02/2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL2625R	Engine No:	HIDDEN
Make & Model:	LAND ROVER EVOQUE, 2.0 (A)	Chassis No:	SALVA2AG9DH821060
Reg. Date:	18/10/2013 (Man. Year: 2013)	Odometer:	22586 km
Colour:	Red		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,627.71	3,653.28	3,974.43	52.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,086.00	4,786.00	3,300.00	40.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,713.71	8,439.28	7,274.43	46.29
+ GST 7.00/7.00% (S\$)	1,099.96	590.75	509.21	46.29
Nett Amount (S\$)	16,813.67	9,030.03	7,783.64	46.29

INSPECTION

Date of Assignment:	01/02/2019	
Date Inspected:	07/02/2019 Inspected At:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road Singapore 159935
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2019)
Parts:	M1-SUV	LAND ROVER EVOQUE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL2625R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR REAR LH EVO 5D	Repair	3,125.90 FS	*- FS
2	1		*DOOR PANEL FRT LH EV	Bent	2,726.50 FS	*2,453.85 FS
3	1		*DOOR SEAL PRIMARY FR	Necessary	218.10 FS	*196.29 FS
4	1		*DOOR SEAL PRIMARY RE	Not Necessary	229.10 FS	*- FS
5	1		*DOOR OUTSIDE MOULDIN	Scratched	257.30 FS	*231.57 FS
6	1		*MOULDING -DOOR OUTS	Scratched	242.40 FS	*218.16 FS
7	2		*SOUND DEADENING PAD	Necessary (1 PCS ONLY)	500.00 FS	*225.00 FS
8	1		*BUMPER NUT XF (13 PCS)	Necessary	51.48 FS	*51.48 FS
9	1		*MOULDING -DOOR WIND	Cracked	276.93 FS	*276.93 FS
Total Parts (S\$)					7,627.71	3,653.28

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE DOOR FRT LH,DOOR REAR LH ,DOOR MOULDING LH,ETC	New	3,600.00	1,800.00
2	TO PUTTY SPRAYPAINT ON DOOR FRT LH,DOOR REAR LH ,ETC	New	3,000.00	2,000.00
3	TO TRANSFER DOOR FRT LH PART	New	500.00	500.00
4	TO TRANSFER DOOR REAR LH PART	New	500.00	0.00
5	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	New	486.00	486.00
Gross Labour Cost (\$\$)			8,086.00	4,786.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >