

22/03/2002

ASS. REC. BY:

REF:

CS3/MSG19002197/11C0302

Special Instruction:

Surveyor
Menmen

Tawhieh

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSG

Date/Time:

4/2/19 @ 12 pm

Estimated Cost:

Bill to:

OD - ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 4048 K

Insured:

SKE 66194

at Workshop m/s

Lian Her Motors

Tel:

82990599

of

Blk 5038 Amk Ave 3 # 01-405

Policy No:

27468640

Claim No:

584148

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/01/2019

CA / REV / REP. / REV 24 HRS

up?

H.O.D. Endorsement:

Date/Time:

7/2/19 @ 9.41 am

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction () Estimate

7/2/19

call back on 8/2/19 as wlep is closed for CNY. (No answer)

SLP 4048K - X

SKE 66194 - X

8/2/19 -

wlep is closed, Repairer ask call back on 11/2/19

Dismantle: 12/2/2019

After repair: 15/2/2019

Tang

REF: MSIG

PRS (Meimien)


ASSIGNMENT

From: Date: 11/2/19
Estimated Cost:
OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLP 4048K
at Workshop n/s: Lion Her Motor
of: BIK 5038 AMK Ave 3 #01-405
Insured:
Policy No:
Claims No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:

Veh No: SLP 4048K Regn: 2017 June
Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Wish CC: 1792
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 144589 T/Radio: Insured / Std / NI / NA
Eng No:
C/No: 2GE 206034373
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 145/65K15
R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:
IDAC Accident Rpt. Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lump Sum: % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 11/2/19 @ 440pm
Survey held at: Lion Her Motor

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$2,800 - \$3,500

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Transportation

1) S + RS \$1

2) Photos

3) Other

4) ...

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$)

120

10

130

21/2/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Feb 2019 16:44		04 Feb 2019 12:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SUZETTE ANN PETERSON, ID: S7176914C		
Main Claimant:	L H CAR RENTAL PTE LTD, Co. Reg. No.: 200009761N		
Vehicle Reg. No.:	SLP4048K	Date of Loss:	31/01/2019 13:00 - :59 [19 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584148	Policy/Cover Note No.:	27468640 (Comprehensive) Coverage: 23/03/2018 - 22/03/2019
Vehicle Reg. No. (Insured):	SKE6619U	Policy No. (Claimant):	
		Excess:	
Repairer:	Lian Her Motors (HQ) Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2, 569541 Ang Mo Kio - Tel: 82990599		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/02/2019]		
Driver/Custodian (Insured):	LEA PATRICIA NG (/ Female), NRIC: S9832670G		
Adj Asg. Remarks:	Liability 50%. SJE disagree - assign LKK. Contact : Mr. James @ 8299 0599 (Please call before going)		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9761N
Vehicle Details	
Vehicle No.:	SLP4048K
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	2ZR1816317
Chassis No.:	ZGE206034373
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$20,133.00
Original Registration Date:	02 Jun 2017
First Registration Date:	02 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$20,187.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jun 2027
PARF Rebate Amount:	\$15,140.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$43,854.00
Total Rebate Amount:	\$58,994.00

The information contained herein is correct as at 23 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	31/01/2019 16:43
Date Of Accident	31/01/2019 13:15
Exact Location Of Accident	OPHIR RD TURNING TO QUEEN RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP4048K
Insured/Policyholder	
Name Of Registered Owner	L H CAR RENTAL PTE LTD
Co Reg No	200009761N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93227428
Alternative Phone No	OFFICE-93227428
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5083404689-02
Cover Note Number	
Driver	
Name of Driver	WONG PENG XIANG
NRIC No	S8931444E
Date Of Birth	09/09/1989
Occupation	OUTDOOR
Date Of Driving Pass	28/05/2009
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93227428
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	18 JLN HIKAYAT
Postcode	769862
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	KIV, SUBMIT BY CLAIMANT WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE6619U
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEA PATRICIA NG
NRIC/Passport Number	S9832670G
Contact Number	81270594
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WONG PENG XIANG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLP4048K

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

L.H CAR RENTAL PTE LTD

L.H CAR RENTAL PTE LTD


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling on OPHIR ROAD, while turning to QUEEN ROAD, vehicle B (SUV KIA) went straight instead of turning right. As a result in a collision.

I wish to state that I have an in-car camera and I have a passenger on board.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

L.H CAR RENTAL PTE LTD

Policyholder's Signature

Date & Time:

L.H CAR RENTAL PTE LTD

00000000000000000000

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



































...CLAIM SUBFOLDER...(Pending for Survey Report)




























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2019 16:44		04 Feb 2019 12:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SUZETTE ANN PETERSON , ID: S7176914C									
Main Claimant: L H CAR RENTAL PTE LTD , Co. Reg. No.: 200009761N									
Vehicle Reg. No.: SLP4048K		Date of Loss: 31/01/2019 13:00 - :59 [19 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 584148		Policy/Cover Note No.: 27468640 (Comprehensive) Coverage: 23/03/2018 - 22/03/2019							
Vehicle Reg. No. (Insured): SKE6619U		Policy No. (Claimant):							
		Excess:							
Repairer: Lian Her Motors (HQ) Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2, 569541 Ang Mo Kio - Tel: 82990599									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 05/02/2019]									
Driver/Custodian (Insured): LEA PATRICIA NG (/ Female) , NRIC: S9832670G Email:									
Adj Asg. Remarks: Liability 50%. SJE disagree - assign LKK. Contact : Mr. James @ 8299 0599 (Please call before going)									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLP4048K (584148)**
[SKE6619U]
TP
L H CAR RENTAL PTE LTD
Jan 31 2019 1:00PM
[SUZETTE ANN PETERSON]
Lian Her Motors

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/02/19 10:39	Accident Statement From: SC - Reg. No: SKE6619U, Claimant: SUZETTE ANN PETERSON	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/02/19 12:53	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/02/19 12:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	23/02/19 12:54	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/02/19 16:47	SLP4048K E-file report	 Load PDF	
2	01/02/19 16:47	PRI from Vision Law LLC	 Load PDF	
3	04/02/19 09:46	Survey Disagree on SJE - assign LKK	 Load PDF	
4	04/02/19 10:00	TP Workshop details	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19002197/T1CD3E2**Date:** 12/03/2019REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27468640

Claimant Vehicle No : SLP4048K**Insured Vehicle No :** SKE6619U

Date of Loss: 31/01/2019

Nature of Claim: TP

Claim No: 584148

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP4048K**

Make & Model: TOYOTA WISH, 1.8 X CVT (A)

Engine No: 2ZR1816317

Reg. Date: 02/06/2017 (Man. Year: 2016)

Chassis No: ZGE206034373

Colour: White

Odometer: 144589 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/02/2019

Date Inspected: 11/02/2019 Inspected At:

Lian Her Motors (HQ)
Block 5038 Ang Mo Kio Avenue 3, #01-405
Ang Mo Kio Industrial Park 2
Singapore 569541

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 - \$3,500.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP4048K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >