

ASS. RECEIPT

REF: CS3/CTI19002204/Ecd3<sup>52</sup>

Special Instruction

wait

Call Vex/01

Minimen

From (Person)

Steve  
Ong chin kiut

ASSIGNMENT (Office)

CTI

Date/Time

1/2/19 @ 5:30pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No.

SKD 9074B

Insured

GBE 8023G

at Workshop m/s

SAT Motors

Tel

9859 9677

of

21 Defu Lane 12

Policy No.

DMCVSN30221618011

Claim No.

SNM190200505

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

26/01/2019

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement

Date/Time

12:08pm @ 7/2/19

Person Contacted

Jerry

Vehicle IN

OUT

Date/Time

Action/Instruction (X) Estimate

7/2/19-

workshop is closed for CNY, call back on 8/2/19 (No answer)

SKD 9074B -X

GBE 8023G - CS/CTI/7012435/Uubm2

Don: 29/1/2017

8/2/19-

called 2 times (No answer)

11/2/19-

called back on 13/2/19 (workshop closed) but not yet

Dismantle: 18/2/2019

PRG

REF: CTE

ASSIGNMENT

Date: 15/2/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

SKD 9074B

at Workshop no

SAT Motor

at

24 Defu bene 12

Insured

Policy No

Claim No

Sum Insured

Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs

2

days

Res.: Yes or No

Lump Sum

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKD 9074B

at Regd

17/01/2012

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta

C.C.

L# 1390.

Colour

Grey

A/C

Insured / Std / NI / NA

Sp. Reading

131249

T/Radio

Insured / Std / NI / NA

Eng No

C No: WVV 222 16 Z CM 067795

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

205 / 55 ZR16

R:

.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GREMAX

Front

Rear

R/Bal

7

mm

R/Bal

7

mm

L/Bal

7

mm

L/Bal

7

mm

D.O.A.

26/1/19

D.O.A.

15/2/19

Survey held at

SAT Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair range 3K - 4K

25/2/2019

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation

1. S + PC

2. Photo

3. Other

TOTAL

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$

Report Format:

PRG

Lump Sum / L.B.L. (\$

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2019		01 Feb 2019 17:30 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	ELAIE CHOY		
Vehicle Reg. No.:	SKD9074B	Date of Loss:	26/01/2019 12:00 - :59
Claim Type:	TP / SNM19D200505	Policy/Cover Note No.:	DMCVSN30221618011
Vehicle Reg. No. (Insured):	GBE8023G	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/02/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupeil@lkkauto.com>  
**Sent:** Monday, 11 February 2019 9:10 AM  
**To:** assignments  
**Subject:** FW: CY.SKD9074B.19.SAT.wp(Lh); Your Ref: GBE 8023G  
**Attachments:** CY.SKD9074B.19.SAT.wp(Lh)\_GIA.PDF

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 8 February 2019 11:19 AM  
**To:** Lheny <lheny@yoga-legal.com>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: CY.SKD9074B.19.SAT.wp(Lh); Your Ref: GBE 8023G

Without Prejudice

Dear Lheny,

We appoint LKK.

Dear LKK,

Kindly proceed pri.

Thank you.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Lheny [mailto:lheny@yoga-legal.com]  
**Sent:** Wednesday, 30 January, 2019 5:51 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** CY.SKD9074B.19.SAT.wp(Lh); Your Ref: GBE 8023G

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SKD 9074B & GBE 8023G ON 26.01.2019 @ 12:40HRS ALONG TAMPINES AVE 7 TWDS AVE 9 JUNCTION**

We are instructed by ELAIE CHOY to notify you of a road traffic accident on 26.01.2019 @ 12:40hrs along Tampines Ave 7 twds Ave 9 junction involving our client's customer's vehicle registration number SKD 9074B and vehicle registration number GBE 8023G driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

At the same time, our proposed list of surveyors is appended as below:

1. Lim Chang Liang
2. Lim Yong Tian, Sebastian
3. Jonathan Lim

As the appointed workshop is a small workshop, we are unable to provide you with more than the above listed motor surveyors. We trust you will able to choose a surveyor from above.

Please be informed that our client's vehicle can be inspected at:  
M/s. SAT Motors  
24 Defu Lane 12, Singapore 539131  
Jonathan (9126 9987) / Jessie (9859 9677)  
Fax No. 6749 1141

Best regards,

Lheny

M/s C YOGARAJAH LLC  
883 North Bridge Road  
#11-03 Southbank  
Singapore 198785

Tel: 6292 5838  
Fax: 6292 5938

Email: [lheny@yoga-legal.com](mailto:lheny@yoga-legal.com)

For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/01/2019 18:11
Date Of Accident	26/01/2019 12:40
Exact Location Of Accident	TAMPINES AVE 7 TOWARDS AVE 9 JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD9074B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ELAINE CHOY
NRIC No	S9328432A
Email Address	EEELAINECHOYYY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97768499
Alternative Phone No	OFFICE-97768499

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102454567
Cover Note Number	

### Driver

Name of Driver	ELAINE CHOY
NRIC No	S9328432A
Date Of Birth	15/08/1993
Occupation	INDOOR
Date Of Driving Pass	06/05/2014
Driving Experience	4 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97768499
Fax Number	
Contact Number	OFFICE-97768499
Email Address	EEELAINECHOYYY@GMAIL.COM

No. Of Passenger (Including Driver)



1. SKETCH PLAN

Tampines Ave 7



A - SKD 9074 B  
B - GBE8023G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/01/19 I was travelling along tampines ave 7 towards ave 9 Junction. As I was approaching the traffic light Junction, I was on the extreme right lane getting ready to turn right into Ave 9.

There are 2 right turning lane. I was in the extreme right. While I was about to make the turn, vehicle B (GBE8023G) on my left cuts into my lane while turning and collided into my car.

We get down and exchange particulars and there are some damages on my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

[Signature]  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

[➤ Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8432A
Vehicle Details	
Vehicle No.:	SKD9074B
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Feb 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1622G5
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	CAX941351
Chassis No.:	WVWZZZ16ZCM067795
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,825.00
Original Registration Date:	17 Jan 2012
First Registration Date:	17 Jan 2012
Transfer Count:	1
Actual ARF Paid:	\$18,825.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2022
PARF Rebate Amount:	\$11,295.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,112.00
COE Rebate Amount:	\$16,366.00
Total Rebate Amount:	\$27,661.00

The information contained herein is correct as at 16 Feb 2019

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2019		01 Feb 2019 17:30 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	ELAIE CHOY		
Vehicle Reg. No.:	SKD9074B	Date of Loss:	26/01/2019 12:00 - :59 [84 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D200505	Policy/Cover Note No.:	DMCVSN30221618011
Vehicle Reg. No. (Insured):	GBE8023G	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 14/02/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SKD9074B (SNM19D200505)**

**[GBE8023G]**

**TP**

**ELAIE CHOY**

**Jan 26 2019 12:00PM**

**[-]**

**Sat Motors**



[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

### Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/02/19 08:32	General View	1	Load JPG	
2	20/02/19 08:32	General View	1	Load JPG	
3	20/02/19 08:32	General View	1	Load JPG	
4	20/02/19 08:32	General View	1	Load JPG	
5	20/02/19 08:32	General View	1	Load JPG	
6	20/02/19 08:32	General View	1	Load JPG	
7	20/02/19 08:32	General View	1	Load JPG	
8	20/02/19 08:32	General View	1	Load JPG	
9	20/02/19 08:32	General View	1	Load JPG	
10	20/02/19 08:32	General View	1	Load JPG	
11	20/02/19 08:32	General View	1	Load JPG	
12	20/02/19 08:32	General View	1	Load JPG	
13	20/02/19 08:32	General View	1	Load JPG	
14	20/02/19 08:32	General View	1	Load JPG	
15	20/02/19 08:32	General View	1	Load JPG	
16	20/02/19 08:32	General View	1	Load JPG	
17	20/02/19 08:32	General View	1	Load JPG	
18	20/02/19 08:32	General View	1	Load JPG	
19	20/02/19 08:32	General View	1	Load JPG	
20	20/02/19 08:32	General View	1	Load JPG	
21	20/02/19 08:32	General View	1	Load JPG	
22	20/02/19 08:32	General View	1	Load JPG	
23	20/02/19 08:32	General View	1	Load JPG	
24	20/02/19 08:32	General View	1	Load JPG	
25	20/02/19 08:32	General View	1	Load JPG	
26	20/02/19 08:32	General View	1	Load JPG	
27	20/02/19 08:32	Chassis Number	1	Load JPG	
28	20/02/19 08:32	General View	1	Load JPG	
29	20/02/19 08:32	General View	1	Load JPG	
30	20/02/19 08:32	General View	1	Load JPG	
31	20/02/19 08:32	General View	1	Load JPG	
32	20/02/19 08:32	General View	1	Load JPG	
33	20/02/19 08:32	General View	1	Load JPG	
34	20/02/19 08:32	Odometer Reading	1	Load JPG	
35	20/02/19 08:32	General View	1	Load JPG	

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	20/02/19 08:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/02/19 08:32	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/02/19 08:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/02/19 08:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/02/19 08:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/02/19 08:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/02/19 08:34	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119002204/ECD3S2

Date: 11/03/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMCVSN30221618011

Claimant Vehicle No: SKD9074B

Insured Vehicle No: GBE8023G

Date of Loss: 26/01/2019

Nature of Claim: TP

Claim No: SNM19D200505

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKD9074B

Make &amp; Model: VOLKSWAGEN JETTA, 1.4 TSI 1622G5 (A)

Engine No: CAX941351

Reg. Date: 17/01/2012 (Man. Year: 2011)

Chassis No: WVVZZZ16ZCM067795

Colour: Grey

Odometer: 131249 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55ZR16

Rear Tyre Size: 205/55ZR16

Front Left Side: Gremax 7 mm

Rear Left Side: Gremax 7 mm

Front Right Side: Gremax 7 mm

Rear Right Side: Gremax 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 01/02/2019

Date Inspected: 15/02/2019

Inspected At:

Sat Motors (HQ)  
24 Defu Lane 12  
Singapore 539131

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 11 Mar 2019)

**Parts:** 143      VOLKSWAGEN JETTA 1.4 TSI 1622G5 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKD9074B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >